

Submittal to District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1040 E. 10th St., Las Cruces, NM 88001
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103

June 19, 2008

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-34561
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: MONUMENT 36 STATE
8. Well Number #2
9. OGRID Number 005380
10. Pool name or Wildcat Goodwin, ABO

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input checked="" type="checkbox"/>	7. Lease Name or Unit Agreement Name: MONUMENT 36 STATE
2. Name of Operator XTO Energy, Inc.	8. Well Number #2
3. Address of Operator 200 N. Loraine, Ste. 800 Midland, TX 79701	9. OGRID Number 005380
4. Well Location Unit Letter <u>I</u> : <u>1632</u> feet from the <u>south</u> line and <u>1298</u> feet from the <u>east</u> line Section <u>13</u> Township <u>19S</u> Range <u>36E</u> NMPM County <u>LEA</u>	10. Pool name or Wildcat Goodwin, ABO
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: Clean-out, Sonic Hammer, Stimulate ☒

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Move in & rack WS.
2. POH w/rods & pump. Set BOP. Tag TD & POH. TIH w/bit & cleanout to TD. POH.
3. TIH w/sonic hammer on WS. RU stripping band.
4. RU acid company & sonic hammer OH w/9# brine while circ. Circ hole clean. Catch samples & analyze. Close in backside & sonic happer OH w/5000 gals 15% mixed 90% acid 10% toulene in inj mode. 500# max on backside. Flush acid w/30 bbls 9# brine. Drop ball to shift sleeve in tool.
5. Flowback or RU swab & swab back acid load. POH w. sonic hammer.
6. TIH w/production equipment & RWTP.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Sherry Pack TITLE Regulatory Analyst DATE 11/24/08
Type or print name Sherry Pack E-mail address: sherry_pack@xtoenergy.com PHONE 432.620.6709

For State Use Only

PETROLEUM ENGINEER

NOV 26 2008


APPROVED BY [Signature] TITLE DATE
Conditions of Approval (if any):

XTO ENERGY



Well: Monument State # 36-2
Area: North Monument
Location: Section 36-18S-36E
County: Lea
Elevation: 3742' GL

WI: 100.000000%
NRI: 87.500000%
Spud: 4/07/99
State: New Mexico



PREPARED BY: Greg Hicks

DATE: 6/5/08