Submit 3 Copies To Appropriate District	State of New Me	xico	Form C-103
District I	Minerals and Natu	ral Resources	June 19, 2008 WELL API NO.
Office District I District I District I District II Office			30-025-0682633607
District II 1301 W Grand Ave, Artesia, NM 88210 District III District			5. Indicate Type of Lease STATE STATE FEE
			6. State Oil & Gas Lease No.
District IV 1220 S St Francis Dr., Santa Fe, NM 87410 87505			B 3654
87505 SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			McGrail State
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)			8. Well Number #9
1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other			
2. Name of Operator Marathon Oil Company			9. OGRID Number 14021
3. Address of Operator			10. Pool name or Wildcat
P.O. Box 3487 Houston, Texa	s 77253-3487 <u>N</u>	<u>1ail Stop</u> #3308	Monument – Yeso-Nothwest
4. Well Location Unit Letter K 1960' feet from the South line and 1650' feet from the West line			
Section 26 Township 19-S Range 36-E NMPM County LEA 11. Elevation (Show whether DR, RKB, RT, GR, etc. 11. Elevation (Show whether DR, RKB, RT, GR, etc. 11. Elevation (Show whether DR, RKB, RT, GR, etc. 11. Elevation (Show whether DR, RKB, RT, GR, etc.			
3,681' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTIO	ΝΤΟ:	SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK D PLUG AND ABANDON REMEDIAL WOR			
		COMMENCE DRI CASING/CEMEN	
PULL OR ALTER CASING DOWNHOLE COMMINGLE		CASING/CEMEN	
	_		_
OTHER: OTHER: Image: Constraint of the state of			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
** Marathon Oil Company is requesting a Temporary Abandonment status for the above mentioned well, McGrail State #9.			
RU WSU. Install and test BOPE. Condition of Approval: Notify OCD Hobbs			
office 24 hours prior to running MIT Test & Chart			
• POOH with tubing and remove ESP equipment.			
• RIH and set CIBP at 6,600'. Load wellbore with fresh water and test to 500 psi per NMOCD			
requirements. (Notify 'NMOC	D' 48-hours prior	to test.).	
Lay down tubing. Install wellhead. RD WSU.			
• 0			
* <u>Note</u> : Fresh water to be used, and no solids or waste are to be generated. <i>There are no plans to remove any fluids from the well during this work, and as indicated above, we plan to top off the well with fresh water once the plug is set. The only fluid on location during this work will be fresh water.</i>			
Spud Date: Estimated: January 2009.	Rig Release Da	tte: Estimated	: January 2009.
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Bick B. Chall TITLE: Regulatory Compliance Representative DATE: 13-Jan-2009			
Type or print name: <u>Rick R Schell</u> , E-mail address: <u>RRSCHELL@MarathonOil.com</u> , PHONE: <u>713-296-3412</u>			
For State Use Only			
APPROVED BY:			

