Submit 3 Copies To Appropriate District State of New Mexico	Form C-103 Revised March 25, 1999
Office District I	WELL API NO.
1625 N. French Dr., Hobbs, NM 88240	30025038100000
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1220 South St. Francis Dr.	STATE FEE
000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe NM 87505	6. State Oil & Gas Lease No.
District IV (220 S. St. Francis Dr., Santa Fe, NM	B-2359
37505	The second secon
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name:
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	LSAU
PROPOSALS.)	
I. Type of Well:	
Oil Well Gas Well Other	8. Well No. 47
2. Name of Operator	6. Well 110. 47
Pure Resources	9. Pool name or Wildcat
3. Address of Operator	San Andres
500 W. Illinois Midland, Texas 79701	· · · · · · · · · · · · · · · · · · ·
4. Well Location	
Unit LetterK: _1980'feet from the _South line and 1	1980'_feet from theWest line
Section 1 Township 17S Range	36E NMPM LEA County
10. Elevation (Show whether DR, RKB, RT,	GR, etc.)
3836' DF' GR	
11. Check Appropriate Box to Indicate Nature of N	lotice, Report or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK I PLUG AND ABANDON REMEDIA	
TEMPORARILY ABANDON 🔲 CHANGE PLANS 📋 COMMEN	ICE DRILLING OPNS. PLUG AND ABANDONMENT
	TEST AND
PULL OR ALTER CASING DULTIPLE CASING COMPLETION CEMENT	
OTHER: OTHER:	Injection well
2. Describe proposed or completed operations. (Clearly state all pertinent details	s, and give pertinent dates, including estimated date of
starting any proposed work). SEE RULE 1103. For Multiple Completions: A	Attach wellbore diagram of proposed completion or
recompilation.	125262720
3 " 50# casing set at 297' (circ)	2324,25262728-29.3
3 5/8" 32# casing set at 3,104' (circ)	
5 1/2 " 17# casing set at 4,620' (circ)	
Open HOLE COMPLETION 4620'-4944'	
Jpen HOLE COMPLETION 4020 4744	51 CD 55 V 20
NITECTION DA CKER SET AT 4467' Baker Lok-set	,iii \‴ ⊡ &/
NIECTION PACKER SET AT 4467' Baker Lok-set	
NJECTION PACKER SET AT 4467' Baker Lok-set	on tubing string.
NJECTION PACKER SET AT 4467' Baker Lok-set Well was pulled to change top joint of tubing that was corroded and could cause sp After pulling top joint, injection string was inspected and found to have 70% loss o	n tubing string.
NJECTION PACKER SET AT 4467' Baker Lok-set Well was pulled to change top joint of tubing that was corroded and could cause sp After pulling top joint, injection string was inspected and found to have 70% loss o Replaced all tubing with new and yellow band IPC 2 3/8 tubing. Install new packer	n tubing string.
NJECTION PACKER SET AT 4467' Baker Lok-set Well was pulled to change top joint of tubing that was corroded and could cause sp After pulling top joint, injection string was inspected and found to have 70% loss o Replaced all tubing with new and yellow band IPC 2 3/8 tubing. Install new packer Post work over mechanical integrity test witnessed by NMOCD Robinson	n tubing string.
NJECTION PACKER SET AT 4467' Baker Lok-set Well was pulled to change top joint of tubing that was corroded and could cause sp After pulling top joint, injection string was inspected and found to have 70% loss o Replaced all tubing with new and yellow band IPC 2 3/8 tubing. Install new packer Post work over mechanical integrity test witnessed by NMOCD Robinson Starting Pressure: 520 P.S.I.	on tuoing string. (9,
NJECTION PACKER SET AT 4467' Baker Lok-set Well was pulled to change top joint of tubing that was corroded and could cause sp After pulling top joint, injection string was inspected and found to have 70% loss o Replaced all tubing with new and yellow band IPC 2 3/8 tubing. Install new packer Post work over mechanical integrity test witnessed by NMOCD Robinson Starting Pressure: 520 P.S.I.	n tubing string.
NJECTION PACKER SET AT 4467' Baker Lok-set Well was pulled to change top joint of tubing that was corroded and could cause sp After pulling top joint, injection string was inspected and found to have 70% loss o Replaced all tubing with new and yellow band IPC 2 3/8 tubing. Install new packer Post work over mechanical integrity test witnessed by NMOCD Robinson Starting Pressure: 520 P.S.I. Final Pressure: 510 P.S.I.	
NJECTION PACKER SET AT 4467' Baker Lok-set Well was pulled to change top joint of tubing that was corroded and could cause sp After pulling top joint, injection string was inspected and found to have 70% loss o Replaced all tubing with new and yellow band IPC 2 3/8 tubing. Install new packer Post work over mechanical integrity test witnessed by NMOCD Robinson Starting Pressure: 520 P.S.I. Final Pressure: 510 P.S.I.	nowledge and belief.
NJECTION PACKER SET AT 4467' Baker Lok-set Well was pulled to change top joint of tubing that was corroded and could cause sp After pulling top joint, injection string was inspected and found to have 70% loss o Replaced all tubing with new and yellow band IPC 2 3/8 tubing. Install new packer Post work over mechanical integrity test witnessed by NMOCD Robinson Starting Pressure: 520 P.S.I. Final Pressure: 510 P.S.I.	nowledge and belief.
NJECTION PACKER SET AT 4467' Baker Lok-set Well was pulled to change top joint of tubing that was corroded and could cause sp After pulling top joint, injection string was inspected and found to have 70% loss o Replaced all tubing with new and yellow band IPC 2 3/8 tubing. Install new packer Post work over mechanical integrity test witnessed by NMOCD Robinson Starting Pressure: 520 P.S.I. Final Pressure: 510 P.S.I. I hereby certify that the information above is true and complete to the best of my keeps SIGNATURE Mathematical Mathematical Mathematical Mathematical Final Pressure: 510 P.S.I. I hereby certify that the information above is true and complete to the best of my keeps	Foreman DATE 12-1-03
NJECTION PACKER SET AT 4467' Baker Lok-set Well was pulled to change top joint of tubing that was corroded and could cause sp After pulling top joint, injection string was inspected and found to have 70% loss o Replaced all tubing with new and yellow band IPC 2 3/8 tubing. Install new packer Post work over mechanical integrity test witnessed by NMOCD Robinson Starting Pressure: 520 P.S.I. Final Pressure: 510 P.S.I. I hereby certify that the information above is true and complete to the best of my ker SIGNATURE Mathematical Mathematical Mathematical Mathematical Type or print name Mit. Mathematical Mathematical Mathematical Mathematical Type or print name Mit.	Telephone No. 805-346-72
NJECTION PACKER SET AT 4467' Baker Lok-set Well was pulled to change top joint of tubing that was corroded and could cause sp After pulling top joint, injection string was inspected and found to have 70% loss o Replaced all tubing with new and yellow band IPC 2 3/8 tubing. Install new packer Post work over mechanical integrity test witnessed by NMOCD Robinson Starting Pressure: 520 P.S.I. Final Pressure: 510 P.S.I. I hereby certify that the information above is true and complete to the best of my keep SIGNATURE Mathematical Mathematical Mathematical After pulling top pressure: 510 P.S.I. Final Pressure: 510 P.S.I. Type or print name Mathematical	Telephone No. 805-346-72
NJECTION PACKER SET AT 4467' Baker Lok-set Well was pulled to change top joint of tubing that was corroded and could cause sp After pulling top joint, injection string was inspected and found to have 70% loss o Replaced all tubing with new and yellow band IPC 2 3/8 tubing. Install new packer Post work over mechanical integrity test witnessed by NMOCD Robinson Starting Pressure: 520 P.S.I. Final Pressure: 510 P.S.I. I hereby certify that the information above is true and complete to the best of my ker SIGNATURE Machine Mite Month Cutt Type or print name Mite Month Cutt (This space for State use)	Telephone No. 805-396-75
NJECTION PACKER SET AT 4467' Baker Lok-set Well was pulled to change top joint of tubing that was corroded and could cause sp After pulling top joint, injection string was inspected and found to have 70% loss o Replaced all tubing with new and yellow band IPC 2 3/8 tubing. Install new packer Post work over mechanical integrity test witnessed by NMOCD Robinson Starting Pressure: 520 P.S.I. Final Pressure: 510 P.S.I. I hereby certify that the information above is true and complete to the best of my keep SIGNATURE Mathematical Ma	Telephone No. 805-396-22 /E-11/STAFF MANAGER DEC 0 3
NJECTION PACKER SET AT 4467' Baker Lok-set Well was pulled to change top joint of tubing that was corroded and could cause sp After pulling top joint, injection string was inspected and found to have 70% loss o Replaced all tubing with new and yellow band IPC 2 3/8 tubing. Install new packer Post work over mechanical integrity test witnessed by NMOCD Robinson Starting Pressure: 520 P.S.I. Final Pressure: 510 P.S.I. I hereby certify that the information above is true and complete to the best of my keep SIGNATURE Mathematical Ma	Telephone No. 805-396-22 /E-11/STAFF MANAGER DEC 0 3
NJECTION PACKER SET AT 4467' Baker Lok-set Well was pulled to change top joint of tubing that was corroded and could cause sp After pulling top joint, injection string was inspected and found to have 70% loss o Replaced all tubing with new and yellow band IPC 2 3/8 tubing. Install new packer Post work over mechanical integrity test witnessed by NMOCD Robinson Starting Pressure: 520 P.S.I. Final Pressure: 510 P.S.I. I hereby certify that the information above is true and complete to the best of my ker SIGNATURE Machine Mite Month Cutt Type or print name Mite Month Cutt (This space for State use)	Telephone No. 805-396-20 Telephone No. 805-396-20 JE 11/STAFF MANAGER DEC 0 3
NJECTION PACKER SET AT 4467' Baker Lok-set Well was pulled to change top joint of tubing that was corroded and could cause sp After pulling top joint, injection string was inspected and found to have 70% loss o Replaced all tubing with new and yellow band IPC 2 3/8 tubing. Install new packer Post work over mechanical integrity test witnessed by NMOCD Robinson Starting Pressure: 520 P.S.I. Final Pressure: 510 P.S.I. I hereby certify that the information above is true and complete to the best of my keep SIGNATURE Mathematical Ma	Telephone No. 805-396-20 Telephone No. 805-396-20 JE 11/STAFF MANAGER DEC 0 3

