



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

Response Required – Deadline Enclosed

Underground Injection Control Program

"Protecting Our Underground Sources of Drinking Water"

28-Jan-09

APACHE CORP

6120 S YALE SUITE 1500

TULSA OK 74136-4224

**LETTER OF VIOLATION and SHUT-IN DIRECTIVE
Failed Mechanical Integrity Test**

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION

EAST BLINEBRY DRINKARD UNIT No.003

30-025-06325-00-00

Active Injection - (All Types)

M-1-21S-37E

Test Date: 1/28/2009

Permitted Injection PSI:

Actual PSI:

Test Reason: Annual IMIT

Test Result: F

Repair Due: 5/3/2009

Test Type: Bradenhead Test

FAIL TYPE: Communication Between

FAIL CAUSE:

Comments on MIT: BHT FAILURE, CONTINUOUS BLOW OF OIL ON SURFACE CSG, BLOW OF WATER ON PROD.
SHUT IN

EAST BLINEBRY DRINKARD UNIT No.018

30-025-06479-00-00

Active Injection - (All Types)

A-11-21S-37E

Test Date: 1/28/2009

Permitted Injection PSI:

Actual PSI:

Test Reason: Annual IMIT

Test Result: F

Repair Due: 5/3/2009

Test Type: Bradenhead Test

FAIL TYPE: Communication Between

FAIL CAUSE:

Comments on MIT: BHT FAILURE, BLOW OF OIL ON PROD. WOULD NOT BLEED DOWN THROUGH VAC. TRUCK.
SHUT IN

LOCKHART B-13 A No.004**30-025-06558-00-00**

Active Salt Water Disposal Well

K-13-21S-37E

Test Date:	1/28/2009	Permitted Injection PSI:	Actual PSI:
Test Reason:	5-year Test	Test Result:	F
Test Type:	Std. Annulus Pres. Test	FAIL TYPE:	Other Internal Failure
Comments on MIT:	Well will not hold pressure WITHIN ACCEPTABLE LIMITS.		

EAST BLINEBRY DRINKARD UNIT No.053**30-025-06566-00-00**

Active Injection - (All Types)

C-13-21S-37E

Test Date:	1/28/2009	Permitted Injection PSI:	Actual PSI:
Test Reason:	Annual IMIT	Test Result:	F
Test Type:	Bradenhead Test	FAIL TYPE:	Other Internal Failure
Comments on MIT:	BHT FAILURE, CONTINUOUS BLOW OF WATER BLEED INTO VAC. TRUCK TOTALLING 10 BBLs.		

STEVENS B No.008**30-025-09329-00-00**

Active Salt Water Disposal Well

A-12-23S-36E

Test Date:	1/28/2009	Permitted Injection PSI:	Actual PSI:
Test Reason:	5-year Test	Test Result:	F
Test Type:	Std. Annulus Pres. Test	FAIL TYPE:	Other Internal Failure
Comments on MIT:	Well will not hold pressure WITHIN ACCEPTABLE LIMITS. BLOW OF WATER ON PRODUCTION CSG. SHUT IN		

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.


Sincerely,

 C. O.

Hobbs OCD District Office

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. * Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



017H15554612
HASLER
\$0.420
01/28/2009
Mailed From 88240
US POSTAGE

APACHE CORP
6120 S YALE SUITE 1500
TULSA, OK 74136-4224