| Submit 3 Copies To Appropriate District Office District I  State of New Mexico Energy, Minerals and Natural Resources  | Form C-103<br>Revised March 25, 1999   |
|--|--|
| <u>District I</u> 1625 N. French Dr., Hobbs, NM 88240  | WELL API NO.                           |
| District II 1301 W. Grand Avenue, Artesia, NM 88210 OIL CONSERVATION DIVISION  | 30-025-10889                           |
| District III 1220 South St. Francis Dr.  | 5. Indicate Type of Lease              |
| 1000 Rio Brazos Rd., Aztec, NM 87410  District IV  Santa Fe, NM 87505  | STATE FEE 6. State Oil & Gas Lease No. |
| 1220 S. St. Francis Dr., Santa Fe, NM 87505  | o. State on & Gas Lease No.            |
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  | 7. Lease Name or Unit Agreement Name:  |
| 1. Type of Well: Oil Well  Gas Well Other  | G.P. Livermore Cowden                  |
| 2. Name of Operator Chevron USA Inc  | 8. Well No.                            |
| 3. Address of Operator 15 Smith Rd, Midland, TX, 79705   | 9. Pool name or Wildcat Langlie Mattix |
| 4. Well Location   |  |
| Unit Letter 0 : 660 feet from the South line and   | 1980feet from theEastline              |
| Section 30 Township 23-S Range 37-E  | NMPM Lea County                        |
| 10. Elevation (Show whether DR, RKB, RT, GR, etc.)   |  |
| 11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data   |  |
|  | SEQUENT REPORT OF:                     |
| PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR  | RK ALTERING CASING                     |
| TEMPORARILY ABANDON  | ILLING OPNS. PLUG AND ABANDONMENT      |
| PULL OR ALTER CASING MULTIPLE CASING TEST A CEMENT JOB   |  |
| OTHER: OTHER:  |  |
| 12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.  |  |
| 1. Tag O.H. at 1721, displace hole w/MLF 9.5# Brine w/12.5# gel P/BBL from 1721-1300.  2. Spot 70sx, plug from 1300-1100 (8 5/8 Shoe, T-Salt), Tag at 1140, OK w/OCD.  3. Displace hole w/MLF 9.5# Brine w/12.5# gel P/BBL.  4. Spot 85sx, plug from 257 to Surf (Surf), Tag at Surf.  5. Install dry hole marker 11-4-03.  Approved as to plugging of the Well Bore.  Liability under bond is retained until surface restoration is completed.  |  |
| I hereby certify that the information above is true and complete to the best of my knowledge and belief.   |  |
| SIGNATURE TITLE Manager/Sur  |  |
| Type or print name Jimmy Bagley  |  |
|  | Telephone No. (432) 561-8600           |
| A THE REPORT OF THE PROPERTY O | DEC 0 5 2003                           |
| APPPROVED BY   | DATE                                   |
| $m{\prime}$  |  |