## RECEIVED

Form C-103 Revised 5-27-2004


State of New Mexico

MAR 0 5 2009

Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION FILE IN TRIPLICATE

DISTRICT I HOBBSOCD OIL	1220 South St. Francis Dr.	WELL API NO.
1625 N. French Dr , Hobbs, NM 88240	1220 South St. Francis Dr. Santa Fe, NM 87505	30-025-07594
<u>DISTRICT II</u>		5. Indicate Type of Lease
1301 W Grand Ave, Artesia, NM 88210		STATE FEE X
DISTRICT III		6. State Oil & Gas Lease No.
1000 Rio Brazos Rd, Aztec, NM 87410	NDTC ON WITH LC	7 Lease Name or Unit Agreement Name
SUNDRY NOTICES AND REPO		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL DIFFERENT RESERVOIR USE "APPLICATION FOR PE		South Hobbs (G/SA) Unit Section 3
1. Type of Well.		8 Well No. 58
Oil Well Gas Well  2 Name of Operator	Other Injection well	a acrupy
Occidental Permian Ltd.		9 OGRID No. 157984
3. Address of Operator		10. Pool name or Wildcat Hobbs (G/SA)
4008 N. Grimes PMB-269, Hobbs, NM 88240		
4 Well Location		,
Unit Letter N 660 Feet From The	South 1980 Fee	et From The West Line
Section 3 Township	19-S Range 38-1	E NMPM Lea County
11. Elevation (Sho) 3607' RDB	w whether DF, RKB, RT GR, etc.)	
Pit or Below-grade Tank Application or Closure		
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water		
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material		
12. Check Appropriate Box NOTICE OF INTENTION TO:	to Indicate Nature of Notice, Report, or Company	Other Data SEQUENT REPORT OF:
NOTICE OF INTENTION TO.	300	SEQUENT REPORT OF.
DEDECORM DEMEDIAL WORK DITTO AND ADAMS	DEMEDIAL MODIC	
PERFORM REMEDIAL WORK PLUG AND ABAND		ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OP	ALTERING CASING  NS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion	COMMENCE DRILLING OP CASING TEST AND CEMEN	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER:	COMMENCE DRILLING OP CASING TEST AND CEMEN OTHER Return well t	ALTERING CASING  NS. PLUG & ABANDONMENT  OF injection  ALTERING CASING  OF INJECTION X
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER:  13. Describe Proposed or Completed Operations (Clearly state	COMMENCE DRILLING OP CASING TEST AND CEMEN OTHER Return well to the call pertinent details, and give pertinent dates	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  To injection  X  In including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER:  13. Describe Proposed or Completed Operations (Clearly state proposed work) SEE RULE 1103. For Multiple Completed Operations (Clearly State proposed Work) SEE RULE 1103.	COMMENCE DRILLING OP CASING TEST AND CEMEN OTHER Return well to the call pertinent details, and give pertinent dates	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  To injection  X  In including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER:  13. Describe Proposed or Completed Operations (Clearly state	COMMENCE DRILLING OP CASING TEST AND CEMEN OTHER Return well to the control of th	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  To injection  X  In including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER:  13. Describe Proposed or Completed Operations (Clearly state proposed work) SEE RULE 1103. For Multiple Comple 1. RU PU AND REV UNIT 2. RIH W/ 4 ¾ BIT, TAG CMNT @ 3875' 3. CIRCULATE WELL, START DRILLING CMNT @ 3	COMMENCE DRILLING OP CASING TEST AND CEMEN OTHER Return well to e all pertinent details, and give pertinent dates tions: Attach wellbore diagram of proposed of	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  To injection  X  In including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER:  13. Describe Proposed or Completed Operations (Clearly state proposed work) SEE RULE 1103. For Multiple Completion RU PU AND REV UNIT 2. RIH W/ 4 ¾ BIT, TAG CMNT @ 3875' 3. CIRCULATE WELL, START DRILLING CMNT @ 3 4 TAG & DRILL CIBP @ 3993', CONT TO CU TO 408	COMMENCE DRILLING OP CASING TEST AND CEMEN OTHER Return well to e all pertinent details, and give pertinent dates tions: Attach wellbore diagram of proposed of	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  To injection  X  In including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER:  13. Describe Proposed or Completed Operations (Clearly state proposed work) SEE RULE 1103. For Multiple Completion 1. RU PU AND REV UNIT 2. RIH W/ 4 ¾ BIT, TAG CMNT @ 3875' 3. CIRCULATE WELL, START DRILLING CMNT @ 3 4. TAG & DRILL CIBP @ 3993', CONT TO CU TO 408 5. CLEAN OUT FROM 4080-4218'	COMMENCE DRILLING OP CASING TEST AND CEMEN OTHER Return well to e all pertinent details, and give pertinent dates tions: Attach wellbore diagram of proposed of 875' 0', CIRCULATE CLEAN	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  To injection  X  In including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER:  13. Describe Proposed or Completed Operations (Clearly state proposed work) SEE RULE 1103. For Multiple Completed Proposed Work) SEE RULE 1103. For Multiple Completed Proposed Work) SEE RULE 1103. For Multiple Completed Proposed Work Proposed	COMMENCE DRILLING OP CASING TEST AND CEMEN OTHER Return well to e all pertinent details, and give pertinent dates tions: Attach wellbore diagram of proposed of 875' 0', CIRCULATE CLEAN	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  To injection  X  In including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER:  13. Describe Proposed or Completed Operations (Clearly state proposed work) SEE RULE 1103. For Multiple Completion 1. RU PU AND REV UNIT 2. RIH W/ 4 ¾ BIT, TAG CMNT @ 3875' 3. CIRCULATE WELL, START DRILLING CMNT @ 3 4. TAG & DRILL CIBP @ 3993', CONT TO CU TO 408 5. CLEAN OUT FROM 4080-4218'	COMMENCE DRILLING OP CASING TEST AND CEMEN OTHER Return well to e all pertinent details, and give pertinent dates tions: Attach wellbore diagram of proposed of 875' 0', CIRCULATE CLEAN R @ 4125', 131 JTS	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  To injection  X  In including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER:  13. Describe Proposed or Completed Operations (Clearly state proposed work) SEE RULE 1103. For Multiple Completed Proposed Work) SEE RULE 1103. For Multiple Completed Proposed Work) SEE RULE 1103. For Multiple Completed Proposed Work SEE RULE 1103. For Multiple Completion Proposed Work SEE RULE 1103. For Multiple Completion Proposed Work SEE RULE 1103. For Multiple Completed Proposed Proposed Work SEE RULE 1103. For Multiple Completed Proposed Proposed Proposed Proposed Proposed Proposed Proposed Propos	COMMENCE DRILLING OP CASING TEST AND CEMEN OTHER Return well to e all pertinent details, and give pertinent dates tions: Attach wellbore diagram of proposed of 875' 0', CIRCULATE CLEAN R @ 4125', 131 JTS	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  To injection  X  In including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER:  13. Describe Proposed or Completed Operations (Clearly state proposed work) SEE RULE 1103. For Multiple Complet 1. RU PU AND REV UNIT 2. RIH W/ 4 ¾ BIT, TAG CMNT @ 3875' 3. CIRCULATE WELL, START DRILLING CMNT @ 34 4 TAG & DRILL CIBP @ 3993', CONT TO CU TO 408 5. CLEAN OUT FROM 4080-4218' 6. RIH W/ 5/12 TREATING PKR & 2 7/8 TBG, SET PK 7. ACIDIZE – ROCK SALT BLOCK 8. RIH W/ 51/2 INJECTION PKR & 130 – 2 7/8 JTS TBG 9. CIRC 1130 BBLS 10# BRINE PKR FLUID 10. RUN MIT FOR STATE OF NM, OK	COMMENCE DRILLING OP CASING TEST AND CEMEN OTHER Return well to all pertinent details, and give pertinent dates tions: Attach wellbore diagram of proposed of the control o	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  To injection  X  In including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER:  13. Describe Proposed or Completed Operations (Clearly state proposed work) SEE RULE 1103. For Multiple Completed Proposed Work Proposed Wo	COMMENCE DRILLING OP CASING TEST AND CEMEN OTHER Return well to all pertinent details, and give pertinent dates tions: Attach wellbore diagram of proposed of the company o	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  To injection  X  In including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER:  13. Describe Proposed or Completed Operations (Clearly state proposed work) SEE RULE 1103. For Multiple Completed. RU PU AND REV UNIT 2. RIH W/ 4 ¾ BIT, TAG CMNT @ 3875′ 3. CIRCULATE WELL, START DRILLING CMNT @ 34 TAG & DRILL CIBP @ 3993′, CONT TO CU TO 408 5. CLEAN OUT FROM 4080-4218′ 6. RIH W/ 5/12 TREATING PKR & 2 7/8 TBG, SET PKR 7. ACIDIZE – ROCK SALT BLOCK 8. RIH W/ 51/2 INJECTION PKR & 130 – 2 7/8 JTS TBG 9. CIRC 1130 BBLS 10# BRINE PKR FLUID 10. RUN MIT FOR STATE OF NM, OK 11. RD PU AND CLEAN LOCATION	COMMENCE DRILLING OP CASING TEST AND CEMEN OTHER Return well to all pertinent details, and give pertinent dates tions: Attach wellbore diagram of proposed of the company o	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  To injection  To inject
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER:  13. Describe Proposed or Completed Operations (Clearly state proposed work) SEE RULE 1103. For Multiple Completed Proposed Work Proposed Wo	COMMENCE DRILLING OP CASING TEST AND CEMEN OTHER Return well to all pertinent details, and give pertinent dates tions: Attach wellbore diagram of proposed of the company o	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  To injection  To inject
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER:  13. Describe Proposed or Completed Operations (Clearly state proposed work) SEE RULE 1103. For Multiple Completed Proposed Work) SEE RULE 1103. For Multiple Completed Proposed Work) SEE RULE 1103. For Multiple Completed Proposed Work SEE RULE 1103. For Multiple Complete Proposed Work SEE RULE 1103. For Multiple Completed Proposed Work SEE RULE 1103. For Multiple Complete Proposed Work SEE RULE 1103. For Multiple Complete 103. For Multiple Completed Proposed Work SEE RULE 1103. For Multiple Completed Proposed	COMMENCE DRILLING OP CASING TEST AND CEMEN OTHER Return well to all pertinent details, and give pertinent dates tions: Attach wellbore diagram of proposed of the second s	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  To injection  To inject
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER:  13. Describe Proposed or Completed Operations (Clearly state proposed work) SEE RULE 1103. For Multiple Completed. RU PU AND REV UNIT 2. RIH W/4 ¾ BIT, TAG CMNT @ 3875' 3. CIRCULATE WELL, START DRILLING CMNT @ 34 4. TAG & DRILL CIBP @ 3993', CONT TO CU TO 408 5. CLEAN OUT FROM 4080-4218' 6. RIH W/5/12 TREATING PKR & 2 7/8 TBG, SET PKR 7. ACIDIZE – ROCK SALT BLOCK 8. RIH W/51/2 INJECTION PKR & 130 – 2 7/8 JTS TBG 9. CIRC 1130 BBLS 10# BRINE PKR FLUID 10. RUN MIT FOR STATE OF NM, OK 11. RD PU AND CLEAN LOCATION  I hereby certify that the information above is true and complete to the constructed or closed according to NMOCD guidelines , a general	COMMENCE DRILLING OP CASING TEST AND CEMEN OTHER Return well to e all pertinent details, and give pertinent dates tions: Attach wellbore diagram of proposed of 875' 0', CIRCULATE CLEAN R @ 4125', 131 JTS G, SET PKR @ 4094'  RU PU 12/23/2008 RD PU 01/02/2009 best of my knowledge and belief. I further certify permit or an (attached) alternative	ALTERING CASING  NS. PLUG & ABANDONMENT  To injection  X  S, including estimated date of starting any completion or recompletion.  That any pit or below-grade tank has been/will be  Be OCD-approved
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER:  13. Describe Proposed or Completed Operations (Clearly state proposed work) SEE RULE 1103. For Multiple Completed. RU PU AND REV UNIT 2. RIH W/ 4 ¾ BIT, TAG CMNT @ 3875' 3. CIRCULATE WELL, START DRILLING CMNT @ 34 4. TAG & DRILL CIBP @ 3993', CONT TO CU TO 408 5. CLEAN OUT FROM 4080-4218' 6. RIH W/ 5/12 TREATING PKR & 2 7/8 TBG, SET PK. 7. ACIDIZE – ROCK SALT BLOCK 8. RIH W/ 51/2 INJECTION PKR & 130 – 2 7/8 JTS TBG 9. CIRC 1130 BBLS 10# BRINE PKR FLUID 10. RUN MIT FOR STATE OF NM, OK 11. RD PU AND CLEAN LOCATION  1 hereby certify that the information above is true and complete to the constructed or closed according to NMOCD guidelines , a general	COMMENCE DRILLING OP CASING TEST AND CEMEN OTHER Return well to e all pertinent details, and give pertinent dates trons: Attach wellbore diagram of proposed of 875' 0', CIRCULATE CLEAN R @ 4125', 131 JTS G, SET PKR @ 4094'  RU PU 12/23/2008 RD PU 01/02/2009 best of my knowledge and belief. I further certify permit or an (attached) alternative plan	ALTERING CASING  NS. PLUG & ABANDONMENT  TO injection  To
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER:  13. Describe Proposed or Completed Operations (Clearly state proposed work) SEE RULE 1103. For Multiple Completed. RU PU AND REV UNIT 2. RIH W/ 4 ¾ BIT, TAG CMNT @ 3875′ 3. CIRCULATE WELL, START DRILLING CMNT @ 34 4. TAG & DRILL CIBP @ 3993′, CONT TO CU TO 408 5. CLEAN OUT FROM 4080-4218′ 6. RIH W/ 5/12 TREATING PKR & 2 7/8 TBG, SET PK. 7. ACIDIZE — ROCK SALT BLOCK 8. RIH W/ 51/2 INJECTION PKR & 130 — 2 7/8 JTS TBG 9. CIRC 1130 BBLS 10# BRINE PKR FLUID 10. RUN MIT FOR STATE OF NM, OK 11. RD PU AND CLEAN LOCATION  Thereby certify that the information above is true and complete to the constructed or closed according to NMOCD guidelines , a general	COMMENCE DRILLING OP CASING TEST AND CEMEN OTHER Return well to call pertinent details, and give pertinent dates tions: Attach wellbore diagram of proposed of 875' 0', CIRCULATE CLEAN R @ 4125', 131 JTS G, SET PKR @ 4094'  RU PU 12/23/2008 RD PU 01/02/2009 best of my knowledge and belief. I further certify permit or an (attached) alternative plan TITLE Administrative nail address. rebecca larmon@oxy.com	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  To injection  To inject
TEMPORARILY ABANDON CHANGE PLANS PULL OR ALTER CASING Multiple Completion OTHER:  13. Describe Proposed or Completed Operations (Clearly state proposed work) SEE RULE 1103. For Multiple Completed. RU PU AND REV UNIT 2. RIH W/4 ¾ BIT, TAG CMNT @ 3875' 3. CIRCULATE WELL, START DRILLING CMNT @ 34 TAG & DRILL CIBP @ 3993', CONT TO CU TO 4085. CLEAN OUT FROM 4080-4218' 6. RIH W/5/12 TREATING PKR & 2 7/8 TBG, SET PK. 7. ACIDIZE – ROCK SALT BLOCK 8. RIH W/51/2 INJECTION PKR & 130 – 2 7/8 JTS TBG. 9. CIRC 1130 BBLS 10# BRINE PKR FLUID 10. RUN MIT FOR STATE OF NM, OK 11. RD PU AND CLEAN LOCATION  I hereby certify that the information above is true and complete to the constructed or closed according to NMOCD guidelines , a general SIGNATURE  , a general SIGN	COMMENCE DRILLING OP CASING TEST AND CEMEN OTHER Return well to call pertinent details, and give pertinent dates trons: Attach wellbore diagram of proposed of 875' 0', CIRCULATE CLEAN R @ 4125', 131 JTS G, SET PKR @ 4094'  RU PU 12/23/2008 RD PU 01/02/2009 best of my knowledge and belief. I further certify permit or an (attached) alternative plan TITLE Administrative	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  To injection  To inject



Pare Truit Canson wexpression (CANONATED 11/40/08)

LARRAY CHINDON WEXPRING SEC. 3. T. 19.5 P. 30. 07.5 P. 30. 07.

ર્લ્સન પૂર્ણપ્રાપુષ્ટ અંદો મહાસાલ છે.