Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
District I 1625 N. French Dr., Hobbs, NM Energy, Minerals and Natural Resources		June 19, 2008 WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM SAND ON ZOUG 1220 South St. Francis Dr.		30-025-36788 🗸
District III APK U 0 ZIIII		5. Indicate Type of Lease STATE FEE X
District III 1000 Rio Brazos Rd , Aztec, NM 870 BBSOCD 13205 St. Ferraria De Start Fe NB BSOCD	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		ROBINSON /
1. Type of Well: Oil Well Gas Well Other		8. Well Number 1
2. Name of Operator TRILOGY OPERATIN	NG, INC.	9. OGRID Number 021602 /
3. Address of Operator		10. Pool name or Wildcat
P.O. BOX 7606 MIDLA	AND, TX. 79708	NADINE-BLINEBRY EAST
Unit Letter L : 1972 feet from the SOUTH line and 342 feet from the WEST line		
	Township 19S Range 39E	NMPM LEA County
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3575		
	3373	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION	NTO SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AN	D ABANDON 🔀 REMEDIAL WORK	
TEMPORARILY ABANDON		_
DOWNHOLE COMMINGLE	E COMPL CASING/CEMENT	JOR []
OTHER:	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion		
or recompletion.	OBE 1103. To Muniple Completions. Att	acti wettoore diagram of proposed completion
WELL BORE DIAGRAM ATTACHED - PROPOSED PLUGGING PROCEDURE		
35'		
1. SET CIBP @ 6100' - DUMP BAIL 30' CEMENT - ISOLATE BLINEBRY PERFS		
2. SET CIBP @ 3000' - DUMP BAIL 30; CEMENT - ISOLOATE 7 RIVERS PERFS 3. CUT OFF 51/2" BETWEEN 1800' 25000' AS PER FREE -POINT		
4. RECOVER 5 1/2" & PLACE 100' CEMENT PLUG ACROSS CASING STUB WOL 5409		
I. RECOVER 5 1/2" & PLACE 100' CEMENT PLUG ACROSS CASING STUB いんこうする 5SET 100' CEMENT PLUG FROM 1668' - 1568' ACROSS 8 5/8" SHOE いっこうする。		
6. SET SURFACE CEMENT PLUG	G FROM 20'- SURFACE-	
SET 100' CMT PWG 350'-	750 The Oil Conserv	vation Division Must be notified
	24 nours prior	to the beginning of plugging operations.
Spud Date:	Rig Release Date:	
I hereby certify that the information above is true	and complete to the best of my knowledge	and belief.
SIGNATURE Why I Wyork	TITLE ENGINEER	DATE 4/6/09
Type or print name MICHAEL G. MOONEY E-mail address: PHONE: 432)686-2027		
For State Use Only MIKE@TRILOGYOPEARTING.COM		
APPROVED BY:	TITLE MESS	DATE 04/13/2009
Conditions of Approval (if any):	•	

COMPLIANCE OFFICER

Company:

Trilogy Operating, Inc.

WELLBORE DIAGRAM

Blk: 19S - 39E

DATE: 4/6/09

API#

30-025-36788

Lease: Location: Robinson

Well No.: 1

Field:

Nadine - Blinebry East

1972' FSL & 342' FWL

Sec: 19

Spud: 11/09/04

Survey:

6130'

6354'

6952'

7136'

7300' 7900'

7900'

6484' 6500'

Perfs

Perfs

PBTD

TD @

G.L.: 3575


Comp: 1/19/05

Ct/St: Lea County, NM K.B.:

D.F.:

Current Stat.: Producing 1/2 BOPD + 20 BWPD + 2 MCFD

Initial Form: Drinkard - Abo



Blinebry Perforations

Frac w/ 152,500# sand

4" Liner top @ 6350'

Drinkard Perforations

Acidized 5000 gals 15% Frac w/ 60,500# - 16/30 sand

5 1/2" - 17# - N80

4" - 10.43# - L80

Production liner

PROPOSED PLUGGING PROCEDURE

- 1) Set CIBP @ 6100'- dump bail cement
- 2) Set CIBP @ 3000' dump bail cement
- 3) Cut off 5 1/2" casing @ 1800'-2000'
- 4) Set 100' cement plug across cut off -woc & fag
- 5) Set 100' cement plug from 1668' 1568' woc & tag
- 6) Set surface plug install dry hole marker

SET100' CMT 350-250