Office	State of New Me			Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240 District II	Energy, Minerals and Natu		WELL API NO. 30-025-218	March 4, 2004
1301 W. Grand Ave , Artesia, NM 88210 District III 1000 Rio Brazos Rd , Aztec, NM 87410	OIL CONSERVATION 1220 South St. Fran	ncis Dr.	5. Indicate Type STATE	of Lease
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87	7505	6. State Oil & G	
SUNDRY NOTICES (DO NOT USE THIS FORM FOR PROPOSALS	AND REPORTS ON WELLS TO DRILL OR TO DEEPEN OR PLI	UG BACK TO A	7. Lease Name of	or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATIO PROPOSALS.)	N FOR PERMIT" (FORM C-101) FO	DR SUCH	West Lovington	
1. Type of Well:	V		8. Well Number	
Oil Well Gas Well Oth	ēr'		57	
2. Name of Operator Chevron Midcont	onent L.P.		9. OGRID Num 241333	
3. Address of Operator #15 Smith Rd.,	10. Pool name or Wildcat Lovington Upper San Andres W.			
4. Well Location	VINGIANIA, EX 78703	THE MALE AND A SECOND S	Lovington Oppe	r San Andres VV.
İ	50 feet from the NORTH	line and 989	feet fro	om the East line
Section 8	T 17-9 D	36.E	NA CONTRACTOR	
	Township 17-S Rate Elevation (Show whether DR,		NMPM LEA	County
Pit or Below-grade Tank Application (For pit or	r below-grade tank closures, a form	C-144 must be attached	1)	• *
Pit Location: UL H Sect 8 Twp 17-S p				carest fresh water well
Distance from nearest surface water			Rog;	
1650 feet from the North line and 989	_feet from the <u>9</u> line (S	iteel Tank)		
NOTICE OF INTER	opriate Box to Indicate N		Report or Other	
PERFORM REMEDIAL WORK PL	UG AND ABANDON 🔟	REMEDIAL WORL		ALTERING CASING
	UG AND ABANDON 🗹 IANGE PLANS 📋		× 🗆	ALTERING CASING PLUG AND
TEMPORARILY ABANDON		REMEDIAL WOR	LLING OPNS.	ALTERING CASING
TEMPORARILY ABANDON	IANGE PLANS	REMEDIAL WORI COMMENCE DRI CASING TEST AN	LLING OPNS.	ALTERING CASING PLUG AND
TEMPORARILY ABANDON CHECK PULL OR ALTER CASING MICCO OTHER: 13. Describe proposed or completed	DANGE PLANS DETIPLE DMPLETION Operations. (Clearly state all)	CASING TEST AN CEMENT JOB OTHER:	LLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT Les. including estimated date
TEMPORARILY ABANDON CHOCK PULL OR ALTER CASING MICCO OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion.	DANGE PLANS DETIPLE DMPLETION Operations. (Clearly state all)	CASING TEST AN CEMENT JOB OTHER: pertinent details, and le Completions: At	LLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT Les. including estimated date
TEMPORARILY ABANDON CHOCK PULL OR ALTER CASING MUCCO OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 1. Notify OCD 24 hrs prior to MI and RU, 2. RIH TAG PBTD at 2957'.	ANGE PLANS DETIPLE DMPLETION Operations. (Clearly state all page 1998) SEE RULE 1103. For Multip	CASING TEST AN CEMENT JOB OTHER:	LLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT Les. including estimated date
TEMPORARILY ABANDON CHOCK PULL OR ALTER CASING MUCCO OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 1. Notify OCD 24 hrs prior to MI and RU.	ANGE PLANS DETIPLE DMPLETION Operations. (Clearly state all places of the control of the contr	CASING TEST AN CEMENT JOB OTHER: pertinent details, and the Completions: At 8. Clean locations.	LLING OPNS.	ALTERING CASING PLUG AND ABANDONMENT Les, including estimated date ram of proposed completion
TEMPORARILY ABANDON CH PULL OR ALTER CASING MUCCO OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 1. Notify OCD 24 hrs prior to MI and RU. 2. RiH TAG PBTD at 2957'. 3. Displace hole w/MLF, 9.5# Brine w/12. 4. Perf and squeeze 40ex coment plug fire 5. Perf and squeeze 55ex carnent plug fire.	ANGE PLANS PLTIPLE DMPLETION Operations. (Clearly state all SEE RULE 1103. For Multip 5# get P/88L. om 2950'-2750' (B.Seit). WOC & Tom 2090'-1800' (T.Sait/Ruetler). W	CASING TEST AN CEMENT JOB OTHER: pertinent details, and the Completions: At 8. Clean locations and the Completion of the	LLING OPNS. D I give pertinent da tach wellbore diagon. Conservation	PLUG AND ABANDONMENT Les, including estimated date ram of proposed completion
TEMPORARILY ABANDON CH PULL OR ALTER CASING MUCCO OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 1. Notify OCD 24 hrs prior to MI and RU. 2. RIH TAG PBTD at 2957'. 3. Displace hole w/MLF, 9.5# Brine w/12. 4. Perf and squeeze 40ex cement plug for	ANGE PLANS DETIPLE DMPLETION Operations. (Clearly state all plants and plan	CASING TEST AN CEMENT JOB OTHER: pertinent details, and the Completions: At 8. Clean locations and the Completion of the	LLING OPNS. D I give pertinent da tach wellbore diagon. Conservation	ALTERING CASING PLUG AND ABANDONMENT Les, including estimated date ram of proposed completion
TEMPORARILY ABANDON CH PULL OR ALTER CASING MUCCO OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 1. Notify OCD 24 hrs prior to MI and RU. 2. RiH TAG PBTD at 2957. 3. Displece hole w/MLF, 9.5# Brine w/12. 4. Perf and squeeze 40ex cement plug fm 5. Perf and squeeze 55ex cement plug fm 6. Perf and squeeze 55ex cement plug fm	ANGE PLANS DETIPLE DMPLETION Operations. (Clearly state all particles) SEE RULE 1103. For Multip S# get P/8BL. Dm 2950'-2750' (B.Seit). WOC & Tom 2090'-1800' (T.Sait/Rustler). Wom 460'-215' (stub/shoe). WOC & TAG. The istrue and complete to the best of the size of the second sec	CASING TEST AN CEMENT JOB OTHER: pertinent details, and le Completions: At 8. Clean location (Co. & TA) The OI TAG. 24 hoursest of my knowledge.	LLING OPNS. D Igive pertinent da tach wellbore diagon. Conservation Dirs prior to the beand belief. I further	PLUG AND ABANDONMENT tes, including estimated date ram of proposed completion Division Must be notified beginning of plugging operation
TEMPORARILY ABANDON CH PULL OR ALTER CASING MUCCO OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 1. Notify OCD 24 hrs prior to MI and RU. 2. RIH TAG PBTD at 2957'. 3. Displace hole w/MLF, 9.5# Brine w/12. 4. Perf and squeeze 40ax cement plug from 5. Perf and squeeze 55ax cement plug from 7. Spot 25ax cement plug from 100'-surfation above 11 hereby certify that the information above 12.	ANGE PLANS DETIPLE DMPLETION Operations. (Clearly state all particles) SEE RULE 1103. For Multip S# get P/8BL. Dm 2950'-2750' (B.Seit). WOC & Tom 2090'-1800' (T.Sait/Rustler). Wom 460'-215' (stub/shoe). WOC & TAG. The istrue and complete to the best of the size of the second sec	CASING TEST AN CEMENT JOB OTHER: pertinent details, and le Completions: At 8. Clean location (Co. & TA) The OI TAG. 24 hoursest of my knowledge.	LLING OPNS. Description of the born of th	PLUG AND ABANDONMENT tes, including estimated date ram of proposed completion Division Must be notified beginning of plugging operation
TEMPORARILY ABANDON CH PULL OR ALTER CASING MUCCO OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 1. Notify OCD 24 hrs prior to MI and RU. 2. RIH TAG PBTD at 2957'. 3. Displace hole w/MLF, 9.5# Brine w/12. 4. Perf and squeeze 40ax cement plug from 5. Perf and squeeze 55ax cement plug from 7. Spot 25ax cement plug from 100'-surfation above grade tank has been/will be constructed or closed.	ANGE PLANS DETIPLE DMPLETION Operations. (Clearly state all SEE RULE 1103. For Multip S# gel P/BBL. om 2950-2750' (B.Sait). WOC & Tom 2950-1800' (T.Sait/Ruetler). Woom 460'-215' (stub/shoe). WOC & toe (surface). WOC & TAG. e is true and complete to the bell setbriding to NMOCD guidelines [COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Pertinent details, and B. Clean location AG. TAG. The Oil TAG. Agent for Cheve	LLING OPNS. ID I give pertinent datach wellbore diagon. Conservation Dirs prior to the beand belief. I furtion an (attached) afterwoon.	PLUG AND ABANDONMENT Tes, including estimated date ram of proposed completion Division Must be notified beginning of plugging operation her certify that any pit or below-mative OCD-approved plan
TEMPORARILY ABANDON CH PULL OR ALTER CASING MUCCO OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 1. Notify OCD 24 hrs prior to MI and RU. 2. RIH TAG PBTD at 2957'. 3. Displece hole w/MLF, 9.5# Brine w/12. 4. Perf and squeeze 40ax cament plug from 5. Perf and squeeze 55ax cament plug from 7. Spot 25ax cament plug from 100'-surfer in the proposed tank has been/will be constructed or closed SIGNATURE	ANGE PLANS DETIPLE DMPLETION Operations. (Clearly state all SEE RULE 1103. For Multip S# get P/8BL. om 2950-2750' (B.Sait). WOC & T om 460'-215' (stub/shoe). WOC & one (surface). WOC & TAG. e is true and complete to the best performing to NMOCD guidelines. TITLE E-mail ac	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Pertinent details, and B. Clean location AG. TAG. The Oil TAG. Agent for Cheve	LLING OPNS. ID I give pertinent datach wellbore diagon. Conservation Dirs prior to the beand belief. I furtion an (attached) afterwoon.	ALTERING CASING PLUG AND ABANDONMENT tes, including estimated date ram of proposed completion Division Must be notified beginning of plugging operation her certify that any pit or below- mative OCD-approved plan DATE 4-9-2009
TEMPORARILY ABANDON CH PULL OR ALTER CASING MUCCO OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 1. Notify OCD 24 hrs prior to Mi and RU. 2. RiH TAG PBTD at 2957. 3. Displece hole wMLF, 9.5# Brine w/12. 4. Perf and equeeze 40ex cement plug fr. 5. Perf and squeeze 55ex cement plug fr. 6. Perf and squeeze 55ex cement plug fr. 7. Spot 25ex cement plug from 100'-surfe. I hereby certify that the information above grade tank has been/will be constructed or closed SIGNATURE Type or print name M. Kee Roapk APPPROVED BY	ANGE PLANS DETIPLE DMPLETION Operations. (Clearly state all SEE RULE 1103. For Multip S# get P/8BL. om 2950-2750' (B.Sait). WOC & T om 460'-215' (stub/shoe). WOC & one (surface). WOC & TAG. e is true and complete to the best performing to NMOCD guidelines. TITLE E-mail ac	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Pertinent details, and B. Clean location AG. TAG. The Oil TAG. Agent for Chevildress:	LLING OPNS. ID I give pertinent datach wellbore diagon. Conservation Dirs prior to the beand belief. I furtion an (attached) afterwoon.	ALTERING CASING PLUG AND ABANDONMENT tes, including estimated date ram of proposed completion Division Must be notified beginning of plugging operation her certify that any pit or below- mative OCD-approved plan DATE 4-9-2009
TEMPORARILY ABANDON CH PULL OR ALTER CASING MUCCO OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 1. Notify OCD 24 hrs prior to MI and RU. 2. RiH TAG PBTD at 2957'. 3. Displace hole w/MLF, 9.5# Brine w/12. 4. Perf and squeeze 40ax cament plug from 5. Perf and squeeze 55ax cament plug from 7. Spot 25ax cament plug from 100'-surfer. I hereby certify that the information above grade tank has been/will be constructed or closed SIGNATURE Type or print name M. Lee Roar APPPROVED BY Conditions of approval, if any:	ANGE PLANS DETIPLE DMPLETION Operations. (Clearly state all SEE RULE 1103. For Multip S# get P/8BL. om 2950-2750' (B.Sait). WOC & T om 460'-215' (stub/shoe). WOC & one (surface). WOC & TAG. e is true and complete to the best performing to NMOCD guidelines. TITLE E-mail ac	COMMENCE DRI CASING TEST AN CEMENT JOB OTHER: Pertinent details, and B. Clean location AG. TAG. The Oil TAG. Agent for Chevildress:	LLING OPNS. ID I give pertinent datach wellbore diagon. Conservation Dirs prior to the beand belief. I furtion an (attached) afterwoon.	PLUG AND ABANDONMENT tes, including estimated date ram of proposed completion Division Must be notified beginning of plugging operation her certify that any pit or below- mative OCD-approved plan . DATE 4-9-2009 Telephone No. 432-561-8600

New Mexico Office of the State Engineer POD Reports and Downloads

NAD27	nship: X:	178 Range:	30E	Sections: 6 Zone:	Search Radius:	<u> </u>
County: LE		Basin:		: "	Number: Si	uffix:
Owner Name: (Fir	rst)		(Last)		_ ONon-Domestic (ODomestic All

AVERAGE DEPTH OF WATER REPORT 04/13/2009

 Bsn
 Twe
 Rng
 Sec
 Zone
 X
 Y
 Wells
 Min
 Max
 Avg

 L
 17S
 36E
 06
 1
 50
 50
 50

Record Count: 1

,

Updated: 11-4-08 by WAYN

By: W.P. Johnson