Submit 3 Copies To Appropriate District  State of New Mexico	Form C-103								
Office District! Resources	May 27, 2004								
District II 1625 N French Dr., Hobbs, NM 87240 District III 1301 W Grand Ave, Artesia, NM 88210 District III 1302 South St. Francis Dr.	WELL API NO.								
1301 W Grand Ave , Artesia, NM 88210 NIGOTO CONSERVATION DIVISION	30-025-34309 5. Indicate Type of Lease								
District III 1000 Rio Brazos Rd . Aztec, NM 87410 HOBBS Santa Fe, NM 87505	STATE S FEE .								
District IV									
1220 S St Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No. L-0061								
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name:  NEW MEXICO "L-61" STATE								
PROPOSALS.)  1. Type of Well:	8. Well Number								
Oil Well X Gas Well Other	2								
2. Name of Operator	9. OGRID Number								
CIMAREX ENERGY CO. OF COLORADO ATTIN: ZENO FARRIS	014245 162683								
3. Address of Operator 5215 N. O'CONNOR BLVD., STE. 1500, IRVING, TEXAS 75039	10. Pool name or Wildcat								
4. Well Location	FLYING "M" SAN ANDRES								
Unit Letter A : 593 feet from the NORTH line and	668 feet from the EAST line								
Section 06 Township 10s Range 33E	NMPM County LEA								
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4,214' QR									
Pit or Below-grade Tank Application or Closure									
Pit type STEEL Depth to Groundwater 50' Distance from nearest fresh water well * Distance from nearest surface water *									
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Constructi	on Material * NONE WITHIN 1,000'								
12 Charle Appropriate Pay to Indicate Nature of Nation	Panart or Other Data								
12. Check Appropriate Box to Indicate Nature of Notice,	• *								
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:								
** *	• *								
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:  ALTERING CASING  ING OPNS. PLUG AND								
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  REMEDIAL WORK	SEQUENT REPORT OF:  ALTERING CASING								
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  PLUG AND ABANDON  REMEDIAL WORK  TEMPORARILY ABANDON  CHANGE PLANS  COMMENCE DRILL  PULL OR ALTER CASING  MULTIPLE  CASING TEST AND	SEQUENT REPORT OF:  ALTERING CASING  ING OPNS. PLUG AND								
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  PLUG AND ABANDON  REMEDIAL WORK  TEMPORARILY ABANDON  CHANGE PLANS  COMMENCE DRILL  PULL OR ALTER CASING  MULTIPLE  CASING TEST AND CEMENT JOB  OTHER: OTHER:	SEQUENT REPORT OF:  ALTERING CASING  ING OPNS. PLUG AND ABANDONMENT  D								
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL  PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB  OTHER:  OTHER:  The Oil Comparison of starting any proposed or completed operations. (Clearly state all pertinent of starting any proposed work) SEE BUILE 1103. For Multiple Comparison.	SEQUENT REPORT OF:  ALTERING CASING  ING OPNS. PLUG AND								
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL  PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB  OTHER: OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent of starting any proposed work). SEE RULE 1103. For Multiple Compor recompletion.	SEQUENT REPORT OF:  ALTERING CASING  ING OPNS.  PLUG AND ABANDONMENT   Inservation Division Must be notified prior to the beginning of plugging operations								
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL  PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB  OTHER:  OTHER:  The Oil Congression of starting any proposed work). SEE RULE 1103. For Multiple Compor recompletion.  COMPLY WITH ALL COMPANY & GOVERNMENT ENVIRONMENT ENVIRONMENT & SAFETTIME.	SEQUENT REPORT OF:  ALTERING CASING  ING OPNS.  PLUG AND ABANDONMENT   Inservation Division Must be notified prior to the beginning of plugging operations								
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL  PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB  OTHER:  OTHER:  The Oil Co 24 hours INTENTION COMPLY WITH ALL COMPANY & COVERNMENT ENVIRONMENT ENVIRONMENT ENVIRONMENT & SAFETY  LOCATION HAS THE AUTHORITY TO SHUT DOWN UNSAFE OPERATIONS.	SEQUENT REPORT OF:  ALTERING CASING  ING OPNS.  PLUG AND ABANDONMENT   Onservation Division Must be notified Divisor to the beginning of plugging operations  A REGULATIONS. ANYONE ON THE JOB								
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL  PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB  OTHER:  OTHER:  OTHER:  The Oil Co 24 hours in the Authority to shut down unsafe operations.  1) SET 4-1/2" CIBP @ 4,150"; MIX & PUMP A 25 SX. CMT. PLUG ON TOP OF	SEQUENT REPORT OF:  ALTERING CASING  ING OPNS. PLUG AND ABANDONMENT  PLUG AND ABANDONMENT  ABANDONMENT  ABANDON Must be notified  PROTECT TO THE JOB  CIBP @ 4,150'; CIRC. WELL W/ MUD.								
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL  PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB  OTHER:  OTHER:  The Oil Co 24 hours INTENTION COMPLY WITH ALL COMPANY & COVERNMENT ENVIRONMENT ENVIRONMENT ENVIRONMENT & SAFETY  LOCATION HAS THE AUTHORITY TO SHUT DOWN UNSAFE OPERATIONS.	SEQUENT REPORT OF:  ALTERING CASING  ING OPNS. PLUG AND ABANDONMENT  PROPERTY OF THE JOB  CIBP @ 4,150'; CIRC. WELL W/ MUD. TOP OF CMT. PLUG.								
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON X  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL  PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB  OTHER:  OTHER:  OTHER:  The Oil Co 24 hours in the Authority to shut down unsafe operations.  (Clearly state all pertinent of starting any proposed work). SEE RULE 1103. For Multiple Compor recompletion.  COMPLY WITH ALL COMPANY & COVERNMENT ENVIRONMENT ENVIRONMENT & SAFETT LOCATION HAS THE AUTHORITY TO SHUT DOWN UNSAFE OPERATIONS.  1) SET 4-1/2" CIBP @ 4,150'; MIX & PUMP A 25 SX. OMT. PLUG ON TOP OF 2) MIX & PUMP A 25 SX. OMT. PLUG @ 2,250'-2,000' (T/YATES); WOC & TAG	ALTERING CASING ALTERING OPENS. PLUG AND ABANDONMENT ALTERING CASING ALTERING								
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON X  REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL  PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB  OTHER:  OTHER:  OTHER:  The Oil Co 24 hours proposed or completed operations. (Clearly state all pertinent of starting any proposed work). SEE RULE 1103. For Multiple Compor recompletion.  COMPLY WITH ALL COMPANY & GOVERNMENT ENVIRONMENT ENVIRONMENT & SAFETT LOCATION HAS THE AUTHORITY TO SHUT DOWN UNSAFE OPERATIONS.  1) SET 4-1/2" CIBP @ 4,150'; MIX & PUMP A 25 SX. CMT. PLUG ON TOP OF 2) MIX & PUMP A 25 SX. CMT. PLUG @ 2,250'-2,000' (T/YATES); WCC & TAG 3) CUT & PULL +/-1,000' 4-1/2" CASING; MIX & PUMP A 35 SX. CMT. STUB	ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING OPENS. PLUG AND ABANDONMENT AREQUIATIONS. ANYONE ON THE JOB  CIBP @ 4,150'; CIRC. WELL W/ MUD. TOP OF OMT. PLUG. PLUG @ 1,050'; WCC & TAG TOP OF OMT. AG TOP OF CMT. PLUG.								
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON COMMENCE DRILL  PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB  OTHER:  OTHER:  OTHER:  The Oil Co 24 hours por recompletion.  COMPLY WITH ALL COMPANY & GOVERNMENT ENVIRONMENT ENVIRONMENT & SAFETT LOCATION HAS THE AUTHORITY TO SHUT DOWN UNSAFE OPERATIONS.  1) SET 4-1/2" CIBP @ 4,150'; MIX & PUMP A 25 SX. CMT. PLUG ON TOP OF 2) MIX & PUMP A 25 SX. CMT. PLUG @ 2,250'-2,000' (T/YATES); WOC & TAG 3) CUT & PULL +/-1,000' 4-1/2" CASING; MIX & PUMP A 35 SX. CMT. STUB 4) MIX & PUMP A 35 SX. CMT. PLUG @ 420'-320' (SURF.CSG.SHOE); WOC & TAG 4) MIX & PUMP A 35 SX. CMT. PLUG @ 420'-320' (SURF.CSG.SHOE); WOC & TAG 4) MIX & PUMP A 35 SX. CMT. PLUG @ 420'-320' (SURF.CSG.SHOE); WOC & TAG 4) MIX & PUMP A 35 SX. CMT. PLUG @ 420'-320' (SURF.CSG.SHOE); WOC & TAG 4) MIX & PUMP A 35 SX. CMT. PLUG @ 420'-320' (SURF.CSG.SHOE); WOC & TAG 4) MIX & PUMP A 35 SX. CMT. PLUG @ 420'-320' (SURF.CSG.SHOE); WOC & TAG 5) MIX & PUMP A 35 SX. CMT. PLUG @ 420'-320' (SURF.CSG.SHOE); WOC & TAG 5) MIX & PUMP A 35 SX. CMT. PLUG @ 420'-320' (SURF.CSG.SHOE); WOC & TAG 5) MIX & PUMP A 35 SX. CMT. PLUG @ 420'-320' (SURF.CSG.SHOE); WOC & TAG 5) MIX & PUMP A 35 SX. CMT. PLUG @ 420'-320' (SURF.CSG.SHOE); WOC & TAG 5) MIX & PUMP A 35 SX. CMT. PLUG @ 420'-320' (SURF.CSG.SHOE); WOC & TAG 5) MIX & PUMP A 35 SX. CMT. PLUG @ 420'-320' (SURF.CSG.SHOE); WOC & TAG 5) MIX & PUMP A 35 SX. CMT. PLUG @ 420'-320' (SURF.CSG.SHOE); WOC & TAG 5) MIX & PUMP A 35 SX. CMT. PLUG @ 420'-320' (SURF.CSG.SHOE); WOC & TAG 5) MIX & PUMP A 35 SX. CMT. PLUG @ 420'-320' (SURF.CSG.SHOE); WOC & TAG 5) MIX & PUMP A 35 SX. CMT. PLUG @ 420'-320' (SURF.CSG.SHOE); WOC & TAG 5) MIX & PUMP A 35 SX. CMT. PLUG @ 420'-320' (SURF.CSG.SHOE); WOC & TAG 5) MIX & PUMP A 35 SX. CMT. PLUG @ 420'-320' (SURF.CSG.SHOE);	ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING OPENS. PLUG AND ABANDONMENT AREQUIATIONS. ANYONE ON THE JOB  CIBP @ 4,150'; CIRC. WELL W/ MUD. TOP OF OMT. PLUG. PLUG @ 1,050'; WCC & TAG TOP OF OMT. AG TOP OF CMT. PLUG.								
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON X  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL  PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB  OTHER:  OTHER:  The Oil Co 24 hours por recompletion.  COMPLY WITH ALL COMPANY & GOVERNMENT ENVIRONMENT ENVIRONMENT & SAFETT LOCATION HAS THE AUTHORITY TO SHUT DOWN UNSAFE OPERATIONS.  1) SET 4-1/2" CIBP @ 4,150'; MIX & PUMP A 25 SX. CMT. PLUG ON TOP OF 2) MIX & PUMP A 25 SX. CMT. PLUG @ 2,250'-2,000' (T/YATES); WCC & TAG 3) CUT & PULL +/-1,000' 4-1/2" CASING; MIX & PUMP A 35 SX. CMT. STUB 4) MIX & PUMP A 35 SX. CMT. PLUG @ 420'-320' (SURF.CSG.SHOE); WCC & TYE 5) MIX & PUMP A 20 SX. CMT. SURF. PLUG @ 63'-3'; DIG CUT & CUT OFF WE PLATE & DRYHOLE MARKER.  Thereby certify that the information above is true and complete to the best of my knowled.	ALTERING CASING  ALTERING CASING  ING OPNS. PLUG AND ABANDONMENT  PLUG AND ABANDONMENT  ABANDONMENT  ABANDONMENT  PROPERTY TO THE JOB  CIBP @ 4,150'; CIRC. WELL W/ MUD.  TOP OF CMT. PLUG.  PLUG @ 1,050'; WCC & TAG TOP OF CMT.  AG TOP OF CMT. PLUG.  ELIHEAD 3' B.G.L.; WELD ON STEEL  ge and belief. I further certify that any pit or below-								
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL  PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB  OTHER:  OTHER:  OTHER:  The Oil Co 24 hours por recompletion.  COMPLY WITH ALL COMPANY & COVERNMENT ENVIRONMENT ENVIRONMENT & SAFET LICCATION HAS THE AUTHORITY TO SHUT DOWN UNSAFE OPERATIONS.  SET 4-1/2" CIBP @ 4,150'; MIX & PUMP A 25 SX. CMT. PLUG CN TOP OF 2) MIX & PUMP A 25 SX. CMT. PLUG Q 2,250'-2,000' (T/YATES); WOC & TAG 3) CUT & PULL +/-1,000' 4-1/2" CASING; MIX & PUMP A 35 SX. CMT. STUB 4) MIX & PUMP A 35 SX. CMT. PLUG @ 420'-320' (SURF.CSG.SHOE); WOC & TAG 5) MIX & PUMP A 20 SX. CMT. SURF. PLUG @ 63'-3'; DIG OUT & CUT OFF WE PLATE & DRYHOLE MARKER.  Thereby certify that the information above is true and complete to the best of my knowled grade tank has been with the constructed of closed according to NMOCD guidelines X, a general permit	ALTERING CASING ALTERING OPING ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT AS TOP OF CMT. PLUG.  PLUG @ 1,050'; WCC & TAG TOP OF CMT. AG TOP OF CMT. PLUG.  PLUG @ 1,050'; WCC & TAG TOP OF CMT. AG TOP OF CMT. PLUG.  ELLHEAD 3' B.G.L.; WELD ON STEEL  ge and belief. I further certify that any pit or below—  or an (attached) alternative OCD-approved plan—								
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON X  REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL  PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT JOB  OTHER:  OTHER:  OTHER:  The Oil Co 24 hours in the Authority to shut down unsafe operations.  COMPLY WITH ALL COMPANY & COVERNMENT ENVIRONMENT ENVIRONMENT & SAFET LOCATION HAS THE AUTHORITY TO SHUT DOWN UNSAFE OPERATIONS.  SET 4-1/2" CIBP @ 4,150"; MIX & PUMP A 25 SX. CMT. PLUG ON TOP OF 2) MIX & PUMP A 25 SX. CMT. PLUG @ 2,250"-2,000" (T/YATES); WOC & TAG 3) CUT & PULL +/-1,000" 4-1/2" CASING; MIX & PUMP A 35 SX. CMT. STUB 4) MIX & PUMP A 35 SX. CMT. PLUG @ 420"-320" (SURF. CSG. SHOE); WOC & TAG 5) MIX & PUMP A 20 SX. CMT. SURF. PLUG @ 63"-3"; DIG OUT & CUT OFF WE PLATE & DRYHOLE MARKER.  Thereby certify that the information above is true and complete to the best of my knowled grade tank has been with the constructed of closed according to NMOCD guidelines X, a general permit SIGNATURE  TITLE ACCORDANCE AND COMMENCE DRILL WORK  COMMENCE DRILL WORK  COMMENCE DRILL WORK  CASING TEST AND CEMENT JOB COMMENCE DRILL WORK  CASING TEST AND CEMENT JOB COMMENCE DRILL WORK  CASING TEST AND CEMENT JOB COMMENT ENVIRONMENT ENVIRONM	ALTERING CASING  ALTERING CASING  ING OPNS. PLUG AND ABANDONMENT  PLUG AND ABANDONMENT  ABANDONMENT  ABANDONMENT  PROPOSE OF CMT. PLUG.  PLUG 4,150'; CIRC. WELL W/ MUD.  TOP OF CMT. PLUG.  PLUG 6 1,050'; WCC & TAG TOP OF CMT.  AG TOP OF CMT. PLUG.  ELLHEAD 3' B.G.L.; WELD ON STEEL  ge and belief. I further certify that any pit or below—  or an (attached) alternative OCD-approved plan  ENT DATE 04/15/09  DEYLER@MILAGRO-RES.COM								
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL  PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB  OTHER:  OTHER:  OTHER:  The Oil Co 24 hours in the Authority to shut down unsafe operations.  COMPLY WITH ALL COMPANY & COVERNMENT ENVIRONMENT	ALTERING CASING  ALTERING CASING  ING OPNS. PLUG AND ABANDONMENT  PLUG AND ABANDONMENT  Inservation Division Must be notified prior to the beginning of plugging operations  INGOPORT TO THE JOB  CIBP @ 4,150'; CIRC. WELL W/ MUD.  TOP OF CMT. PLUG.  PLUG @ 1,050'; WCC & TAG TOP OF CMT.  AG TOP OF CMT. PLUG.  ELLHEAD 3' B.G.L.; WELD ON STEEL  ge and belief. I further certify that any pit or below—  or an (attached) alternative OCD-approved plan—  ENT DATE 04/15/09								
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON X  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL  PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB  OTHER:  OTHER:  OTHER:  The Oil Co 24 hours or recompletion.  CMPLY WITH ALL COMPANY & COVERNMENT ENVIRONMENT ENVIRONMENT & SAFETT LOCATION HAS THE AUTHORITY TO SHUT DOWN UNSAFE OPERATIONS.  SET 4-1/2" CIBP @ 4,150'; MIX & PUMP A 25 SX. CMT. PLUG ON TOP OF 2) MIX & PUMP A 25 SX. CMT. PLUG (2,250'-2,000' (T/YATES); WOC & TAG 3) CUT & PULL +/-1,000' 4-1/2" CASING; MIX & PUMP A 35 SX. CMT. STUB 4) MIX & PUMP A 35 SX. CMT. PLUG @ 420'-320' (SURF.CSG.SHOE); WOC & TAG 5) MIX & PUMP A 20 SX. CMT. PLUG @ 63'-3'; DIG CUT & CUT OFF WE PLATE & DRYHOLE MARKER.  Thereby certify that the information above is true and complete to the best of my knowled grade tank has been will be constructed by closed according to NMOCD guidelines X, a general permit SIGNATURE  TITLE ACCORDANCE TITLE ACCORDANCE TO THE STATE ACCORDANCE TO THE ACCORDANCE TO THE STATE ACCORDANCE TO THE	ALTERING CASING ALTERING OPINS.  PLUG AND ABANDONMENT  Inservation Division Must be notified brior to the beginning of plugging operations  REGULATIONS. ANYONE ON THE JOB  CIBP @ 4,150'; CIRC. WELL W/ MUD.  TOP OF OMT. PLUG.  PLUG @ 1,050'; WCC & TAG TOP OF OMT.  AG TOP OF CMT. PLUG.  ELIHEAD 3' B.G.L.; WELD ON STEEL  ge and belief. I further certify that any pit or below—  or an (attached) alternative OCD-approved plan  DATE 04/15/09  DEYLER@MILACRO-RES.COM  Telephone No. (432) 687–3033								
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL  PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB  OTHER:  OTHER:  OTHER:  The Oil Co 24 hours por recompletion.  COMPLY WITH ALL COMPANY & COVERNMENT ENVIRONMENT ENVIRONMENT & SAFET LOCATION HAS THE AUTHORITY TO SHUT DOWN UNSAFE OPERATIONS.  SET 4-1/2" CIEP @ 4,150'; MIX & PUMP A 25 SX. CMT. PLUG ON TOP OF 2) MIX & PUMP A 25 SX. CMT. PLUG @ 2,250'-2,000' (T/YATES); WCC & TAG 3) CUT & PULL +/-1,000' 4-1/2" CASING; MIX & PUMP A 35 SX. CMT. STUB 4) MIX & PUMP A 35 SX. CMT. PLUG @ 420'-320' (SURF.CSG.SHOE); WCC & TAG 5) MIX & PUMP A 20 SX. CMT. PLUG @ 420'-320' (SURF.CSG.SHOE); WCC & TEST SY COMP A 20 SX. CMT. SURF. PLUG @ 63'-3'; DIG CUT & CUT OFF WE PLATE & DRYHOLE MARKER.  I hereby certify that the information above is true and complete to the best of my knowled grade tank has been/will be constructed on closed according to NMOCD guidelines X, a general permit SIGNATURE  TITLE ACCOMMENCE DRILL WORK  CASING TEST AND COMMENCE DRILL WORK  CASING TEST AND COMMENCE DRILL WORK  CASING TEST AND CEMENT JOB COMMENCE DRILL WORK  The Oil Co 24 hours poor CASING TO THE OIL CASING TO THE OIL CASING TEST AND CEMENT JOB COMPONITY & SAFETY.  The Oil Co 24 hours poor CASING TEST AND CEMENT JOB COMPONITY & SAFETY.  The Oil Co 24 hours poor CASING TEST AND CEMENT JOB COMPONITY AS A SAFETY.  The Oil Co 24 hours poor CASING TEST AND CEMENT JOB COMPONITY AS A SAFETY.  The Oil Co 24 hours poor CASING TEST AND CEMENT JOB COMPONITY AS A SAFETY.  The Oil Co 24 hours poor CASING TEST AND CEMENT JOB COMPONITY AS A SAFETY.  The Oil Co 24 hours poor CASING TEST AND CEMENT JOB COMPONITY AS A SAFETY.  The Oil Co 24 hours poor CASING TEST AND CEMENT JOB COMPONITY AS A SAFETY.  The Oil Co 24 hours poor CASING TEST AND CEMENT JOB COMPONITY AS A SAFETY.  The Oil Co 24 hours poor CASING TEST AND CEMENT JOB COMPONITY AS A SAFETY.  The Oil Co 25 NOT CASING TEST AND CEMENT JOB COMPONITY AS A SAFETY.  The Oil Co 25 NOT	ALTERING CASING ALTERING OPINS.  PLUG AND ABANDONMENT  Inservation Division Must be notified brior to the beginning of plugging operations  REGULATIONS. ANYONE ON THE JOB  CIBP @ 4,150'; CIRC. WELL W/ MUD.  TOP OF OMT. PLUG.  PLUG @ 1,050'; WCC & TAG TOP OF OMT.  AG TOP OF CMT. PLUG.  ELIHEAD 3' B.G.L.; WELD ON STEEL  ge and belief. I further certify that any pit or below—  or an (attached) alternative OCD-approved plan  DATE 04/15/09  DEYLER@MILACRO-RES.COM  Telephone No. (432) 687–3033								

: .										
		JGGING & ABANDO	NMENT WO	DRKSH	EE	T	( STR			
g-	30-0	25 - 34 309	OPERATO	R C	TM	AREX	ENE2	<u>69 C</u>	is of Co.	
•	*1 ' I	1 1	LEASENAM	<u> </u>	EW	mrXI	WELL		2	
1	<b>'</b> \( \)		SECT	06	T\/	VAI		RNG	33E	
	<b>A</b>	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	FROM		ØSL			ØW L		
	진	5	TD:	4,500		FOR			5.A.	
	××××		PBTD:	4,302					TD 5.A.	
ı	X	<b>X</b>		SIZE	3	SET @	TOC	TOC DET	TERMINED BY	
	Ä	8-5/8"	SURFACE	8-5/8		369'	SUPF.	CIPC.		
		@ 369'	INTMED 1							
	l	TOC SURF.	INTMED 2		L.				· · · · · · · · · · · · · · · · · · ·	
ı	1		PROD	4-1/2		500'	1,055	CALC.		
				SIZE	L.	TOP	BOT	TOC	DETERMINED BY	
I			LINER 1	ļ	-		<del> </del>	<del> </del>		
		TOO ~ 1055'	LINER 2	OUT O						
	Ş	× TOC~1,055'	INITES A	CUT &	PU	.L. (0)		<del> </del>	TOP - BOTTOM	
I	<b>∕</b> s	χ	INTMED 1 INTMED 2		·		PERFS	4,220	- 4,357	
	$\hat{\lambda}$	χ .	PROD	<del> </del>			OPENHOLE	<del> </del>		
	Á	x		1/20 % 5050	on r					
	X	ľx l	* REQUIRED PLA	UGS DISTA	] *	PLUG	TYPE	SACKS		
	X	×	RUSTLER (ANHYD) YATES	<del> </del>	1	1 1200	PLUG	CMNT	DEPTH	
	Ŷ	X	QUEEN	<del> </del>		5XAMPLES	1200	CIVARA		
•	×	X	GRAYBURG		1	PLUO#1	OH	25 SXS	9850'	
1	X)	X '	SAN ANDRES		1	PLUG# 2	SHOE	50 SXS	8700'-8800'	
	Ŋ	×				PLUG#3	CIBP/35'		5300'	
1	, j	×	Capitan Reef		*	PLUG#3	CIBP	25 SXS	5300'	
- 1	` 🎗	¥ I				PLUG#4	STUB	50 SXS	4600'-4700'	
	X	\$< 4,226'-GO'	DELAWARE			PLUG#6	RETNR SQZ	200 SXS	100	
ı	Ş	1 224'-96'	BELL CANYON			PLUG#7	SURF	10 SXS	0-10'	
ı	Ŕ	我くかという。	CHERRY CANYON	ļ		PLUG#1				
- 1	XXXXX	\$ < 4,308'-57	BRUSHY CANYON	•		PLUG#2				
- 1	Ş	X 4-1/2"	BONE SPRING			PLX0#3				
ł	۵	4, 274'-96' 4,308'-57' 4-1/2" Q 4,500 TOC 1,055' CALC.				PLUG#4				
		TOC / 055'	GLORIETA BLOVEBRY			PLUCIAS		<b></b>		
- 1		CALC.	TUBB			PLUG#4				
			DRINKARD			PLUG#1				
			ABO			PLUGRO				
-	•	Ì				PLUG# 10				
ł			wc			PLUGA				
			Penn			PLUGA				
1			STRAWN							
			ATOKA							
j		TD // 200 /	MORROW							
		TD <u>4,500</u>	écas.						,	
1			DEVONIAN							
Ī					- 1		ł		•	