Form 3160-5 (Nc·vember 1894)	Cvember 1594) DEPARTMENT OF THE INTERIOR			OMB No 1004-0135		
BUREAU OF LAND MANAGEMENT				5 Lease	Expires July 31, 1996 Serial No.	
·		OCI	D-HOBBS	NM-3622	X	
·	SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an				n, Allottee or Tribe Name	
abandoned well. Use form 3160-3 (APD) for such proposals.					a the second sec	
				7 If Unit o	or CA/Agreement, Name and/or No.	
SUBMIT IN	I TRIPLICATE - Other instructio	ns on reverse side				
1. Type of Well     X   Oil Well   Gas Well   Other				8. Well Name and No.		
2. Name of Operator				Scout 18 Federal No. 9 9. API Well No.		
Cimarex Energy Co. of Colorado				9. API We 30 <b>-02</b> 5-	29295	
3a. Address PO Box 140907; Irving, T	3b. Phone No (include area code) 972-401-3111		10. Field and Pool, or Exploratory Area			
4 Location of Well (Footage, Sec , T., R , M , or Survey Description)				Tonto; 7 Rivers		
2510' FNL & 720' FWL				11. County or Parish, State		
18-19S-34E Lea County, NM   12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA						
	APPROPRIATE BOX(ES) T		PE OF ACTION	L, KEI OK	1, 01(011)21(0.11)	
TYPE OF SUBMISSION	······································					
X Notice of Intent	Acidize	Deepen	Production (Start/	Resume)	Water Shut-Off	
	Alter Casing	Fracture Treat	Reclamation		Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete		X Other Request permit	
	Change Plans	Plug and Abandon	Temporarily Aban	don	extension	
Final Abandonment Notice	Deration (clearly state all pertinent details	Plug Back	Water Disposal		the second se	
testing has been completed. Final determined that the site is ready for	d operations. If the operation results in a Abandonment Notices shall be filed only r final inspection.) nced well is due to expire 01-04	after all requirements, inclu	ding reclamation, have	e been completed		
	RECEIVED					
	JAN 222008					
	HOBBS OC	A			Y	
			<b>-</b> .			
			<u>Expir</u>	<u>es</u>	01-04-2010	
14. I hereby certify that the foregoing is Name (Printed/Typed)	true and correct	Title				
Natalie Krueger		Reg Analyst	1			
Signature	,	Date				
1) atalie A	rulat	January 3, 20				
	THIS SPACE FO	R FEDERAL OR STAT				
Approved by	DAVID D. EVANS	Gor		MANAG	ER <sup>Date</sup> JAN 16 2008	
Conditions of Approval, if any, are atta certify that the applicant holds legal or	iched Approval of this notice does not equitable title to those rights in the sub	warrant or	CARLSB	AD FIEL	D OFFICE	
which would entitle the applicant to co	nduct operations thereon. t a crime for any person knowingly and	willfully to make to any dep				
fraudulent statements or representation	ons as to any matter within its jurisdiction	n <u> </u>				
(Instructions on reverse)		K	t			

## PECOS DISTRICT CONDITIONS OF APPROVAL

OPERATOR'S NAME: LEASE NO.: WELL NAME & NO.: SURFACE HOLE FOOTAGE:	NM3622 Scout 18 Federal #9
	Section 18, T. 19 S., R 34 E., NMPM Lea County, New Mexico

## I. DRILLING

## A. DRILLING OPERATIONS REQUIREMENTS

The BLM is to be notified a minimum of 4 hours in advance for a representative to witness:

- a. Spudding well
- b. Setting and/or Cementing of all casing strings
- c. BOPE tests

## 🛛 Lea County

Call the Hobbs Field Station, 414 West Taylor, Hobbs NM 88240, (575) 393-3612

- 1. Although Hydrogen Sulfide has not been reported in this section, it is always a possible hazard. It has been reported in Sections 4, 6, and 7 at a range of 200ppm to 600ppm in the gas stream. If Hydrogen Sulfide is encountered, please report measured amounts to the BLM.
- 2. Unless the production casing has been run and cemented or the well has been properly plugged, the drilling rig shall not be removed from over the hole without prior approval.
- 3. Floor controls are required for 3M or Greater systems. These controls will be on the rig floor, unobstructed, readily accessible to the driller and will be operational at all times during drilling and/or completion activities. Rig floor is defined as the area immediately around the rotary table; the area immediately above the substructure on which the draw works are located, this does not include the dog house or stairway area.



JAN 2 2 2008 HOBBS OCD

#### **B.** CASING

1. The <u>8 5/8 inch</u> surface casing shall be set a minimum of <u>25 feet into the Rustler</u> <u>Anhydrite and above the salt at approximately 1620 feet</u> and cemented to the surface.

Onshore Order II requires casing to be set across a competent bed and the Rustler Anhydrite is the first formation that meets that criteria.

Possible lost circulation in the Grayburg and Bone Springs.

Fresh water mud to be used to the top of the Rustler Anhydrite approximately 1620 feet.

- a. If cement does not circulate to the surface, the appropriate BLM office shall be notified and a temperature survey utilizing an electronic type temperature survey with a surface log readout will be used or a cement bond log shall be run to verify the top of the cement.
- b. Wait on cement (WOC) time for a primary cement job will be a minimum 18 hours for a water basin, 24 hours in the potash area, or 500 pounds compressive strength, whichever is greater. (This is to include the lead cement).
- c. Please provide WOC times to inspector for cement slurries.
- d. Wait on cement (WOC) time for a remedial job will be a minimum of 4 hours after bringing cement to surface or 500 pounds compressive strength, whichever is greater.
- e. If cement falls back, remedial action will be done prior to drilling out that string.
- 2. The minimum required fill of cement behind the 5 1/2 inch Production casing is:
  - Cement to surface. If cement does not circulate, contact the appropriate BLM office.
  - a. Please provide WOC times to inspector for cement slurries.
- 3. If hardband drill pipe is rotated inside casing, returns will be monitored for metal. If metal is found in samples, drill pipe will be pulled and rubber protectors which have a larger diameter than the tool joints of the drill pipe will be installed prior to continuing drilling operations.



JAN 222008

HOBBS OCD

Page 2 of 3

## C. PRESSURE CONTROL

. .

- 1. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.
- 2. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be 3000 (3M) psi. As submitted in APD.
- 3. The appropriate BLM office shall be notified a minimum of 4 hours in advance for a representative to witness the tests.
  - a. The tests shall be done by an independent service company.
  - b. The results of the test shall be reported to the appropriate BLM office.
  - c. All tests are required to be recorded on a calibrated test chart. A copy of the BOP/BOPE test chart and a copy of independent service company test will be submitted to the appropriate BLM office.
  - d. The BOP/BOPE test shall include a low pressure test from 250 to 300 psi. The test will be held for a minimum of 10 minutes if test is done with a test plug and 30 minutes without a test plug.

## D. DRILL STEM TEST

If drill stem tests are performed, Onshore Order 2.III.D shall be followed.

Engineer on call phone (after hours only): Carlsbad: (575) 706-2779

JDW/1/15/2008 (date)

## RECEIVED

JAN 222008

# HOBBS OCD