Form 3160-5 (August 1999)

its jurisdiction.


PECEIVED HOLDS FORM APROVED OCD-ARTESIA OMB NO. 1004-0135 EXPIRES: NOVEMBER 30, 2000

5. Lease Serial No.

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUNDRY NOTICES AND REPORTS ON WELLS BSOLED

Do not use this form for proposals to drill or to re-enter an	NM-81958
abandoned well. Use Form 3160-3 (APD) for such proposals	6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE	
	7. Unit or CA Agreement Name and No.
1a. Type of Well 🗸 Oil Well 🔲 Gas Well 🔲 Other	8 Well Name and No.
	1 / I
2. Name of Operator	9. API Well No.
DEVON ENERGY PRODUCTION COMPANY, LP	30-025-30997
3. Address and Telephone No.	
20 North Broadway, Ste 1500, Oklahoma City, OK 73102 405-552-4615	10. Field and Pool, or Exploratory
4. Location of Well (Report location clearly and in accordance with Federal requirements)*	WEST CORBIN DELAWARE 12. County or Parish 13. State
660 FNL 660 FEL Sec 13 T18S R32E	
	LEA NM
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OS SUBMISSION TO THE DATA TYPE OF ACTION	
V Notice of Intent	on (Start/Resume) Water Shut-Off Well Integrity
Alter Casing Fracture Treat Reclamat Alter Casing Repair New Construction Recompleted Rec	
Change Plans	rily Abandon
☐ Final Abandonment Notice ☐ Convert to Injection ☐ Plug Back ☐ Water Di	
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof. If the proposal deepen directionally or recomplete horizontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection)	
Plug & Abandonment Procedure: 1. MIRU. POOH w/rod pump and production tubing. 2. Set CIBP @ 4950'. Dump 35' cement on top. (Delaware perforations from 4970' to 4998') 3. Circulate wellbore w/10 ppg mud. 4. Spot 25 sx cement @ 2610'. Calc. TOC @ 2363'. (base of salt @ 2610') Z_6 D . WOC Z_7 5. Spot 25 sx cement @ 1600'. Calc. TOC @ 1353'. (top of salt @ 1600') /650 . WOC Z_7 6. Spot 25 sx cement @ 478'. WOC & Tag. Calc. TOC @ 231'. (8-5/8" casing shoe @ 428') 7. Spot 25 sx cement to surface. 8. Cut wellhead off, set dry hole marker, and clean location. SEE ATTACHED FOR CONDITIONS OF APPROVAL	
14. I hereby certify that the foregoing is true and correct	APPROVED
Signed Round Stack Title Round Technician	APPROVED 5/20/2009
(This space for Federal or State Office use)	MAY 3 0 2009
Approved by Conditions of approval, if any:	Date LAMES A AMOS

Title 16 U.S.C. Section 1001, makes it a crime for any person knowingly and williamy to make any department or agency or the United States any raise, horizontal




5300' TD

<u>DELAWARE</u> 4970' - 4986' 4988' - 4998'

7-7/8" Hole 5-1/2", 15.5#, K55, STC & LTC, @ 5300' Cmt'd w/1275 sx, circulated to surface

Proposed:

- 1. Set CIBP @ 4950'
- 2. Dump 35' cement on top



BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1 Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed prior to commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs

- 6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker well name and number, name of the operator, lease serial number; surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.