

Submit 3 Copies To Appropriate District Office  
District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
1301 W Grand Ave, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd, Aztec, NM 87410  
District IV  
1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico

Department of Energy, Minerals and Natural Resources

Form C-103  
June 19, 2008

RECEIVED

JUN 05 2009  
OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505  
HOBBSOCD

WELL API NO. <b>30-025-32394</b>
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name <b>Galado Brine Well</b>
8. Well Number <b>2</b>
9. OGRID Number
10. Pool name or Wildcat <b>Galado</b>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) <b>3073</b>

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other **Brine**

2. Name of Operator  
**Basic Energy Services**

3. Address of Operator  
**P.O. Box 10460 Midland, TX. 79702**

4. Well Location  
Unit Letter **A**: **1305** feet from the **North** line and **60** feet from the **East** line  
Section **20** Township **25 S** Range **37 E** NMPM County **Lea**

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: **Gonar Survey**

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Rig up Rig. POH with tubing. Run bit and scraper to bottom of casing POH. Run packer on work string and test casing and run chart witnessed by State. POH run 6" bit on 4 1/2 work over pipe to 1700' TD. Cut of bit and start surveying ext of hole. Run 1658' of 2 3/8 production string back in put back on production

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

**Steve Prather**

TITLE

**District Manager**

DATE

**6/3/09**

Type or print name

**Steve Prather**

E-mail address:

**steve.prather@state.nm.gov**

PHONE:

**505.394.3235**

For State Use Only

APPROVED BY:

**Camille W. Hill**

TITLE

**DISTRICT 1 SUPERVISOR**

DATE

**JUN 08 2009**

Conditions of Approval (if any):