

Office

Energy, Minerals and Natural Resources

June 19, 2008

District I

1625 N. French Dr., Hobbs, NM 88241

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

OIL CONSERVATION DIVISION

AUG 10 2009

South St. Francis Dr.

Santa Fe, NM 87505

HOBBSD

WELL API NO.

30-025-11684

5. Indicate Type of Lease

STATE ☐FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Lanehart

8. Well Number

3

9. OGRID Number

192143

10. Pool name or Wildcat

Jalmat - Tan - Yates - 7 - Rms - (Gca)

SUNDRIY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other ☐

2. Name of Operator

Herman L. Loeb

3. Address of Operator

P O Box 838 Lawrenceville, IL 62439

4. Well Location

Unit Letter L 2310 feet from the south line and 990 feet from the west line
Section 21 Township 25S Range 37E NMPM County Lea ☒

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3054 ft (top of casing), Cable tool hole

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS: ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Set cast iron bridge plug @ 2800', RIH w/ tbg to 2,800', spot 25 sk of cement on plug, POH w/ 7 jts tbg, spot 31 bbl of mud-laden water, POH w/ tbg.

2. Perforate 2 holes @ 1295', RIH w/ tbg & packer, set pkr @ 800', attempt to squeeze w/ 100 sk cement to fill 1295' to 900'. Displace cement to 900'. WOC release pkr, RIH w/ tbg & tag.

3. Perforate 2 holes @ 375', attempt to circulate cement to the surface. WOC.

4. Cut off well head 3' below ground level, top off casing & annulus as necessary.

The Oil Conservation Division **Must be notified**
24 hours prior to the beginning of plugging operations.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Petroleum Engineer

DATE 7/22/09

Type or print name G. A. Payne

E-mail address: gapayne@sigecon.net

PHONE: 812.453.0385

For State Use Only

APPROVED BY:

TITLE Compliance Officer

DATE 8-12-2009

Conditions of Approval (if any):

Lease: Lanehart
Well #: 3

Diagram: 07/22/2009
Elev KB: 3054
TD: 2928

Comp Date: 09/28/1937
Elev GL: 3054
PBSD: 0

Permit: 30-025-11684
Location: NE NW SW 21-25S-37E
County: Lea
State: New Mexico
Field: Jalmat
Operator: Herman Loeb

