

Form 3160-5  
(June 1990)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

OCD-HOBBS  
**RECEIVED**  
AUG 18 2009  
HOBBSOCD

FORM APPROVED  
Budget Bureau No 1004-0135  
Expires: March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT-" for such proposals

**SUBMIT IN TRIPLICATE**

1. Type of Well

☐ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

CHI OPERATING, INC. ✓

3. Address and Telephone No

P.O. BOX 1799 MIDLAND, TEXAS 79702

4. Location of Well (Footage, T, R, M, or Survey Description)

1980 FSL & 1980 FEL, J-30-21S-32E ✓

5. Lease Designation and Serial No

NM 104764

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No

Bilbrey "30" Federal #5 ✓

9. API Well No.

30-025-33647 ✓

10. Field and Pool, or Exploratory Area

11. County or Parish, State

Lea County ✓

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent  
☒ Subsequent Report  
☒ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment  
☐ Recompletion  
☒ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other

- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- 1) RD DD PU. POOH w/RBP, pkr and 2-7/8" production tbg.
- 2) Dump 5sx cmt on top of RBP @ 6700' to abandon all Brushy Canyon perms.
- 3) Set CIBP @ 4550' (above Bell Canyon) and spot 250' of cmt on top & tag.
- 4) Perforate 5 1/2" csg @ 855' & squeeze w/40sx cmt. Solid plug In & Out f/755-805' & tag.
- 5) Perforate 5 1/2" csg @ 100' & squeeze w/40sx cmt, circ to surf. Spot 100' surface plug.
- 6) Cut off well head. Install dry hole marker and reclaim location.

**Accepted as to plugging of the well bore.  
Liability under bond is retained until  
Surface restoration is completed.**

14. I hereby certify that the foregoing is true and correct.

Signed

Title REGULATORY CLERK

**ACCEPTED FOR RECORD**  
Date 5/28/09

(This space for Federal or State office use)

Approved by

Title

**DISTRICT 1 SUPERVISOR**

Date

AUG 15 2009

Conditions of approval, if any.

Title 18 U S C Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*See Instructions on Reverse Side

\*Need to remove all power poles, Notify Jim Amos @ 575-234-5909 when removed.

Name: B30\_5 ID: 30025336470000 Type: DEL Date: 19981013  
 KB: 3692.0 TD: 8916.0 PBTD: 6700.0 Comp Date: 0

