Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires November 30, 2000

6. If Indian, Allottee or Tribe Name


NM90587

SUNDRY NOTICES	AND REPORTS O	MA AAETTO	HOBBEOOR
SUNDRY NUTICES Do not use this form for	proposale to drill or	to re-enter a	

5. Lease Serial No.

abandoned well. Use For	m 3160-3 (APD) for s	uch proposals.		
SUBMIT IN TRIPLICATE - Other instructions on reverse side			7 If Unit or CA/Agreement, Name and/or No	
1. Type of Well X Oil Well Gas Well Other	/			8. Well Name and No Livingston Ridge #3 /
2. Name of Operator OXY USA Inc.		16696		19 Federal
3a Address	3	b. Phone No (include ar	ea code)	9 APJ Well No 30-015-36029
P.O. Box 50250, Midland, TX 79710-		432-685-5717		10. Field and Pool, or Exploratory Area
4 Location of Well (Footage, Sec, T., R, M, or Survey				Livingston Ridge Delaware, E
2510 FSL 330 FWL NWSW(L) Sec 19 T22S R32E				11. County or Parish, State
	•			Lea NM
12. CHECK APPROPRIATE	BOX(ES) TO INDIC	CATE NATURE OF	NOTICE, REP	ORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION			
X Notice of Intent	Acidize	Deepen	Production	(Start/Resume) Water Shut-Off
	Alter Casing	Fracture Treat	Reclamatio	on X Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomplet	
First About town and Makes	Change Plans	Plug and Abandon		ly Abandon
Final Abandonment Notice	Convert to Injection	Plug Back	Water Dist	posal
1. POOH w/ production equipment. 2. RIH & tag CIBP @ 8150', spot 2 3. RIH & set CIBP @ 6840' 4. Notify BLM/NMOCD of casing int 5. RU pump truck, circulate well	s well to an SWD. 36-7134' 8190-8338 25 SK Plug 25sx cmt on top. 36egrity test 24hrs	(160) CIBP-8150 (160) CIBP-8150 (160) ACC	0' : 1055 Top	poF Bone Springs @ 8421
SEE ATTACHED FOR	OVAT			
CONDITIONS OF APPR LAST frod. 12/2008 /well	(UVAL //Dr.][ed 6]	/		
	Mr./led			
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) David Stewart		Title Sr. Re	gulatory And	alyst
la: Sal			8/25/09	
THIS	S SPACE FOR FEDE			
Approved by /s/ JD Whitlock J	lr 1917)	Title (PET .	Date 8/2/29
Conditions of approval, if any, are attached. Approval of certify that the applicant holds legal or equitable title to which would entitle the applicant to conduct operations to	of this notice does not war those rights in the subjec	rant or Office	Fo	1: / 8 // 6 //

OXY USA Inc. - Proposed Livingston Ridge 19 Federal #3 API No. 30-025-36029




CIBP @ 6840'

25sx @ 8150'

3/04-CIBP @ 8150'

OXY USA Inc. - Current Livingston Ridge 19 Federal #3 API No. 30-025-36029



BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. **Submits a subsequent Sundry Notice** (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Livingston Ridge 19 Federal #3. Well may be approved to be TA/SI for a period of 6 months after successful MIT and subsequent report is submitted. This will be the last and only TA/SI approval. Well must be P&A or plans to convert to SWD submitted by 2/2010.

- 1. Also need to spot a 25 sk plug @ 8470' at the top of the Bone Springs.
- 2. Missing Jan. and Feb. 2009 production reports to MMS, need to submit.