| - | UNITED STATI DEPARTMENT OF THE BUREAU OF LAND MAN. RY NOTICES AND REPO | INTERIOR Hobbs, agement | French Drive | FORM APPROVED OMB No 1004-0135 Expires November 30, 2000 5. Lease Serial No. LC 031670B |
|--|--|--|---|--|
| Do not use t | this form for proposals to well. Use Form 3160-3 (Al | o drill or to re-enter a | nn Is. | 6. If Indian, Allottee or Tribe Name |
| SUBMIT IN TH | RELICATE - Other Instr | uctions on reverse | side | 7. If Unit or CA/Agreement, Name and/or No Warren Unit Blinebry Tubb WF |
| Oil Well Gas Well | C Other | | | 8. Well Name and No. #43 |
| ConocoPhillips Company | onocoPhillips Company | | | 9. API Well No. 30-025-25360 |
| 3a. Address 4001 Penbrook Street Od | essa TX 79762 | 3b. Phone No. (include (432)368-1667 | le area code) | 10. Field and Pool, or Exploratory Area |
| 4. Location of Well (<i>Footage, S.</i> Sec. 21, T-20-S, R-38-E, I 660' FSL & 1980' FWL | ec., T., R., M., or Survey Descript UL "N" | ion) | | Warren; Blinebry-Tubb Oil & Gas 11. County or Parish, State Lea NM |
| 12. CHECK A | PPROPRIATE BOX(ES) 1 | O INDICATE NATU | RE OF NOTICE, R | REPORT, OR OTHER DATA |
| TYPE OF SUBMISSION | | ТҮ | PE OF ACTION | |
| Notice of Intent Subsequent Report Final Abandonment Notice | Acidize Alter Casing Casing Repair Change Plans Convert to Injection | Deepen Fracture Treat New Construction Plug and Abandon Plug Back | Production (Stat Reclamation Recomplete Temporarily Ab. Water Disposal | Well Integrity Other Downhole |
| tollowing completion of the in- testing has been completed. Fin determined that the site is ready | volved operations. If the operation nal Abandonment Notices shall be y for final inspection.) re, ConocoPhillips wishe | vide the Bond No. on file was a results in a multiple comple e filed only after all requiren as to perform the sub | ith BLM/BIA. ,Required etion or recompletion ir nents, including reclama ject work, includir | errical depths of all pertinent markers and zones. d subsequent reports shall be filed within 30 days a a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has ang downhole commingling the Warre |
| following completion of the intesting has been completed. Findetermined that the site is ready Per the following Procedu Blinebry-Tubb Oil & Gas MIRU. Pull rods, & put RIH and drill out fill, ce | volved operations. If the operation nal Abandonment Notices shall be y for final inspection.) re, ConocoPhillips wishe (#62965) with the Warren mp. ND WH/ NU BOP. ment plug and CIBP star | vide the Bond No. on file was a results in a multiple comple e filed only after all requiren as to perform the sub n; Drinkard (#63080) POH w/ production t | ith BLM/BIA. ,Required etion or recompletion ir nents, including reclama ject work, includir | d subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has ing downhole commingling the Warre |
| following completion of the invitesting has been completed. Findetermined that the site is ready Per the following Procedu Blinebry-Tubb Oil & Gas 1) MIRU. Pull rods, & put | volved operations. If the operation nal Abandonment Notices shall be y for final inspection.) re, ConocoPhillips wishe (#62965) with the Warren mp. ND WH/ NU BOP. ment plug and CIBP star o perfs from 5902-6696'. ut as necessary. P/ NU WH. | vide the Bond No. on file was a results in a multiple comple- tiled only after all requiren the to perform the sub- n; Drinkard (#63080) POH w/ production to ting at +/- 6743'. | ith BLM/BIA. ,Required etion or recompletion ir nents, including reclama ject work, includir | d subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has ing downhole commingling the Warre |
| following completion of the intesting has been completed. Findetermined that the site is ready Per the following Procedu Blinebry-Tubb Oil & Gas (1) MIRU. Pull rods, & pull RIH and drill out fill, ce Isolate Blinebry & Tubb Frac Drinkard. Flow back and clean of RIH w/ tubing. ND BO | volved operations. If the operation nal Abandonment Notices shall be y for final inspection.) re, ConocoPhillips wishe (#62965) with the Warren mp. ND WH/ NU BOP. ment plug and CIBP star o perfs from 5902-6696'. ut as necessary. P/ NU WH. | vide the Bond No. on file was a results in a multiple comple- tiled only after all requiren the to perform the sub- n; Drinkard (#63080) POH w/ production to ting at +/- 6743'. | ith BLM/BIA. , Required etion or recompletion ir nents, including reclama ject work, includir ubing. Subject to ike Approva by State | d subsequent reports shall be filed within 30 days is a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has ing downhole commingling the Warre and the operator has ing downhole commingling the Warre Received 1 Hobbs 5 0CD 5 1 Hobbs 5 0CD 5 1 Hobbs 5 Hobbs 5 |
| following completion of the intesting has been completed. Findetermined that the site is ready Per the following Procedu Blinebry-Tubb Oil & Gas MIRU. Pull rods, & put RIH and drill out fill, ce Isolate Blinebry & Tubb Frac Drinkard. Flow back and clean oi RIH w/ tubing. ND BO RIH w/pump assembly Isolate G. Dale | volved operations. If the operation nal Abandonment Notices shall be y for final inspection.) re, ConocoPhillips wishe (#62965) with the Warren mp. ND WH/ NU BOP. ment plug and CIBP star o perfs from 5902-6696'. ut as necessary. P/ NU WH. & rods and RTP. | vide the Bond No. on file was a results in a multiple comple e filed only after all requiren as to perform the sub n; Drinkard (#63080) POH w/ production t ting at +/- 6743'. | ith BLM/BIA. Required etion or recompletion ir nents, including reclama ject work, includir ubing. Bubject to ike Approva by State CON CANI | d subsequent reports shall be filed within 30 days is a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has ing downhole commingling the Warre $\sqrt{22222} \times 2526 \times 28}$ $\sqrt{10} \times 2005$ $\sqrt{10} \times 2005$ |
| following completion of the im- testing has been completed. Fir determined that the site is ready Per the following Procedu Blinebry-Tubb Oil & Gas (1) MIRU. Pull rods, & put 2) RIH and drill out fill, ce Isolate Blinebry & Tubb Frac Drinkard. Flow back and clean oi RIH w/ tubing. ND BO. RIH w/ pump assembly | volved operations. If the operation nal Abandonment Notices shall be y for final inspection.) re, ConocoPhillips wishe (#62965) with the Warren mp. ND WH/ NU BOP. ment plug and CIBP star o perfs from 5902-6696'. ut as necessary. P/ NU WH. & rods and RTP. | vide the Bond No. on file was a results in a multiple complection is to perform the sub n; Drinkard (#63080) POH w/ production t ting at +/- 6743'. | ith BLM/BIA. , Required etion or recompletion ir nents, including reclama ject work, includir ubing. Bubject to ike Approva by State <u>con</u> cani tory Analyst | d subsequent reports shall be filed within 30 days is a new interval, a Form 3160-4 shall be filed once ation, have been completed, and the operator has and downhole commingling the Warre |
| following completion of the impletion of the imp | volved operations. If the operation nal Abandonment Notices shall be y for final inspection.) re, ConocoPhillips wishe (#62965) with the Warres mp. ND WH/ NU BOP. ment plug and CIBP star o perfs from 5902-6696'. ut as necessary. P/ NU WH. & rods and RTP. | vide the Bond No. on file was a results in a multiple comple e filed only after all requiren as to perform the sub n; Drinkard (#63080) POH w/ production t ting at +/- 6743'. | ith BLM/BIA. Required etion or recompletion ir nents, including reclama ject work, includir ubing. Subject to ike Approva by State <u>con</u> CANI tory Analyst District 2005 | d subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once thion, have been completed, and the operator has and downhole commingling the Warre |
| following completion of the impletion of the imp | volved operations. If the operation nal Abandonment Notices shall be y for final inspection.) re, ConocoPhillips wishe (#62965) with the Warren mp. ND WH/ NU BOP. ment plug and CIBP star o perfs from 5902-6696'. ut as necessary. P/ NU WH. & rods and RTP. mg is true and correct <u>A AULL</u> THIS SPACES | vide the Bond No. on file was a results in a multiple complection is to perform the sub n; Drinkard (#63080) POH w/ production t ting at +/- 6743'. Title Regula Date 04/19/2 OR FEDERAL OR ST | ith BLM/BIA. Required etion or recompletion ir nents, including reclama ject work, includir ubing. Subject to ike Approva by State CON CANI tory Analyst District 2005 | d subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once thion, have been completed, and the operator has and downhole commingling the Warre |
| following completion of the im- testing has been completed. Fir determined that the site is ready Per the following Procedu Blinebry-Tubb Oil & Gas 1) MIRU. Pull rods, & pur 2) RIH and drill out fill, ce 3) Isolate Blinebry & Tubk 4) Frac Drinkard. 5) Flow back and clean oi 7) RIH w/ tubing. ND BO. 8) RIH w/pump assembly 14. I hereby certify that the foregoin Name (<i>PrintedTyped</i>) Celeste G. Dale Signature Automatical Signature | volved operations. If the operation nal Abandonment Notices shall be y for final inspection.) re, ConocoPhillips wishe (#62965) with the Warren mp. ND WH/ NU BOP. ment plug and CIBP star operfs from 5902-6696'. ut as necessary. P/ NU WH. & rods and RTP. mg is true and correct M. M. M. THIS SPACES DAVED & COMP attached. Approval of this notic or equitable title to those rights | vide the Bond No. on file was a results in a multiple comple e filed only after all requiren as to perform the sub n; Drinkard (#63080) POH w/ production t ting at +/- 6743'. Title Regula Date 04/19/2 OR FEDERAL OR ST 12 J re does not warrant or Of | ith BLM/BIA. Required etion or recompletion ir nents, including reclama ject work, includir ubing. Subject to ike Approva by State <u>con</u> CANI tory Analyst District 2005 | d subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once thion, have been completed, and the operator has and downhole commingling the Warre |
| following completion of the impletion of the imp | volved operations. If the operation nal Abandonment Notices shall be y for final inspection.) re, ConocoPhillips wishe (#62965) with the Warren mp. ND WH/ NU BOP. ment plug and CIBP star operfs from 5902-6696'. ut as necessary. P/ NU WH. & rods and RTP. mg is true and correct HIS SPACES DAVED & COMMENDED attached. Approval of this notic or equitable title to those rights conduct operations thereon. is it a crime for any person know | vide the Bond No. on file was a results in a multiple comple- e filed only after all requiren as to perform the sub- n; Drinkard (#63080) POH w/ production t ting at +/- 6743'. Title Regula Date 04/19/2 OR FEDERAL OR ST 12 J re does not warrant or in the subject lease Tingly and willfully to make | ith BLM/BIA. Required etion or recompletion ir nents, including reclama ject work, includir ubing. Subject to ike Approva by State CON CANI tory Analyst District 2005 ATE OFFICE USE | d subsequent reports shall be filed within 30 days in a new interval, a Form 3160-4 shall be filed once thion, have been completed, and the operator has and downhole commingling the Warre |

| 1 | | | |
|---|---|----|--|
| | ٨ | ;: | |

Recommended Procedure

1. MIRU workover unit. POOH with rods & pump and lay down same. ND wellhead and NU BOP's and test. POOH with 2³/₈" tubing.

. . . .

- 2. RIH with bit for 7" 23/26# casing on 2%", 4.7# production tubing as workstring to 6776'±, circulating well clean with 2% KCL water. Drill out CIBP and continue TIH to PBTD at 6991'±. POOH with 2%" workstring.
- MIRU Schlumberger wireline. RU 1000 psi lubricator. Run GR-CCL log from 6960'± to 5500'±. Correlate to Schlumberger Compensated Neutron log dated 12/18/76. Perforate the Tubb from 6509-6525' with 2 SPF, 90° phasing (32 holes). Perforate the Blinebry from 5794-5797, and 5811-5825' with 2 SPF, 90° phasing (34 holes), using 3½" High Shot Density, 34JL Ultrajet, HMX 22.7g, (API 19B: Pen 28.94", EHD 0.37")
- 4. RDMO wireline and lubricator.
- 5. TIH with packer and 2³/₄" workstring. Set packer at 5750'±. Acidize the Blinebry perfs with 3100 gals 15% HCl acid. Release packer and POOH.
- 6. RIH with the 2³/₄" production tubing (per tubing design in WellView). Place the EOT at 6960'± with the tubing anchor at 5750'±. Maintain a dynamic fluid column (DFC) while running tubing. (Trickle some 2% KCl water down the tubing head valve.)
- 7. ND BOPs and NU wellhead. RIH with pump and rods (per rod design in WellView). Space and hang well on. Load tubing and check pump action.
- 8. RDMO well service rig. Release any ancillary equipment. Clean up location.
- 9. Turn well over to Operations. Place well on production. Report well tests on morning report. Place stabilized well test in FieldView. Contact chemical representative to place well on corrosion inhibition and scale squeeze program if needed. Submit change of status report.



