Submit 3 Copies To Appropriate District State of New Mexico Office Finergy Minerals and Natural Resources	Form C-103
District I	May 27, 2004 WELL API NO.
1625 N. French Dr., Hobbs, NMRECEIVECONSERVATION DIVISION District II 1301 W. Grand Ave , Artesia, NM 88210	<u>30-025-25596</u> 5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87460 OY 2009 1220 South St. Francis Dr. Santa Fe, NM 87505	STATE X FEE
District IV 1220 S. St. Francis Dr., Santa Felt OBBSOCD	6. State Oil & Gas Lease No. B-229
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH (PROPOSALS.)	7. Lease Name or Unit Agreement Name: Arnott Ramsey NCT E
1. Type of Well:	8. Well Number
Oil Well X Gas Well Other 2. Name of Operator	9. OGRID Number
OXY USA Inc.	16696
3. Address of Operator P.O. Box 50250 Midland, TX 79710-0250	10. Pool name or Wildcat Langlie Mattix ; 7 Rurs - Q - Grayburg
4. Well Location	,, _,, _
Unit Letter <u>I</u> : <u>1980</u> feet from the <u>south</u> line and <u></u>	660 feet from the east line
Section16Township25SRange37E11. Elevation (Show whether DR, RKB, RT, GR, elevation)	
3099' GR	(C.)
Pit or Below-grade Tank Application or Closure	
Pit type Depth to Groundwater Distance from nearest fresh water well Di Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction to the cons	
12. Check Appropriate Box to Indicate ₁ Nature of Notice	Report, or Other Data
	SEQUENT REPORT OF:
	•
	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON X CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE CASING TEST AND	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON X CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: Run MIT OTHER: Run MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attack	ALTERING CASING ALTERING CASING ING OPNS. PLUG AND ABANDONMENT ABANDONMENT ABANDONMENT Pertinent dates, including estimated date
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: Run MIT OTHER: Run MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attack or recompletion. 0XY USA Inc requests to temporarily abandon this well, this well is curved.	SEQUENT REPORT OF: ALTERING CASING ING OPNS. PLUG AND ABANDONMENT & TA xe pertinent dates, including estimated date h wellbore diagram of proposed completion
 PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: Run MIT I3. Describe proposed or completed operations. (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion. OXY USA Inc requests to temporarily abandon this well, this well is cuuse. TD-3700' PBTD-3682' Perfs-3382-3484' 9/10-9/11/09 MIRU, POOH and lay down rods and pump, Release TAC and PORIH & Set CIBP @ 3320', circ packer fluid (90 bbls) Pressure up on plumin. POH w/ Tbg. SDON. NDP Finish come out of hole w/ Tbg, NDBOP, NUWH 9/14/09 Pressure up to 500 psi. Held for 30 min. Called NMOCD. Got MIT This work was originally planned as a workover, while on well decompleted. 	ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ALTERING CASING ALTERING ALTER
 PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION OTHER: Run MIT Describe proposed or completed operations. (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attack or recompletion. OXY USA Inc requests to temporarily abandon this well, this well is cuuse. TD-3700' PBTD-3682' Perfs-3382-3484' 9/10-9/11/09 MIRU, POOH and lay down rods and pump, Release TAC and PORIH & Set CIBP @ 3320', circ packer fluid (90 bbls) Pressure up on plumin. POH w/ Tbg. SDON. NDP Finish come out of hole w/ Tbg, NDBOP, NUWH 9/14/09 Pressure up to 500 psi. Held for 30 min. Called NMOCD. Got MIT 	ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ABANDONMENT ADDRESS AD
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON Image: Change Plans COMMENCE DRILL PULL OR ALTER CASING Image: MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: Run MIT Image: OTHER: Run MIT OTHER: Run MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attack or recompletion. OXY USA Inc requests to temporarily abandon this well, this well is cuase. TD-3700' PBTD-3682' Perfs-3382-3484' 9/10-9/11/09 MIRU, POOH and lay down rods and pump, Release TAC and PO RIH & Set CIBP @ 3320', circ packer fluid (90 bbls) Pressure up on plu min. POH w/ Tbg. SDON. NDP Finish come out of hole w/ Tbg, NDBOP, NUWH 9/14/09 Pressure up to 500 psi. Held for 30 min. Called NMOCD. Got MIT This work was originally planned as a workover, while on well decomplete to the best of my knowledg grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permit	BSEQUENT REPORT OF: ALTERING CASING ING OPNS. PLUG AND ABANDONMENT & TA e pertinent dates, including estimated date in wellbore diagram of proposed completion rrently being evaluated for future OH w/ tubing, SDON. g to 500 psi bleed off 10 psi in 30 , RDPU Chart and OK. Of //3/2014 ided to TANIS Approval of Temporary Abandonment Expires e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan tory Analyst DATE LOCLES
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: Run MIT OTHER: Run MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attack or recompletion. 0XY USA Inc requests to temporarily abandon this well, this well is cu use. TD-3700' TD-3700' PBTD-3682' Perfs-3382-3484' 9/10-9/11/09 MIRU, POOH and lay down rods and pump, Release TAC and PO RIH & Set CIBP @ 3320', circ packer fluid (90 bbls) Pressure up on plu min. POH w/ Tbg. SDON. NDP Finish come out of hole w/ Tbg, NDBOP, NUWH 9/14/09 Pressure up to 500 psi. Held for 30 min. Called NMOCD. Got MIT This work was originally planned as a workover, while on well dec I hereby certify that the information above is true and complete to the best of my knowledg grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permit	ALTERING CASING ALTERING CASING ING OPNS. PLUG AND ABANDONMENT & TA te pertinent dates, including estimated date in wellbore diagram of proposed completion rrently being evaluated for future OH w/ tubing, SDON. g to 500 psi bleed off 10 psi in 30 , RDPU Chart and OK. OA/13/2014 ided to TANIS Approval of Temporary Abandonment Expires e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST AND CEMENT JOB OTHER: Run MIT OTHER: Run MIT OTHER: Run MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, and giv of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion. OTHER: Run MIT 0XY USA Inc requests to temporarily abandon this well, this well is cu use. TD-3700' PBTD-3682' Perfs-3382-3484' 9/10-9/11/09 MIRU, POOH and lay down rods and pump, Release TAC and PO RIH & Set CIBP @ 320', circ packer fluid (90 bbls) Pressure up on plu min. POH w/ Tbg. SDON. NDP Finish come out of hole w/ Tbg, NDBOP, NUWH 9/14/09 Pressure up to 500 psi. Held for 30 min. Called NMOCD. Got MIT This work was originally planned as a workover, while on well dec I hereby certify that the information above is true and complete to the best of my knowledg grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permit SIGNATURE TITLESr. Requida E-mail address: Type or print name David Stewart TUP O	ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING CASING ALTERING OPNS. ALTERING CASING ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ABANDONMENT ADAINATE ADAINATION ADAINATIONATION ADAINATIONATIONATIONATIONATIONATIONATIONAT

