Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103	
Office <u>District I</u> 1625 N French Dr., Hobbs, NM 8 <b>RECEIVE</b> District II	gy, Minerals and Natural Resources	June 19, 2008	
1625 N French Dr., Hobbs, NM 8 RECEIVE		WELL API NO.	
District II OII	CONSERVATION DIVISION	30-025233532	
District III District IIII District IIII District III District III District III		5. Indicate Type of Lease	
District III 1000 Pio Brazos P.d. Aztec, NM 87410	1220 South St. Francis Dr.	STATE X FEE	
1000 Rio Brazos Rd , Aztec, NM 87440	🔰 Santa Fe, NM 87505	6. State Oil & Gas Lease No.	
1220 S St Francis Dr., Santa Fe, NM			
87505			
SUNDRY NOTICES AND		7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DR		Jordan State	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PROPOSALS )	(PERMIT (FORM C-TOT) FOR SUCH		
1. Type of Well: Oil Well X Gas Well	Other	8. Well Number 1	
2. Name of Operator		9. OGRID Number	
2. Name of Operator Chesapeake Operating,	Inc.	147179	
3. Address of Operator P.O. Box 18496		10. Pool name or Wildcat	
Oklahoma City, Ok 73154-0496		Mescalero; Cisco, Northeast	
4 Wall Leastion			
4. Well Location			
Unit Letter <u>B</u> : 660'	_feet from the <u>North</u> line and <u>165</u>	60'feet from the Eastline	
Section 12	Township 10S Range 32E	NMPM County Lea	
经合适于成为工具计划发展的新闻,把自己的原始的新闻,在自己的问题,这些法律的问题,并且一部	ation (Show whether DR, RKB, RT, GR, etc.)		
4200' 0	JK	and the state of the	
12. Check Appropria	te Box to Indicate Nature of Notice,	Report or Other Data	
	,	•	
NOTICE OF INTENTIO	N TO: SUB	SEQUENT REPORT OF:	

	IENTION IO.		SUBSEQUENT REPORT OF	•
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK	CASING 🗌
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING OPNS 🗍 🛛 P AND A	
PULL OR ALTER CASING	MULTIPLE COMPL		CASING/CEMENT JOB	
OTHER Add perfs		X	OTHER:	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Please find the procedure to add perforations in the Bough "B" of the Cisco formation along with NMOCD's C-144(CLEZ) pit permit.

٩.

١.,

1.00

Spud Date:	Rig Release Date:	
I hereby certify that the information above is true and co	omplete to the best of my knowledge and belief.	
SIGNATURE Buy Ann	TITLE Senior Regulatory Compl. Sp.	DATE 09/24/2009
Type or print name Bryan Arrant	E-mail address: <u>byran.arrant@chk.com</u>	PHONE: (405)935-3782
For State Use Only APPROVED BY: Conditions of Approval (if any):	TITLE PETROLEUM ENGINEER	_DATEOCT1_4_2009



#### Jordan State #1 Bough B Recompletion Lea County, NM

## **Current Wellbore Information**

### TD: 9,250' PBTD: 8,888'

Casing	OD	Weight	Grade	Depth Set	Тос
Surface	13-3/8"	48#	H40	400'	Surface
Intermediate	8-5/8"	32#	J55	3,597'	Surface
Production	5-1/2"	17#	N80 & J55	9,250'	5,600'

Renfs	Top Perf	Bottom Perf	Status	SPE at	Holes
Bough C	8,833'	8,838'	Producing	2	10
Bough C	8,851'	8,857'	Producing	2	12
Bough D	8,898'	<u>8,9</u> 05'	Plugged	2	14

OIH	Size	Location
Cement Retainer	5-1/2"	8,888'

### GL: 4,200' KB: 18' KB Height: 4,216'

### **Procedure**

Hold Tailgate Safety meeting prior to beginning work each morning and as required for specific operations.

- 1. Prep location. Check anchors and clean area for workover.
- 2. Rack and tally work string consisting of 8,888' of 2-7/8, 6.5#, J-55 tubing.
- 3. MIRU workover rig. ND WH. NU and test BOP.
- 4. RU wireline unit. RIH w/ bit and scraper to 8,888'. POH.
- 5. RIH w/ CBP and set @ +/- 7,000' and test casing to 3,500# for 15 minutes to test casing integrity.
- PU bit and work string and TIH to DO CBP @ +/- 7,000 and clean out to PBTD @ 8,888'. Circulate hole clean. TOH.
- Install Frac Frac Valve and lubricator. MU 4" HSC Perforating Guns loaded 2 spf w/ 120 degree phasing (23 g minimum charges) and RIH. Correlate to the attached log dated.10/01/1996 and perforate the Bough B as follows:

Formation		SPE -	Total Shots
Bough B	8,801' - 8,804'	2 spf	8
Bough B	8,779' - 8,782'	2 spf	8
Total	25	能加加的	16

POOH w/ tubing and perforating guns and verify all shots fired. RDMO Wireline.

- RD Lubricator. RU Treating Company and pump a total of 4,000 gallons of 15% NEFE acid dropping 57 perf balls throughout the job. Flush acid to bottom perf w/ 2% KCL. SI and wait 1 hour. See attached acid procedure.
- 9. RIH w/ bit and scraper to PBTD @ 8,888' to clear perfs.
- 10. RU frac service and frac Bough B perfs 8,779' 8,804' (16 holes). Frac per attached procedure. (5-1/2" 17# J55 & N80 Internal Yield = 5,320 psi) Record ISIP-5-10-15 min pressures. RDMO frac equipment.
- 11. PU bit and work string and TIH to clean out to PBTD @ 8,888'. Circulate hole clean. TOH.
- 12. Swab well to determine productivity.
- 13. TIH with production tubing and SN. Set seat nipple at 8,864' (below perfs).
- 14. ND BOP. NU WH. TIH with pump and rods. Fill tubing and space out pump accordingly. Verify pump action. Place well on test.
- 15. RDMO workover rig. Clean location.

# <u>Contacts</u>

Production Foreman Steve Serna Office: 575-391-1462 Cell: 575-390-9053 Asset Manager Kim Henderson Office: 405-935-8583 Cell: 405-312-1840