9000 B	UNITED STATES EPARTMENT OF THE INTI UREAU OF LAND MANAGEN NOTICES AND REPORTS is form for proposals to dri II. Use form 3160-3 (APD) form	VILDIVI	LLS enter an roposals.		OMB N			
	PLICATE - Other instruction				7. If Unit or CA/Agre	eement, Name and/or N		
1 Type of Well ☑ Oil Well ☐ Gas Well ☐ Ot 2. Name of Operator CHESAPEAKE OPERATING,	Contact: LIN	DA GOOD ik com			8. Well Name and No EDITH FEDERA 9. API Well No 30-025-28856			
3a Address P.O. BOX 18496 OKLAHOMA CITY, OK 7315	4-0496	. Phone No. n: 405-935	(include area code 5-4275	*)	10. Field and Pool, or Exploratory			
4 Location of Well (Footage, Sec., 7 Sec 25 T18S R33E SESW 66	1	Un;		NOTICE PE	11. County or Parish, LEA COUNTY,	NM /		
TYPE OF SUBMISSION	TO THE			F ACTION	roki, ok otne	N DATA		
Subsequent Report Subsequent Report Final Abandonment Notice	which will be performed or provide the soperations. If the operation results pandonment Notices shall be filed on nal inspection.) uests permission to recomple ure: BTD: 10,490' Current PBTD: ks or float, flow back tank(s), & tubing. Lay down all but thods & couplings.	New Plug Plug Plug ails, includin subsurface lo Bond No. on an amultiple ally after all resette this well: 10,530' and toilet, e rods nec	completion seessary for Delaces	Production Reclamat Recompletion Water Di g date of any produced and true vert Required subsoling reclamation, are Formation	posed work and appropriate the sequent reports shall be we interval, a Form 314 have been completed. Details of all perticular and the sequent reports shall be we interval, a Form 314 have been completed. Details of the sequence of the	nent markers and zones e filed within 20 days 60-4 shall be filed once and the operator has		
14 I hereby certify that the foregoing is	true and correct. Electronic Submission #7486	5 verified t	ov the BLM Well	Information S		#**		
Name (Printed/Typed) LINDA GO			NG, INC., sent to the Hobbs Title SR REGULATORY COMPLIANCE SPEC					
Signature (Electronic S	ubmission)	1	Date 09/28/20	009				
	THIS SPACE FOR F	EDERAL	OR STATE (OFFICE USE	.			
Approved By						roposed Plugs, Pro erfs and Reoposed		
Conditions of approval, if any, are attached certify that the applicant holds legal or equ which would entitle the applicant to conduction	ect lease	Office	V	_ /	JW ENGINEER 2 3 2000			

Additional data for EC transaction #74865 that would not fit on the form

32. Additional remarks, continued

and proposed squeeze holes.

7. Bond Long well from CIBP to TOC or 500' into intermediate casing whichever is higher.

Pressure test casing to 1,000 psi.

- RU bailer & dump-bail a minimum of 35' CLASS 'H' cement on top of CIBP. (2 runs).
- 10. RU pack-off. RIH w/casing gun & perforate squeeze holes from 6,150' to 6,152' w/4 holes total phased 90 degrees.

11. Establish circulation thru squeeze holes & production x intermediate casing annulus. Circulate clean.

- WL set Retainer @ 6,150'. Stand-down wireline.
 MU stinger & tubing & hydrotest in hole to 4,500 psi.
 Circulate hole clean. Sting into retainer & re-establish circulation.
 RU cementers and squeeze manifold. Block squeeze Delaware formation. Sting out. Circulate hole clean w/20 KCL RD Cementers. hole clean w/2% KCI. RD Cementers. 16. POOH w/stinger & WOC

- 17. RUN CBL
- 18. Perf 2nd Delaware from 5,674' to 5,724' (50') w/2 spf @ 60 or 120 degree phase. RD WL.

19. MU packer & SN & TIH. Set packer @ +5,550'.

- Swab test perfs.
- MIRU acid trucks to acidize well w/+2500 gallons of 7.5% HCL NeFe Acid and + 125 ball sealers. Design to follow.

- 22. Šwab test well.23. Release packer & run through perfs.
- No Bope & NU frac valve or frac well utilizing tree saver thru Bop's. Design to follow.
 ND Bope & NU frac valve or frac well utilizing tree saver thru Bop's. Design to follow.
 Flow back well to tank. NU Bope, if necessary.
 MU notch collar, SN & tubing and TIH to swab test well.

- 27. MIO notch collar, SN & tubing and TIH to swap test well.
 28. POOH w/tubing. clean out adequate rat-hole if necessary.
 29. Run pumping tubing assembly (MA, perf sub, SN, 12 jts, 30K set TAC & tubing) and lay down any unnecessary tubing in order to land perf sub + 125' below perfs.
 30. ND BOP. Set TAC. NU wellhead.
 31. Swab well before running pump.
 32. MU 2.5" x 1.50" x ?' RHAC pump on 1.5" KBars, 3/4" & 7/8" Class D rods. Design to follow.
 Space out to leave 4-6' of polish rod available for subsequent rod tag.

Space out to leave 4-6' of polish rod available for subsequent rod tag.

33. Load & test tubing w/2% KCl water or clean produced Delaware water.

34. Place well on production.

35. RMDO service unit.

ATTACHMENTS: Current & Proposed Wellbore Diagrams & Procedure. (Proposed Procedure shows the Casing, Formation Tops, Existing Perfs, Proposed Plugs, Proposed Sqz Perfs and Proposed Production Perfs)

(CHK PN 890759)

CURRENT WELLBORE SCHEMATIC


WELL: EDITH FEDERAL 1
FIELD: E K Bone Spring

COUNTY/STATE: LEA/ NEW MEXICO

LOCATION: 2,310.0 FWL & 660.0 FSL OF THE SVY, SEC 25, A-

ELEVATION: 3,864.00 GR 3,876.00 RKB

PN: 890759 Chesapeake API: 3002528856 SPUD DATE: 8/29/1984 RIG RELEASE: 9/28/1984 FIRST SALES:



Proposal for Workover



EDITH FEDERAL 1

Field: County: E K Bone Spring LEA


State: Location: **NEW MEXICO**

SEC 25, 18S-33E, 660 FSL & 2310 FWL

Elevation: GL 3,864.00 **KB** Height: 12.00

KB 3,876.00

Spud Date: 8/29/1984 Initial Compl. Date: API #: 3002528856 CHK Propterty #: 890759 1st Prod Date: 10/31/1984 PBTD: Original Hole - 10450.0 TD: 10,530.0



Diet	ric	f T

1625 N. French Dr., Hobbs, NM 88240

State of New Mexico

Form C-102

District II

1301 W. Grand Avenue, Artesia, NM 88210

DIL CONSERVATION DIVISION

Revised October 12, 2005 Submit to Appropriate District Office

District III

OCT 2.2 2009

1220 South St. Francis Dr.

State Lease - 4 Copies Fee Lease - 3 Copies

1000 Rio Brazos Rd., Aztec, NM 87410

1000 Rio Brazos Ro	d., Aztec, NI		1 1 1 1 1 1))a • 🖍			Santa Fe N	JM 87505			ree	Lease -	3 Copies
District IV 1220 S. St. Francis	Dr., Santa I	HOBBSOCD Santa Fe, NM 87505						[☐ AMENDED REPORT				
WELL LOCATION AND ACREAGE DEDICATION PLAT													
¹ API Numbery ¹ P				Code			' Pool Na	me					
30-025-2885	56 /	,	ļ	216	555		,]	E-K; Delaware					
Property C	Property Code Property Name								'Well Number				
		Edith Federal /							1				
'OGRID'	No.	/ Operator Name							'Elevation				
147179		Chesapeake Operating, Inc.						3864' GR					
¹⁰ Surface Location													
UL or lot no.	Section	Township	,	Range	Lot	t Idn	Feet from th	e North/South line	Feet from the	East/West line			County
N	25	18S	33	3E			660'	South	2310'	West		Lea	
11 Bottom Hole Location If Different From Surface													
UL or lot no.	Section	Township	,	Range	Lot	t Idn	Feet from th	e North/South line	Feet from the	East	/West line		County
			Ì										
" Dedicated Acres	" Joint or	r Infill	" Consoli	idation (Code	" Orde	er No.						
40													

No allowable will be assigned to this completion until all interests have been consolidated or a non-standard unit has been approved by the division.

			Bryan Arrant Printed Name 18 SURVEYOR CERTIFICATION I hereby certify that the well location shown on this plat
			was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief Date of Survey Signature and Seal of Professional Surveyor.
2310' FWL -	660' FSL		Please refer to original plat Certificate Number

Chesapeake Operating, Inc. Edith Federal # 1 SESW Sec. 25, T18S-R33E Lea-County, New Mexico API # 30-025-28856

Bone Spring P&A and Delaware Re-Completion Procedure August 11, 2009

Drill TD: 10,566'

Original PBTD: 10,490'

Current PBTD: ?

KB 12'

CASING:

13-3/8", 54.5# @ 362' KB in 17.5" hole.

Cemented w/400 sacks type 'C' to surface.

8.625", 32# @ 3,665' in 12.25" hole.

Cmt w/1,600 sacks 'H' Lite and 200 sacks neat to surface.

5.5", 17, 20 & 23#, N80 @ 10,566' in 7.875" hole.

650 sacks 50:50 type 'H'. Calculated fill of 3,400' assuming 30% excess. Estimated TOC @ 7,166'.

FORMATION TOPS: (GL Elevation = 3,864', KB Elevation = 3,876')

Rustler Base of Salt ? Queen 4,361' Penrose 4,631' Delaware 5,352' 1st Delaware Sand 5.390' 2nd Delaware Sand 5,648' Bone Spring 7,536 2nd Bone Spring Sand 9,422' Wolfcamp 10,477

EXISTING PERFORATIONS:

9,428 - 9,4849,726 - 9,802(76'? perfs,? holes)

(23' net perfs, 46 holes)

2ND Bone Spring Sand - Oct. 1984 Lower Bone Spring Sand - May 1991

PROPOSED PLUG(s): (Permanently Abandon all Bone Spring Perfs & Depths Below)

9,400'

CIBP Depth + 35' Cmt Cap to P&A. TOC $@\pm 9,415$ '

6,100

Cement Retainer Utilized for Squeeze TOC @ 3,100'

PROPOSED SQUEEZE PERFORATIONS: (To Block Squeeze Delaware Sand)

6,150' - 6,152'

(2', 4 holes @ 90% phasing)

PROPOSED PRODUCTION PERFORATIONS: (2ND Delaware Sand)

5,674' - 5,724'

(50' perfs)

2 spf, 60 - 120 degree phased

PROPOSED PROCEDURE:

- 1. MIRU Service rig, pipe racks or float, flow back tank(s), and toilet.
- 2. Unseat pump. Hot-oil rods & tubing. Lay down all but the rods necessary for Delaware production. Visually inspect rods & couplings.
- 3. ND wellhead. NU BOPE.
- 4. Release TAC. POOH. Lay down all but $\pm 6{,}100$ ' of tubing. (See #6 below).
- 5. MIRU wire line unit. Make gauge ring run. WL set CIBP @ 9,400' ± (w/in 50' of top perf).
- 6. Load hole w/clean 2% KCL. Note: Check w/BLM on Plug Mud requirements for cavity between CIBP and proposed squeeze holes.
- 7. Bond Long well from CIBP to TOC or 500' into intermediate casing whichever is higher.
- 8. Pressure test casing to 1,000 psi.
- 9. RU bailer & dump-bail a minimum of 35' CLASS 'H' cement on top of CIBP. (2 runs).
- 10. RU pack-off. RIH w/casing gun & perforate squeeze holes from 6,150 to 6,152 w/4 holes total phased 90 degrees.
- 11. Establish circulation thru squeeze holes & production x intermediate casing annulus. Circulate clean.
- 12. WL set Retainer @ 6,150'. Stand-down wireline.
- 13. MU stinger & tubing & hydrotest in hole to 4,500 psi.
- 14. Circulate hole clean. Sting into retainer & re-establish circulation.
- 15. RU cementers and squeeze manifold. Block squeeze Delaware formation. Sting out. Circulate hole clean w/2% KCl. RD Cementers.
- 16. POOH w/stinger & WOC
- 17. Run CBL.
- 18. Perf. 2nd Delaware from 5,674 to 5,724' (50') w/2 spf @ 60 or 120 degree phase. RD WL.
- 19. MU packer & SN & TIH. Set packer @ ± 5,550°.
- 20. Swab test perfs.
- 21. MIRU acid trucks to acidize well w/ \pm 2,500 gallons of 7.5% HCL NeFe Acid and \pm 125 ball sealers. Design to follow.
- 22. Swab test well.
- 23. Release packer & run through perfs.
- 24. Swab csg & tbg from rathole to remove acid & swab well down. POOH w/pkr & tubing.
- 25. ND BOPE & NU frac valve or frac well utilizing tree saver thru BOPs. Design to follow.
- 26. Flow back well to tank. NU BOPE, if necessary.
- 27. MU notch collar, SN & tubing and TIH to swab test well.
- 28. POOH w/tubing. Clean out adequate rat-hole if necessary.
- 29. Run pumping tubing assembly (MA, perf sub, SN, 12 jts, 30K set TAC & tubing) and lay down any unnecessary tubing in order to land perf sub ± 125' below perfs.
- 30. ND BOP. Set TAC. NU wellhead.
- 31. Swab well before running pump.
- 32. MU 2.5" x 1.50"x? RHAC pump on 1.5" KBars, 3/4" & 7/8" Class D rods. Design to follow. Space out to leave 4 6' of polish rod available for subsequent rod tag.
- 33. Load & test tubing w/2 % KCl water or clean produced Delaware water.
- 34. Place well on production.
- 35. RDMO service unit.

REMARKS:

- Shoot fluid level to determine BHP of Bone Spring perfs prior to starting work.
- Provide at least 48 hours notice before abandonment of Bone Spring perfs to BLM's Wesley Ingram at (575) 234-5982 and to the New Mexico Oil Conservation Commission (575) 393-6161. Note contact information on reports.
- Note the transfer of any tubing, rods, or other equipment from location on morning report.

CURRENT WELLBORE SCHEMATIC


WELL: EDITH FEDERAL 1
FIELD: E K Bone Spring

COUNTY / STATE: LEA / NEW MEXICO

LOCATION: 2,310.0 FWL & 660.0 FSL OF THE SVY, SEC 25, A-

ELEVATION: 3,864.00 GR 3,876.00 RKB

PN: 890759 Chesapeake API: 3002528856 SPUD DATE: 8/29/1984 RIG RELEASE: 9/28/1984 FIRST SALES:



Edith Federal 1 30-025-28856 Chesapeake Operating, INC October 6, 2009 Conditions of Approval

- 1. Surface disturbance beyond the existing pad must have prior approval.
- 2. Closed loop system required.
- 3. 3M BOP is required and must be tested prior to setting CIBP over Bone Spring perforations.
- 4. Contact BLM 575-361-2822 a minimum of 24 hours prior to setting CIBP above Bone Spring.
- 5. Subsequent sundry and completion report required.
- 6. Must submit a copy of the CBL to the BLM.

MAK 100609