Submit 3 Copies To Appropriate District State of New Mexico Office Discourse Minorella and Natural Resources	Form C-103 June 19, 2008
District I District I District II District III District II District II District II Distri	WELL API NO. 30-025-00528
District III District II District III District III District III District III District III Dis	5. Indicate Type of Lease STATE FEE
1000 RIO Brazos Rd, Aztec, NMON10 6 2009 District IV 1220 S St Francis Dr, Santa POBBSOCD 7505	6. State Oil & Gas Lease No.
87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Caprock Maljamar Unit 8. Well Number 13
1. Type of Well: Oil Well Gas Well Other Injection 2. Name of Operator /	9. OGRID Number 8041
Forest Oil Corporation 3. Address of Operator	10. Pool name or Wildcat
707 17 th Street Suite 3600 Denver Colorado 80202	Maljamar (Grayburg San Andres)
4. Well Location Unit Letter J : 1980 feet from the South line and 1980	feet from the East line
Section 13 Township T17S Range 32E NMPM County Lea V	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4110' GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI	K ALTERING CASING ALTERING OPNS P AND A
PULL OR ALTER CASING - MULTIPLE COMPL CASING/CEMEN	ГЈОВ
OTHER: <u>Intert TH</u> OTHER: <u>Intert TH</u> 13. Describe proposed or completed operations.' (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
 Forest Oil Corporation respectfully requests the following for the CMU #13 well. 1. MIRUPU. Install BOP's as required. 2. POOH w/ tubing and packer. Visually inspect tubing, replace as necessary. 3. RIH w/ RBP, packer, and workstring. Set packer and RBP at various depths to determine if casing leaks exist. 4. Depending of results of Step 4, proceed as directed to next Step(s) 6, or 8. 5. Clean out well to PBTD as necessary. Run injection tubing and packer. 6. Acidize perfs (4,029' - 4,362') w/4,800 gal 15% HCl in two stages, separating stages w/ rock salt. 7. Obtain witnessed MIT, return well to active injection. Send MIT pressure charts to Denver office for submittal to State and Federal regulatory agencies. 8. Set CIBP 50' above top perf, rig down, and await approved F&A operations. 	
	Approval : Notify OCD Hobbs ours prior to running MIT Test & Chart
	and the second sec
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE THERE THERE TITLE POPULATONY IE	estoil.com
Type or print name <u>KON HAVVIS</u> E-mail address:	PHONE: 3038121676
For State Use Only APPROVED BY: Conditions of Approval (if any):	
\mathcal{V}	

/