Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources	June 19, 2008 WELL API NO. 7
District II 1301 W Grand Ave. Artesia NM 8504	EMEONSERVATION DIVISION 1220 South St. Francis Dr.	30-025-35975
District III	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE X
District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV	07 ^{γ(γ) Δ} Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	RPOCD	
SUNDRY NOTICES	S AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		Royal Stimulator
1. Type of Well: Oil Well Gas	s Well 🗓 Other	8. Well Number 2
2. Name of Operator DAVID H. ARR		9. OGRID Number 5898
3. Address of Operator PO BOX 2071 MIDLAND, T	X 79702	10. Pool name or Wildcat Wildcat ; Miss
4. Well Location		W. Macat. 7 17 1(85
Unit Letter E: 2235 feet from the North line and 330 feet from the West line		
Section 31	Township 15S Range 36E	NMPM County Lea
	1. Elevation (Show whether DR, RKB, RT, GR, etc. 3927' GL	
		Taxon in the selection of the selection
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTE	NTION TO: SUB	SEQUENT REPORT OF:
	LUG AND ABANDON REMEDIAL WOR	
	HANGE PLANS	
DOWNHOLE COMMINGLE	OASING/CEMEN	1. 100 Brown 100 Control of the Cont
	l	
OTHER:	OTHER: Tempora	arily Abandon X
: 13: Describe proposed or completed	OTHER: Temporal operations. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
13: Describe proposed or completed of starting any proposed work).	OTHER: Temporal operations. (Clearly state all pertinent details, an SEE RULE 1103. For Multiple Completions: At	d give pertinent dates, including estimated date
of starting any proposed work). or recompletion.	d operations. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date
of starting any proposed work). or recompletion. 11/30/2009 - Notify OCD Hobbs RU unit	d operations. (Clearly state all pertinent details, an SEE RULE 1103. For Multiple Completions: Ai	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
of starting any proposed work). or recompletion. 11/30/2009 - Notify OCD Hobbs RU unit Load hole & insure well is dead.	d operations. (Clearly state all pertinent details, an SEE RULE 1103. For Multiple Completions: At This Approval of T	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion emporary 7.7.2014
of starting any proposed work). or recompletion. 11/30/2009 - Notify OCD Hobbs RU unit	d operations. (Clearly state all pertinent details, an SEE RULE 1103. For Multiple Completions: Ai	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion emporary 7.7.2014
of starting any proposed work). or recompletion. 11/30/2009 - Notify OCD Hobbs RU unit Load hole & insure well is dead. RU BOP Release pkr & POOH w/ tbg & pkr RIH w/ gauge ring & junk basket to	d operations. (Clearly state all pertinent details, an SEE RULE 1103. For Multiple Completions: At This Approval of Abandonment Exp. 12,050' -	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion emporary 7.7.2014
of starting any proposed work). or recompletion. 11/30/2009 - Notify OCD Hobbs RU unit Load hole & insure well is dead. RU BOP Release pkr & POOH w/ tbg & pkr RIH w/ gauge ring & junk basket to 1 RIH w/ CIBP and set @ 12,100' & ca	d operations. (Clearly state all pertinent details, an SEE RULE 1103. For Multiple Completions: An This Approval of Abandonment Expands and Mandonment Expands a	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion emporary 7.7.2014
of starting any proposed work). or recompletion. 11/30/2009 - Notify OCD Hobbs RU unit Load hole & insure well is dead. RU BOP Release pkr & POOH w/ tbg & pkr RIH w/ gauge ring & junk basket to 1 RIH w/ CIBP and set @ 12,100' & ca RIH w/ CIBP and set @ 11,960' & ca Prs test csg to 500 psi	d operations. (Clearly state all pertinent details, an SEE RULE 1103. For Multiple Completions: At This Approval of Abandonment Expands ap w/ 35' cmt ap w/ 35' cmt	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion emporary 7.7.2014
of starting any proposed work). or recompletion. 11/30/2009 - Notify OCD Hobbs RU unit Load hole & insure well is dead. RU BOP Release pkr & POOH w/ tbg & pkr RIH w/ gauge ring & junk basket to 1 RIH w/ CIBP and set @ 12,100' & ca RIH w/ CIBP and set @ 11,960' & ca Prs test csg to 500 psi POOH w/ tbg - RDMO PU	d operations. (Clearly state all pertinent details, an SEE RULE 1103. For Multiple Completions: An This Approval of Abandonment Expands and Mandonment Expands a	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion emporary 7.7.2014
of starting any proposed work). or recompletion. 11/30/2009 - Notify OCD Hobbs RU unit Load hole & insure well is dead. RU BOP Release pkr & POOH w/ tbg & pkr RIH w/ gauge ring & junk basket to l RIH w/ CIBP and set @ 12,100' & ca RIH w/ CIBP and set @ 11,960' & ca Prs test csg to 500 psi POOH w/ tbg - RDMO PU Shut well in and police location	d operations. (Clearly state all pertinent details, an SEE RULE 1103. For Multiple Completions: At This Approval of Abandonment Expands ap w/ 35' cmt ap w/ 35' cmt	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion emporary 7.7.2014
of starting any proposed work). or recompletion. 11/30/2009 - Notify OCD Hobbs RU unit Load hole & insure well is dead. RU BOP Release pkr & POOH w/ tbg & pkr RIH w/ gauge ring & junk basket to 1 RIH w/ CIBP and set @ 12,100' & ca RIH w/ CIBP and set @ 11,960' & ca Prs test csg to 500 psi POOH w/ tbg - RDMO PU	d operations. (Clearly state all pertinent details, an SEE RULE 1103. For Multiple Completions: At This Approval of Abandonment Expands ap w/ 35' cmt ap w/ 35' cmt	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion emporary 7.7.2014
of starting any proposed work). or recompletion. 11/30/2009 - Notify OCD Hobbs RU unit Load hole & insure well is dead. RU BOP Release pkr & POOH w/ tbg & pkr RIH w/ gauge ring & junk basket to l RIH w/ CIBP and set @ 12,100' & ca RIH w/ CIBP and set @ 11,960' & ca Prs test csg to 500 psi POOH w/ tbg - RDMO PU Shut well in and police location	d operations. (Clearly state all pertinent details, an SEE RULE 1103. For Multiple Completions: At This Approval of Abandonment Expands ap w/ 35' cmt ap w/ 35' cmt	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion emporary 7.7.2014
of starting any proposed or completed of starting any proposed work). or recompletion. 11/30/2009 - Notify OCD Hobbs RU unit Load hole & insure well is dead. RU BOP Release pkr & POOH w/ tbg & pkr RIH w/ gauge ring & junk basket to 1 RIH w/ CIBP and set @ 12,100' & ca RIH w/ CIBP and set @ 11,960' & ca Prs test csg to 500 psi POOH w/ tbg - RDMO PU Shut well in and police location	This Approval of T Abandonment Exp 12,050' - ap w/ 35' cmt ap w/ 35' cmt Rig Release Date:	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion emporary 7.7.2014
of starting any proposed work). or recompletion. 11/30/2009 - Notify OCD Hobbs RU unit Load hole & insure well is dead. RU BOP Release pkr & POOH w/ tbg & pkr RIH w/ gauge ring & junk basket to 1 RIH w/ CIBP and set @ 12,100' & ca RIH w/ CIBP and set @ 11,960' & ca Prs test csg to 500 psi POOH w/ tbg - RDMO PU Shut well in and police location	This Approval of Abandonment Expany w/ 35' cmt Rig Release Date:	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion emporary 2-7-20/4 prices
of starting any proposed work). or recompletion. 11/30/2009 - Notify OCD Hobbs RU unit Load hole & insure well is dead. RU BOP Release pkr & POOH w/ tbg & pkr RIH w/ gauge ring & junk basket to 1 RIH w/ CIBP and set @ 12,100' & ca RIH w/ CIBP and set @ 11,960' & ca Prs test csg to 500 psi POOH w/ tbg - RDMO PU Shut well in and police location	This Approval of Abandonment Expany w/ 35' cmt Rig Release Date:	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion emporary 2-7-2014 prices
of starting any proposed or completed of starting any proposed work). or recompletion. 11/30/2009 - Notify OCD Hobbs RU unit Load hole & insure well is dead. RU BOP Release pkr & POOH w/ tbg & pkr RIH w/ gauge ring & junk basket to 1 RIH w/ CIBP and set @ 12,100' & ca RIH w/ CIBP and set @ 11,960' & ca Prs test csg to 500 psi POOH w/ tbg - RDMO PU Shut well in and police location Spud Date:	This Approval of Abandonment Expansion of Aban	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion emporary 2-7-2014 pires
of starting any proposed work). or recompletion. 11/30/2009 - Notify OCD Hobbs RU unit Load hole & insure well is dead. RU BOP Release pkr & POOH w/ tbg & pkr RIH w/ gauge ring & junk basket to l RIH w/ CIBP and set @ 12,100' & ca RIH w/ CIBP and set @ 11,960' & ca Prs test csg to 500 psi POOH w/ tbg - RDMO PU Shut well in and police location Spud Date:	This Approval of Abandonment Expansion of Aban	e and belief. DATE 12/02/2009
of starting any proposed work). or recompletion. 11/30/2009 - Notify OCD Hobbs RU unit Load hole & insure well is dead. RU BOP Release pkr & POOH w/ tbg & pkr RIH w/ gauge ring & junk basket to 1 RIH w/ CIBP and set @ 12,100' & ca RIH w/ CIBP and set @ 11,960' & ca Prs test csg to 500 psi POOH w/ tbg - RDMO PU Shut well in and police location Spud Date: I hereby certify that the information above SIGNATURE SIGNATURE Type or print name DEBBIE FREEMA	Title Engineer tech	e and belief. DATE 12/02/2009
of starting any proposed work). or recompletion. 11/30/2009 - Notify OCD Hobbs RU unit Load hole & insure well is dead. RU BOP Release pkr & POOH w/ tbg & pkr RIH w/ gauge ring & junk basket to l RIH w/ CIBP and set @ 12,100' & ca RIH w/ CIBP and set @ 11,960' & ca Prs test csg to 500 psi POOH w/ tbg - RDMO PU Shut well in and police location Spud Date:	This Approval of Abandonment Expands we is true and complete to the best of my knowledge TITLE ENGINEER TECH E-mail address: DEBBIE@ARR	e and belief. DATE 12/02/2009 NGTONOIL.COMONE: (432)682-6685
of starting any proposed work). or recompletion. 11/30/2009 - Notify OCD Hobbs RU unit Load hole & insure well is dead. RU BOP Release pkr & POOH w/ tbg & pkr RIH w/ gauge ring & junk basket to 1 RIH w/ CIBP and set @ 12,100' & ca RIH w/ CIBP and set @ 11,960' & ca Prs test csg to 500 psi POOH w/ tbg - RDMO PU Shut well in and police location Spud Date: I hereby certify that the information above SIGNATURE SIGNATURE Type or print name DEBBIE FREEMA	This Approval of Abandonment Expansion of Aban	e and belief. DATE 12/02/2009 NGTONOIL.COMONE: (432)682-6685

