•	PIA'L. OK TO RELEAST. exico PIA'L. OK TO RELEAST. Form C-103 May 27 2004
· •	THOUSE 12/10/2009
Submit 3 Copies To Appropriate District Office State of New Me	exico Form C-103 may 27, 2004
Office District 1 1625 N. French Dr., Hobbs, N. 1992	WELL API NO.
1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV OIL CONSERVATION 1220 South St. Fra Santa Fe, NM 8	nncis Dr. STATE FEE 🔯
District IV 1220 S. St. Francis Dr., Sand Fe, 19191 6	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WEL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OF DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-10 PROPOSALS.)	OR PLUG BACK TO A G T HANNERS //
1. Type of Well: Oil Well X Gas Well Other	8. Well Number #1
2. Name of Operator	9. OGRID Number
SABER RESOURCES LLC /	236378
3. Address of Operator	10. Pool name or Wildcat Gladidla;
400 W ILLINOIS SUITE 950 MIDLAND TX 79701 4. Well Location	- DENTAN DEVONIAN
	THE P. I. 1000 C.A.C. Alex FACT line
Unit Letter 0 50 : 660 feet from the SO	JTH line and 1980 feet from the EAST line
Section 18 Township 128	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
Pit or Below-grade Tank Application or Closure	
Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness: mil Below-Grade Tank: Volume	bbls; Construction Material
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB
OTHER:	OTHER:
13. Describe proposed or completed operations. (Clearly state all pe	ertinent details, and give pertinent dates, including estimated date
C. A. Communication of the Communication of the Market of the Communication of the Communicat	
or recompletion.	e Completions: Attach wellbore diagram of proposed completion
or recompletion. 4-14-08 M.I.R.U. BASIC ENERGY SERVICES PSA RIG 1273	e Completions: Attach wellbore diagram of proposed completion 3 4-14-08 SPOT 25 SX PLUG @ 6040' O.K. BY N.M.O.D.C.O.
or recompletion. 4-14-08 M.I.R.U. BASIC ENERGY SERVICES PSA RIG 1273 MAXIE BROWN @ 1:20 CDT WOC & TAG @ 5777. CIRCULATE	e Completions: Attach wellbore diagram of proposed completion 3 4-14-08 SPOT 25 SX PLUG @ 6040' O.K. BY N.M.O.D.C.O. HOLE W/ 10# MLF PULL TBG TO 5011' SPOT 135 SXS CMT
or recompletion. 4-14-08 M.I.R.U. BASIC ENERGY SERVICES P&A RIG 1273 MAXIE BROWN @ 1:20 CDT WOC & TAG @ 5777. CIRCULATE W.O.C. 4-15-08 TAG TOC @ 4624 . SPOT 30 SXS CMT WOC	e Completions: Attach wellbore diagram of proposed completion 8 4-14-08 SPOT 25 SX PLUG @ 6040' O.K. BY N.M.O.D.C.O. HOLE W/ 10# MLF PULL TBG TO 5011' SPOT 135 SXS CMT C & TAG 4543' PULL TGB TO 1599' SPLT 40 SXS CMT
or recompletion. 4-14-08 M.I.R.U. BASIC ENERGY SERVICES P&A RIG 1273 MAXIE BROWN @ 1:20 CDT WOC & TAG @ 5777. CIRCULATE W.O.C. 4-15-08 TAG TOC @ 4624 . SPOT 30 SXS CMT WOC	e Completions: Attach wellbore diagram of proposed completion 3 4-14-08 SPOT 25 SX PLUG @ 6040' O.K. BY N.M.O.D.C.O. HOLE W/ 10# MLF PULL TBG TO 5011' SPOT 135 SXS CMT C & TAG 4543' PULL TCB TO 1599' SPLT 40 SXS CMT S CMT . POOH W/ TBG WCC 4-17 TAG TCC @ 276' PULL CUT OF Approved for plugging of well bore only.
or recompletion. 4-14-08 M.I.R.U. BASIC ENERGY SERVICES PSA RIG 1273 MAXIE BROWN @ 1:20 CDT WOC & TAG @ 5777. CIRCULATE W.O.C. 4-15-08 TAG TOC @ 4624 . SPOT 30 SXS CMT WOC CIRCULATED TOC @ 1450' PULL TBG TO 396' SPOT 40 SXS	e Completions: Attach wellbore diagram of proposed completion 3 4-14-08 SPOT 25 SX PLUG @ 6040' O.K. BY N.M.O.D.C.O. HOLE W/ 10# MLF PULL TBG TO 5011' SPOT 135 SXS CMT C & TAG 4543' PULL TGB TO 1599' SPLT 40 SXS CMT S CMT .POOH W/ TBG WCC 4-17 TAG TOC @ 276' PULL OUT OF
or recompletion. 4-14-08 M.I.R.U. BASIC ENERGY SERVICES PSA RIG 1273 MAXIE BROWN @ 1:20 CDT WOC & TAG @ 5777. CIRCULATE W.O.C. 4-15-08 TAG TOC @ 4624 . SPOT 30 SXS CMT WOC CIRCULATED TOC @ 1450' PULL TBG TO 396' SPOT 40 SXS	e Completions: Attach wellbore diagram of proposed completion 3 4-14-08 SPOT 25 SX PLUG @ 6040' O.K. BY N.M.O.D.C.O. HOLE W/ 10# MLF PULL TBG TO 5011' SPOT 135 SXS CMT C & TAG 4543' PULL TCB TO 1599' SPLT 40 SXS CMT S CMT . POOH W/ TBG WCC 4-17 TAG TCC @ 276' PULL CUT OF Approved for plusging of well hore only. Liability under bond is retained pending receipt of C.103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under
or recompletion. 4-14-08 M.I.R.U. BASIC ENERGY SERVICES PSA RIG 1273 MAXIE BROWN @ 1:20 CDT WOC & TAG @ 5777. CIRCULATE W.O.C. 4-15-08 TAG TOC @ 4624 . SPOT 30 SXS CMT WOC CIRCULATED TOC @ 1450' PULL TBG TO 396' SPOT 40 SXS HOLE TO 30' SPOT 10 SXS SURFACE PLUG 30' TO 3 RDMO.	e Completions: Attach wellbore diagram of proposed completion 8 4-14-08 SPOT 25 SX PLUG @ 6040' O.K. BY N.M.O.D.C.O. HOLE W/ 10# MLF PULL TBG TO 5011' SPOT 135 SXS CMT C & TAG 4543' PULL TCB TO 1599' SPLT 40 SXS CMT S CMT . POOH W/ TBG WCC 4-17 TAG TCC @ 276' PULL CUT OF Approved for plugging of well here only. Liability under bond is retained pending receipt of C.103 (Subsequent Report of Well Plugging) which may be found at OC1 Web Page under Forms, www.cmnrd.state.nm.us/ocd.
or recompletion. 4-14-08 M.I.R.U. BASIC ENERGY SERVICES PSA RIG 1273 MAXIE BROWN @ 1:20 CDT WOC & TAG @ 5777. CIRCULATE W.O.C. 4-15-08 TAG TOC @ 4624 . SPOT 30 SXS CMT WOC CIRCULATED TOC @ 1450' PULL TBG TO 396' SPOT 40 SXS HOLE TO 30' SPOT 10 SXS SURFACE PLUG 30' TO 3 RDMO.	B 4-14-08 SPOT 25 SX PLUG @ 6040' O.K. BY N.M.O.D.C.O. HOLE W/ 10# MLF PULL TBG TO 5011' SPOT 135 SXS CMT C & TAG 4543' PULL TCB TO 1599' SPLT 40 SXS CMT S CMT .POOH W/ TBG WCC 4-17 TAG TCC @ 276' PULL CUT OF Approved for plusging of well here only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd. best of my knowledge and belief. I further certify that any pit or belowes, a general permit or an (attached) alternative OCD-approved plan
or recompletion. 4-14-08 M.I.R.U. BASIC ENERGY SERVICES PSA RIG 1273 MAXIE BROWN @ 1:20 CDT WOC & TAG @ 5777. CIRCULATE W.O.C. 4-15-08 TAG TOC @ 4624 . SPOT 30 SXS CMT WOC CIRCULATED TOC @ 1450' PULL TBG TO 396' SPOT 40 SXS HOLE TO 30' SPOT 10 SXS SURFACE PLUG 30' TO 3 RDMO. I hereby certify that the information above is true and complete to the grade tank has been/will be constructed or closed according to MOCD guideline SIGNATURE	B 4-14-08 SPOT 25 SX PLUG @ 6040' O.K. BY N.M.O.D.C.O. HOLE W/ 10# MLF PULL TBG TO 5011' SPOT 135 SXS CMT C & TAG 4543' PULL TCB TO 1599' SPLT 40 SXS CMT S CMT .POOH W/ TBG WCC 4-17 TAG TCC @ 276' PULL CUT OF Approved for plugging of well hore only. Liability under bond is retained pending receipt of C.103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmrd.state.nm.us/ocd. best of my knowledge and belief. I further certify that any pit or belowes, a general permit or an (attached) alternative OCD-approved plan
or recompletion. 4-14-08 M.I.R.U. BASIC ENERGY SERVICES PSA RIG 1273 MAXIE BROWN @ 1:20 CDT WOC & TAG @ 5777. CIRCULATE W.O.C. 4-15-08 TAG TOC @ 4624 . SPOT 30 SXS CMT WOC CIRCULATED TOC @ 1450' PULL TBG TO 396' SPOT 40 SXS HOLE TO 30' SPOT 10 SXS SURFACE PLUG 30' TO 3 RDMO. I hereby certify that the information above is true and complete to the grade tank has been/will be constructed or closed according to MOCD guideline SIGNATURE	B 4-14-08 SPOT 25 SX PLUG @ 6040' O.K. BY N.M.O.D.C.O. HOLE W/ 10# MLF PULL TBG TO 5011' SPOT 135 SXS CMT C & TAG 4543' PULL TCB TO 1599' SPLT 40 SXS CMT S CMT .POOH W/ TBG WCC 4-17 TAG TCC @ 276' PULL CUT OF Approved for plusging of well here only. Liability under bond is retained pending receipt of C.103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmrd.state.nm.us/ocd. best of my knowledge and belief. I further certify that any pit or belowes, a general permit or an (attached) alternative OCD-approved plan
or recompletion. 4-14-08 M.I.R.U. BASIC ENERGY SERVICES PSA RIG 1273 MAXIE BROWN @ 1:20 CDT WOC & TAG @ 5777. CIRCULATE W.O.C. 4-15-08 TAG TOC @ 4624 . SPOT 30 SXS CMT WOC CIRCULATED TOC @ 1450' PULL TBG TO 396' SPOT 40 SXS HOLE TO 30' SPOT 10 SXS SURFACE PLUG 30' TO 3 RDMO. I hereby certify that the information above is true and complete to the grade tank has been/will be constructed or closed according to MOCD guideline SIGNATURE TITLE- E-1	B 4-14-08 SPOT 25 SX PLUG @ 6040' O.K. BY N.M.O.D.C.O. HOLE W/ 10# MLF PULL TBG TO 5011' SPOT 135 SXS CMT C & TAG 4543' PULL TCB TO 1599' SPLT 40 SXS CMT S CMT .POOH W/ TBG WCC 4-17 TAG TCC @ 276' PULL CUT OF Approved for plugging of well hore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmrd.state.nm.us/ocd. best of my knowledge and belief. I further certify that any pit or belowes, a general permit or an (attached) alternative OCD-approved plan TLE PSA SUPERVISOR DATE 4-22-08 mail address:

Conditions of Approval, if any: