P/A'd. OK	TO RELEASE.
Submit 1 Copy To Appropriate District State of New Mexico	B. 12/22/2009 Form U-103
Office Energy, Minerals and Natural Resourc	
1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Ave. Artesia NM 88240 OIL CONSERVATION DIVISION	N 30-025-01130 \(\sqrt{5} \) Indicate Type of Lease
District III	STATE X FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No. B -9560
87505 HOBES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	New Mexico BG State NCT-1
PROPOSALS.) 1. Type of Well: X Oil Well Gas Well Other	8. Well Number
2. Name of Operator	9. OGRID Number / 213190
CrownQuest Operating, LLC 3. Address of Operator	10. Pool name or Wildcat
303 Veterans Airpark Lane, STE 5100, PO Box 53310, Midland, TX 79710	Saunders Permo Upper Penn
4. Well Location Unit Letter M 660 feet from the South line and 660 feet from the west	line
Section 14 Township 14S Range 33E 11. Elevation (Show whether DR, RKB, RT, G	NMPM County Lea
11. Elevation (Snow whether DR, RRB, R1, 6	т, ес.)
12. Check Appropriate Box to Indicate Nature of No.	otice Penort or Other Data
** *	-
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL	-
	CE DRILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/C	EMENT JOB
DOWNHOLE COMMINGLE	
DOWNHOLE COMMINGLE	Location is ready for OCD inspection after P&A
DOWNHOLE COMMINGLE OTHER: X	Location is ready for OCD inspection after P&A
DOWNHOLE COMMINGLE	e Operator's pit permit and closure plan. been properly abandoned.
DOWNHOLE COMMINGLE OTHER: OTHER: X X All pits have been remediated in compliance with OCD rules and the terms of the X Rat hole and cellar have been filled and leveled. Cathodic protection holes have X A steel marker at least 4" in diameter and at least 4' above ground level has been	e Operator's pit permit and closure plan. been properly abandoned. a set in concrete. It shows the
DOWNHOLE COMMINGLE OTHER: OTHER: X X All pits have been remediated in compliance with OCD rules and the terms of the X Rat hole and cellar have been filled and leveled. Cathodic protection holes have X A steel marker at least 4" in diameter and at least 4' above ground level has been OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUAUNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION	e Operator's pit permit and closure plan. been properly abandoned. set in concrete. It shows the RTER/QUARTER LOCATION OR
DOWNHOLE COMMINGLE OTHER: OTHER: X X All pits have been remediated in compliance with OCD rules and the terms of the X Rat hole and cellar have been filled and leveled. Cathodic protection holes have X A steel marker at least 4" in diameter and at least 4' above ground level has been OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUA UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	e Operator's pit permit and closure plan. been properly abandoned. set in concrete. It shows the RTER/QUARTER LOCATION OR HAS BEEN WELDED OR
DOWNHOLE COMMINGLE OTHER: OTHER: X X All pits have been remediated in compliance with OCD rules and the terms of the X Rat hole and cellar have been filled and leveled. Cathodic protection holes have X A steel marker at least 4" in diameter and at least 4' above ground level has been OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUA UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour an other production equipment.	e Operator's pit permit and closure plan. been properly abandoned. set in concrete. It shows the RTER/QUARTER LOCATION OR HAS BEEN WELDED OR d has been cleared of all junk, trash, flow lines and
DOWNHOLE COMMINGLE OTHER: OTHER: X X All pits have been remediated in compliance with OCD rules and the terms of the X Rat hole and cellar have been filled and leveled. Cathodic protection holes have X A steel marker at least 4" in diameter and at least 4" above ground level has been OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUA UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour an other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below	e Operator's pit permit and closure plan. been properly abandoned. I set in concrete. It shows the RTER/QUARTER LOCATION OR HAS BEEN WELDED OR d has been cleared of all junk, trash, flow lines and w ground level.
DOWNHOLE COMMINGLE OTHER: OTHER: X X All pits have been remediated in compliance with OCD rules and the terms of the X Rat hole and cellar have been filled and leveled. Cathodic protection holes have X A steel marker at least 4" in diameter and at least 4' above ground level has been OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUA UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour an other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below X If this is a one-well lease or last remaining well on lease, the battery and pit locat OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines	e Operator's pit permit and closure plan. been properly abandoned. I set in concrete. It shows the RTER/QUARTER LOCATION OR HAS BEEN WELDED OR d has been cleared of all junk, trash, flow lines and w ground level. ion(s) have been remediated in compliance with
DOWNHOLE COMMINGLE OTHER: OTHER: X X All pits have been remediated in compliance with OCD rules and the terms of the X Rat hole and cellar have been filled and leveled. Cathodic protection holes have X A steel marker at least 4" in diameter and at least 4' above ground level has been OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUA UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour an other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below X If this is a one-well lease or last remaining well on lease, the battery and pit locat OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines from lease and well location.	e Operator's pit permit and closure plan. been properly abandoned. I set in concrete. It shows the RTER/QUARTER LOCATION OR HAS BEEN WELDED OR d has been cleared of all junk, trash, flow lines and w ground level. iion(s) have been remediated in compliance with s, production equipment and junk have been removed
OTHER: OTHER: OTHER: X X All pits have been remediated in compliance with OCD rules and the terms of the X Rat hole and cellar have been filled and leveled. Cathodic protection holes have X A steel marker at least 4" in diameter and at least 4' above ground level has been OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUA UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour an other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below X If this is a one-well lease or last remaining well on lease, the battery and pit locat OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines from lease and well location. X All metal bolts and other materials have been removed. Portable bases have been to be removed.)	e Operator's pit permit and closure plan. been properly abandoned. I set in concrete. It shows the RTER/QUARTER LOCATION OR HAS BEEN WELDED OR d has been cleared of all junk, trash, flow lines and w ground level. iion(s) have been remediated in compliance with s, production equipment and junk have been removed
OTHER: OTHER: OTHER: OTHER: X X All pits have been remediated in compliance with OCD rules and the terms of the X Rat hole and cellar have been filled and leveled. Cathodic protection holes have X A steel marker at least 4" in diameter and at least 4' above ground level has been OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUA UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour an other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below X If this is a one-well lease or last remaining well on lease, the battery and pit locat OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines from lease and well location. X All metal bolts and other materials have been removed. Portable bases have been to be removed.) X All other environmental concerns have been addressed as per OCD rules. X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NI	e Operator's pit permit and closure plan. been properly abandoned. I set in concrete. It shows the RTER/QUARTER LOCATION OR HAS BEEN WELDED OR d has been cleared of all junk, trash, flow lines and w ground level. ion(s) have been remediated in compliance with s, production equipment and junk have been removed. (Poured onsite concrete bases do not have
DOWNHOLE COMMINGLE OTHER: OTHER: X X All pits have been remediated in compliance with OCD rules and the terms of the X Rat hole and cellar have been filled and leveled. Cathodic protection holes have X A steel marker at least 4" in diameter and at least 4' above ground level has been OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUA UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour an other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below X If this is a one-well lease or last remaining well on lease, the battery and pit locat OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines from lease and well location. X All metal bolts and other materials have been removed. Portable bases have been to be removed.) X All other environmental concerns have been addressed as per OCD rules.	e Operator's pit permit and closure plan. been properly abandoned. I set in concrete. It shows the RTER/QUARTER LOCATION OR HAS BEEN WELDED OR d has been cleared of all junk, trash, flow lines and w ground level. ion(s) have been remediated in compliance with s, production equipment and junk have been removed removed. (Poured onsite concrete bases do not have
OTHER: X All pits have been remediated in compliance with OCD rules and the terms of the X Rat hole and cellar have been filled and leveled. Cathodic protection holes have X A steel marker at least 4" in diameter and at least 4' above ground level has been OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUA UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour an other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below X If this is a one-well lease or last remaining well on lease, the battery and pit locat OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines from lease and well location. X All metal bolts and other materials have been removed. Portable bases have been to be removed.) X All other environmental concerns have been addressed as per OCD rules. X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 No retrieved flow lines and pipelines. X I hereby certify that the information above is true and complete to the best of my	e Operator's pit permit and closure plan. been properly abandoned. I set in concrete. It shows the RTER/QUARTER LOCATION OR HAS BEEN WELDED OR d has been cleared of all junk, trash, flow lines and w ground level. ion(s) have been remediated in compliance with s, production equipment and junk have been removed removed. (Poured onsite concrete bases do not have MAC. All fluids have been removed from non-knowledge and belief.
OTHER: OTHER: OTHER: OTHER: X X All pits have been remediated in compliance with OCD rules and the terms of the X Rat hole and cellar have been filled and leveled. Cathodic protection holes have X A steel marker at least 4" in diameter and at least 4' above ground level has been OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUA UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour an other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below X If this is a one-well lease or last remaining well on lease, the battery and pit locat OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines from lease and well location. X All metal bolts and other materials have been removed. Portable bases have been to be removed.) X All other environmental concerns have been addressed as per OCD rules. X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 Ni retrieved flow lines and pipelines. X I hereby certify that the information above is true and complete to the best of my When all work has been completed, return this form to the appropriate District office.	e Operator's pit permit and closure plan. been properly abandoned. set in concrete. It shows the RTER/QUARTER LOCATION OR HAS BEEN WELDED OR d has been cleared of all junk, trash, flow lines and v ground level. ion(s) have been remediated in compliance with s, production equipment and junk have been removed removed. (Poured onsite concrete bases do not have MAC. All fluids have been removed from non- knowledge and belief.
OTHER: X All pits have been remediated in compliance with OCD rules and the terms of the X Rat hole and cellar have been filled and leveled. Cathodic protection holes have it X A steel marker at least 4" in diameter and at least 4" above ground level has been OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUA UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour an other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below X If this is a one-well lease or last remaining well on lease, the battery and pit locat OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines from lease and well location. X All metal bolts and other materials have been removed. Portable bases have been to be removed.) X All other environmental concerns have been addressed as per OCD rules. X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 Ni retrieved flow lines and pipelines. X I hereby certify that the information above is true and complete to the best of my When all work has been completed, return this form to the appropriate District office SIGNATURE TITLE Manager of Special	e Operator's pit permit and closure plan. been properly abandoned. I set in concrete. It shows the RTER/QUARTER LOCATION OR HAS BEEN WELDED OR I d has been cleared of all junk, trash, flow lines and or ground level. I junk ion(s) have been remediated in compliance with start production equipment and junk have been removed removed. (Poured onsite concrete bases do not have MAC. All fluids have been removed from non-knowledge and belief. I to schedule an inspection. Projects DATE 12301
OTHER: OTHER: OTHER: OTHER: X X All pits have been remediated in compliance with OCD rules and the terms of the X Rat hole and cellar have been filled and leveled. Cathodic protection holes have X A steel marker at least 4" in diameter and at least 4' above ground level has been OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUA UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour an other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below X If this is a one-well lease or last remaining well on lease, the battery and pit locat OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines from lease and well location. X All metal bolts and other materials have been removed. Portable bases have been to be removed.) X All other environmental concerns have been addressed as per OCD rules. X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 Ni retrieved flow lines and pipelines. X I hereby certify that the information above is true and complete to the best of my When all work has been completed, return this form to the appropriate District office.	e Operator's pit permit and closure plan. been properly abandoned. I set in concrete. It shows the RTER/QUARTER LOCATION OR HAS BEEN WELDED OR I d has been cleared of all junk, trash, flow lines and or ground level. I junk ion(s) have been remediated in compliance with start production equipment and junk have been removed removed. (Poured onsite concrete bases do not have MAC. All fluids have been removed from non-knowledge and belief. I to schedule an inspection. Projects DATE 12301
OTHER: OTHER: OTHER: OTHER: X X All pits have been remediated in compliance with OCD rules and the terms of the X Rat hole and cellar have been filled and leveled. Cathodic protection holes have X A steel marker at least 4" in diameter and at least 4' above ground level has been OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUA UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION PERMANENTLY STAMPED ON THE MARKER'S SURFACE. X The location has been leveled as nearly as possible to original ground contour an other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below X If this is a one-well lease or last remaining well on lease, the battery and pit locat OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines from lease and well location. X All metal bolts and other materials have been removed. Portable bases have been to be removed.) X All other environmental concerns have been addressed as per OCD rules. X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 Ni retrieved flow lines and pipelines. X I hereby certify that the information above is true and complete to the best of my When all work has been completed, return this form to the appropriate District office SIGNATURE TITLE Manager of Special Type or print name Don Rogers E-mail address: drogers@cr	e Operator's pit permit and closure plan. been properly abandoned. I set in concrete. It shows the RTER/QUARTER LOCATION OR HAS BEEN WELDED OR I d has been cleared of all junk, trash, flow lines and or ground level. I junk ion(s) have been remediated in compliance with start production equipment and junk have been removed removed. (Poured onsite concrete bases do not have MAC. All fluids have been removed from non-knowledge and belief. I to schedule an inspection. Projects DATE 12301