District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

			Rele	ease Notific	ation	n and Co	orrective A	ction	1		
					OPERA	TOR X Initial Report Final R			Final Repo		
Name of Company XTO Energy					Contact Gene Hudson						
Address PO Box 700, Eunice, NM 88231					Telephone No. 575-441-1634						
Facility Name Section 27 SWD # 2					Facility Type Injection Well						
Surface Owner Larry Squires STATE Mineral Owner:				wner:	r: State Lease No. 30.025.03142						
				LOCA	TIO	N OF RE	LEASE	•		-0'	
Unit Letter H	Section 27	Township 18S	Range 35E	Feet from the	North	rth/South Line Feet from the East/West Line County Lea					
Latitude_32 43'25.79" Longitude_103 26'19.12"											
				NAT	URE	OF REL	EASE				
Type of Releas						1	Release 600			Recovered 480	
Source of Rele	ease Steel	Valve				Date and H	Iour of Occurrenc	e		Hour of Discove 08:30 am	ry
Was Immediat	e Notice G		-			If YES, To	Whom? Geoff L		MOCD		
		Х	Yes 🗌	No Not Req	juired		Larry S	quires/	Land owner	r	
By Whom? G	ene Hudso	n				Date and Hour 12/28/09 08:30 am					
Was a Waterco	ourse Reac		Yes X	No		If YES, Volume Impacting the Watercourse.					
If a Watercour											
Describe Cause of Problem and Remedial Action Taken.* The leak was caused by internal corrosion on steel valve/valve was repaired.											
Describe Area Affected and Cleanup Action Taken.* The affected area is approximately 195' X 1,000'. Vacuum trucks were called to remove standing fluid and SESI was called for assessment. An appropriate work plan will follow.											
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.											
rotoria, state, or rotar faws and/or regulations.				OIL CONSERVATION DIVISION							
Signature: Land Juden											
Printed Name: Gene Hudson				Approved by District Supervisor:							
Title: Maintenance Foreman				1	Approval Dat	ate: Expiration Date:					
E-mail Address: Richard_hudson@xtoenergy.com					Conditions of Approval:			Attached			
Date: 12/29/09 Phone: 575-441-1634 IRP#10.1.2385 Attach Additional Sheets If Necessary						1. 2385					

XTO Energy Section 27 SWD #2 Township 18 South, Range 35 East, Section 27 Lea County, New Mexico

Work Plan

December 28, 2009



Prepared for:

XTO Energy P.O. Box 700 Eunice, New Mexico 88231-0700

Prepared by:

Safety & Environmental Solutions, Inc. 703 East Clinton Street Hobbs, New Mexico 88240 (575) 397-0510

TABLE OF CONTENTS

I.	COMPANY CONTACTS	1
И.	BACKGROUND	1
III.	SURFACE AND GROUND WATER	1
IV.	WORK PERFORMED	1
V.	ACTION PLAN	1
VI.	FIGURES & APPENDICES	4 5
	Appendix C - C-141	•••

I. Company Contacts

NAME	Company	Telephone	E-mail
Gene Hudson	XTO Energy	575.441.1634	Richard Hudson@xtoenergy.com
Bob Allen	SESI	575.390.7063	ballen@sesi-nm.com

II. Background

Safety and Environmental Solutions, Inc. (SESI) was engaged by XTO Energy to perform clean-up services at the Section 27 SWD #2 release. Approximately 600 barrels of produced water was released due to internal corrosion of a steel valve on the injection well, and recovered approximately 480 barrels.

III. Surface and Ground Water

The closest groundwater of record with the Office of the State Engineer is located in the same township, range, and section. The depth of water in this well was 70' in August 1958.

IV. Work Performed

On December 28, 2009, SESI was onsite with Hungry Horse to install a total of eight (8) test trenches (See Figure 2). Samples were retrieved at depths ranging from one (1) to two (2) feet. The samples were properly preserved and transported under Chain-of-Custody to Cardinal Laboratories of Hobbs, New Mexico for analysis. The samples were analyzed for Chlorides (EPA method 4500-Cl⁻B) (See Appendix A).

The results of the analysis are as follows:


Sample Point	Chlorides (mg/kg)
TT #1-2'	80
TT #2-2'	832
TT #3-2'	736
TT #4-1'	<16
TT #5-1 1/2'	1,500
TT #6-2'	2,040
TT #7-2'	1,400
TT #8-1'	32


V. Action Plan


It is requested that the top 1 to 1 $\frac{1}{2}$ of soil be excavated from the spill area and transported to an NMOCD approved facility for disposal. The excavation will be backfilled with clean soils, and then the area will be contoured to natural grade and reseeded in the next growing period.

VI. Figures & Appendices

Figure 1 – Vicinity Map Figure 2 – Site Plan Appendix A – Analytical Results Appendix B – Site Photos Appendix C – C-141









January 5, 2010

Bob Allen Safety & Environmental Solutions, Inc. 703 East Clinton, #102 Hobbs, NM 88240

Re: Section 27 SWD #2 (XTO-09-014)

Enclosed are the results of analyses for sample number H18974, received by the laboratory on 12/31/09 at 3:00 pm.

Cardinal Laboratories is accredited through Texas NELAP for:

Method SW-846 8021 Benzene, Toluene, Ethyl Benzene, and Total Xylenes
Method SW-846 8260 Benzene, Toluene, Ethyl Benzene, and Total Xylenes
Method TX 1005 Total Petroleum Hydrocarbons

Certificate number T104704398-08-TX. Accreditation applies to solid and chemical materials and non-potable water matrices.

Cardinal Laboratories is accredited though the State of Colorado Department of Public Health and Environment for:

Method EPA 552.2 Haloacetic Acids (HAA-5)
Method EPA 524.2 Total Trihalomethanes (TTHM)
Method EPA 524.2 Regulated VOCs (V2, V3)

Accreditation applies to public drinking water matrices.

Total Number of Pages of Report: 3 (includes Chain of Custody)

Sincerely,

Celey D. Keene Laboratory Director



ANALYTICAL RESULTS FOR

SAFETY & ENVIRONMENTAL SOLUTIONS, INC.

ATTN: BOB ALLEN 703 E. CLINTON, #102 HOBBS, NM 88240 FAX TO: (575) 393-4388

Receiving Date: 12/31/09 Reporting Date: 01/04/10

Project Number: XTO-09-014 (XTO ENERGY)

Project Name: SECTION 27 SWD #2

Project Location: BUCKEYE, NM

Analysis Date: 01/04/10 Sampling Date: 12/31/09

Sample Type: SOIL

Sample Condition: COOL & INTACT @ 4°C

Sample Received By: CK

Analyzed By: HM

		CIT
LAB NO.	SAMPLE ID	(mg/kg)
H18974-1	TT #1 2'	80
H18974-2	TT #2 2'	832
H18974-3	TT #3 2'	736
H18974-4	TT #4 1'	< 16
H18974-5	TT #5 1 ¹ / ₂ '	1,500
H18974-6	TT #6 2'	2,040
H18974-7	TT #7 2'	1,400
H18974-8	TT #8 1'	32
Quality Cor		510
True Value		500
% Recover		102
Relative Pe	rcent Difference	2.0

METHOD: Standard Methods 4500-CIB

Note: Analyses performed on 1:4 w:v aqueous extracts.

Chemist

Date




(575) 202 2226 Env (575) 202 2476

(575) 393-2326 Fax (575) 393-2476		Pageof			
Company Name: SES	BILL TO	ANALYSIS REQUEST			
Company Name: SESE Project Manager: Rob Allen	P.O. #:				
Address: 703 E clinton	Company:				
City: What State: MM Zip: 882VD	Attn:				
Phone #: 5 75 - 367 - 05/O Fax #:	Address: Sime				
Project #: X70-09-614 Project Owner: X70 ENERGY	City:				
Phone #: 575-367-05/0 Fax #: Project #: X70-09-614 Project Owner: X70 Energy Project Name: Section 27 SWD # Z Project Location: Buckeye M	State: Zip:				
Project Location: Buckeye, no.	Phone #:				
Project Location: Buckeye, nm Sampler Name: ISGAC Kincgirk	Fax #:				
Tabilo D Sample D D D D D D D D D	PRESERV SAMPLING TO USE TIME OSSO OSSO OSSO OSSO OSSO OSSO OSSO O				
PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising whether based in contract, and the cause whatsoever shall be deemed waived unless made in writing tending. In no event shall Cardinal be liable for incidental or consequental damages, including without limitation, business interruption.	and received by Cardinal within 30 days after completion of	the applicable			
allitates or successors arising out of or related to the performance of services hereunder by Cerdinal, regardless of whether such cla	in is based upon any of the above stated reasons or other	vist.			
Sampler Relinguished Date: 12/31/09 Received By:	Fax Res	Fax.Result: D No Add'i Fax #: REMARKS:			
1500	Тамент				
Relinquished By: Date: Received By:					
Time: Wu All	M				
Delivered By: (Circle One) Temp. Sample Condition CHECKED BY: Copy Intact (Intigels)					
Sampler - UPS - Bus - Other:	res No				

[†] Cardinal cannot accept verbal changes. Please fax written changes to 575-393-2476.


Appendix B Site Photos XTO Section 27 site photos 12-28-09




Well Sign




Release point




Release area facing east




Release area facing southeast




Release area facing southeast



Release area facing south




Release area facing south




Release area facing southeast




Release area facing west




Release area facing northeast




Release area facing northwest







Release area facing west




Release area facing south




Release area facing west




South release area facing south



South release area facing west



South release area facing south



South release area facing south




South release area facing east



South release area facing east




South release area facing east



South release area facing north



South release area facing west




Release area facing northwest



North release area facing north



North release area facing east



North release area facing east




North release area facing east




North release area facing north



North release area facing east



North release area facing east



North release area facing east