


**Range Operating New Mexico, Inc.
Greenwood Battery
Section 9, Township 22S, Range 37E
Lea County, New Mexico**

Work Plan

June 26, 2009



IRP # 10.2.2429

Prepared for:

**Range Operating New Mexico, Inc.
281 North New Mexico Highway 248
PO Box 1570
Eunice, New Mexico 88231**

By:

**Safety & Environmental Solutions, Inc.
703 East Clinton Street
Hobbs, New Mexico 88240
(575) 397-0510**

TABLE OF CONTENTS

I. COMPANY CONTACTS	1
II. BACKGROUND	1
III. SURFACE AND GROUND WATER	1
IV. WORK PERFORMED	1
V. ACTION PLAN	1
VI. FIGURES & APPENDICES	1
Figure 1 - Vicinity Map.....	2
Figure 2 - Site Plan	3
Appendix A– Site Photos	4
Appendix B– C-141	5

I. Company Contacts

NAME	Company	Telephone	E-mail
Steve Almager	Range Operating NM, Inc.	575-394-1485	salmager@rangeresources.com
Sergio Contreras	SESI	575-397-0510	scontreras@sesi-nm.com

II. Background

Safety and Environmental Solutions, Inc. (SESI) was engaged by Range Resources Corporation to perform a site assessment at the Greenwood Battery. This is an active battery located in Section 9, Township 22S, Range 37E. On June 26, 2009 an over pressured flowline spilt releasing an unknown amount of produced fluids.

III. Surface and Ground Water

According the database provided by the Office of State Engineer (OSE) online database, the average depth of water in this area is 94'.

IV. Work Performed

On June 26, 2009, SESI was onsite to map the area. The area was mapped using a Trimble Geo XM GPS. SESI observed overspray to the North of the battery with minor staining to vegetation and soil. Produced fluid ran off location and mixed with rain water on lease road. Two (2) vacuum trucks were utilized to recover 200 barrels of produced fluid, which included the standing rain water on the lease road.

V. Action Plan

It is requested that the highly contaminated and/or saturated soils be excavated and transported offsite to an NMOCD approved disposal facility. The excavation will be backfilled with clean soils from offsite and contoured back to grade. The appropriate reports will be filed with the NMOCD upon completion.

VI. Figures & Appendices

Figure 1 – Vicinity Map
Figure 2 – Site Plan
Appendix A – Site Photos
Appendix B – C-141






Figure 2
Site Plan



Point of Release

Auger Hole #1



Auger hole # 1 facing west

Appendix B
C-141

Jun 29 09 10:13a

p.2

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Range Resources Corporation	Contact: Steve Almager
Address: 100 Throckmorton Ste 1200	Telephone No. (575)394-1485
Facility Name: Greenwood # 23	Facility Type: Battery

Surface Owner <u>Private</u>	Mineral Owner	Lease No.
------------------------------	---------------	-----------

LOCATION OF RELEASE

API 30.025.374B

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	09	22S	37E					Lea

Latitude: 32.4029934 Longitude: 103.1673759

WTR 80'

NATURE OF RELEASE

SD

30

Type of Release Produced Water	Volume of Release Unknown	Volume Recovered 200 bbls - NOT IN WTR
Source of Release Flowline Split	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 6/26/09 8:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Larry Johnson, NMOCD	
By Whom? Susana Rodriguez, SESI	Date and Hour 6/26/09 1:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Overpressured pipe causing flowline to spill. Produced fluid mixed with rain water on lease road. Flowline repaired and a vacuum truck retrieved spilled fluid and rainwater.

Describe Area Affected and Cleanup Action Taken.*

SESI was contacted for assessment. Area will be delineated and an appropriate work plan submitted upon results.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: <u>Steve Almager</u>	Approved by District Supervisor <u>[Signature]</u>	
Printed Name: Steve Almager	ENVIRONMENTAL ENGINEER	
Title: Production Supervisor II	Approval Date: 2.19.10	Expiration Date: 4.19.10
E-mail Address: salmager@rangeresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6/26/09 Phone: (575) 394-1485		WTR 10-2.2429

* Attach Additional Sheets If Necessary