Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office District I	Energy, Minerals and Natural Resource	ces May 27, 2004
1625 N French Dr , Hobbs, NM 88240	-	WELL API NO.
District II	A ON THE CONSERVATION DIVISIO	N 30-025-38783
District III	OHFCONSERVATION DIVISIO 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd , Aztec, NM 87410 District IV MAR 0 1 6	Filds Conta Co NIM 97505	STATE X FEE
District IV MAR U I	ZUIÜ Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St Francis Dr., Santa Fe, NM 87505 HOBBS	CD	
SUNDRY NOTICES	AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	TO DRILL OR TO DEEPEN OR PLUG BACK TO	
DIFFERENT RESERVOIR USE "APPLICATIO		UNIT
, PROPOSALS)	w n 🗆 od	
1. Type of Well: Oil Well Gas	Well _ Other	8. Well Number 405
2. Name of Operator		9. OGRID Number 4323
CHEVRON U.S.A. INC.		10 Prolumna - Wildow
3. Address of Operator	7, 70705	10. Pool name or Wildcat
15 SMITH ROAD, MIDLAND, TEXAS	5 /9/05	VACUUM GRAYBURG S/A
4. Well Location		,
Unit Letter H: 1910 feet from t	the NORTH line and 40 feet from the EAS	ST line
Section 1 Township 18-S	S Range 34-E NMPN	M County LEA
	Elevation (Show whether DR, RKB, RT, C	
397		, , , , , , , , , , , , , , , , , , ,
Pit or Below-grade Tank Application ☐ or Close		Specific Annual Control of Contro
Pit type Depth to Groundwater	Distance from nearest fresh water well	Distance from nearest surface water
		obls; Construction Material
12. Check Appro	opriate Box to Indicate Nature of N	otice, Report or Other Data
NOTICE OF INTEN		SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLU	UG AND ABANDON ☐ REMEDIA	L WORK ALTERING CASING
PERFORM REMEDIAL WORK PLU	UG AND ABANDON ☐ REMEDIA ANGE PLANS ☐ COMMEN	L WORK ALTERING CASING CE DRILLING OPNS. P AND A
PERFORM REMEDIAL WORK PLUTEMPORARILY ABANDON CH	UG AND ABANDON ☐ REMEDIA ANGE PLANS ☐ COMMEN	L WORK ALTERING CASING
PERFORM REMEDIAL WORK PLUTEMPORARILY ABANDON CH	UG AND ABANDON REMEDIA ANGE PLANS COMMEN ULTIPLE COMPL CASING/C	L WORK ALTERING CASING CE DRILLING OPNS. P AND A CEMENT JOB
PERFORM REMEDIAL WORK PLUTEMPORARILY ABANDON MU	UG AND ABANDON REMEDIA ANGE PLANS COMMEN ULTIPLE COMPL CASING/O OTHER:	L WORK
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MU OTHER: 13. Describe proposed or completed	UG AND ABANDON REMEDIA ANGE PLANS COMMEN ULTIPLE COMPL CASING/O OTHER: operations. (Clearly state all pertinent det	L WORK ALTERING CASING CE DRILLING OPNS. P AND A CEMENT JOB ADD PERFS Tails, and give pertinent dates, including estimated date
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MU OTHER: 13. Describe proposed or completed of starting any proposed work).	UG AND ABANDON REMEDIA ANGE PLANS COMMEN ULTIPLE COMPL CASING/O OTHER: operations. (Clearly state all pertinent det	L WORK
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MU OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion.	UG AND ABANDON REMEDIA ANGE PLANS COMMEN ULTIPLE COMPL CASING/O OTHER: operations. (Clearly state all pertinent det	L WORK ALTERING CASING CE DRILLING OPNS. P AND A CEMENT JOB ADD PERFS Tails, and give pertinent dates, including estimated date
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MU OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 12-11-09: MIRU.	UG AND ABANDON REMEDIA ANGE PLANS COMMEN ULTIPLE COMPL CASING/C OTHER: operations. (Clearly state all pertinent det SEE RULE 1103. For Multiple Completion	L WORK ALTERING CASING CE DRILLING OPNS. P AND A CEMENT JOB ADD PERFS Tails, and give pertinent dates, including estimated date
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MU OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 12-11-09: MIRU. 12-13-09: TIH & TAG @ 4900. NO FILE	UG AND ABANDON REMEDIA ANGE PLANS COMMEN ULTIPLE COMPL CASING/O OTHER: operations. (Clearly state all pertinent det SEE RULE 1103. For Multiple Completion	L WORK ALTERING CASING CE DRILLING OPNS. P AND A CEMENT JOB ADD PERFS Tails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MU OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 12-11-09: MIRU. 12-13-09: TIH & TAG @ 4900. NO FILI 12-14-09: TIH & LOG WELL W/GR/CN	UG AND ABANDON REMEDIA ANGE PLANS COMMEN CASING/O OTHER: operations. (Clearly state all pertinent det SEE RULE 1103. For Multiple Completion L. NL/CCL FR SURF TO TD. PERF: 4829-	L WORK ALTERING CASING CE DRILLING OPNS. P AND A CEMENT JOB ADD PERFS Tails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion 36, 4814-20, 4802-10, 4796-4800,
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MU OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 12-11-09: MIRU. 12-13-09: TIH & TAG @ 4900. NO FILI 12-14-09: TIH & LOG WELL W/GR/CN 4786-93, 4758-69, 4753-56, 4746-49, 473	UG AND ABANDON REMEDIA ANGE PLANS COMMEN CASING/O OTHER: operations. (Clearly state all pertinent det SEE RULE 1103. For Multiple Completion L. NL/CCL FR SURF TO TD. PERF: 4829- 8-42, 4730-35. TIH W/PKR, SN & WS.	L WORK ALTERING CASING CE DRILLING OPNS. P AND A CEMENT JOB ADD PERFS Tails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion 36, 4814-20, 4802-10, 4796-4800,
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MU OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 12-11-09: MIRU. 12-13-09: TIH & TAG @ 4900. NO FILI 12-14-09: TIH & LOG WELL W/GR/CN 4786-93, 4758-69, 4753-56, 4746-49, 473 12-15-09: SET PKR @ 4465. ACIDIZE	UG AND ABANDON REMEDIA ANGE PLANS COMMEN CASING/O OTHER: operations. (Clearly state all pertinent det SEE RULE 1103. For Multiple Completic L. NL/CCL FR SURF TO TD. PERF: 4829- 8-42, 4730-35. TIH W/PKR, SN & WS. 3 W/10,000 GALS 15 NEFE.	L WORK ALTERING CASING CE DRILLING OPNS. P AND A ADD PERFS Tails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion 36, 4814-20, 4802-10, 4796-4800, PKR HANGING @ 4465.
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MU OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 12-11-09: MIRU. 12-13-09: TIH & TAG @ 4900. NO FILI 12-14-09: TIH & LOG WELL W/GR/CN 4786-93, 4758-69, 4753-56, 4746-49, 473 12-15-09: SET PKR @ 4465. ACIDIZE 12-16-09: REL PKR. RU ELECTRIC LII	UG AND ABANDON REMEDIA ANGE PLANS COMMEN CASING/O OTHER: operations. (Clearly state all pertinent det SEE RULE 1103. For Multiple Completic L. NL/CCL FR SURF TO TD. PERF: 4829- 8-42, 4730-35. TIH W/PKR, SN & WS. 3 W/10,000 GALS 15 NEFE.	L WORK ALTERING CASING CE DRILLING OPNS. P AND A CEMENT JOB ADD PERFS Tails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion 36, 4814-20, 4802-10, 4796-4800,
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MU OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 12-11-09: MIRU. 12-13-09: TIH & TAG @ 4900. NO FILI 12-14-09: TIH & LOG WELL W/GR/CN 4786-93, 4758-69, 4753-56, 4746-49, 473 12-15-09: SET PKR @ 4465. ACIDIZE 12-16-09: REL PKR. RU ELECTRIC LIT PKR @ 4298.	UG AND ABANDON REMEDIA ANGE PLANS COMMEN CASING/O OTHER: operations. (Clearly state all pertinent det SEE RULE 1103. For Multiple Completion L. NL/CCL FR SURF TO TD. PERF: 4829- 88-42, 4730-35. TIH W/PKR, SN & WS. W/10,000 GALS 15 NEFE. NE & PERF TUBING @ 2092. CUT SAN	L WORK ALTERING CASING CE DRILLING OPNS. P AND A ADD PERFS Tails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion 36, 4814-20, 4802-10, 4796-4800, PKR HANGING @ 4465.
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MU OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 12-11-09: MIRU. 12-13-09: TIH & TAG @ 4900. NO FILI 12-14-09: TIH & LOG WELL W/GR/CN 4786-93, 4758-69, 4753-56, 4746-49, 473 12-15-09: SET PKR @ 4465. ACIDIZE 12-16-09: REL PKR. RU ELECTRIC LII PKR @ 4298. 12-17-09: PUMP & SCALE SQUEEZE V	UG AND ABANDON REMEDIA ANGE PLANS COMMEN CASING/O OTHER: Operations. (Clearly state all pertinent det SEE RULE 1103. For Multiple Completion L. NL/CCL FR SURF TO TD. PERF: 4829- 88-42, 4730-35. TIH W/PKR, SN & WS. WW/10,000 GALS 15 NEFE. NE & PERF TUBING @ 2092. CUT SAN W/330 GALS SCW 358. REL PKR.	L WORK ALTERING CASING CE DRILLING OPNS. P AND A CEMENT JOB ADD PERFS Tails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion 36, 4814-20, 4802-10, 4796-4800, PKR HANGING @ 4465. NDLINE @ 260'. TIH W/BIT @ 4918 & TAG. SET
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MU OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 12-11-09: MIRU. 12-13-09: TIH & TAG @ 4900. NO FILI 12-14-09: TIH & LOG WELL W/GR/CN 4786-93, 4758-69, 4753-56, 4746-49, 473 12-15-09: SET PKR @ 4465. ACIDIZE 12-16-09: REL PKR. RU ELECTRIC LIT PKR @ 4298.	UG AND ABANDON REMEDIA ANGE PLANS COMMEN CASING/O OTHER: Operations. (Clearly state all pertinent det SEE RULE 1103. For Multiple Completion L. NL/CCL FR SURF TO TD. PERF: 4829- 88-42, 4730-35. TIH W/PKR, SN & WS. WW/10,000 GALS 15 NEFE. NE & PERF TUBING @ 2092. CUT SAN W/330 GALS SCW 358. REL PKR.	L WORK ALTERING CASING CE DRILLING OPNS. P AND A CEMENT JOB ADD PERFS Tails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion 36, 4814-20, 4802-10, 4796-4800, PKR HANGING @ 4465. NDLINE @ 260'. TIH W/BIT @ 4918 & TAG. SET
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MU OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 12-11-09: MIRU. 12-13-09: TIH & TAG @ 4900. NO FILI 12-14-09: TIH & LOG WELL W/GR/CN 4786-93, 4758-69, 4753-56, 4746-49, 473 12-15-09: SET PKR @ 4465. ACIDIZE 12-16-09: REL PKR. RU ELECTRIC LII PKR @ 4298. 12-17-09: PUMP & SCALE SQUEEZE N 12-19-09: RIH W/SUB PUMP & TBG TO	ANGE PLANS COMMEN CASING/O OTHER: Operations. (Clearly state all pertinent det SEE RULE 1103. For Multiple Completion L. NL/CCL FR SURF TO TD. PERF: 4829- 88-42, 4730-35. TIH W/PKR, SN & WS. No. 100,000 GALS 15 NEFE. NE & PERF TUBING @ 2092. CUT SAN W/330 GALS SCW 358. REL PKR. O 4592. RIG DOWN. FINAL REPORT.	L WORK ALTERING CASING CE DRILLING OPNS. P AND A CEMENT JOB ADD PERFS Tails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion 36, 4814-20, 4802-10, 4796-4800, PKR HANGING @ 4465. NDLINE @ 260'. TIH W/BIT @ 4918 & TAG. SET
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MU OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 12-11-09: MIRU. 12-13-09: TIH & TAG @ 4900. NO FILI 12-14-09: TIH & LOG WELL W/GR/CN 4786-93, 4758-69, 4753-56, 4746-49, 473 12-15-09: SET PKR @ 4465. ACIDIZE 12-16-09: REL PKR. RU ELECTRIC LID PKR @ 4298. 12-17-09: PUMP & SCALE SQUEEZE V 12-19-09: RIH W/SUB PUMP & TBG To	UG AND ABANDON REMEDIA ANGE PLANS COMMEN CASING/O OTHER: Operations. (Clearly state all pertinent det SEE RULE 1103. For Multiple Completion L. NL/CCL FR SURF TO TD. PERF: 4829- 88-42, 4730-35. TIH W/PKR, SN & WS. WW. 10,000 GALS 15 NEFE. NE & PERF TUBING @ 2092. CUT SAN W/330 GALS SCW 358. REL PKR. O 4592. RIG DOWN. FINAL REPORT. The is true and complete to the best of my kn	L WORK ALTERING CASING CE DRILLING OPNS. P AND A CEMENT JOB ADD PERFS Tails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion 36, 4814-20, 4802-10, 4796-4800, PKR HANGING @ 4465. NDLINE @ 260'. TIH W/BIT @ 4918 & TAG. SET Owledge and belief. I further certify that any pit or below-
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MU OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 12-11-09: MIRU. 12-13-09: TIH & TAG @ 4900. NO FILI 12-14-09: TIH & LOG WELL W/GR/CN 4786-93, 4758-69, 4753-56, 4746-49, 473 12-15-09: SET PKR @ 4465. ACIDIZE 12-16-09: REL PKR. RU ELECTRIC LID PKR @ 4298. 12-17-09: PUMP & SCALE SQUEEZE V 12-19-09: RIH W/SUB PUMP & TBG To	UG AND ABANDON REMEDIA ANGE PLANS COMMEN CASING/O OTHER: Operations. (Clearly state all pertinent det SEE RULE 1103. For Multiple Completion L. NL/CCL FR SURF TO TD. PERF: 4829- 88-42, 4730-35. TIH W/PKR, SN & WS. WW. 10,000 GALS 15 NEFE. NE & PERF TUBING @ 2092. CUT SAN W/330 GALS SCW 358. REL PKR. O 4592. RIG DOWN. FINAL REPORT. The is true and complete to the best of my kn	L WORK ALTERING CASING CE DRILLING OPNS. P AND A CEMENT JOB ADD PERFS Tails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion 36, 4814-20, 4802-10, 4796-4800, PKR HANGING @ 4465. NDLINE @ 260'. TIH W/BIT @ 4918 & TAG. SET
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MU OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 12-11-09: MIRU. 12-13-09: TIH & TAG @ 4900. NO FILI 12-14-09: TIH & LOG WELL W/GR/CN 4786-93, 4758-69, 4753-56, 4746-49, 473 12-15-09: SET PKR @ 4465. ACIDIZE 12-16-09: REL PKR. RU ELECTRIC LID PKR @ 4298. 12-17-09: PUMP & SCALE SQUEEZE V 12-19-09: RIH W/SUB PUMP & TBG To	UG AND ABANDON ☐ REMEDIA COMMEN CASING/COMMEN CASING/COMPL ☐ COMMEN CASING/COMPL ☐ COMMEN CASING/COMPL COMPLETE COMPLET	L WORK
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MU OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 12-11-09: MIRU. 12-13-09: TIH & TAG @ 4900. NO FILI 12-14-09: TIH & LOG WELL W/GR/CN 4786-93, 4758-69, 4753-56, 4746-49, 473 12-15-09: SET PKR @ 4465. ACIDIZE 12-16-09: REL PKR. RU ELECTRIC LID PKR @ 4298. 12-17-09: PUMP & SCALE SQUEEZE N 12-19-09: RIH W/SUB PUMP & TBG TO I hereby certify that the information above grade tank has been/will be constructed or closed	UG AND ABANDON ☐ REMEDIA COMMEN CASING/COMMEN CASING/COMPL ☐ COMMEN CASING/COMPL ☐ COMMEN CASING/COMPL COMPLETE COMPLET	L WORK ALTERING CASING CE DRILLING OPNS. P AND A CEMENT JOB ADD PERFS Tails, and give pertinent dates, including estimated date ons: Attach wellbore diagram of proposed completion 36, 4814-20, 4802-10, 4796-4800, PKR HANGING @ 4465. NDLINE @ 260'. TIH W/BIT @ 4918 & TAG. SET Owledge and belief. I further certify that any pit or below-
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MU OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 12-11-09: MIRU. 12-13-09: TIH & TAG @ 4900. NO FILI 12-14-09: TIH & LOG WELL W/GR/CN 4786-93, 4758-69, 4753-56, 4746-49, 473 12-15-09: SET PKR @ 4465. ACIDIZE 12-16-09: REL PKR. RU ELECTRIC LID PKR @ 4298. 12-17-09: PUMP & SCALE SQUEEZE V 12-19-09: RIH W/SUB PUMP & TBG TO I hereby certify that the information above grade tank has been/will be constructed or closed SIGNATURE	UG AND ABANDON ☐ REMEDIA COMMEN CASING/COMMEN CASING/COMPL ☐ COMMEN CASING/COMPL ☐ COMMEN CASING/COMPL COMPLETE COMPLET	L WORK
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MU OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 12-11-09: MIRU. 12-13-09: TIH & TAG @ 4900. NO FILI 12-14-09: TIH & LOG WELL W/GR/CN 4786-93, 4758-69, 4753-56, 4746-49, 473 12-15-09: SET PKR @ 4465. ACIDIZE 12-16-09: REL PKR. RU ELECTRIC LID PKR @ 4298. 12-17-09: PUMP & SCALE SQUEEZE V 12-19-09: RIH W/SUB PUMP & TBG TO I hereby certify that the information above grade tank has been/will be constructed or closed SIGNATURE	ANGE PLANS COMMEN CASING/O OTHER: operations. (Clearly state all pertinent det SEE RULE 1103. For Multiple Completions.) L. NL/CCL FR SURF TO TD. PERF: 4829-18-42, 4730-35. TIH W/PKR, SN & WS. W/10,000 GALS 15 NEFE. NE & PERF TUBING @ 2092. CUT SAN W/330 GALS SCW 358. REL PKR. O 4592. RIG DOWN. FINAL REPORT. e is true and complete to the best of my kn according to NMOCD guidelines \(\text{\tex	L WORK
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MU OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 12-11-09: MIRU. 12-13-09: TIH & TAG @ 4900. NO FILI 12-14-09: TIH & LOG WELL W/GR/CN 4786-93, 4758-69, 4753-56, 4746-49, 473 12-15-09: SET PKR @ 4465. ACIDIZE 12-16-09: REL PKR. RU ELECTRIC LII PKR @ 4298. 12-17-09: PUMP & SCALE SQUEEZE N 12-19-09: RIH W/SUB PUMP & TBG TO I hereby certify that the information above grade tank has been/will be constructed or closed SIGNATURE SUMMER SIGNATURE Type or print name Denise Pinkerton For State Use Only	ANGE PLANS COMMEN CASING/O OTHER: operations. (Clearly state all pertinent det SEE RULE 1103. For Multiple Completions.) L. NL/CCL FR SURF TO TD. PERF: 4829-18-42, 4730-35. TIH W/PKR, SN & WS. W/10,000 GALS 15 NEFE. NE & PERF TUBING @ 2092. CUT SAN W/330 GALS SCW 358. REL PKR. O 4592. RIG DOWN. FINAL REPORT. e is true and complete to the best of my kn according to NMOCD guidelines \(\text{\tex	L WORK
PERFORM REMEDIAL WORK PLU TEMPORARILY ABANDON CH PULL OR ALTER CASING MU OTHER: 13. Describe proposed or completed of starting any proposed work). or recompletion. 12-11-09: MIRU. 12-13-09: TIH & TAG @ 4900. NO FILI 12-14-09: TIH & LOG WELL W/GR/CN 4786-93, 4758-69, 4753-56, 4746-49, 473 12-15-09: SET PKR @ 4465. ACIDIZE 12-16-09: REL PKR. RU ELECTRIC LID PKR @ 4298. 12-17-09: PUMP & SCALE SQUEEZE N 12-19-09: RIH W/SUB PUMP & TBG TO I hereby certify that the information above grade tank has been/will be constructed or closed SIGNATURE	ANGE PLANS COMMEN CASING/O OTHER: operations. (Clearly state all pertinent det SEE RULE 1103. For Multiple Completions.) L. NL/CCL FR SURF TO TD. PERF: 4829-18-42, 4730-35. TIH W/PKR, SN & WS. W/10,000 GALS 15 NEFE. NE & PERF TUBING @ 2092. CUT SAN W/330 GALS SCW 358. REL PKR. O 4592. RIG DOWN. FINAL REPORT. e is true and complete to the best of my kn according to NMOCD guidelines \(\text{\tex	L WORK