Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resources	October 13, 2009
1625 N. French Dr., Hobbs, NM 88240		WELL API NO. 30-025-36748
1301 W. Grand Ave , Artesia, NM 88240	VE CONSERVATION DIVISION	5. Indicate Type of Lease
District III	1220 South St. Francis Dr.	STATE STEE
1000 Rio Brazos Rd, Aztec, NM 87470AK 0	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S St. Francis Dr , Santa Fe, NOBBS	SOCD	VO-5543
0,505		7. 1 N 11-2 A N
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Cash BNG State Com
PROPOSALS.)	w # M od	8. Well Number
1. Type of Well: Oil Well Gas	s Well 🛛 Other	3
2. Name of Operator		9. OGRID Number
Yates Petroleum Corporation	·	025575
3. Address of Operator		10. Pool name or Wildcat
105 South Fourth Street Arte	esia, NM 88210	X-4 Ran Wildeat, Atoka (Gas)
4. Well Location		
Unit Letter K:	1400 feet from the South line and	1605 feet from the West line
Section 18	Township 10 South Range 34 East	NMPM Lea County
1	1. Elevation (Show whether DR, RKB, RT, GR, etc.	C.)
	4205' GL	
12. Check App	propriate Box to Indicate Nature of Notice	, Report or Other Data
NOTICE OF INTE		BSEQUENT REPORT OF:
	LUG AND ABANDON REMEDIAL WO	
<u> </u>		RILLING OPNS. P AND A
	MULTIPLE COMPL CASING/CEMEN	NT JOB
DOWNHOLE COMMINGLE		
OTHER:	□ OTHER	Plugback & Recomplete □ ⊠
OTHER:	OTHER d operations. (Clearly state all pertinent details, a	
OTHER: 13. Describe proposed or complete of starting any proposed work).	d operations. (Clearly state all pertinent details, a SEE RULE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete	d operations. (Clearly state all pertinent details, a SEE RULE 19.15.7.14 NMAC. For Multiple Co	nd give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete of starting any proposed work). proposed completion or recomp	d operations. (Clearly state all pertinent details, a SEE RULE 19.15.7.14 NMAC. For Multiple Colletion.	nd give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete of starting any proposed work). proposed completion or recomp 1/15/10 MIRU. ND wellhead & tree. N	d operations. (Clearly state all pertinent details, a SEE RULE 19.15.7.14 NMAC. For Multiple Colletion. NU BOP. Unset pkr & POOH.	nd give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete of starting any proposed work). proposed completion or recomp 1/15/10 MIRU. ND wellhead & tree. No 1/18/10 Set CIBP @ 12,150° w/35° cem	d operations. (Clearly state all pertinent details, a. SEE RULE 19.15.7.14 NMAC. For Multiple Collection. NU BOP. Unset pkr & POOH. nent. Perforate Atoka 11,936-42' (36).	nd give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete of starting any proposed work). proposed completion or recomp 1/15/10 MIRU. ND wellhead & tree. M 1/18/10 Set CIBP @ 12,150' w/35' cen 1/19/10 Acidized w/500 gal 7-1/2% Mo	d operations. (Clearly state all pertinent details, a. SEE RULE 19.15.7.14 NMAC. For Multiple Collection. NU BOP. Unset pkr & POOH. nent. Perforate Atoka 11,936-42' (36). perrow-acid & 40 balls.	nd give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete of starting any proposed work). proposed completion or recomp 1/15/10 MIRU. ND wellhead & tree. No 1/18/10 Set CIBP @ 12,150° w/35° cem	d operations. (Clearly state all pertinent details, a. SEE RULE 19.15.7.14 NMAC. For Multiple Collection. NU BOP. Unset pkr & POOH. nent. Perforate Atoka 11,936-42' (36). perrow-acid & 40 balls.	nd give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete of starting any proposed work). proposed completion or recomp 1/15/10 MIRU. ND wellhead & tree. No 1/18/10 Set CIBP @ 12,150' w/35' cem 1/19/10 Acidized w/500 gal 7-1/2% Mo 2/05/10 Fraced w/12,000 gal 60Q C02 for the complete of the complete o	d operations. (Clearly state all pertinent details, a. SEE RULE 19.15.7.14 NMAC. For Multiple Collection. NU BOP. Unset pkr & POOH. nent. Perforate Atoka 11,936-42' (36). perrow-acid & 40 balls.	nd give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete of starting any proposed work). proposed completion or recomp 1/15/10 MIRU. ND wellhead & tree. M 1/18/10 Set CIBP @ 12,150' w/35' cen 1/19/10 Acidized w/500 gal 7-1/2% Mo	d operations. (Clearly state all pertinent details, a. SEE RULE 19.15.7.14 NMAC. For Multiple Collection. NU BOP. Unset pkr & POOH. nent. Perforate Atoka 11,936-42' (36). perrow-acid & 40 balls.	nd give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete of starting any proposed work). proposed completion or recomp 1/15/10 MIRU. ND wellhead & tree. No 1/18/10 Set CIBP @ 12,150' w/35' cem 1/19/10 Acidized w/500 gal 7-1/2% Mo 2/05/10 Fraced w/12,000 gal 60Q C02 for the complete of the complete o	d operations. (Clearly state all pertinent details, a. SEE RULE 19.15.7.14 NMAC. For Multiple Collection. NU BOP. Unset pkr & POOH. nent. Perforate Atoka 11,936-42' (36). perrow-acid & 40 balls.	nd give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete of starting any proposed work). proposed completion or recomp 1/15/10 MIRU. ND wellhead & tree. No 1/18/10 Set CIBP @ 12,150' w/35' cem 1/19/10 Acidized w/500 gal 7-1/2% Mo 2/05/10 Fraced w/12,000 gal 60Q C02 for the complete of the complete o	d operations. (Clearly state all pertinent details, a. SEE RULE 19.15.7.14 NMAC. For Multiple Collection. NU BOP. Unset pkr & POOH. nent. Perforate Atoka 11,936-42' (36). perrow-acid & 40 balls.	nd give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete of starting any proposed work). proposed completion or recomp 1/15/10 MIRU. ND wellhead & tree. No 1/18/10 Set CIBP @ 12,150' w/35' cem 1/19/10 Acidized w/500 gal 7-1/2% Mo 2/05/10 Fraced w/12,000 gal 60Q C02 for the complete of the complete o	d operations. (Clearly state all pertinent details, a. SEE RULE 19.15.7.14 NMAC. For Multiple Collection. NU BOP. Unset pkr & POOH. nent. Perforate Atoka 11,936-42' (36). perrow-acid & 40 balls.	nd give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete of starting any proposed work). proposed completion or recomp 1/15/10 MIRU. ND wellhead & tree. No 1/18/10 Set CIBP @ 12,150' w/35' cem 1/19/10 Acidized w/500 gal 7-1/2% Mo 2/05/10 Fraced w/12,000 gal 60Q C02 for the complete of the complete o	d operations. (Clearly state all pertinent details, a. SEE RULE 19.15.7.14 NMAC. For Multiple Collection. NU BOP. Unset pkr & POOH. nent. Perforate Atoka 11,936-42' (36). perrow-acid & 40 balls.	nd give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete of starting any proposed work). proposed completion or recomp 1/15/10 MIRU. ND wellhead & tree. No 1/18/10 Set CIBP @ 12,150' w/35' cem 1/19/10 Acidized w/500 gal 7-1/2% Mo 2/05/10 Fraced w/12,000 gal 60Q C02 for the complete of the complete o	d operations. (Clearly state all pertinent details, a. SEE RULE 19.15.7.14 NMAC. For Multiple Collection. NU BOP. Unset pkr & POOH. nent. Perforate Atoka 11,936-42' (36). perrow-acid & 40 balls.	nd give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete of starting any proposed work). proposed completion or recomp 1/15/10 MIRU. ND wellhead & tree. N 1/18/10 Set CIBP @ 12,150' w/35' cem 1/19/10 Acidized w/500 gal 7-1/2% Mo 2/05/10 Fraced w/12,000 gal 60Q C02 f	d operations. (Clearly state all pertinent details, a. SEE RULE 19.15.7.14 NMAC. For Multiple Collection. NU BOP. Unset pkr & POOH. nent. Perforate Atoka 11,936-42' (36). orrow-acid & 40 balls. foam & 12,000# 20/40 Sinterball.	nd give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete of starting any proposed work). proposed completion or recomp 1/15/10 MIRU. ND wellhead & tree. N 1/18/10 Set CIBP @ 12,150' w/35' cem 1/19/10 Acidized w/500 gal 7-1/2% Mo 2/05/10 Fraced w/12,000 gal 60Q C02 f	d operations. (Clearly state all pertinent details, a. SEE RULE 19.15.7.14 NMAC. For Multiple Collection. NU BOP. Unset pkr & POOH. nent. Perforate Atoka 11,936-42' (36). orrow-acid & 40 balls. foam & 12,000# 20/40 Sinterball.	nd give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completee of starting any proposed work). proposed completion or recomp 1/15/10 MIRU. ND wellhead & tree. N 1/18/10 Set CIBP @ 12,150' w/35' cem 1/19/10 Acidized w/500 gal 7-1/2% Mc 2/05/10 Fraced w/12,000 gal 60Q C02 f 2-7/8" tubing and packer @ 11,647' Spud Date:	d operations. (Clearly state all pertinent details, a. SEE RULE 19.15.7.14 NMAC. For Multiple Collection. NU BOP. Unset pkr & POOH. nent. Perforate Atoka 11,936-42' (36). orrow-acid & 40 balls. foam & 12,000# 20/40 Sinterball.	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or completee of starting any proposed work). proposed completion or recomp 1/15/10 MIRU. ND wellhead & tree. N 1/18/10 Set CIBP @ 12,150' w/35' cem 1/19/10 Acidized w/500 gal 7-1/2% Mc 2/05/10 Fraced w/12,000 gal 60Q C02 f 2-7/8" tubing and packer @ 11,647' Spud Date:	d operations. (Clearly state all pertinent details, a. SEE RULE 19.15.7.14 NMAC. For Multiple Collection. NU BOP. Unset pkr & POOH. nent. Perforate Atoka 11,936-42' (36). orrow-acid & 40 balls. foam & 12,000# 20/40 Sinterball. Rig Release Date:	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or complete of starting any proposed work). proposed completion or recomp 1/15/10 MIRU. ND wellhead & tree. In 1/18/10 Set CIBP @ 12,150' w/35' cem 1/19/10 Acidized w/500 gal 7-1/2% Mod 2/05/10 Fraced w/12,000 gal 60Q C02 for 2-7/8" tubing and packer @ 11,647' Spud Date:	d operations. (Clearly state all pertinent details, a. SEE RULE 19.15.7.14 NMAC. For Multiple Collection. NU BOP. Unset pkr & POOH. nent. Perforate Atoka 11,936-42' (36). borrow-acid & 40 balls. foam & 12,000# 20/40 Sinterball. Rig Release Date:	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of ge and belief.
OTHER: 13. Describe proposed or completee of starting any proposed work). proposed completion or recomp 1/15/10 MIRU. ND wellhead & tree. N 1/18/10 Set CIBP @ 12,150' w/35' cem 1/19/10 Acidized w/500 gal 7-1/2% Mc 2/05/10 Fraced w/12,000 gal 60Q C02 f 2-7/8" tubing and packer @ 11,647' Spud Date:	d operations. (Clearly state all pertinent details, a. SEE RULE 19.15.7.14 NMAC. For Multiple Collection. NU BOP. Unset pkr & POOH. nent. Perforate Atoka 11,936-42' (36). borrow-acid & 40 balls. foam & 12,000# 20/40 Sinterball. Rig Release Date:	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
OTHER: 13. Describe proposed or complete of starting any proposed work). proposed completion or recomp 1/15/10 MIRU. ND wellhead & tree. M. 1/18/10 Set CIBP @ 12,150' w/35' cen. 1/19/10 Acidized w/500 gal 7-1/2% Mc. 2/05/10 Fraced w/12,000 gal 60Q C02 f. 2-7/8" tubing and packer @ 11,647' Spud Date: I hereby certify that the information above. SIGNATURE	d operations. (Clearly state all pertinent details, a. SEE RULE 19.15.7.14 NMAC. For Multiple Cooletion. NU BOP. Unset pkr & POOH. nent. Perforate Atoka 11,936-42' (36). orrow-acid & 40 balls. foam & 12,000# 20/40 Sinterball. Rig Release Date: ve is true and complete to the best of my knowled. TITLE Regulatory Comp	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of ge and belief. DATE
OTHER: 13. Describe proposed or complete of starting any proposed work). proposed completion or recomp 1/15/10 MIRU. ND wellhead & tree. In 1/18/10 Set CIBP @ 12,150' w/35' cem 1/19/10 Acidized w/500 gal 7-1/2% Mod 2/05/10 Fraced w/12,000 gal 60Q C02 for 2-7/8" tubing and packer @ 11,647' Spud Date:	d operations. (Clearly state all pertinent details, a. SEE RULE 19.15.7.14 NMAC. For Multiple Cooletion. NU BOP. Unset pkr & POOH. nent. Perforate Atoka 11,936-42' (36). orrow-acid & 40 balls. foam & 12,000# 20/40 Sinterball. Rig Release Date: ve is true and complete to the best of my knowled. TITLE Regulatory Comp	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of ge and belief. DATE
OTHER: 13. Describe proposed or completee of starting any proposed work). proposed completion or recomp 1/15/10 MIRU. ND wellhead & tree. In 1/18/10 Set CIBP @ 12,150' w/35' cent 1/19/10 Acidized w/500 gal 7-1/2% Mcc 2/05/10 Fraced w/12,000 gal 60Q C02 for 2-7/8" tubing and packer @ 11,647' Spud Date: I hereby certify that the information about the starting of the proposed for print name Allison Barton.	d operations. (Clearly state all pertinent details, a. SEE RULE 19.15.7.14 NMAC. For Multiple Cooletion. NU BOP. Unset pkr & POOH. nent. Perforate Atoka 11,936-42' (36). orrow-acid & 40 balls. foam & 12,000# 20/40 Sinterball. Rig Release Date: ve is true and complete to the best of my knowled. TITLE Regulatory Comp	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of ge and belief. DATE
OTHER: 13. Describe proposed or complete of starting any proposed work). proposed completion or recomp 1/15/10 MIRU. ND wellhead & tree. N 1/18/10 Set CIBP @ 12,150' w/35' cent 1/19/10 Acidized w/500 gal 7-1/2% Mc 2/05/10 Fraced w/12,000 gal 60Q C02 for section of the complete of	Rig Release Date: Rig Release Date: Rig Release Date: TITLE Regulatory Comp E-mail address:abarton@yatespetrole	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of ge and belief. DATE
OTHER: 13. Describe proposed or complete of starting any proposed work). proposed completion or recomp 1/15/10 MIRU. ND wellhead & tree. N 1/18/10 Set CIBP @ 12,150' w/35' cent 1/19/10 Acidized w/500 gal 7-1/2% Mc 2/05/10 Fraced w/12,000 gal 60Q C02 for section of the complete of	d operations. (Clearly state all pertinent details, a. SEE RULE 19.15.7.14 NMAC. For Multiple Cooletion. NU BOP. Unset pkr & POOH. nent. Perforate Atoka 11,936-42' (36). orrow-acid & 40 balls. foam & 12,000# 20/40 Sinterball. Rig Release Date: ve is true and complete to the best of my knowled. TITLE Regulatory Comp	nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of ge and belief. DATE