

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103

May 27, 2004

RECEIVED
MAR 03 2010
HOBBSOCD

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.

30-025-38571 ✓

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

Pevehouse 8 ✓

8. Well No. 1 ✓

9. OGRID Number

161485 ✓

10. Pool name or Wildcat

Morrow

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other

2. Name of Operator

Lone Star Oil & Gas, Inc. ✓

3. Address of Operator

PO Box 2696, Midland, TX 79702

4. Well Location

Unit Letter **P** : **660** feet from the **South** line and **900** feet from the **East** line
Section **8** Township **24-S** Range **36-E** NMPM County **Lea** ✓

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3409 RKB

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. MIRU rig and cementing equipment.

2. NU BOP. POH w/ production tbg. RIH and tag existing plug @ 9124'. POH to 8650'. Spot 20 sx @ 8650-8550. WOC and tag

3. Spot 25 sx plug @ 6500-6350.

4. Spot 45 sx plug @ 5050-4850.

5. Spot 45 sx plug @ 2500-2350.

6. Spot 45 sx plug @ 600-450.

7. Spot 10 sx surface plug. 205K

8. Cut off well head and weld on Dry Hole Marker.

SPOT 20 SXCMT WOC-TAG (5528-5430)
SPOT 20 SXCMT (5025-4925) WOC TAG
SPOT 40 SXCMT (1360-1260)The Oil Conservation Division **Must be notified**
24 hours prior to the beginning of plugging operationsI hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.SIGNATURE Ben Montgomery TITLE Agent DATE 03/02/10Type or print name Ben MontgomeryE-mail address: ben@benandassociates.com Telephone No. 4325807161

For State Use Only

APPROVED BY [Signature] TITLE STAFF MGR DATE 3-16-10

Conditions of Approval (if any):

Pevehouse 8-1

