Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resources	October 13, 2009
1625 N. French Dr., Hobbs, NM 88240 District II		WELL API NO. / 30-025-26381
1301 W. Grand Ave., Artesia	CONSERVATION DIVISION 1220 South St. Francis Dr.	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd. Aztec. NM 87410	1220 South St. Francis Dr.	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV MAK 1	9 2010 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S St. Francis Dr., Santa Fe, NM 87505	SOCO	B-1840-1
SUNDRY NOT	ICES AND REPORTS ON WELLS OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
	ICATION FOR PERMIT" (FORM C-101) FOR SUCH	East Vacuum GB/SA Unit Tract 2739
1. Type of Well: Oil Well	Gas Well Other	8. Well Number 6
2. Name of Operator		9. OGRID Number 217817
ConocoPhillips Company		10. Pool name or Wildcat
3. Address of Operator P.O. Box 51810 Midland, Tx 797	10	Vacuum GB/SA
4. Well Location	1310 South	1330 East
Unit Letter	teet from the line and _	teet from theline
Section 27	Township 17S Range 35E	NMPM Lea County
	11. Elevation (Show whether DR, RKB, RT, GR, e 3929 GL	(c.)
12 (1 1	Annual Color De la La Parta Niction a CNI d'a	Donata College Date
	Appropriate Box to Indicate Nature of Notic	-
		BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK		PRK ☐ ALTERING CASING ☐ RILLING OPNS.☐ P AND A ☐
TEMPORARILY ABANDON DULL OR ALTER CASING	│ CHANGE PLANS │ COMMENCE □ │ MULTIPLE COMPL │ CASING/CEME	-
DOWNHOLE COMMINGLE		
OTHER:	□ OTHER:	TA X
	OTHER: pleted operations. (Clearly state all pertinent details,	and give pertinent dates, including estimated date
13. Describe proposed or com of starting any proposed w	pleted operations. (Clearly state all pertinent details, york). SEE RULE 19.15.7.14 NMAC. For Multiple (and give pertinent dates, including estimated date
13. Describe proposed or com	pleted operations. (Clearly state all pertinent details, york). SEE RULE 19.15.7.14 NMAC. For Multiple (and give pertinent dates, including estimated date
13. Describe proposed or com of starting any proposed w proposed completion or re	pleted operations. (Clearly state all pertinent details, york). SEE RULE 19.15.7.14 NMAC. For Multiple (and give pertinent dates, including estimated date
13. Describe proposed or com of starting any proposed w proposed completion or re Workover 2/22/2010-3/1/2010	pleted operations. (Clearly state all pertinent details, york). SEE RULE 19.15.7.14 NMAC. For Multiple (and give pertinent dates, including estimated date completions: Attach wellbore diagram of
13. Describe proposed or com of starting any proposed w proposed completion or re Workover 2/22/2010-3/1/2010	pleted operations. (Clearly state all pertinent details, york). SEE RULE 19.15.7.14 NMAC. For Multiple (completion. BP and set at 4349. Load casing and pressure tested.	and give pertinent dates, including estimated date completions: Attach wellbore diagram of
13. Describe proposed or com of starting any proposed w proposed completion or re Workover 2/22/2010-3/1/2010 MIRU. Clean out well. RIH w/CIE	pleted operations. (Clearly state all pertinent details, york). SEE RULE 19.15.7.14 NMAC. For Multiple (completion. BP and set at 4349. Load casing and pressure tested.	and give pertinent dates, including estimated date completions: Attach wellbore diagram of
13. Describe proposed or com of starting any proposed w proposed completion or re Workover 2/22/2010-3/1/2010 MIRU. Clean out well. RIH w/CIE	pleted operations. (Clearly state all pertinent details, york). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. BP and set at 4349. Load casing and pressure tested. Completion.	and give pertinent dates, including estimated date completions: Attach wellbore diagram of Good test. COP respectfully request TA status for
13. Describe proposed or com of starting any proposed w proposed completion or re Workover 2/22/2010-3/1/2010 MIRU. Clean out well. RIH w/CIE	pleted operations. (Clearly state all pertinent details, york). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. BP and set at 4349. Load casing and pressure tested. Completion.	and give pertinent dates, including estimated date completions: Attach wellbore diagram of Good test. COP respectfully request TA status for
13. Describe proposed or com of starting any proposed w proposed completion or re Workover 2/22/2010-3/1/2010 MIRU. Clean out well. RIH w/CIE	pleted operations. (Clearly state all pertinent details, york). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. BP and set at 4349. Load casing and pressure tested. Completion.	and give pertinent dates, including estimated date completions: Attach wellbore diagram of
13. Describe proposed or com of starting any proposed w proposed completion or re Workover 2/22/2010-3/1/2010 MIRU. Clean out well. RIH w/CIE	pleted operations. (Clearly state all pertinent details, york). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. BP and set at 4349. Load casing and pressure tested. Completion.	and give pertinent dates, including estimated date completions: Attach wellbore diagram of Good test. COP respectfully request TA status for
13. Describe proposed or com of starting any proposed w proposed completion or re Workover 2/22/2010-3/1/2010 MIRU. Clean out well. RIH w/CIE	pleted operations. (Clearly state all pertinent details, york). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. BP and set at 4349. Load casing and pressure tested. Completion.	and give pertinent dates, including estimated date completions: Attach wellbore diagram of Good test. COP respectfully request TA status for
13. Describe proposed or com of starting any proposed w proposed completion or re Workover 2/22/2010-3/1/2010 MIRU. Clean out well. RIH w/CIE	pleted operations. (Clearly state all pertinent details, york). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. BP and set at 4349. Load casing and pressure tested. Completion.	and give pertinent dates, including estimated date completions: Attach wellbore diagram of Good test. COP respectfully request TA status for
13. Describe proposed or com of starting any proposed w proposed completion or re Workover 2/22/2010-3/1/2010 MIRU. Clean out well. RIH w/CIE	pleted operations. (Clearly state all pertinent details, york). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. BP and set at 4349. Load casing and pressure tested. Completion.	and give pertinent dates, including estimated date completions: Attach wellbore diagram of Good test. COP respectfully request TA status for
13. Describe proposed or com of starting any proposed w proposed completion or re Workover 2/22/2010-3/1/2010 MIRU. Clean out well. RIH w/CIE a time period up to 5 years. Chart is	pleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. BP and set at 4349. Load casing and pressure tested. Completion. This Approval of Abandonment	and give pertinent dates, including estimated date completions: Attach wellbore diagram of Good test. COP respectfully request TA status for
13. Describe proposed or com of starting any proposed w proposed completion or re Workover 2/22/2010-3/1/2010 MIRU. Clean out well. RIH w/CIE a time period up to 5 years. Chart i	pleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. BP and set at 4349. Load casing and pressure tested. Completion. This Approval of Abandonment is a Rig Release Date:	and give pertinent dates, including estimated date completions: Attach wellbore diagram of Good test. COP respectfully request TA status for the Temporary 3-/9-2015 Expires
13. Describe proposed or com of starting any proposed w proposed completion or re Workover 2/22/2010-3/1/2010 MIRU. Clean out well. RIH w/CIE a time period up to 5 years. Chart i	pleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. BP and set at 4349. Load casing and pressure tested. Completion. This Approval of Abandonment	and give pertinent dates, including estimated date completions: Attach wellbore diagram of Good test. COP respectfully request TA status for the Temporary 3-/9-2015 Expires
13. Describe proposed or com of starting any proposed w proposed completion or re Workover 2/22/2010-3/1/2010 MIRU. Clean out well. RIH w/CIE a time period up to 5 years. Chart i	pleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. BP and set at 4349. Load casing and pressure tested. Complete attached. This Approval of Abandonment is above is true and complete to the best of my knowled.	and give pertinent dates, including estimated date completions: Attach wellbore diagram of good test. COP respectfully request TA status for expires
13. Describe proposed or com of starting any proposed w proposed completion or re Workover 2/22/2010-3/1/2010 MIRU. Clean out well. RIH w/CIE a time period up to 5 years. Chart i	pleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. BP and set at 4349. Load casing and pressure tested. Complete attached. This Approval Complete Abandonment is above is true and complete to the best of my knowled. TITLE Sr. Regulatory St.	and give pertinent dates, including estimated date completions: Attach wellbore diagram of good test. COP respectfully request TA status for Expires
13. Describe proposed or com of starting any proposed w proposed completion or re Workover 2/22/2010-3/1/2010 MIRU. Clean out well. RIH w/CIE a time period up to 5 years. Chart is Spud Date: I hereby certify that the information SIGNATURE Type or print name Donna Will	pleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. BP and set at 4349. Load casing and pressure tested. Completions attached. This Approval Complete Abandonment is above is true and complete to the best of my knowled above is true and complete to the best of my knowled Donna.J.W.	and give pertinent dates, including estimated date completions: Attach wellbore diagram of Good test. COP respectfully request TA status for Expires
13. Describe proposed or com of starting any proposed w proposed completion or re Workover 2/22/2010-3/1/2010 MIRU. Clean out well. RIH w/CIE a time period up to 5 years. Chart i	Pleted operations. (Clearly state all pertinent details, work). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. BP and set at 4349. Load casing and pressure tested. (Is attached.) This Approval of Abandonment is above is true and complete to the best of my knowled. TITLE Sr. Regulatory of Donna.J.W. Liams E-mail address: Conocophi.	and give pertinent dates, including estimated date completions: Attach wellbore diagram of good test. COP respectfully request TA status for Expires
13. Describe proposed or com of starting any proposed w proposed completion or re Workover 2/22/2010-3/1/2010 MIRU. Clean out well. RIH w/CIE a time period up to 5 years. Chart is Spud Date: I hereby certify that the information SIGNATURE Type or print name Donna Will	pleted operations. (Clearly state all pertinent details, york). SEE RULE 19.15.7.14 NMAC. For Multiple Completion. BP and set at 4349. Load casing and pressure tested. Complete is attached. This Approval of Abandonment is above is true and complete to the best of my knowled above is true and complete to the best of my knowled Donna.J.W.	and give pertinent dates, including estimated date completions: Attach wellbore diagram of Good test. COP respectfully request TA status for Expires

