Submit's Copies To Appropriate District State of New Mexico Office Energy Minerals and Natural Resources District 1 1625 N. French Dr., Hobbs, NM RECEIVED District 11 1625 N. French Dr., Hobbs, NM RECEIVED			Form C-103	
		WELL API NO.	June 19, 2008	
District III		<u>30-025-29614</u>		
		5. Indicate Type of Lease STATE X F	YEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1230 S at Fernand Pr. Septe Fe NM 87505		6. State Oil & Gas Lease N		
1220 S. St. Francis Dr., Santa Fe, NM		0. State On & Sus Ecuse i	10.	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Ag Eunice Monument South		
1. Type of Well: Oil Well Gas Well Other Injection		8. Well Number 189	189 -	
2. Name of Operator		9. OGRID Number		
XTO Energy, Inc.		005380 10. Pool name or Wildcat		
3. Address of Operator 200 N. Loraine, Ste. 800 Midland, TX 79701		Eunice Monument; Grayburg-San Andres		
4. Well Location				
Unit Letter <u>B</u> : 760' feet from the <u>North</u> line and <u>1780'</u> feet from the <u>East</u> line				
Section 6 Township 215		NMPM Coun	nty Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
		BSEQUENT REPORT	OF:	
PERFORM REMEDIAL WORK D PLUG AND ABANDON REMEDIAL WORK				
		LING OPNS. 🔲 🛛 P AN	ID A	
OTHER: Omt Sqz & Coil Tbg Clean Out	OTHER:			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
1. MI & rack 4000' of 2-7/8" N-80 WS. Unset pkr & POOH with IPC injection tbg. RIH w/4-3/4" bit on 2-7/8"				
WS. RIH & tag for fill. RIH w/CIBP & set @3770'. POOH. RIH w/CICR & set @3600'. 2. RIH w/stinger & 2-7/8" WS. Circulate TCA w/fresh wtr. Sting into CICR Establish an injection rate with				
fresh wtr & sqz perfs 3700'-3765'. Displace cement below CICR. If perfs sqz off before cmt clears CICR				
sting out of CICR & reverse.				
3. RIH w/bit, drill collars & 2-7/8" WS. DO CICR & cmt. Circulate. Test sqz. DO CIBP & push to bottom. Circulate. POOH LD WS, drill collars, & bit. RDMO.				
Procedure Cont'd. on next page.				
Spud Date: Rig	Release Date:			
I hereby certify that the information above is true and complete	to the best of my knowled	lge and belief.		
they to blaid				
SIGNATURE Ching Nava		tory Analyst DATE	2/19/10	
Type or print name Kristy Ward	kristy_ward@x _E-mail address:		IE <u>432-620-6740</u>	
For State Use Only				
APPROVED BY Complex TITLE STAFF MGR DATE 3-22-10				
Conditions of Approval (if any): Condition of Approval: Notify OCD Hobbs				
office 24 hours prior to running MIT Test & Chart.				

EMSU #189 WIW Cmt Sqz & Coil Tbg. Clean Out Cont'd.

٦

- 4. RIH w/notch collar on 2-7/8" WS & tag. PUH to 3870'. It will take 14.2461 lbs/ft of 20/40 mesh sand. Based on new PBTD, drop 14.2461 lbs of 20/40 mesh sand per foot to plug back to a depth of 3935' with sand.
- 5. Spot 1.5 sx of Class "C" cmt w/2% CaCl on top of sand. New PBTD s/b 3920'.
- 6. RIH w/5-1/2" treating pkr on 2-7/8" WS. Set pkr @ 3770'.
- 7. RIH w/1.250" sonic hammer on 1.250" coil tbg to 3778'. Wash down through perfs from 3778' to 3909' w/9 ppg brine. Wash perfs w/3 passes. Circulate bottoms up.
- 8. Spot 2 bbls 20% 90/10 acid @ 3909'. Reciprocate through perfs while acid washing with the backside closed in with 2500 gals 20% 90/10 acid. Displace coil tbg w/25 bbls brine water.
- 9. POOH. RDMO CTU. Swab back acid load. RD. Release pkr.
- 10. RIH w/5-1/2" injection pkr & on/off tool with 1.781" profile nipple on 2-3/8" IPC tbg. Set pkr @ 3640'. Pressure test TCA to 500 psig, then circulate w/pkr fluid.
- 11. Record pressure on chart for MIT. Establish injection rate. RDMO. RWTI.