

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103

May 27, 2004

RECEIVED
MAR 16 2010
HOBBSON

CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO.

30-025-37804

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Caudill 33

8. Well Number 1

9. OGRID Number 264748

10. Pool name or Wildcat
Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

Element Petroleum Operating, LLC

3. Address of Operator

P. O. Box 35888, Tulsa, OK 74153-0888

4. Well Location

Unit Letter M : 660 feet from the south line and 500 feet from the west line.
Section 33 Township 14S Range 36E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3934 GR

Pit or Below-grade Tank Application ☐ or Closure ☐Pit type Depth to Groundwater Distance from nearest fresh water well Distance from nearest surface water Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK

PLUG AND ABANDON ☒TEMPORARILY ABANDON ☐CHANGE PLANS ☐PULL OR ALTER CASING ☐MULTIPLE COMPL ☐OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐P AND A ☐CASING/CEMENT JOB ☐OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

The Oil Conservation Division **Must be notified****24 hours prior** to the beginning of plugging operations

1.) Circulate hole w/10 ppg mud.

2.) Cut & pull 5-1/2" casing @ +/- 6000'.

3.) Spot 100 sx @ +/- 6000'. ← STUG 50' inside - WOC - TAG

4.) Spot 100 sx @ 4900' WOC and tag.

5.) Spot 55 sx @ 1100'. ← PERF # SQ 55 SX - WOC - TAG


6.) Spot 55 sx @ 550' WOC and tag. PERF # SQ 55 SX - WOC - TAG

7.) Set 15 sx top plug.

8.) Install P&A marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE

TITLE Regulatory AdministratorDATE 03/11/10Type or print name Connie SwanE-mail address: CSSwan@elementpetro.com

Telephone No. (918) 621-6533

For State Use OnlyAPPROVED BY: TITLE STAFF memberDATE 4-6-10

Conditions of Approval (if any):