Submit 3 Copies

to Appropriate

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

District Office

DISTRICT I

P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OII	CONCER	VATION	DIVISION
		V /7 I I V/I V	

2040 Pacheco St. Santa Fe, NM 87505	WELL API NO. 30 - 025 - 36193 5. Indicate Type of Lease STATE X FEE 6. State Oil & Gas Lease No.				
REPORTS ON WELLS DRILL OR TO DEEPEN OR PLUG BACK TO A APPLICATION FOR PERMIT" CH PROPOSALS.) OTHER	7. Lease Name or Unit Agreement Name North Hobbs G/SA Unit				
	I a				

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					/. Lease Nam	7. Lease Name or Unit Agreement Name North Hobbs G/SA Unit			
1. Type of Well: OIL X	GAS WELL		OTHER						
2. Name of Operator						8. Well No.	•		
Occidental Permi	an Limited Pa	rtnership					549		
3. Address of Operator P.O. Box 4294. H	ouston. TX 7	7210-4294				9. Pool name Hobbs	or Wildcat : Grayburg - S	an Andres	
4. Well Location Unit Letter	I : 1802	_ Feet From The _	Sout	:h	Line and		_	ast Line	
Section	24	Township	18-S	Range	37-E	NMPM	Lea	County	
		10. Elevar	tion (Show w		RKB, RT, GR, e	tc.)			

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data **NOTICE OF INTENTION TO:** SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON **ALTERING CASING REMEDIAL WORK TEMPORARILY ABANDON** PLUG AND ABANDONMENT **CHANGE PLANS** COMMENCE DRILLING OPNS.

PULL OR ALTER CASING CASING TEST AND CEMENT JOB Run 5-1/2" Casing OTHER:

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/1/03: Run 109 jts. 5-1/2", 15.5#, J-55, LT&C casing with 12 centralizers and set at 4424'. Cement first stage with 250 sx. Premium Plus. Plug down and circulate 84 sx. to surface

Circulate 4 hours between stages. Cement second stage with 550 sx. Interfi 100 sx. Premium Plus (tail). Plug down and circulate 147 sx. to surface. N Cut off casing x install wellhead x rig down.	13	slips.	9303
Release drilling rig at 4:00 a.m., 4/2/03.	5/10/8/19202	VIEW SING	123450
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		45171119	
SIGNATURE	DATE	4/8/03	

TYPE OR PRINT NAME <u> Mark Stephens</u>

TELEPHONE NO.

OC FIELD REPRESENTATIVE IVSTAFF MANAGER

DATE