

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised May 08, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-11666
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Justis, V.H.
8. Well Number 002
9. OGRID Number 002175
10. Pool name or Wildcat Jalmat Tansill Yates 7 Rivers

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator Bettis, Boyle & Stovall	
3. Address of Operator P.O. Box 1240, Graham, TX 76450	
4. Well Location Unit Letter <u>D</u> : <u>370</u> feet from the <u>N</u> line and <u>420</u> feet from the <u>W</u> line Section <u>20</u> Township <u>25S</u> Range <u>37E</u> NMPM <u>Lea</u> County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3084 DF	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐


SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1) Notify OCD 24 hrs. prior to beginning P&A operations.
- 2) MIRU Pulling Unit.
- 3) Tag plug in hole @ 3000', set 25 sx of cement on top of plug.
- 4) Set 25 sx plug @ base of salt - 2700'.
- 5) Set 25 sx plug @ top of salt - 1030'.
- 6) Casing shoe @ 317', perf @ 367' & bring cement 50' on the outside & inside of casing & tag cement @ 267'.
- 7) Set 10 sx plug from 60' to surface.
- 8) Cut off well casing 4' below ground level & weld on plate.
- 9) Clean up location.

Estimated date to plug & abandon is April 19, 2004.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kim Ligon TITLE Regulatory Analyst DATE 1/27/04
Type or print name Kim Ligon Telephone No. 940-549-0780

(This space for State use)

APPROVED BY Hayden White TITLE OC FIELD REPRESENTATIVE II / STAFF MANAGER DATE JAN 30 2004
Conditions of approval, if any

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.