Form 3160-5 (April 2004) UNITED STATES DEPARTMENT OF THE INTERIOR D-HOBBS BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE- Other instructions on reverse side. 1. Type of Well Qil Well Gas Well Descrete Shacke/ford Oil Company				FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007 5. Lease Serial No. <i>NM NM 17238</i> 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No. 8. Well Name and No. <i>Tourfo Federal #3</i> 9. API Well No.							
						3a Address 3b. Phone			le area code)	30-	025-34728 1
						3510 n Ast Bdg B Ste. 100 432- 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			9789		Pool, or Exploratory Area
						330 FEL + 330 FSL V			1		r Parish, State
							OS R33E			Leg	1
	APPROPRIATE BOX(ES) T			REPORT, OR	OTHER DATA						
TYPE OF SUBMISSION		TY	TYPE OF ACTION								
Notice of Intent	Acidize	Deepen	Production (S	tart/Resume)	Water Shut-Off						
, -	Alter Casing	Fracture Treat			Well Integrity						
Subsequent Report	Change Plans	New Construction	Recomplete	handon	Other						
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposa								
determined that the site is re	See At	Haba 1	/								
	Jee M	/401270	-								
					APPROVED						
	ι,	R	CEIVED	9	MAY 3 0 2010						
			IN 04 2010		MAY 3 0 2010						
			BBSUCD		AMES A. AMOS						
		0 00 1									
		0 U C		4	SUPERVISOR-EPS						
14. I hereby certify that the f	oregoing is true and correct				SUPERVISOR-EPS						
14. I hereby certify that the f Name (Printed/Typed)	1/ 1			<u> </u>	SUPERVISOR-EPS						
Clay A	oregoing is true and correct	Title	OPenal	1042	SUPERVISOR-EPS						
	y R/A	Title Date	OPenal		SUPERVISOR-EPS						
Clay F	1/ 1	Title Date	OPenal		SUPERVISOR-EPS						

.

.

7. mi

Tonto Federal #3

<u>ء</u> د

Procedure of Recompletion to lower Delaware

- .
- 1. MIRU WELL SERVICING UNIT
- 2. POOH WITH RODS AND TBG
- 3. RIH W/BIT AND SCRAPER TO 8100 AND CIR W/2% KCL WTR
- 4. POOH W/ BIT AND SCRAPER
- 5. RU WIRELINE PERF WELL @ 8066 TO8090
- 6. RIH W/ PKR SET @ 7960 AND SWAB TEST
- 7. ACIDIZE WELL W/ 15% ACID TOTAL 2500 GALS W/ADD
- 8. SWAB WELL TO DETERMINE FRAC RATES
- 9. FRAC WELL W/ 60000 #SAND FLOWBACK
- 10. SWAB TEST
- **11. M PUT ON PRODUCTION**