RECEIVED

State of New Mexico

JUN 14 ZUNEnergy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE HOBBSOCD OIL CONSERVATION DIVISION	
DISTRICT I 1220 South St. Francis Dr.	WELL API NO.
1625 N. French Dr , Hobbs, NM 88240 Santa Fe, NM 87505	30-025-29098 ✓
<u>DISTRICT II</u>	5. Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 88210	STATE X FEE
DISTRICT III	6 State Oil & Gas Lease No
1000 Rio Brazos Rd, Aztec, NM 87410	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	Section 24
1. Type of Well:	8 Well No. 442
Oil Well Gas Well Other Injector	9. OGRID No. 157984
2. Name of Operator Occidental Permian Ltd.	9. OGRID 140. 13/984
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	
4 Well Location	
Unit Letter P: 1260 Feet From The South 200 F	eet From The East Line
Section 24 Township 18-S Range 37	-E NMPM Lea County
Section 24 Township 18-S Range 37	-E Millim Eea county
3662' GL	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
•••	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction N	naterial
12. Check Appropriate Box to Indicate Nature of Notice, Report, or	
NOTICE OF INTENTION TO:	SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING O	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING O	PNS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING O PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME	PNS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING O PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: Clean out/Acid Treat X OTHER:	PNS. PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMBER OTHER: Clean out/Acid Treat X OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent datails)	PNS. PLUG & ABANDONMENT ENT JOB es, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF CASING TEST AND CEME OTHER: Clean out/Acid Treat 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent data proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed	PNS. PLUG & ABANDONMENT ENT JOB es, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMBER OTHER: Clean out/Acid Treat X OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed I. Kill well. POOH w/injection equipment.	PNS. PLUG & ABANDONMENT ENT JOB es, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMBER OTHER: Clean out/Acid Treat X OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. Kill well. POOH w/injection equipment. 2. Clean out well to PBTD @4326'.	PNS. PLUG & ABANDONMENT ENT JOB es, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Clean out/Acid Treat Test Note That Test Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed I. Kill well. POOH w/injection equipment. 2. Clean out well to PBTD @4326'. 3. Acid treat w/2520 gal of 15% PAD acid.	PNS. PLUG & ABANDONMENT ENT JOB es, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Clean out/Acid Treat Test Note That Test Test and give pertinent data proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed I. Kill well. POOH w/injection equipment. 2. Clean out well to PBTD @4326'. 3. Acid treat w/2520 gal of 15% PAD acid. 4. Perform scale squeeze.	PNS. PLUG & ABANDONMENT ENT JOB es, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Clean out/Acid Treat Test Note That Test Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed I. Kill well. POOH w/injection equipment. 2. Clean out well to PBTD @4326'. 3. Acid treat w/2520 gal of 15% PAD acid.	PNS. PLUG & ABANDONMENT ENT JOB es, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Clean out/Acid Treat Test all pertinent details, and give pertinent data proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. Kill well. POOH w/injection equipment. 2. Clean out well to PBTD @4326'. 3. Acid treat w/2520 gal of 15% PAD acid. 4. Perform scale squeeze. 5. Run back in hole w/dual injection packers.	PNS. PLUG & ABANDONMENT ENT JOB es, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Clean out/Acid Treat X OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. Kill well. POOH w/injection equipment. 2. Clean out well to PBTD @4326'. 3. Acid treat w/2520 gal of 15% PAD acid. 4. Perform scale squeeze. 5. Run back in hole w/dual injection packers. 6. Test casing and chart for the NMOCD.	PNS. PLUG & ABANDONMENT ENT JOB es, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENTED TO CASING TEST AND CEM	PNS. PLUG & ABANDONMENT ENT JOB es, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Clean out/Acid Treat X OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. Kill well. POOH w/injection equipment. 2. Clean out well to PBTD @4326'. 3. Acid treat w/2520 gal of 15% PAD acid. 4. Perform scale squeeze. 5. Run back in hole w/dual injection packers. 6. Test casing and chart for the NMOCD.	PNS. PLUG & ABANDONMENT ENT JOB es, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENTED TO CASING TEST AND CEM	PNS. PLUG & ABANDONMENT ENT JOB es, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENTED THER: Clean out/Acid Treat X OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent data proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. Kill well. POOH w/injection equipment. 2. Clean out well to PBTD @4326'. 3. Acid treat w/2520 gal of 15% PAD acid. 4. Perform scale squeeze. 5. Run back in hole w/dual injection packers. 6. Test casing and chart for the NMOCD. 7. Return well to injection.	PNS. PLUG & ABANDONMENT ENT JOB es, including estimated date of starting any discompletion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENTED THER: Clean out/Acid Treat X OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent data proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. Kill well. POOH w/injection equipment. 2. Clean out well to PBTD @4326'. 3. Acid treat w/2520 gal of 15% PAD acid. 4. Perform scale squeeze. 5. Run back in hole w/dual injection packers. 6. Test casing and chart for the NMOCD. 7. Return well to injection.	PNS. PLUG & ABANDONMENT ENT JOB es, including estimated date of starting any discompletion or recompletion. fy that any pit or below-grade tank has been/will be
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENTED THER: Clean out/Acid Treat X OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent data proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. Kill well. POOH w/injection equipment. 2. Clean out well to PBTD @4326'. 3. Acid treat w/2520 gal of 15% PAD acid. 4. Perform scale squeeze. 5. Run back in hole w/dual injection packers. 6. Test casing and chart for the NMOCD. 7. Return well to injection.	PNS. PLUG & ABANDONMENT ENT JOB es, including estimated date of starting any discompletion or recompletion. fy that any pit or below-grade tank has been/will be
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENTER: Clean out/Acid Treat X OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent data proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. Kill well. POOH w/injection equipment. 2. Clean out well to PBTD @4326'. 3. Acid treat w/2520 gal of 15% PAD acid. 4. Perform scale squeeze. 5. Run back in hole w/dual injection packers. 6. Test casing and chart for the NMOCD. 7. Return well to injection. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certificonstructed or closed according to NMOCD guidelines , a general permit or an (attached) alternation plan	PNS. PLUG & ABANDONMENT es, including estimated date of starting any discompletion or recompletion. fy that any pit or below-grade tank has been/will be live OCD-approved
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING O PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: Clean out/Acid Treat 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dat proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed. 1. Kill well. POOH w/injection equipment. 2. Clean out well to PBTD @4326'. 3. Acid treat w/2520 gal of 15% PAD acid. 4. Perform scale squeeze. 5. Run back in hole w/dual injection packers. 6. Test casing and chart for the NMOCD. 7. Return well to injection. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certificonstructed or closed according to NMOCD guidelines agency agency or an (attached) alternation plan. SIGNATURE COMMENCE DRILLING OCCUMENTS. CASING TEST AND CEMENTS. CHANGE PLANS OF THE STAND CEMENTS. Attach wellbore diagram of proposed. 1. Kill well. POOH w/injection equipment. 2. Clean out well to PBTD @4326'. 3. Acid treat w/2520 gal of 15% PAD acid. 4. Perform scale squeeze. 5. Run back in hole w/dual injection packers. 6. Test casing and chart for the NMOCD. 7. Return well to injection. Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certification and the proposed works are proposed works. Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certification and the proposed works are proposed works. Thereby certify that the information above is true and complete to the best of my knowledge and belief. I further certification and the proposed works are proposed works. Administration of the proposed works are proposed works and the proposed works are proposed works. Administration of the proposed works are proposed works and the proposed works are proposed work	PNS. PLUG & ABANDONMENT es, including estimated date of starting any discompletion or recompletion. Ty that any pit or below-grade tank has been/will be live OCD-approved The Associate DATE 06/10/2010
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING O PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: Clean out/Acid Treat X OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dat proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed I. Kill well. POOH w/injection equipment. 2. Clean out well to PBTD @4326'. 3. Acid treat w/2520 gal of 15% PAD acid. 4. Perform scale squeeze. 5. Run back in hole w/dual injection packers. 6. Test casing and chart for the NMOCD. 7. Return well to injection. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certificonstructed or closed according to NMOCD guidelines , a general permit or an (attached) alternation plan SIGNATURE TITLE Administrative TYPE OR PRINT NAME Mendy A Johnson E-mail address: mendy johnson@oxy.co	PNS. PLUG & ABANDONMENT es, including estimated date of starting any decompletion or recompletion. by that any pit or below-grade tank has been/will be live OCD-approved the Associate DATE 06/10/2010 TELEPHONE NO. 806-592-6280
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENTH OTHER: Clean out/Acid Treat X OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent data proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. Kill well. POOH w/injection equipment. 2. Clean out well to PBTD @4326'. 3. Acid treat w/2520 gal of 15% PAD acid. 4. Perform scale squeeze. 5. Run back in hole w/dual injection packers. 6. Test casing and chart for the NMOCD. 7. Return well to injection. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certificonstructed or closed according to NMOCD guidelines agency agency or an (attached) alternation plan SIGNATURE TITLE Administrative TYPE OR PRINT NAME Mendy A Johnson E-mail address: mendy johnson@oxy.co	PNS. PLUG & ABANDONMENT es, including estimated date of starting any decompletion or recompletion. Ty that any pit or below-grade tank has been/will be live OCD-approved The Associate DATE 06/10/2010 TELEPHONE NO. 806-592-6280
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING O PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER: Clean out/Acid Treat X OTHER: 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dat proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed. 1. Kill well. POOH w/injection equipment. 2. Clean out well to PBTD @4326'. 3. Acid treat w/2520 gal of 15% PAD acid. 4. Perform scale squeeze. 5. Run back in hole w/dual injection packers. 6. Test casing and chart for the NMOCD. 7. Return well to injection. 1 hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines a general permit or an (attached) alternation plan SIGNATURE TITLE Administrative mendy johnson@oxy.co For State Use Only	PNS. PLUG & ABANDONMENT es, including estimated date of starting any discompletion or recompletion. Ty that any pit or below-grade tank has been/will be live OCD-approved The Associate DATE 06/10/2010