## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE RECEIVED ONSERVATION DIVISION	
DISTRICT I 1220 South St. Francis Dr.	WELL API NO
1625 N. French Dr., Hobbs, NM 88240  JUN 28 2010  Santa Fe, NM 87505	30-025-28942
<u>BISTINICI II</u>	5. Indicate Type of Lease  STATE X FEE
1301 W. Grand Ave, Artesia, NM 88210  DISTRICT III  HOBBSOCD	6. State Oil & Gas Lease No
DISTRICT III 1000 Rto Brazos Rd, Aztec, NM 87410	o. State on a gas bease no
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	Section 30
1. Type of Well	8. Well No. 233
Oil Well Gas Well Other Injector  2. Name of Operator	9. OGRID No. 157984
Occidental Permian Ltd.	]
3. Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	
	et From The West Line
Unit Letter K: 2455 Feet From The South 1480 Feet	et From The West Line
Section 30 Township 18-S Range 38-	E NMPM Lea County
11 Elevation (Show whether DF, RKB, RT GR, etc.) 3666' KB	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Ma	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or NOTICE OF INTENTION TO: SUB	Other Data SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF	ALTERING CASING PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEI	ALTERING CASING PLUG & ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER Clean out/Acid treat X OTHER:	ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER Clean out/Acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date.	ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB s, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME OTHER Clean out/Acid treat X OTHER:	ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB s, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMES OTHER Clean out/Acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed	ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB s, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMES OTHER Clean out/Acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. Kill well.	ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB s, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMES OTHER Clean out/Acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed	ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB s, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMES OTHER Clean out/Acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. Kill well. 2. RU coiled tubing unit. 3. Clean out to 4300'. 4. Acid treat w/2500 gal of 15% NEFE HCL acid	ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB s, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME!  OTHER Clean out/Acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date: proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. Kill well. 2. RU coiled tubing unit. 3. Clean out to 4300'. 4. Acid treat w/2500 gal of 15% NEFE HCL acid 5. RD coiled tubing unit.	ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB s, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME!  OTHER Clean out/Acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date: proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. Kill well. 2. RU coiled tubing unit. 3. Clean out to 4300'. 4. Acid treat w/2500 gal of 15% NEFE HCL acid 5. RD coiled tubing unit. 6. RIH w/injection equipment.	ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB s, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME!  OTHER Clean out/Acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date: proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. Kill well. 2. RU coiled tubing unit. 3. Clean out to 4300'. 4. Acid treat w/2500 gal of 15% NEFE HCL acid 5. RD coiled tubing unit.	ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB s, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME!  OTHER Clean out/Acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date: proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. Kill well. 2. RU coiled tubing unit. 3. Clean out to 4300'. 4. Acid treat w/2500 gal of 15% NEFE HCL acid 5. RD coiled tubing unit. 6. RIH w/injection equipment. 7. Test casing and chart for the NMOCD.	ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB s, including estimated date of starting any
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEROTHER Clean out/Acid treat To THER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. Kill well. 2. RU coiled tubing unit. 3. Clean out to 4300'. 4. Acid treat w/2500 gal of 15% NEFE HCL acid 5. RD coiled tubing unit. 6. RIH w/injection equipment. 7. Test casing and chart for the NMOCD. 8. Return well to injection.	ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB s, including estimated date of starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEME!  OTHER Clean out/Acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date: proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. Kill well. 2. RU coiled tubing unit. 3. Clean out to 4300'. 4. Acid treat w/2500 gal of 15% NEFE HCL acid 5. RD coiled tubing unit. 6. RIH w/injection equipment. 7. Test casing and chart for the NMOCD.	ALTERING CASING PNS. PLUG & ABANDONMENT NT JOB s, including estimated date of starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEL OTHER Clean out/Acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. Kill well. 2. RU coiled tubing unit. 3. Clean out to 4300'. 4. Acid treat w/2500 gal of 15% NEFE HCL acid 5. RD coiled tubing unit. 6. RIH w/injection equipment. 7. Test casing and chart for the NMOCD. 8. Return well to injection.  1 hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative	ALTERING CASING PLUG & ABANDONMENT NT JOB  s, including estimated date of starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMES OTHER Clean out/Acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. Kill well. 2. RU coiled tubing unit. 3. Clean out to 4300°. 4. Acid treat w/2500 gal of 15% NEFE HCL acid 5. RD coiled tubing unit. 6. RIH w/injection equipment. 7. Test casing and chart for the NMOCD. 8. Return well to injection.  1. Ihereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan	ALTERING CASING PLUG & ABANDONMENT NT JOB  s, including estimated date of starting any completion or recompletion.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEL OTHER Clean out/Acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. Kill well. 2. RU coiled tubing unit. 3. Clean out to 4300'. 4. Acid treat w/2500 gal of 15% NEFE HCL acid 5. RD coiled tubing unit. 6. RIH w/injection equipment. 7. Test casing and chart for the NMOCD. 8. Return well to injection.  1 hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative	ALTERING CASING PLUG & ABANDONMENT NT JOB  s, including estimated date of starting any completion or recompletion.  That any pit or below-grade tank has been/will be The OCD-approved  .
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMES OTHER Clean out/Acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. Kill well. 2. RU coiled tubing unit. 3. Clean out to 4300°. 4. Acid treat w/2500 gal of 15% NEFE HCL acid 5. RD coiled tubing unit. 6. RIH w/injection equipment. 7. Test casing and chart for the NMOCD. 8. Return well to injection.  1 hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan	ALTERING CASING PLUG & ABANDONMENT  S, including estimated date of starting any completion or recompletion.  That any pit or below-grade tank has been/will be re OCD-approved  Associate  DATE 06/24/2010
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEIOTHER Clean out/Acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. Kill well. 2. RU coiled tubing unit. 3. Clean out to 4300'. 4. Acid treat w/2500 gal of 15% NEFE HCL acid 5. RD coiled tubing unit. 6. RIH w/injection equipment. 7. Test casing and chart for the NMOCD. 8. Return well to injection.  1 hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan  SIGNATURE TITLE Administrative	ALTERING CASING PLUG & ABANDONMENT  S, including estimated date of starting any completion or recompletion.  That any pit or below-grade tank has been/will be re OCD-approved  Associate  DATE 06/24/2010  TELEPHONE NO 806-592-6280
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OF PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER Clean out/Acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent date proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. Kill well. 2. RU coiled tubing unit. 3. Clean out to 4300°. 4. Acid treat w/2500 gal of 15% NEFE HCL acid 5. RD coiled tubing unit. 6. RIH w/injection equipment. 7. Test casing and chart for the NMOCD. 8. Return well to injection.  1 hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan  SIGNATURE TYPE OR PRINT NAME Mendy Albhason E-mail address: mendy johnson@oxy.com	ALTERING CASING PLUG & ABANDONMENT  S, including estimated date of starting any completion or recompletion.  That any pit or below-grade tank has been/will be re OCD-approved  Associate  DATE 06/24/2010