Submit 3 Copies To Appropriate State of New Mexico District Office Energy, Minerals and Natural Resources	Form C-103 May 27, 2004
1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Ave , Artesia CECEV 2420 South St. Francis Dr. 88210	WELL API NO. 30-025-11712 5. Indicate Type of Lease
88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
District IV 1220 S St Francis Dr., Santa British SOCD	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Name SOUTH JUSTIS UNIT
1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other	8. Well Number D-20 /
2. Name of Operator LEGACY RESERVES OPERATING LP	9. OGRID Number 240974 🗸
3. Address of Operator P.O. BOX 10848 MIDLAND, TX 79702	10. Pool name or Wildcat JUSTIS-BLINEBRY-TUBB-DRINKARD
4. Well Location	A
Unit Letter <u>H:2310</u> feet_from the <u>NORTH</u> line and Section 23 Township T25S Range R37E	<u>330</u> feet from the <u>EAST</u> line. NMPM LEA County ✓
11. Elevation (Show whether DR, RKB, RT, GR	
3032.4' GR Pit or Below-grade Tank Application □ or Closure □	
Pit typeDepth to GroundwaterDistance from nearest frsh water well	Distance from pograet surface
water	
Pit Liner Thickness: mil Below-Grade Tank: Volume	obls; Construction Material
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
12. Check Appropriate Box to Indicate Nature of Notice	, Report or Other Data
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
	SEQUENT REPORT OF: K
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	SEQUENT REPORT OF: K
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	SEQUENT REPORT OF: K ALTERING CASING LING OPNS. P AND A C T JOB POT ACIDIZE & REPLACE FAILED ESP A tails, and give pertinent dates, including
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT OTHER: OTHER: OTHER: SPENDONS 13. Describe proposed or completed operations. (Clearly state all pertinent de estimated date of starting any proposed work). SEE RULE 1103. For Multiple Section 2010	SEQUENT REPORT OF: K ALTERING CASING LING OPNS. P AND A C T JOB POT ACIDIZE & REPLACE FAILED ESP A tails, and give pertinent dates, including
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT OTHER: OTHER: OTHER: SF 13. Describe proposed or completed operations. (Clearly state all pertinent de estimated date of starting any proposed work). SEE RULE 1103. For Multidiagram of proposed completion or recompletion.	SEQUENT REPORT OF: K ALTERING CASING LLING OPNS. P AND A T JOB P POT ACIDIZE & REPLACE FAILED ESP A Atalis, and give pertinent dates, including iple Completions: Attach wellbore Tag at 5919'. Mill to 5930'. POH.
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT OTHER: OTHER: OTHER: SF 13. Describe proposed or completed operations. (Clearly state all pertinent de estimated date of starting any proposed work). SEE RULE 1103. For Multidiagram of proposed completion or recompletion. ESTIMATED DATE: 6/9/10 6/9/10-6/17/10 MIRU pulling unit. POH tbg and ESP. RIH mill and tbg. RIH w/ tbg. Spot 2000 gal 15% NEFE HCL and solvent (90/10 mixture) and solvent (90/10 mixture) and solvent (90/10 mixture) SUB	SEQUENT REPORT OF: K ALTERING CASING LLING OPNS. P AND A T JOB P POT ACIDIZE & REPLACE FAILED ESP A Atalis, and give pertinent dates, including iple Completions: Attach wellbore Tag at 5919'. Mill to 5930'. POH.
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT OTHER: OTHER: OTHER: SF 13. Describe proposed or completed operations. (Clearly state all pertinent de estimated date of starting any proposed work). SEE RULE 1103. For Multidiagram of proposed completion or recompletion. ESTIMATED DATE: 6/9/10 6/9/10-6/17/10 MIRU pulling unit. POH tbg and ESP. RIH mill and tbg. RIH w/ tbg. Spot 2000 gal 15% NEFE HCL and solvent (90/10 mixture) a Recover 184 bbls. RIH ESP and tbg. Put back on production. PERFS: 5046-5956' PBTD: 5980' TD: 5984'	SEQUENT REPORT OF: ALTERING CASING LLING OPNS. P AND A T JOB POT ACIDIZE & REPLACE FAILED ESP tails, and give pertinent dates, including iple Completions: Attach wellbore Tag at 5919'. Mill to 5930'. POH. across perfs. Swab back load.
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT OTHER: OTHER: OTHER: SPENDENCE 13. Describe proposed or completed operations. (Clearly state all pertinent destimated date of starting any proposed work). SEE RULE 1103. For Multidiagram of proposed completion or recompletion. ESTIMATED DATE: 6/9/10 6/9/10-6/17/10 MIRU pulling unit. POH tbg and ESP. RIH mill and tbg. RIH w/ tbg. Spot 2000 gal 15% NEFE HCL and solvent (90/10 mixture) a Recover 184 bbls. RIH ESP and tbg. Put back on production.	SEQUENT REPORT OF: ALTERING CASING LLING OPNS. P AND A T JOB POT ACIDIZE & REPLACE FAILED ESP tails, and give pertinent dates, including iple Completions: Attach wellbore Tag at 5919'. Mill to 5930'. POH. across perfs. Swab back load.
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT OTHER: OTHER: OTHER: SPENDENCE 13. Describe proposed or completed operations. (Clearly state all pertinent de estimated date of starting any proposed work). SEE RULE 1103. For Multidiagram of proposed completion or recompletion. ESTIMATED DATE: 6/9/10 6/9/10-6/17/10 MIRU pulling unit. POH tbg and ESP. RIH mill and tbg. RIH w/ tbg. Spot 2000 gal 15% NEFE HCL and solvent (90/10 mixture) at Recover 184 bbls. RIH ESP and tbg. Put back on production. PERFS: 5046-5956' PBTD: 5980' TD: 5984' I hereby certify that the information above is true and complete to the best of my kn pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines [alternative OCD-approved plan]. SIGNATURE MAMM	SEQUENT REPORT OF: ALTERING CASING LLING OPNS. P AND A T JOB POT ACIDIZE & REPLACE FAILED ESP tails, and give pertinent dates, including iple Completions: Attach wellbore Tag at 5919'. Mill to 5930'. POH. across perfs. Swab back load. owledge and belief. I further certify that any , a general permit or an (attached)
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT OTHER: OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent de estimated date of starting any proposed work). SEE RULE 1103. For Multidiagram of proposed completion or recompletion. ESTIMATED DATE: 6/9/10 6/9/10-6/17/10 MIRU pulling unit. POH tbg and ESP. RIH mill and tbg. RIH w/ tbg. Spot 2000 gal 15% NEFE HCL and solvent (90/10 mixture) at Recover 184 bbls. RIH ESP and tbg. Put back on production. PERFS: 5046-5956' PBTD: 5980' TD: 5984' I hereby certify that the information above is true and complete to the best of my kn pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines [alternative OCD-approved plan]. SIGNATURE MAMMM	SEQUENT REPORT OF: ALTERING CASING LLING OPNS. P AND A T JOB POT ACIDIZE & REPLACE FAILED ESP Atails, and give pertinent dates, including iple Completions: Attach wellbore Tag at 5919'. Mill to 5930'. POH. across perfs. Swab back load. Owledge and belief. I further certify that any , a general permit or an (attached) DATE 07/06/10 Telephone No. (432)689-5200