	of New Mex	xico	Form C-	103
Submit 3 Copies To Approximate Office State District I Energy, Miner	als and Natur	al Resources	May 27,	2004
1625 N. French Dr , Hobbs, NN 88240 2010 District II			WELL API NO.	
1301 W. Grand Ave., Artesia, NM 88249 OCD OIL CONSE District III HOBBSOCD 1220 So	ERVATION	DIVISION	30-025-23961 5. Indicate Type of Lease	,
District III HOBBSUUL 1220 So 1000 Rio Brazos Rd , Aztec, NM 87410	outh St. Fran	cis Dr.	STATE STATE	
District IV Santa	a Fe, NM 87	505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505			B-1258-1	
SUNDRY NOTICES AND REPORTS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO D			7. Lease Name or Unit Agreement Nam	le:
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FO			New Mexico AE State	
PROPOSALS)	_ /		8. Well No. 24	
1. Type of Well: Oil Well Gas Well Othe   2. Name of Operator /	r		9. OGRID Number	
Legacy Reserves Operating LP			240974	
3. Address of Operator			10. Pool name or Wildcat	
PO Box 10848, Midland, TX 79702			Vacuum; ABO Reef	
4. Well Location		11 1		
	the North	$\underline{\qquad}$ line and $\underline{550}$		line
Section 11 Township		nge $34-E$	NMPM County Lea 🗸	
The Devation (Show		<b>KB: 4019'</b>		
Pit or Below-grade Tank Application 🗌 or Closure	1			
	– ce from nearest fi	resh water well	Distance from nearest surface water	
Pit Liner Thickness: mil Below-Grade Ta	ank: Volume _	bb	ls; Construction Material	
12. Check Appropriate Box to	Indicate Na	ture of Notice, I	Report or Other Data	
PERFORM REMEDIAL WORK PLUG AND ABANDO		SUB REMEDIAL WORK	SEQUENT REPORT OF:	
		COMMENCE DRIL		
PULL OR ALTER CASING 🔲 MULTIPLE		CASING/CEMENT		
COMPLETION				
OTHER:		OTHER:		П
13. Describe proposed or completed operations. (Clearly	/ state all perti	nent details, and give	ve pertinent dates, including estimated da	te of
starting any proposed work). SEE RULE 1103. For				
	Multiple Com	pletions: Attach w	ellbore diagram of proposed completion	
recompletion.		-		or
07/01/10 Clear off brush on location. MIRU rig and co	ementing equi	pment. Dig out ce	llar. NU BOP. Picj up work string and	or
07/01/10 Clear off brush on location. MIRU rig and co RIH to 8100'. No Plug. Pump 50 BBLS. mud laden flu	ementing equi id. Spot 20 sx	pment. Dig out ce cement. Pull out c	llar. NU BOP. Picj up work string and of cement. SDFN.	or
07/01/10 Clear off brush on location. MIRU rig and co RIH to 8100'. No Plug. Pump 50 BBLS. mud laden flu 07/02/10 Tagged plug @ 7580'. POH to 6600'. Pumpe	ementing equi id. Spot 20 sx ed 40 BBLS of	pment. Dig out ce cement. Pull out c mud laden fluid.	llar. NU BOP. Picj up work string and of cement. SDFN. Spot 25 sx cement. POH to 4850'. SDF	or N.
07/01/10 Clear off brush on location. MIRU rig and co RIH to 8100'. No Plug. Pump 50 BBLS. mud laden flu 07/02/10 Tagged plug @ 7580'. POH to 6600'. Pumpe 07/05/10 Spot 50 sx cement plug @ 4850-4500. Lay do	ementing equi id. Spot 20 sx id 40 BBLS of wn tbg. Perf.	pment. Dig out ce cement. Pull out c mud laden fluid. csg.@ 3300'. RIH	llar. NU BOP. Picj up work string and of cement. SDFN. Spot 25 sx cement. POH to 4850'. SDF w/ Packer to 2900'. Get pump in rate of	or N. of
07/01/10 Clear off brush on location. MIRU rig and co RIH to 8100'. No Plug. Pump 50 BBLS. mud laden flu 07/02/10 Tagged plug @ 7580'. POH to 6600'. Pumpe	ementing equi id. Spot 20 sx d 40 BBLS of wn tbg. Perf. 3157'. POH to	pment. Dig out ce cement. Pull out c mud laden fluid. csg.@ 3300'. RIH 1500'. Perf'd casi	llar. NU BOP. Picj up work string and of cement. SDFN. Spot 25 sx cement. POH to 4850'. SDF w/ Packer to 2900'. Get pump in rate on ng @ 1860'. Could not pump into. RIF	or N. of I w/
07/01/10 Clear off brush on location. MIRU rig and co RIH to 8100'. No Plug. Pump 50 BBLS. mud laden flut 07/02/10 Tagged plug @ 7580'. POH to 6600'. Pumpe 07/05/10 Spot 50 sx cement plug @ 4850-4500. Lay do 1500 psi. Sqz'd 30 sx cement. WOC & tagged plug @ 3 tbg to 1910'. Spot 25 sx cement. WOC and tagged plug cement to surface w/ 50 sx cement.	ementing equi id. Spot 20 sx d 40 BBLS of wn tbg. Perf. 3157'. POH to	pment. Dig out ce cement. Pull out c mud laden fluid. csg.@ 3300'. RIH 1500'. Perf'd casi	llar. NU BOP. Picj up work string and of cement. SDFN. Spot 25 sx cement. POH to 4850'. SDF w/ Packer to 2900'. Get pump in rate on ng @ 1860'. Could not pump into. RIF	or N. of I w/
07/01/10 Clear off brush on location. MIRU rig and co RIH to 8100'. No Plug. Pump 50 BBLS. mud laden flu 07/02/10 Tagged plug @ 7580'. POH to 6600'. Pumpe 07/05/10 Spot 50 sx cement plug @ 4850-4500. Lay do 1500 psi. Sqz'd 30 sx cement. WOC & tagged plug @ 3 tbg to 1910'. Spot 25 sx cement. WOC and tagged plug cement to surface w/ 50 sx cement. 07/06/10 Rigged down moved off.	ementing equi id. Spot 20 sx id 40 BBLS of wn tbg. Perf. 3157'. POH to g @ 1650'. PO	pment. Dig out ce cement. Pull out c mud laden fluid. csg.@ 3300'. RIH 1500'. Perf'd casi H w/ packer and t	llar. NU BOP. Picj up work string and of cement. SDFN. Spot 25 sx cement. POH to 4850'. SDF w/ Packer to 2900'. Get pump in rate on ng @ 1860'. Could not pump into. RIH bg. RIH open ended to 400'. Circulate	or N. of I w/ d
07/01/10 Clear off brush on location. MIRU rig and co RIH to 8100'. No Plug. Pump 50 BBLS. mud laden flu 07/02/10 Tagged plug @ 7580'. POH to 6600'. Pumpe 07/05/10 Spot 50 sx cement plug @ 4850-4500. Lay do 1500 psi. Sqz'd 30 sx cement. WOC & tagged plug @ 3 tbg to 1910'. Spot 25 sx cement. WOC and tagged plug cement to surface w/ 50 sx cement. 07/06/10 Rigged down moved off. 07/13/10 Moved in backhoe and welder. Dig out cellar	ementing equi id. Spot 20 sx id 40 BBLS of wn tbg. Perf. 3157'. POH to g @ 1650'. PO	pment. Dig out ce cement. Pull out c mud laden fluid. csg.@ 3300'. RIH 1500'. Perf'd casi H w/ packer and t	llar. NU BOP. Picj up work string and of cement. SDFN. Spot 25 sx cement. POH to 4850'. SDF w/ Packer to 2900'. Get pump in rate on ng @ 1860'. Could not pump into. RIH bg. RIH open ended to 400'. Circulate	or N. of I w/ d
07/01/10 Clear off brush on location. MIRU rig and co RIH to 8100'. No Plug. Pump 50 BBLS. mud laden flu 07/02/10 Tagged plug @ 7580'. POH to 6600'. Pumpe 07/05/10 Spot 50 sx cement plug @ 4850-4500. Lay do 1500 psi. Sqz'd 30 sx cement. WOC & tagged plug @ 3 tbg to 1910'. Spot 25 sx cement. WOC and tagged plug cement to surface w/ 50 sx cement. 07/06/10 Rigged down moved off. 07/13/10 Moved in backhoe and welder. Dig out cellar dead men and clean location. Move off.	ementing equi id. Spot 20 sx id 40 BBLS of own tbg. Perf. 3157'. POH to g @ 1650'. PO r. Cut off well	pment. Dig out ce cement. Pull out c mud laden fluid. csg.@ 3300'. RIH 1500'. Perf'd casi H w/ packer and t	llar. NU BOP. Picj up work string and of cement. SDFN. Spot 25 sx cement. POH to 4850'. SDF w/ Packer to 2900'. Get pump in rate of ng @ 1860'. Could not pump into. RIH bg. RIH open ended to 400'. Circulate Dry Hole Marker. Back fill cellar. cut	or N. of I w/ d
07/01/10 Clear off brush on location. MIRU rig and co RIH to 8100'. No Plug. Pump 50 BBLS. mud laden flu 07/02/10 Tagged plug @ 7580'. POH to 6600'. Pumpe 07/05/10 Spot 50 sx cement plug @ 4850-4500. Lay do 1500 psi. Sqz'd 30 sx cement. WOC & tagged plug @ 3 tbg to 1910'. Spot 25 sx cement. WOC and tagged plug cement to surface w/ 50 sx cement. 07/06/10 Rigged down moved off. 07/13/10 Moved in backhoe and welder. Dig out cellar	ementing equi id. Spot 20 sx id 40 BBLS of wn tbg. Perf. 3157'. POH to g @ 1650'. PO c. Cut off well Approved for phy Liability under b	pment. Dig out ce cement. Pull out c mud laden fluid. csg.@ 3300'. RIH 1500'. Perf'd casi H w/ packer and t head and weld on	llar. NU BOP. Picj up work string and of cement. SDFN. Spot 25 sx cement. POH to 4850'. SDF w/ Packer to 2900'. Get pump in rate of ng @ 1860'. Could not pump into. RIH bg. RIH open ended to 400'. Circulate Dry Hole Marker. Back fill cellar. cut	or N. of I w/ d
07/01/10 Clear off brush on location. MIRU rig and co RIH to 8100'. No Plug. Pump 50 BBLS. mud laden flu 07/02/10 Tagged plug @ 7580'. POH to 6600'. Pumpe 07/05/10 Spot 50 sx cement plug @ 4850-4500. Lay do 1500 psi. Sqz'd 30 sx cement. WOC & tagged plug @ 3 tbg to 1910'. Spot 25 sx cement. WOC and tagged plug cement to surface w/ 50 sx cement. 07/06/10 Rigged down moved off. 07/13/10 Moved in backhoe and welder. Dig out cellar dead men and clean location. Move off.	ementing equi id. Spot 20 sx id 40 BBLS of wn tbg. Perf. 3157'. POH to g @ 1650'. PO c. Cut off well Approved for plu Liability under to of C-103 (Subsect	pment. Dig out ce cement. Pull out c mud laden fluid. csg.@ 3300'. RIH 1500'. Perf'd casi H w/ packer and t head and weld on ugging of well bore only out is retained pendin quent Report of Well Pl	llar. NU BOP. Picj up work string and of cement. SDFN. Spot 25 sx cement. POH to 4850'. SDF w/ Packer to 2900'. Get pump in rate of ng @ 1860'. Could not pump into. RIH bg. RIH open ended to 400'. Circulate Dry Hole Marker. Back fill cellar. cut areceipt ugging)	or N. of I w/ d
07/01/10 Clear off brush on location. MIRU rig and co RIH to 8100'. No Plug. Pump 50 BBLS. mud laden flui 07/02/10 Tagged plug @ 7580'. POH to 6600'. Pumpe 07/05/10 Spot 50 sx cement plug @ 4850-4500. Lay do 1500 psi. Sqz'd 30 sx cement. WOC & tagged plug @ 3 tbg to 1910'. Spot 25 sx cement. WOC and tagged plug cement to surface w/ 50 sx cement. 07/06/10 Rigged down moved off. 07/13/10 Moved in backhoe and welder. Dig out cellar dead men and clean location. Move off.	ementing equi id. Spot 20 sx id 40 BBLS of wn tbg. Perf. 3157'. POH to g @ 1650'. PO c. Cut off well Approved for plu Liability under to of C-103 (Subse- which may be fo	pment. Dig out ce cement. Pull out c mud laden fluid. csg.@ 3300'. RIH 1500'. Perf'd casi H w/ packer and t head and weld on	llar. NU BOP. Picj up work string and of cement. SDFN. Spot 25 sx cement. POH to 4850'. SDF w/ Packer to 2900'. Get pump in rate of ng @ 1860'. Could not pump into. RIH bg. RIH open ended to 400'. Circulate Dry Hole Marker. Back fill cellar. cut areceipt ugging)	or N. of I w/ d
07/01/10 Clear off brush on location. MIRU rig and co RIH to 8100'. No Plug. Pump 50 BBLS. mud laden flui 07/02/10 Tagged plug @ 7580'. POH to 6600'. Pumpe 07/05/10 Spot 50 sx cement plug @ 4850-4500. Lay do 1500 psi. Sqz'd 30 sx cement. WOC & tagged plug @ 3 tbg to 1910'. Spot 25 sx cement. WOC and tagged plug cement to surface w/ 50 sx cement. 07/06/10 Rigged down moved off. 07/13/10 Moved in backhoe and welder. Dig out cellar dead men and clean location. Move off.	ementing equi id. Spot 20 sx id 40 BBLS of wn tbg. Perf. 3157'. POH to g @ 1650'. PO c. Cut off well Approved for plu Liability under to of C-103 (Subse- which may be fo	pment. Dig out ce cement. Pull out c 'mud laden fluid. csg.@ 3300'. RIH 1500'. Perf'd casi H w/ packer and t head and weld on ugging of well bore only ound is retained pendin quent Report of Well Pl und at OCD Web Page	llar. NU BOP. Picj up work string and of cement. SDFN. Spot 25 sx cement. POH to 4850'. SDF w/ Packer to 2900'. Get pump in rate of ng @ 1860'. Could not pump into. RIH bg. RIH open ended to 400'. Circulate Dry Hole Marker. Back fill cellar. cut areceipt ugging)	or N. of I w/ d
07/01/10 Clear off brush on location. MIRU rig and co RIH to 8100'. No Plug. Pump 50 BBLS. mud laden flut 07/02/10 Tagged plug @ 7580'. POH to 6600'. Pumpe 07/05/10 Spot 50 sx cement plug @ 4850-4500. Lay do 1500 psi. Sqz'd 30 sx cement. WOC & tagged plug @ 3 tbg to 1910'. Spot 25 sx cement. WOC and tagged plug cement to surface w/ 50 sx cement. 07/06/10 Rigged down moved off. 07/13/10 Moved in backhoe and welder. Dig out cellar dead men and clean location. Move off.	ementing equi id. Spot 20 sx id 40 BBLS of own tbg. Perf. 3157'. POH to g @ 1650'. PO r. Cut off well Approved for plu Liability under b of C-103 (Subsec which may be for Forms, www.emu	pment. Dig out ce cement. Pull out of 'mud laden fluid. csg.@ 3300'. RIH 1500'. Perf'd casi H w/ packer and t head and weld on ugging of well bore only bond is retained pendin quent Report of Well Pl und at OCD Web Page ard.state.nm.us/ocd.	llar. NU BOP. Picj up work string and of cement. SDFN. Spot 25 sx cement. POH to 4850'. SDF w/ Packer to 2900'. Get pump in rate of ng @ 1860'. Could not pump into. RIH bg. RIH open ended to 400'. Circulate Dry Hole Marker. Back fill cellar. cut a receipt ugging) under	or N. of Lw/ d
07/01/10 Clear off brush on location. MIRU rig and co RIH to 8100'. No Plug. Pump 50 BBLS. mud laden flui 07/02/10 Tagged plug @ 7580'. POH to 6600'. Pumpe 07/05/10 Spot 50 sx cement plug @ 4850-4500. Lay do 1500 psi. Sqz'd 30 sx cement. WOC & tagged plug @ 3 tbg to 1910'. Spot 25 sx cement. WOC and tagged plug cement to surface w/ 50 sx cement. 07/06/10 Rigged down moved off. 07/13/10 Moved in backhoe and welder. Dig out cellar dead men and clean location. Move off.	ementing equi id. Spot 20 sx id 40 BBLS of own tbg. Perf. 3157'. POH to g @ 1650'. PO c. Cut off well Liability under b of C-103 (Subse- which may be for Forms, www.cm)	pment. Dig out ce cement. Pull out of 'mud laden fluid. csg.@ 3300'. RIH 1500'. Perf'd casi H w/ packer and t head and weld on ugging of well bore only oond is retained pendin, quent Report of Well Pl und at OCD Web Page ard.state.mm.us/ocd.	llar. NU BOP. Picj up work string and of cement. SDFN. Spot 25 sx cement. POH to 4850'. SDF w/ Packer to 2900'. Get pump in rate of ng @ 1860'. Could not pump into. RIH bg. RIH open ended to 400'. Circulate Dry Hole Marker. Back fill cellar. cut areceipt ugging) under	or N. of I w/ d off
07/01/10 Clear off brush on location. MIRU rig and co RIH to 8100'. No Plug. Pump 50 BBLS. mud laden flut 07/02/10 Tagged plug @ 7580'. POH to 6600'. Pumpe 07/05/10 Spot 50 sx cement plug @ 4850-4500. Lay do 1500 psi. Sqz'd 30 sx cement. WOC & tagged plug @ 3 tbg to 1910'. Spot 25 sx cement. WOC and tagged plug cement to surface w/ 50 sx cement. 07/06/10 Rigged down moved off. 07/13/10 Moved in backhoe and welder. Dig out cellar dead men and clean location. Move off.	ementing equi id. Spot 20 sx id 40 BBLS of white the second second second second second second second second second c. Cut off well Approved for plu Liability under to of C-103 (Subsect which may be for Forms, www.emp to the best of my idelines _, a g	pment. Dig out ce cement. Pull out of mud laden fluid. csg.@ 3300'. RIH 1500'. Perf'd casi H w/ packer and the head and weld on ugging of well bore only bond is retained pending quent Report of Well Pl und at OCD Web Page ard.state.nm.us/ocd.	llar. NU BOP. Picj up work string and of cement. SDFN. Spot 25 sx cement. POH to 4850'. SDF w/ Packer to 2900'. Get pump in rate of ng @ 1860'. Could not pump into. RIH obg. RIH open ended to 400'. Circulate Dry Hole Marker. Back fill cellar. cut areceipt ugging) under	or N. of I w/ d off
07/01/10 Clear off brush on location. MIRU rig and co RIH to 8100'. No Plug. Pump 50 BBLS. mud laden flut 07/02/10 Tagged plug @ 7580'. POH to 6600'. Pumpe 07/05/10 Spot 50 sx cement plug @ 4850-4500. Lay do 1500 psi. Sqz'd 30 sx cement. WOC & tagged plug @ 3 tbg to 1910'. Spot 25 sx cement. WOC and tagged plug cement to surface w/ 50 sx cement. 07/06/10 Rigged down moved off. 07/13/10 Moved in backhoe and welder. Dig out cellar dead men and clean location. Move off.	ementing equi id. Spot 20 sx id 40 BBLS of white the second second second second second second second second second c. Cut off well Approved for plu Liability under to of C-103 (Subsect which may be for Forms, www.emp to the best of my idelines _, a g	pment. Dig out ce cement. Pull out of mud laden fluid. csg.@ 3300'. RIH 1500'. Perf'd casi H w/ packer and the head and weld on ugging of well bore only bond is retained pending quent Report of Well Pl und at OCD Web Page ard.state.nm.us/ocd.	llar. NU BOP. Picj up work string and of cement. SDFN. Spot 25 sx cement. POH to 4850'. SDF w/ Packer to 2900'. Get pump in rate of ng @ 1860'. Could not pump into. RIH bg. RIH open ended to 400'. Circulate Dry Hole Marker. Back fill cellar. cut areceipt ugging) under	or N. of I w/ d off
07/01/10 Clear off brush on location. MIRU rig and co RIH to 8100'. No Plug. Pump 50 BBLS. mud laden flu 07/02/10 Tagged plug @ 7580'. POH to 6600'. Pumpe 07/05/10 Spot 50 sx cement plug @ 4850-4500. Lay do 1500 psi. Sqz'd 30 sx cement. WOC & tagged plug @ 3 tbg to 1910'. Spot 25 sx cement. WOC and tagged plug cement to surface w/ 50 sx cement. 07/06/10 Rigged down moved off. 07/13/10 Moved in backhoe and welder. Dig out cellar dead men and clean location. Move off.	ementing equi id. Spot 20 sx id 40 BBLS of wn tbg. Perf. 3157'. POH to g @ 1650'. PO c. Cut off well Approved for phy Liability under b of C-103 (Subse- which may be for Forms, www.cm) to the best of my idelines, a g	pment. Dig out ce cement. Pull out of mud laden fluid. csg.@ 3300'. RIH 1500'. Perf'd casi H w/ packer and t head and weld on ugging of well bore only bond is retained pending quent Report of Well Pl und at OCD Web Page ard.state.nm.us/ocd.	llar. NU BOP. Picj up work string and of cement. SDFN. Spot 25 sx cement. POH to 4850'. SDF w/ Packer to 2900'. Get pump in rate of ng @ 1860'. Could not pump into. RIH bg. RIH open ended to 400'. Circulate Dry Hole Marker. Back fill cellar. cut areceipt ugging) under ef. I further certify that any pit or below-grad in (attached) alternative OCD-approved plan perintendent_DATE_07/15/1	or N. of I w/ d off
07/01/10 Clear off brush on location. MIRU rig and co RIH to 8100'. No Plug. Pump 50 BBLS. mud laden flut 07/02/10 Tagged plug @ 7580'. POH to 6600'. Pumpe 07/05/10 Spot 50 sx cement plug @ 4850-4500. Lay do 1500 psi. Sqz'd 30 sx cement. WOC & tagged plug @ 3 tbg to 1910'. Spot 25 sx cement. WOC and tagged plug cement to surface w/ 50 sx cement. 07/06/10 Rigged down moved off. 07/13/10 Moved in backhoe and welder. Dig out cellar dead men and clean location. Move off.	ementing equi id. Spot 20 sx id 40 BBLS of white the second second second second second second second second second c. Cut off well Approved for plu Liability under to of C-103 (Subsect which may be for Forms, www.emp to the best of my idelines _, a g	pment. Dig out ce cement. Pull out of mud laden fluid. csg.@ 3300'. RIH 1500'. Perf'd casi H w/ packer and t head and weld on ugging of well bore only bond is retained pending quent Report of Well Pl und at OCD Web Page ard.state.nm.us/ocd.	llar. NU BOP. Picj up work string and of cement. SDFN. Spot 25 sx cement. POH to 4850'. SDF w/ Packer to 2900'. Get pump in rate of ng @ 1860'. Could not pump into. RIH obg. RIH open ended to 400'. Circulate Dry Hole Marker. Back fill cellar. cut areceipt ugging) under	or N. of I w/ d off
07/01/10 Clear off brush on location. MIRU rig and co RIH to 8100'. No Plug. Pump 50 BBLS. mud laden flui 07/02/10 Tagged plug @ 7580'. POH to 6600'. Pumpe 07/05/10 Spot 50 sx cement plug @ 4850-4500. Lay do 1500 psi. Sqz'd 30 sx cement. WOC & tagged plug @ 3 tbg to 1910'. Spot 25 sx cement. WOC and tagged plug cement to surface w/ 50 sx cement. 07/06/10 Rigged down moved off. 07/13/10 Moved in backhoe and welder. Dig out cellar dead men and clean location. Move off. 07/ Signature Berry Johnson For State Use Only	ementing equi id. Spot 20 sx id 40 BBLS of swn tbg. Perf. 3157'. POH to g @ 1650'. PO c. Cut off well Approved for plu Liability under b of C-103 (Subse- which may be fo Forms, www.cmi to the best of my idelines [], a g 	pment. Dig out ce cement. Pull out of mud laden fluid. csg.@ 3300'. RIH 1500'. Perf'd casi H w/ packer and the head and weld on ugging of well bore only bond is retained pendin, quent Report of Well Pl und at OCD Web Page ard.state.nm.us/ocd.	llar. NU BOP. Picj up work string and of cement. SDFN. Spot 25 sx cement. POH to 4850'. SDF w/ Packer to 2900'. Get pump in rate of ng @ 1860'. Could not pump into. RIH bg. RIH open ended to 400'. Circulate Dry Hole Marker. Back fill cellar. cut areceipt ugging) under ef. I further certify that any pit or below-grad in (attached) alternative OCD-approved plan perintendent_DATE_07/15/1 Telephone No. 432-689-5	or N. of I w/ d off
07/01/10 Clear off brush on location. MIRU rig and co RIH to 8100'. No Plug. Pump 50 BBLS. mud laden flut 07/02/10 Tagged plug @ 7580'. POH to 6600'. Pumpe 07/05/10 Spot 50 sx cement plug @ 4850-4500. Lay do 1500 psi. Sqz'd 30 sx cement. WOC & tagged plug @ 3 tbg to 1910'. Spot 25 sx cement. WOC and tagged plug cement to surface w/ 50 sx cement. 07/06/10 Rigged down moved off. 07/13/10 Moved in backhoe and welder. Dig out cellar dead men and clean location. Move off. 07/13/10 Moved in backhoe and welder. Dig out cellar dead men and clean location. Move off. 07 Signature Signature Signature Fype or print name Beatry Johnson For State Use Only	ementing equi id. Spot 20 sx id 40 BBLS of wn tbg. Perf. 3157'. POH to g @ 1650'. PO c. Cut off well Approved for phy Liability under b of C-103 (Subse- which may be for Forms, www.cm) to the best of my idelines, a g	pment. Dig out ce cement. Pull out of mud laden fluid. csg.@ 3300'. RIH 1500'. Perf'd casi H w/ packer and the head and weld on ugging of well bore only bond is retained pendin, quent Report of Well Pl und at OCD Web Page ard.state.nm.us/ocd.	llar. NU BOP. Picj up work string and of cement. SDFN. Spot 25 sx cement. POH to 4850'. SDF w/ Packer to 2900'. Get pump in rate of ng @ 1860'. Could not pump into. RIH bg. RIH open ended to 400'. Circulate Dry Hole Marker. Back fill cellar. cut areceipt ugging) under ef. I further certify that any pit or below-grad in (attached) alternative OCD-approved plan perintendent_DATE_07/15/1	or N. of I w/ d off
07/01/10 Clear off brush on location. MIRU rig and co RIH to 8100'. No Plug. Pump 50 BBLS. mud laden flui 07/02/10 Tagged plug @ 7580'. POH to 6600'. Pumpe 07/05/10 Spot 50 sx cement plug @ 4850-4500. Lay do 1500 psi. Sqz'd 30 sx cement. WOC & tagged plug @ 3 tbg to 1910'. Spot 25 sx cement. WOC and tagged plug cement to surface w/ 50 sx cement. 07/06/10 Rigged down moved off. 07/13/10 Moved in backhoe and welder. Dig out cellar dead men and clean location. Move off. 07/13/10 Moved in backhoe and welder. Dig out cellar dead men and clean location. Move off. 07/13/10 Moved in backhoe according to NMOCD gu SIGNATURE SIGNATURE SIGNATURE SIGNATURE SIGNATURE SIGNATURE ABPROVED BY Conditions of Approval (if ary):	ementing equi id. Spot 20 sx id 40 BBLS of swn tbg. Perf. 3157'. POH to g @ 1650'. PO c. Cut off well Approved for plu Liability under b of C-103 (Subse- which may be fo Forms, www.cmi to the best of my idelines [], a g 	pment. Dig out ce cement. Pull out of mud laden fluid. csg.@ 3300'. RIH 1500'. Perf'd casi H w/ packer and the head and weld on ugging of well bore only bond is retained pending quent Report of Well Pl und at OCD Web Page ard.state.nm.us/ocd.	Ilar. NU BOP. Picj up work string and of cement. SDFN.      Spot 25 sx cement. POH to 4850'. SDF w/ Packer to 2900'. Get pump in rate of ng @ 1860'. Could not pump into. RIH obg. RIH open ended to 400'. Circulate      Dry Hole Marker. Back fill cellar. cut      icareccipt      ugging)      under      ef. I further certify that any pit or below-grad in (attached) alternative OCD-approved plan      perintendent    DATE      07/15/1      Telephone No. 432-689-5	or N. of I w/ d off = tank 
07/01/10 Clear off brush on location. MIRU rig and co RIH to 8100'. No Plug. Pump 50 BBLS. mud laden flut 07/02/10 Tagged plug @ 7580'. POH to 6600'. Pumpe 07/05/10 Spot 50 sx cement plug @ 4850-4500. Lay do 1500 psi. Sqz'd 30 sx cement. WOC & tagged plug @ 3 tbg to 1910'. Spot 25 sx cement. WOC and tagged plug cement to surface w/ 50 sx cement. 07/06/10 Rigged down moved off. 07/13/10 Moved in backhoe and welder. Dig out cellar dead men and clean location. Move off. 07/13/10 Moved in backhoe and welder. Dig out cellar dead men and clean location. Move off. 07 Signature Signature Signature Fype or print name Beatry Johnson For State Use Only	ementing equi id. Spot 20 sx id 40 BBLS of swn tbg. Perf. 3157'. POH to g @ 1650'. PO c. Cut off well Approved for plu Liability under b of C-103 (Subse- which may be fo Forms, www.cmi to the best of my idelines [], a g 	pment. Dig out ce cement. Pull out of mud laden fluid. csg.@ 3300'. RIH 1500'. Perf'd casi H w/ packer and the head and weld on ugging of well bore only bond is retained pending quent Report of Well Pl und at OCD Web Page ard.state.nm.us/ocd.	llar. NU BOP. Picj up work string and of cement. SDFN. Spot 25 sx cement. POH to 4850'. SDF w/ Packer to 2900'. Get pump in rate of ng @ 1860'. Could not pump into. RIH bg. RIH open ended to 400'. Circulate Dry Hole Marker. Back fill cellar. cut areceipt ugging) under ef. I further certify that any pit or below-grad in (attached) alternative OCD-approved plan perintendent_DATE_07/15/1 Telephone No. 432-689-5	or N. of I w/ d off = tank 

3070

DW.
-----