Form 3160-5	UNITED STATES	OCD-HOBBS	<b>;</b>	FORM APPRO OMB No 1004	
	PARTMENT OF THE INT	ERIOR	5. Lease S	Expires July 3	
	EAU OF LAND MANAG		N	A-16835	
Do not use this i	NOTICES AND REPORT form for proposals to a Use Form 3160-3 (APD	Irill or to re-enter ar	•	n, Allottee or Tribe Nam	,
	IT IN TRIPLICATE – Other inst	······································		of CA/Agreement, Name	and/or No
1 Type of Well		/	8 Well N	ame and No	
Oıl Well 🔽 Gas V	Well Other			ederal AG Com #1	<u> </u>
2. Name of Operator DEVON ENE	RGY PRODUCTION COMPA		9 API W	30-025-26620	✓
3a. Address PO BOX 250 ARTESIA, NM 88211	•	Phone No. <i>(include area co</i> 575-748-3371	Wes	and Pool or Exploratory at Osudo Morrow	Area
4 Location of Well (Footage, Sec, T			11 Count Le	ry or Parish, State	
1980' FNL & 1980' FWL, SEC 14, T205				¥	
12 CHE	CK THE APPROPRIATE BOX(I				
TYPE OF SUBMISSION			PE OF ACTION		
Notice of Intent	Acıdize	Deepen Fracture Treat	Production (State) Reclamation		er Shut-Off ] Integrity
	Casing Repair	New Construction	Recomplete	— Oth	er
Subsequent Report	Change Plans	Plug and Abandon	Temporarily At	andon	
Final Abandonment Notice 13 Describe Proposed or Completed	Convert to Injection	Plug Back	Water Disposal		
	rinspection after P&A. Onsteption	r to recl	amatio AC	CEPTED FO	R RECORD
L	RECEN	VED		JUL 16	2010
	JUL 212				
	ין ב ב ו ג	2010		4 Chan	l
	HOBBS			BUREAU OF LAND N CARLSBAD FIEL	
	HOBBS				
<ul> <li>14 I hereby certify that the foregoing a Name (<i>Printed/Typed</i>)</li> <li>Ronnie Carre</li> </ul>	HOBBS	DCD	ompletions Foreman		
Name (Printed/Typed)	HOBBS				
Name (Printed/Typed) Ronnie Carre	HOBBS( is true and correct	Title C Date 06/22/	2010	CARLSBAD FIEL	
Name (Printed/Typed) Ronnie Carre	HOBBS( is true and correct	Title C Date 06/22/ OR FEDERAL OR S	2010 TATE OFFICE U	CARLSBAD FIEL	DOFFICE
Name (Printed/Typed) Ronnie Carre Signature Roman Approved by Conditions of approval, if any, are attaction that the applicant holds legal or equitable	HOBBS Is true and correct THIS SPACE FO THIS SPACE FO CACC THIS SPACE OF CACC THIS SPACE OF THIS SPAC	DCD Title C Date 06/22/ OR FEDERAL OR S 7-2/-/ Dtle ot warrant or certify	2010 TATE OFFICE U	CARLSBAD FIEL	
Name (Printed/Typed) Ronnie Carre	HOBBSC is true and correct THIS SPACE FO ELECTION In the subject I ins thereon 43 U S C Section 1212, make it a ci	Title C Date 06/22/ OR FEDERAL OR S 7-21-1011e ot warrant or certify case which would Office	2010 TATE OFFICE U	CARLSBAD FIEL	D OFFICE JL 2 2 2010

ł

orm 3160-5 U February 2005) DEPARTM		PERATO	R'S COP	Y NPS	OMB N	M APROVED IO. 1004-0137 : March 31, 2007
DUILLING		en re B <i>J</i>	vece!	VED	5 Lease Serial No.	. Waldi 01,2001
	ES AND REPORTS ON WI	re-enter an			N	M 16835
abandoned well. Use F	Corm 3160-3 (APD) for suc	n proposais	<u>JUL 217</u>	2 <b>01</b> 0	6. If Indian, Allottee or	Tribe Name
		H	OBBSC	)CD	7 Unit or CA Agreem	ent Name and No.
Type of Well 🗌 Oil Well 🗹 Gas Well	Other				8 Well Name and No.	
Name of Operator DEVON ENERGY PRODUCTIO	ON COMPANY, LP				9. API Well No.	al AG Com #1
Ba, Address		3b. Phone No	o. (include area	code)		-025-26620
0 North Broadway, Ste 1500, Oklahoma		405-552-4615 ion)			10. Field and Pool, or Exploratory Area         West Osudo Morrow         11       County or Parish, State         LEA       NM	
4. Location of Well (Footage, Sec., T., R. 1980 FNL 1980 FWL F 14 1	. M., or Survey Description) T20S R35E					
12 CHECK A	APPROPRIATE BOX(es) T	O INDICATE NA	TURE OF NOT	TICE, REPO	RT OR OTHER DATA	
TYPE OS SUBMISSION			TYPE (	OF ACTION		
Notice of Intent	Acidize	Deepen	Ē	Productio		Water Shut-Off Well Integrity Other
✓ Subsequent Report	Casing Repair	New Con			rily Abandon	
Final Abandonment Notice Final Abandonment Notice S. Describe Proposed or Completed Operations (Clear	Convert to Injection	Plug Bac	k l	Water Di	sposal	
PLUGGED & ABANDONED 4/*2/10 - 5/25/10				• Ľ)		dillon s of t
<ol> <li>MIRU Circulate wellbore w/1</li> <li>Spot 50 sx H plug @ 10850'</li> <li>Spot 60 sx H plug @ 9025'</li> <li>Spot 36 sx C plug @ 5247' T</li> <li>Spot 50 sx C plug @ 5247' T</li> <li>Spot 50 sx C plug @ 5195'-</li> <li>Cut 7-5/8" casing at 4295' P</li> <li>Spot 80 sx C plug @ 4174' - 40</li> <li>Spot 60 sx C plug @ 3755'-</li> <li>Spot 60 sx C plug @ 3755'-</li> <li>Spot 60 sx C plug @ 448'. T</li> </ol>	Tag @ 10574' Tag @ 8807' (DV too 8090' 5704' Tag @ 5195' 4920' OOH and lay down 7- Tag @ 4174' 31' 3602' (base of salt) 24'. ag @ 313'.		Well	d 3/4/11 mail da	ugged accordir 0. Clarified w/ ted 6/11/10R	Jim Amos in Ronnie Slack
<ol> <li>Spot 50 sx H plug @ 10850'</li> <li>Spot 60 sx H plug @ 9025'</li> <li>Spot 41 sx H plug @ 8275' - 4</li> <li>Spot 36 sx C plug @ 5902' - 4</li> <li>Spot 50 sx C plug @ 5247' T</li> <li>Spot 50 sx C plug @ 5195' - 4</li> <li>Cut 7-5/8" casing at 4295' P</li> <li>Spot 80 sx C plug @ 4174' - 40</li> <li>Spot 60 sx C plug @ 3755' - 12</li> <li>Spot 60 sx C plug @ 2467' 232</li> </ol>	Tag @ 10574' Tag @ 8807' (DV too 8090' 5704' 'ag @ 5195' 4920' 'OOH and lay down 7- Tag @ 4174' 31' 3602' (base of salt) 24'. ag @ 313'. ' to surface hole marker.		Well	was pl d 3/4/11 mail da 	ugged accordir 0. Clarified w/ ted 6/11/10R	Jim Amos in connie Slack
<ol> <li>Spot 50 sx H plug @ 10850'</li> <li>Spot 60 sx H plug @ 9025'</li> <li>Spot 41 sx H plug @ 8275' - 4</li> <li>Spot 36 sx C plug @ 5902' - 4</li> <li>Spot 50 sx C plug @ 5247' T</li> <li>Spot 50 sx C plug @ 5195' - 4</li> <li>Cut 7-5/8" casing at 4295' P</li> <li>Spot 60 sx C plug @ 41/45'.</li> <li>Spot 60 sx C plug @ 41/45'.</li> <li>Spot 60 sx C plug @ 3755' - 12.</li> <li>Spot 60 sx C plug @ 448'. T</li> <li>Spot 60 sx C plug @ 448'. T</li> <li>Curculate 45 sx cmt from 112'</li> <li>Cut wellhead off and set dry</li> <li>5/25/10-Plugged &amp; Abandon</li> </ol>	Tag @ 10574' Tag @ 8807' (DV too 8090' 5704' 5704' 5704' 5704' 5704' 5704' 500H and lay down 7- Tag @ 4174' 31' 3602' (base of salt) 24'. ag @ 313'. ' to surface hole marker. ied		Well	was pl d 3/4/11 mail da 	ugged accordin 0. Clarified w/ ted 6/11/10R billity ender bore	Jim Amos in connie Slack
<ol> <li>Spot 50 sx H plug @ 10850'</li> <li>Spot 60 sx H plug @ 9025'</li> <li>Spot 41 sx H plug @ 8275' - 4</li> <li>Spot 36 sx C plug @ 5902' - 4</li> <li>Spot 50 sx C plug @ 5247' T</li> <li>Spot 50 sx C plug @ 5195' - 8</li> <li>Cut 7-5/8" casing at 4295' P</li> <li>Spot 80 sx C plug @ 4174' - 40</li> <li>Spot 60 sx C plug @ 3755' -</li> <li>Spot 60 sx C plug @ 3755' -</li> <li>Spot 60 sx C plug @ 448'. T</li> <li>Spot 60 sx C plug @ 448'. T</li> <li>Curculate 45 sx cmt from 112</li> <li>Cut wellhead off and set dry</li> </ol>	Tag @ 10574' Tag @ 8807' (DV too 8090' 5704' 5704' 5704' 5704' 5704' 5704' 500H and lay down 7- Tag @ 4174' 31' 3602' (base of salt) 24'. ag @ 313'. ' to surface hole marker. ied	5/8" casing.	Well	was pl d 3/4/11 mail da	ugged accordin 0. Clarified w/ ted 6/11/10R billity ender bore	Jim Amos in connie Slack
<ol> <li>Spot 50 sx H plug @ 10850'</li> <li>Spot 60 sx H plug @ 9025'</li> <li>Spot 41 sx H plug @ 8275' - 4</li> <li>Spot 36 sx C plug @ 5902' - 4</li> <li>Spot 50 sx C plug @ 5247' T</li> <li>Spot 50 sx C plug @ 5195' - 4</li> <li>Cut 7-5/8" casing at 4295' P</li> <li>Spot 60 sx C plug @ 41/45'.</li> <li>Spot 60 sx C plug @ 41/45'.</li> <li>Spot 60 sx C plug @ 4174' - 40</li> <li>Spot 60 sx C plug @ 47/5' - 12.</li> <li>Spot 60 sx C plug @ 448'. T</li> <li>Spot 60 sx C plug @ 448'. T</li> <li>Circulate 45 sx cmt from 112'</li> <li>Cut wellhead off and set dry</li> <li>5/25/10-Plugged &amp; Abandon</li> </ol>	Tag @ 10574'         Tag @ 8807'       (DV too         8090'       5704'         5704       5704'         'ag @ 5195'       4920'         'OOH and lay down 7-       7-         Tag @ 4174'       31'         3602'       (base of salt)         24'.       ag @ 313'.         ' to surface       hole marker.         hole marker.       indicate the salt of the sa	5/8" casing.	Well date an e prations Techn 5/26/2010	was pli d 3/4/11 mail da	ugged accordin 0. Clarified w/ ted 6/11/10R solity soler bors unface restoration for	Jim Amos in connie Slack
<ol> <li>Spot 50 sx H plug @ 10850'</li> <li>Spot 60 sx H plug @ 9025'</li> <li>Spot 41 sx H plug @ 8275' - 4</li> <li>Spot 36 sx C plug @ 5902' - 4</li> <li>Spot 50 sx C plug @ 5247' T</li> <li>Spot 50 sx C plug @ 5195' - 8</li> <li>Cut 7-5/8" casing at 4295' P</li> <li>Spot 80 sx C plug @ 4174' - 40</li> <li>Spot 60 sx C plug @ 3755' - 12</li> <li>Spot 60 sx C plug @ 4174' - 40</li> <li>Spot 60 sx C plug @ 448'. T</li> <li>Circulate 45 sx cmt from 112</li> <li>Cut wellhead off and set dry</li> <li>5/25/10-Plugged &amp; Abandon</li> </ol>	Tag @ 10574'         Tag @ 8807'       (DV too         8090'       5704'         5704       5704'         'ag @ 5195'       4920'         'OOH and lay down 7-       7-         Tag @ 4174'       31'         3602'       (base of salt)         24'.       ag @ 313'.         ' to surface       hole marker.         Hole marker.       Hole marker.         Head correct       Tittle	5/8" casing.	Well date an e prations Techn 5/26/2010	was pli d 3/4/11 mail da	ugged accordin 0. Clarified w/ ted 6/11/10R solity soler bors unface restoration for	Jim Amos in connie Slack
<ol> <li>Spot 50 sx H plug @ 10850'</li> <li>Spot 60 sx H plug @ 9025'</li> <li>Spot 41 sx H plug @ 8275' - 4</li> <li>Spot 36 sx C plug @ 5902' - 4</li> <li>Spot 50 sx C plug @ 5247' T</li> <li>Spot 50 sx C plug @ 5195' - 8</li> <li>Cut 7-5/8" casing at 4295' P</li> <li>Spot 80 sx C plug @ 4174' - 40</li> <li>Spot 60 sx C plug @ 3755' - 12</li> <li>Spot 60 sx C plug @ 4174' - 40</li> <li>Spot 60 sx C plug @ 448'. T</li> <li>Circulate 45 sx cmt from 112</li> <li>Cut wellhead off and set dry</li> <li>5/25/10-Plugged &amp; Abandon</li> </ol>	Tag @ 10574'         Tag @ 8807'       (DV too         8090'       5704'         5704       5704'         'ag @ 5195'       4920'         'OOH and lay down 7-       7         Tag @ 4174'       31'         3602'       (base of salt)         24'.       ag @ 313'.         ' to surface       hole marker.         hole marker.       This SPACE FO	5/8" casing.	Well date an e prations Techn 5/26/2010	was pli d 3/4/11 mail da	ugged accordin 0. Clarified w/ ted 6/11/10R bility under borsa unface restoration for USE	Jim Amos in Ronnie Slack
<ol> <li>Spot 50 sx H plug @ 10850'</li> <li>Spot 60 sx H plug @ 9025'</li> <li>Spot 36 sx C plug @ 5902'</li> <li>Spot 36 sx C plug @ 5902'</li> <li>Spot 50 sx C plug @ 5247' T</li> <li>Spot 50 sx C plug @ 5195'</li> <li>Cut 7-5/8" casing at 4295' P</li> <li>Spot 80 sx C plug @ 4174' - 40</li> <li>Spot 60 sx C plug @ 4174' - 40</li> <li>Spot 60 sx C plug @ 3755'</li> <li>Spot 60 sx C plug @ 448'. T</li> <li>Circulate 45 sx cmt from 112</li> <li>Cut wellhead off and set dry</li> <li>5/25/10-Plugged &amp; Abandon</li> <li>H hereby certify that the foregoing is transmission</li> <li>Signature Kamu Liand</li> </ol>	Tag @ 10574'         Tag @ 8807'       (DV too         8090'       5704'         5704       5704'         'ag @ 5195'       4920'         'OOH and lay down 7-       7-         Tag @ 4174'       31'         3602'       (base of salt)         24'.       ag @ 313'.         ' to surface       hole marker.         hole marker.       indicate the salt of the sa	5/8" casing.	Well date an e prations Techn 5/26/2010	was pli d 3/4/11 mail da	ugged accordin 0. Clarified w/s ted 6/11/10R bility under bore artice restoration in USE	Jim Amos in Ronnie Slack
<ol> <li>Spot 50 sx H plug @ 10850'</li> <li>Spot 60 sx H plug @ 9025'</li> <li>Spot 36 sx C plug @ 5902'</li> <li>Spot 36 sx C plug @ 5902'</li> <li>Spot 50 sx C plug @ 5247' T</li> <li>Spot 50 sx C plug @ 5195'</li> <li>Cut 7-5/8" casing at 4295' P</li> <li>Spot 80 sx C plug @ 4174' - 40</li> <li>Spot 60 sx C plug @ 4174' - 40</li> <li>Spot 60 sx C plug @ 3755'</li> <li>Spot 60 sx C plug @ 448'. T</li> <li>Circulate 45 sx cmt from 112</li> <li>Cut wellhead off and set dry</li> <li>5/25/10-Plugged &amp; Abandon</li> <li>H hereby certify that the foregoing is transmission</li> <li>Signature Kamu Liand</li> </ol>	Tag @ 10574'         Tag @ 8807' (DV too         8090'         5704'         'ag @ 5195'         4920'         'OOH and lay down 7-         Tag @ 4174'         31'         3602' (base of salt)         24'.         ag @ 313'.         ' to surface         hole marker.         ed         This SPACE FO         This SPACE FO         Title         Dat         This SPACE FO         Title         Dat	5/8" casing.	Well date an e prations Techn 5/26/2010	was pli d 3/4/11 mail da	ugged accordin 0. Clarified w/ ted 6/11/10R bility under borsa unface restoration for USE	Jim Amos in Ronnie Slack

•17 · · ···\*\*\*

•

