Submit 3 Copies To Appropriate District	State of New Mexico	Form C-103
Office Energ	gy, Minerals and Natural Resource	s May 27, 2004
District I 1625 N. French Dr., Hobbs, N District II 1301 W. Grand Ave., Artesia, NM 88210		WELL API NO.
District II	CONSERVATION DIVISION	N 30-041-20745
L MSTEICE FEE	1220 South St. Francis Dr.	/
1000 Rio Brazos Rd., Aztec, NMAUGO 2 3 2010	Santa Fe, NM 87505	STATE TEE X
District IV 1220 S. St. Francis Dr , Santa FOBBSOCD		6. State Oil & Gas Lease No.
	D REPORTS ON WELLS	7. Lagge Name on Unit Agreement Names
(DO NOT USE THIS FORM FOR PROPOSALS TO DIFFERENT RESERVOIR. USE "APPLICATION F PROPOSALS.)	DRILL OR TO DEEPEN OR PLUG BACK	7. Lease Name or Unit Agreement Name: WILCOX TS
1. Type of Well: Oil Well X Gas Well O	ther V	8. Well Number
2. Name of Operator	/	9. OGRID Number
-	ATIN: BRIDGET HELFRICH	143199
3. Address of Operator		10. Pool name or Wildcat
1001 FANNIN ST., STE. 800, HOUST	ON. TEXAS 77002	TOMAHAWK (SAN ANDRES)
4. Well Location		
Unit Letter H : 1650	feet from theNORTH line a	and 990 feet from the EAST line
Section 19	. I . I . I . I . I . I . I . I . I . I	32E NMPM County ROOSEVELT
11. El	evation (Show whether DR, RKB, RT, 4,467' - GR	GR, etc.)
Pit or Below-grade Tank Application or Close		Provide the same of the same o
Pit type STEEL Depth to Groundwater		* Distance from people's surface water *
		onstruction Material * NONE WITHIN 1,000'.
rit Liner i nickness: mii B	elow-Grade Tank: VolumeDDB; C	onstruction Material 1888 MILLION 17000 .
12 Check Appropri	riate Box to Indicate _l Nature of N	Notice, Report, or Other Data
	N TO:	* *
NOTICE OF INTENTIO		SUBSEQUENT REPORT OF:
NOTICE OF INTENTIO PERFORM REMEDIAL WORK PLUG	AND ABANDON REMEDIAL V	SUBSEQUENT REPORT OF: WORK ALTERING CASING
NOTICE OF INTENTIO PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHAN	AND ABANDON REMEDIAL V	SUBSEQUENT REPORT OF: WORK ALTERING CASING
NOTICE OF INTENTIO PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHAN	AND ABANDON REMEDIAL V GE PLANS COMMENCE TO CASING TES	SUBSEQUENT REPORT OF: WORK ALTERING CASING DEDICATION AND ABANDONMENT STANDARD ABANDONMENT
NOTICE OF INTENTIO PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHAN	AND ABANDON REMEDIAL V GE PLANS COMMENCE TO CASING TES	SUBSEQUENT REPORT OF: WORK ALTERING CASING DEDICATION AND ABANDONMENT STANDARD ABANDONMENT
NOTICE OF INTENTIO PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHAN	AND ABANDON REMEDIAL V GE PLANS COMMENCE TO CASING TES	SUBSEQUENT REPORT OF: WORK ALTERING CASING DEDICATION AND ABANDONMENT STANDARD ABANDONMENT
NOTICE OF INTENTIO PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHAN	AND ABANDON REMEDIAL V GE PLANS COMMENCE TO CASING TES	SUBSEQUENT REPORT OF: WORK ALTERING CASING DEDILLING OPNS. PLUG AND
NOTICE OF INTENTIO PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHAN PULL OR ALTER CASING MULT COMP OTHER: 13. Describe proposed or completed operation of starting any proposed work). SEE Rior recompletion. 08/17/10: SET 4-1/2" CIBP @ 4,00	AND ABANDON REMEDIAL V GE PLANS COMMENCE CASING TES CEMENT JO OTHER: Ons. (Clearly state all pertinent details, ULE 1103. For Multiple Completions:	SUBSEQUENT REPORT OF: WORK ALTERING CASING DEDICATION AND ABANDONMENT STANDARD ABANDONMENT
NOTICE OF INTENTIO PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHAN PULL OR ALTER CASING MULT COMP OTHER: 13. Describe proposed or completed operati of starting any proposed work). SEE RI or recompletion. 08/17/10: SET 4-1/2" CIBP @ 4,00 PUMP A 25 SX. CMT. PLU 08/18/10: PERF. X SQZ. A 40 SX.	AND ABANDON REMEDIAL V GE PLANS COMMENCE CASING TES CEMENT JO OTHER: Ons. (Clearly state all pertinent details, ULE 1103. For Multiple Completions: 0'; PUMP A 25 SX. CMT. PLUG @ 45 G @ 3,550'-3,330' (CALC.).	SUBSEQUENT REPORT OF: NORK ALTERING CASING PLUG AND ABANDONMENT ST AND lability under hand is retained pending retained and give pertinent date and proposed completion. Attach wellbore diagram of proposed completion
NOTICE OF INTENTIO PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON MULT COME OTHER: 13. Describe proposed or completed operati of starting any proposed work). SEE Ri or recompletion. 08/17/10: SET 4-1/2" CIBP @ 4,00 PUMP A 25 SX. CMT. PLU 08/18/10: PERF. X SQZ. A 40 SX. CASING @ 1,719'.	AND ABANDON REMEDIAL V GE PLANS COMMENCE CASING TES CEMENT JO OTHER: Ons. (Clearly state all pertinent details. ULE 1103. For Multiple Completions: O'; PUMP A 25 SX. CMT. PLUG @ 4 G @ 3,550'-3,330' (CALC.). CMT. PLUG @ 2,310'; WCC X TAG C	SUBSEQUENT REPORT OF: WORK ALTERING CASING PLUG AND Approved for plugging of well bore only, Both And Subsequent Report of Well bore only, Porms, www.cound.d. OCD Well plugging of well bore only, and give pertinent disconnilly of well bore only, Attach wellbore diagram of the plugging to the plugging of the plu
NOTICE OF INTENTIO PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHAN PULL OR ALTER CASING MULT COME OTHER: 13. Describe proposed or completed operation of starting any proposed work). SEE Rivor recompletion. 08/17/10: SET 4-1/2" CIBP @ 4,00 PUMP A 25 SX. CMT. PLU 08/18/10: PERF. X SQZ. A 40 SX. CASING @ 1,719". 08/19/10: PUMP A 50 SX. CMT. PLU	AND ABANDON REMEDIAL V GE PLANS COMMENCE TIPLE CASING TES CEMENT JO OTHER: Ons. (Clearly state all pertinent details, ULE 1103. For Multiple Completions: O'; PUMP A 25 SX. CMT. PLUG @ 4 G @ 3,550'-3,330' (CALC.). CMT. PLUG @ 2,310'; WCC X TAG CO G @ 1,755'; WCC X TAG TOP OF CA	SUBSEQUENT REPORT OF: NORK ALTERING CASING PLUG AND ABANDONMENT ST AND lability under hond is retained pending receipt which may be found at oct well bore only; And give pertinent disconning chicking estimated date Attach wellbore diagram of proposed completion 4,000'-3,750'; CIRC. WELL W/ PXA MID.; MT. PLUG @ 1,592'; PUMP A 50 SX. CMT. PLUG
NOTICE OF INTENTIO PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHAN PULL OR ALTER CASING MULT COME OTHER: 13. Describe proposed or completed operation of starting any proposed work). SEE Rivor recompletion. 08/17/10: SET 4-1/2" CIBP @ 4,000 PUMP A 25 SX. CMT. PLU 08/18/10: PERF. X SQZ. A 40 SX. CASING @ 1,719". 08/19/10: PUMP A 50 SX. CMT. PLU @ 400"-250" (CALC.); ME	AND ABANDON REMEDIAL V GE PLANS COMMENCE TIPLE CASING TES CEMENT JO OTHER: TONS. (Clearly state all pertinent details, ULE 1103. For Multiple Completions: O'; PUMP A 25 SX. CMT. PLUG @ 4 G @ 3,550'-3,330' (CALC.). CMT. PLUG @ 2,310'; WCC X TAG C X X CIRCULATE TO SURFACE A 49 S	SUBSEQUENT REPORT OF: NORK ALTERING CASING PLUG AND ABANDONMENT ST AND Lability under hand is retained pending receipt and give pertinent data and color well bore entry and give pertinent data and color well plus entry Attach wellbore diagram of proposed completion A,000'-3,750'; CIRC. WELL W/ PXA MUD.; OMT. PLUG @ 1,592'; PUMP A 50 SX. CMT. PLUG EXC. CMT. PLUG @ 150'-3'; DIG OUT X CUT OFF
NOTICE OF INTENTIO PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHAN PULL OR ALTER CASING MULT COMF OTHER: 13. Describe proposed or completed operati of starting any proposed work). SEE Ri or recompletion. 08/17/10: SET 4-1/2" CIBP @ 4,00 PUMP A 25 SX. CMT. PLU 08/18/10: PERF. X SQZ. A 40 SX. CASING @ 1,719'. 08/19/10: PUMP A 50 SX. CMT. PLU @ 400'-250'(CALC.); ME WELLHEAD 3' B.G.L.; WELLY WELLHEAD 3' B.G.L.; WELLY ONE TEMPORARILY ABANDON CHAN PUMP A 50 SX. CMT. PLU 08/19/10: PUMP A 50 SX. CMT. PLU	AND ABANDON REMEDIAL V GE PLANS COMMENCE TIPLE CASING TES CEMENT JO OTHER: Ons. (Clearly state all pertinent details, ULE 1103. For Multiple Completions: O'; PUMP A 25 SX. CMT. PLUG @ 4 G @ 3,550'-3,330'(CALC.). CMT. PLUG @ 2,310'; WCC X TAG C X X CIRCULATE TO SURFACE A 49 S LD ON STEEL PLATE TO CASINGS X	SUBSEQUENT REPORT OF: NORK ALTERING CASING PLUG AND ABANDONMENT ST AND Lability under hand is retained pending receipt and give pertinent data and color well bore entry and give pertinent data and color well plus entry Attach wellbore diagram of proposed completion A,000'-3,750'; CIRC. WELL W/ PXA MUD.; OMT. PLUG @ 1,592'; PUMP A 50 SX. CMT. PLUG EXC. CMT. PLUG @ 150'-3'; DIG OUT X CUT OFF
NOTICE OF INTENTIO PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHAN PULL OR ALTER CASING MULT COME OTHER: 13. Describe proposed or completed operati of starting any proposed work). SEE RI or recompletion. 08/17/10: SET 4-1/2" CIBP @ 4,00 PUMP A 25 SX. CMT. PLU 08/18/10: PERF. X SQZ. A 40 SX. CASING @ 1,719". 08/19/10: PUMP A 50 SX. CMT. PLU @ 400'-250'(CALC.); ME WELL PLUGGED X ABANDONED 08/19/10	AND ABANDON REMEDIAL V GE PLANS COMMENCE TIPLE CASING TES CEMENT JO OTHER: Ons. (Clearly state all pertinent details. ULE 1103. For Multiple Completions: O'; PUMP A 25 SX. CMT. PLUG @ 4 G @ 3,550'-3,330' (CALC.). CMT. PLUG @ 2,310'; WCC X TAG CO X X CIRCULATE TO SURFACE A 49 S LD ON STEEL PLATE TO CASINGS X O	SUBSEQUENT REPORT OF: WORK ALTERING CASING PLUG AND APPROVED for Plugging of Well bore only, BY
NOTICE OF INTENTIO PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHAN PULL OR ALTER CASING MULT COME OTHER: 13. Describe proposed or completed operati of starting any proposed work). SEE Ri or recompletion. 08/17/10: SET 4-1/2" CIBP @ 4,00 PUMP A 25 SX. CMT. PLU 08/18/10: PERF. X SQZ. A 40 SX. CASING @ 1,719'. 08/19/10: PUMP A 50 SX. CMT. PLU @ 400'-250'(CALC.); MI WELLHEAD 3' B.G.L.; WE WELL PLUGGED X ABANDONED 08/19/10 I hereby certify that the information above is	AND ABANDON REMEDIAL V GE PLANS COMMENCE TIPLE CASING TES CEMENT JO OTHER: Ons. (Clearly state all pertinent details. ULE 1103. For Multiple Completions: O'; PUMP A 25 SX. CMT. PLUG @ 4 G @ 3,550'-3,330' (CALC.). CMT. PLUG @ 2,310'; WCC X TAG CO X X CIRCULATE TO SURFACE A 49 S LID ON STEEL PLATE TO CASINGS X O true and complete to the best of my k	SUBSEQUENT REPORT OF: NORK ALTERING CASING PLUG AND ABANDONMENT ST AND Lability under hand is retained pending receipt and give pertinent data and color well bore entry and give pertinent data and color well plus entry Attach wellbore diagram of proposed completion A,000'-3,750'; CIRC. WELL W/ PXA MUD.; OMT. PLUG @ 1,592'; PUMP A 50 SX. CMT. PLUG EXC. CMT. PLUG @ 150'-3'; DIG OUT X CUT OFF
NOTICE OF INTENTIO PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHAN PULL OR ALTER CASING MULT COME OTHER: 13. Describe proposed or completed operati of starting any proposed work). SEE Ri or recompletion. 08/17/10: SET 4-1/2" CIBP @ 4,00 PUMP A 25 SX. CMT. PLU 08/18/10: PERF. X SQZ. A 40 SX. CASING @ 1,719'. 08/19/10: PUMP A 50 SX. CMT. PLU @ 400'-250'(CALC.); MI WELLHEAD 3' B.G.L.; WE WELL PLUGGED X ABANDONED 08/19/10 I hereby certify that the information above is	AND ABANDON REMEDIAL V GE PLANS COMMENCE TIPLE CASING TES CEMENT JO OTHER: Ons. (Clearly state all pertinent details. ULE 1103. For Multiple Completions: O'; PUMP A 25 SX. CMT. PLUG @ 4 G @ 3,550'-3,330' (CALC.). CMT. PLUG @ 2,310'; WCC X TAG CO X X CIRCULATE TO SURFACE A 49 S LD ON STEEL PLATE TO CASINGS X O true and complete to the best of my k cording to NMOCD guidelines X, a general	SUBSEQUENT REPORT OF: NORK ALTERING CASING PLUG AND ABANDONMENT STAND Lability under hond is retained pending receipt which may be found at OCD While Plus and give pertinent discounting for their plus and give pertinent discounting for an (attached) alternative OCD-approved plan discounting for an (attached) alternative OCD-approved plan discounting for their plus and give pertinent discounting for an (attached) alternative OCD-approved plan discounting for their plus and give pertinent discounting for their plus and
NOTICE OF INTENTIO PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHAN PULL OR ALTER CASING MULT COME OTHER: 13. Describe proposed or completed operation of starting any proposed work). SEE Rivor recompletion. 08/17/10: SET 4-1/2" CIBP @ 4,00 PUMP A 25 SX. CMT. PLU 08/18/10: PERF. X SQZ. A 40 SX. CASING @ 1,719". 08/19/10: PUMP A 50 SX. CMT. PLU @ 400"-250" (CALC.); ME WELL PLUCCED X ABANDONED 08/19/10 I hereby certify that the information above is grade tank has been will be constructed or closed accounts.	AND ABANDON REMEDIAL V GE PLANS COMMENCE TIPLE CASING TES CEMENT JO OTHER: Ons. (Clearly state all pertinent details, ULE 1103. For Multiple Completions: O'; FUMP A 25 SX. CMT. PLUG @ 4 G @ 3,550'-3,330' (CALC.). CMT. PLUG @ 2,310'; WCC X TAG CO X X CIRCULATE TO SURFACE A 49 S LD ON STEEL PLATE TO CASINGS X O true and complete to the best of my k cording to NMOCD guidelines X, a general	SUBSEQUENT REPORT OF: WORK ALTERING CASING PLUG AND ABANDONMENT STAND Lability under hond is retained pending receipt which may be found at OCD Willing receipt and give pertinent Greaning for well bore only, and give pertinent Greaning for their greated date Attach wellbore diagram of proposed completion 4,000'-3,750'; CIRC. WELL W/ PXA MUD.; MT. PLUG @ 2,150'; CUT X LAY DOWN 4-1/2" MT. PLUG @ 1,592'; PUMP A 50 SX. CMT. PLUG SX. CMT. PLUG @ 150'-3'; DIG CUT X CUT OFF INSTALL DRY HOLE MARKER.
NOTICE OF INTENTIO PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHAN PULL OR ALTER CASING MULT COMF OTHER: 13. Describe proposed or completed operati of starting any proposed work). SEE RI or recompletion. 08/17/10: SET 4-1/2" CIBP @ 4,00 PUMP A 25 SX. CMT. PLU 08/18/10: PERF. X SQZ. A 40 SX. CASING @ 1,719". 08/19/10: PUMP A 50 SX. CMT. PLU @ 400'-250'(CALC.); MI WELLHEAD 3' B.G.L.; WE WELL PLUCCED X ABANDONED 08/19/10 I hereby certify that the information above is grade tank has been will be constructed or closed according to the constructed or c	AND ABANDON REMEDIAL V GE PLANS COMMENCE CASING TES CEMENT JO OTHER: Ons. (Clearly state all pertinent details. ULE 1103. For Multiple Completions: O'; PUMP A 25 SX. CMT. PLUG @ 4 G @ 3,550'-3,330' (CALC.). CMT. PLUG @ 2,310'; WCC X TAG CO X X CIRCULATE TO SURFACE A 49 S LD ON STEEL PLATE TO CASINGS X O true and complete to the best of my k cording to NMOCD guidelines X, a general TITLE E-mail address:	SUBSEQUENT REPORT OF: WORK ALTERING CASING PLUG AND ABANDONMENT BE DRILLING OPNS. PLUG OPNING BE DRILLING OPNING BE DRILLING OPNING BE DRILLING OPNS. PLUG OPNING BE DRILLING OP
NOTICE OF INTENTIO PERFORM REMEDIAL WORK PLUG TEMPORARILY ABANDON CHAN PULL OR ALTER CASING MULT COMF OTHER: 13. Describe proposed or completed operati of starting any proposed work). SEE RI or recompletion. 08/17/10: SET 4-1/2" CIBP @ 4,00	AND ABANDON REMEDIAL V GE PLANS COMMENCE CASING TES CEMENT JO OTHER: Ons. (Clearly state all pertinent details. ULE 1103. For Multiple Completions: O'; PUMP A 25 SX. CMT. PLUG @ 4 G @ 3,550'-3,330' (CALC.). CMT. PLUG @ 2,310'; WCC X TAG CO X X CIRCULATE TO SURFACE A 49 S LD ON STEEL PLATE TO CASINGS X O true and complete to the best of my k cording to NMOCD guidelines X, a general TITLE E-mail address:	SUBSEQUENT REPORT OF: WORK ALTERING CASING PLUG AND ABANDONMENT STAND Lability under hond is retained pending receipt which may be found at OCD Writing plus sense teld date and give pertinent Cheaning for their gesting testing testin