## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE OIL CONSERVATION DIVISION	
DISTRICT I 1220 South St. Francis Dr.	WELL API NO. 30-025-37481
DISTRICT II AUG 23 7010 Santa Fe, NM 87505	5 Indicate Type of Lease
1301 W. Grand Ave, Artesia, NM 882140BBSOCD	STATE X FEE
DISTRICT III	6. State Oil & Gas Lease No
1000 Rio Brazos Rd, Aztec, NM 87410	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals )  1. Type of Well:	Section 25  8. Well No. 731
Oil Well X Gas Well Other	o. wom.to. 731
2. Name of Operator Occidental Permian Ltd.	9 OGRID No. 157984
3 Address of Operator	10 Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	ì î
4 Well Location	(105×
Unit Letter B · 863 Feet From The North 2020 Fee	et From The West Line
Section 25 Township 18-S Range 37-	E NMPM Lea County
11. Elevation (Show whether DF, RKB, RT GR, etc.) 3678' KB	
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well	Distance from nearest surface water
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Ma	aterial
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Company of the	
NOTICE OF WITCHTION TO	OF OUT DEDOOT OF
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	SEQUENT REPORT OF:  ALTERING CASING
	ALTERING CASING
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING  NS. PLUG & ABANDONMENT
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP	ALTERING CASING  NS. PLUG & ABANDONMENT
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN  OTHER. OAP and acid treat X OTHER:	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  s, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT  OTHER. OAP and acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertunent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  s, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER. OAP and acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. Kill well. POOH w/ESP & equipment. 2. Clean out to PBTD @4396'.	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  s, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER. OAP and acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. Kill well. POOH w/ESP & equipment. 2. Clean out to PBTD @4396'. 3. Perforate hole @4326-35', 4345-60'.	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  s, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER. OAP and acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. Kill well. POOH w/ESP & equipment. 2. Clean out to PBTD @4396'. 3. Perforate hole @4326-35', 4345-60'. 4. Acid treat well w/3444 gal of 15% NEFE acid.	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  s, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT  OTHER. OAP and acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. Kill well. POOH w/ESP & equipment.  2. Clean out to PBTD @4396'.  3. Perforate hole @4326-35', 4345-60'.  4. Acid treat well w/3444 gal of 15% NEFE acid.  5. Perform scale squeeze.	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  s, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER. OAP and acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. Kill well. POOH w/ESP & equipment. 2. Clean out to PBTD @4396'. 3. Perforate hole @4326-35', 4345-60'. 4. Acid treat well w/3444 gal of 15% NEFE acid.	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  s, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT  OTHER. OAP and acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. Kill well. POOH w/ESP & equipment.  2. Clean out to PBTD @4396'.  3. Perforate hole @4326-35', 4345-60'.  4. Acid treat well w/3444 gal of 15% NEFE acid.  5. Perform scale squeeze.  6. Run back in hole with ESP equipment.	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  s, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT  OTHER. OAP and acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. Kill well. POOH w/ESP & equipment.  2. Clean out to PBTD @4396'.  3. Perforate hole @4326-35', 4345-60'.  4. Acid treat well w/3444 gal of 15% NEFE acid.  5. Perform scale squeeze.  6. Run back in hole with ESP equipment.	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  s, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP  PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT  OTHER. OAP and acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. Kill well. POOH w/ESP & equipment.  2. Clean out to PBTD @4396'.  3. Perforate hole @4326-35', 4345-60'.  4. Acid treat well w/3444 gal of 15% NEFE acid.  5. Perform scale squeeze.  6. Run back in hole with ESP equipment.	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  s, including estimated date of starting any
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER. OAP and acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. Kill well. POOH w/ESP & equipment. 2. Clean out to PBTD @4396'. 3. Perforate hole @4326-35', 4345-60'. 4. Acid treat well w/3444 gal of 15% NEFE acid. 5. Perform scale squeeze. 6. Run back in hole with ESP equipment. 7. Return well to production.	ALTERING CASING PLUG & ABANDONMENT NT JOB  s, including estimated date of starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion OTHER. OAP and acid treat  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. Kill well. POOH w/ESP & equipment. 2. Clean out to PBTD @4396'. 3. Perforate hole @4326-35', 4345-60'. 4. Acid treat well w/3444 gal of 15% NEFE acid. 5. Perform scale squeeze. 6. Run back in hole with ESP equipment. 7. Return well to production.  I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative	ALTERING CASING PLUG & ABANDONMENT NT JOB  s, including estimated date of starting any completion or recompletion.
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER. OAP and acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. Kill well. POOH w/ESP & equipment. 2. Clean out to PBTD @4396'. 3. Perforate hole @4326-35', 4345-60'. 4. Acid treat well w/3444 gal of 15% NEFE acid. 5. Perform scale squeeze. 6. Run back in hole with ESP equipment. 7. Return well to production.  I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  s, including estimated date of starting any completion or recompletion.  that any pit or below-grade tank has been/will be e OCD-approved
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion TOTHER. OAP and acid treat  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed  1. Kill well. POOH w/ESP & equipment. 2. Clean out to PBTD @4396'. 3. Perforate hole @4326-35', 4345-60'. 4. Acid treat well w/3444 gal of 15% NEFE acid. 5. Perform scale squeeze. 6. Run back in hole with ESP equipment. 7. Return well to production.  I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan.  SIGNATURE  TITLE Administrative	ALTERING CASING  PLUG & ABANDONMENT  NT JOB  s, including estimated date of starting any completion or recompletion.  that any pit or below-grade tank has been/will be  e OCD-approved  Associate  DATE 08/18/2010
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER. OAP and acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed I. Kill well. POOH w/ESP & equipment.  2. Clean out to PBTD @4396'.  3. Perforate hole @4326-35', 4345-60'.  4. Acid treat well w/3444 gal of 15% NEFE acid.  5. Perform scale squeeze.  6. Run back in hole with ESP equipment.  7. Return well to production.  I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan.  SIGNATURE TITLE Administrative TYPE OR PRINT NAME Mendy Johnson E-mail address: mendy johnson@oxy.com	ALTERING CASING  PLUG & ABANDONMENT  NT JOB  s, including estimated date of starting any completion or recompletion.  that any pit or below-grade tank has been/will be  e OCD-approved  Associate  DATE 08/18/2010
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion THER. OAP and acid treat The proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed 1. Kill well. POOH w/ESP & equipment.  2. Clean out to PBTD @4396'. 3. Perforate hole @4326-35', 4345-60'. 4. Acid treat well w/3444 gal of 15% NEFE acid. 5. Perform scale squeeze. 6. Run back in hole with ESP equipment. 7. Return well to production.  Thereby certify that the information above is true and complete to the best of my knowledge and behef. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan  SIGNATURE TITLE Administrative mendy Johnson@oxy.com  For State Use Only	ALTERING CASING  NS. PLUG & ABANDONMENT  S, including estimated date of starting any completion or recompletion.  That any pit or below-grade tank has been/will be e OCD-approved  Associate DATE 08/18/2010  TELEPHONE NO. 806-592-6280
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER. OAP and acid treat X OTHER:  13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed I. Kill well. POOH w/ESP & equipment.  2. Clean out to PBTD @4396'.  3. Perforate hole @4326-35', 4345-60'.  4. Acid treat well w/3444 gal of 15% NEFE acid.  5. Perform scale squeeze.  6. Run back in hole with ESP equipment.  7. Return well to production.  I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative plan.  SIGNATURE TITLE Administrative TYPE OR PRINT NAME Mendy Johnson E-mail address: mendy johnson@oxy.com	ALTERING CASING  NS. PLUG & ABANDONMENT  NT JOB  s, including estimated date of starting any completion or recompletion.  that any pit or below-grade tank has been/will be  e OCD-approved  Associate DATE 08/18/2010  TELEPHONE NO. 806-592-6280