State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE OIL CONSERVATION DIVISION	
DISTRICT I 1625 N French Dr , Hobbs, NM 8820 C Santa Fe, NM 87505	WELL API NO 30-025-05505
DISTRICT II	5. Indicate Type of Lease
1301 W Grand Ave, Artesia, NM 88210CT 18 2010	STATE X FEE
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 874140BBSUCD	6 State Oil & Gas Lease No
SUNDRY NOTICES AND REPORTS ON WELLS	7 Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	North Hobbs (G/SA) Unit
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals)	Section 25
1 Type of Well Oil Well Gas Well Other Temporarily Abandoned	8 Well No 321
2 Name of Operator	9 OGRID No 157984
Occidental Permian Ltd. 3 Address of Operator	10. Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323	<u> </u>
4 Well Location	
Unit Letter G 1980 Feet From The North 1980 Fee	t From The <u>East</u> Line
Section 25 Township 18-S Range 37-E	NMPM Lea County
11 Elevation (Show whether DF, RKB, RT GR, etc.) 3658' GL	
Pit or Below-grade Tank Application or Closure	j
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Ma	terial
12. Check Appropriate Box to Indicate Nature of Notice, Report, or C	
NOTICE OF INTENTION TO: SUBS	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERNO CACINO
	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPI	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPI PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN	NS. PLUG & ABANDONMENT
	NS. PLUG & ABANDONMENT
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMEN OTHER: Return well to production OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates.)	T JOB
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Return well to production OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed or complete the proposed of	T JOB
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Return well to production OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the Kill well.	T JOB
PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT OTHER: Return well to production OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed or complete the proposed of	T JOB
PULL OR ALTER CASING Multiple Completion OTHER: Return well to production OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the Kill well. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the total complete	T JOB
PULL OR ALTER CASING Multiple Completion OTHER: Return well to production OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the Kill well. 2. Drill out CIBPs set @3900', 4095', 4132'. 3. Squeeze perfs. 4. Clean out to 4130'. 5. Deepen well to 4335'.	T JOB
PULL OR ALTER CASING Multiple Completion OTHER: Return well to production OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the Kill well. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the total complete	T JOB
PULL OR ALTER CASING Multiple Completion OTHER: Return well to production OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the Kill well. 2. Drill out CIBPs set @3900', 4095', 4132'. 3. Squeeze perfs. 4. Clean out to 4130'. 5. Deepen well to 4335'. 6. Run CNL/GR/CCL from TD to 3355'. 7. Perforate well. 9. RIH w/ESP equipment.	T JOB
PULL OR ALTER CASING Multiple Completion OTHER: Return well to production OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the Kill well. 2. Drill out CIBPs set @3900', 4095', 4132'. 3. Squeeze perfs. 4. Clean out to 4130'. 5. Deepen well to 4335'. 6. Run CNL/GR/CCL from TD to 3355'. 7. Perforate well.	T JOB
PULL OR ALTER CASING Multiple Completion OTHER: Return well to production OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the Kill well. 2. Drill out CIBPs set @3900', 4095', 4132'. 3. Squeeze perfs. 4. Clean out to 4130'. 5. Deepen well to 4335'. 6. Run CNL/GR/CCL from TD to 3355'. 7. Perforate well. 9. RIH w/ESP equipment.	T JOB
PULL OR ALTER CASING Multiple Completion OTHER: Return well to production OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the Kill well. 2. Drill out CIBPs set @3900', 4095', 4132'. 3. Squeeze perfs. 4. Clean out to 4130'. 5. Deepen well to 4335'. 6. Run CNL/GR/CCL from TD to 3355'. 7. Perforate well. 9. RIH w/ESP equipment. 10. Return well to production.	PLUG & ABANDONMENT T JOB including estimated date of starting any ompletion or recompletion.
PULL OR ALTER CASING Multiple Completion OTHER: Return well to production OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the Kill well. 2. Drill out CIBPs set @3900', 4095', 4132'. 3. Squeeze perfs. 4. Clean out to 4130'. 5. Deepen well to 4335'. 6. Run CNL/GR/CCL from TD to 3355'. 7. Perforate well. 9. RIH w/ESP equipment. 10. Return well to production.	PLUG & ABANDONMENT T JOB including estimated date of starting any ompletion or recompletion.
PULL OR ALTER CASING Multiple Completion OTHER: Return well to production OTHER. 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed of the Kill well. 2. Drill out CIBPs set @3900', 4095', 4132'. 3. Squeeze perfs. 4. Clean out to 4130'. 5. Deepen well to 4335'. 6. Run CNL/GR/CCL from TD to 3355'. 7. Perforate well. 9. RIH w/ESP equipment. 10. Return well to production.	PLUG & ABANDONMENT T JOB including estimated date of starting any ompletion or recompletion.
PULL OR ALTER CASING	PLUG & ABANDONMENT T JOB including estimated date of starting any ompletion or recompletion. that any pit or below-grade tank has been/will be
PULL OR ALTER CASING	PLUG & ABANDONMENT T JOB including estimated date of starting any ompletion or recompletion. that any pit or below-grade tank has been/will be
PULL OR ALTER CASING	Including estimated date of starting any ompletion or recompletion. T JOB
PULL OR ALTER CASING	Including estimated date of starting any ompletion or recompletion. T JOB