RECEIVED

Form 3160-5

OCT 2 1 2010

UNITED STATES

FORM APPROVED

SUNDRY Do not use t	DEPARTMENT OF THE BUREAU OF LAND MAN NOTICES AND RE his form for proposals in tell. Use Form 3160-3 (NAGEMENT PORTS ON V	re-enter an	5. Lease Serial NM 0113			
SUBMIT IN TR	7. If Unit or CA/Agreement, Name and/or No.						
2. Name of Operator Edge Petrole 3a Address POB 51937 Midland, TX 7	eum Operating Company, Inc.,	3b. Phone No. (inc. 432-682-1002	clude area code)	8. Well Name and No. South Lusk 33 Federal #1 9. API Well No. 30-025-36312 10. Field and Pool, or Exploratory Area			
4. Location of Well (Footage, Sec., 1545' FNL & 1980' FWL / Sec. 33, T-19S, R-32E					Parish, State		
12. CHECK A	PPROPRIATE BOX(ES) TO		TURE OF NOTICE, RE	EPORT, OR (OTHER DATA		
✓ Notice of Intent ☐ Subsequent Report ☐ Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abando Plug Back	Production (Star Reclamation Recomplete	, [Water Shut-Off Well Integrity Other		
following completion of the inv	ne work will be performed or provide object on the control of the operations. If the operation real Abandonment Notices shall be fi	y, give subsurface locate the Bond No. on file the Bond No. on file sults in a multiple co	estimated starting date of any ations and measured and true le with BLM/BIA. Required	vertical depths of subsequent repo	of all pertinent markers and zones orts shall be filed within 30 days	S.	

Edge Petroleum is requesting approval to plug & abandon the South Lusk 33 Federal #1. Edge also requests that a 90 day period be granted to have P&A completed. Procedure to P & A well is attached.

SEE ATTACHED FOR CONDITIONS OF APPROVAL

RECLAMATION PROCEDURE ATTACHED

determined that the site is ready for final inspection.)

 I hereby certify that the foregoing is true and correct Name (Printed/Typed) 	1									
Angela Lightner angela@rkford.com		Title Regulatory Consultant								
Signature lingola hichtney		Date 10/04/2010								
THIS SPACE FOR FEDERAL OF STATE OFFICE (SEE ROVE)										
	<i>77</i>	<u> </u>) HAAH	VOVLU					
Approved by		Title			Date					
Conditions of approval if any, are attached. Approval of this notice does not warrar certify that the applicant holds legal or equitable title to those rights in the subject lea which would entitle the applicant to conduct operations thereon.	nt or	Office	/s	OCT : Dustin	2 0 2010 Winkler	``				
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and will the hard the statements or representations as to any matter within its jurisdiction. CARL SBAD FIELD OFFICE										
(Instructions on page 2)	F	DISTR	IGT :	I SUPER						
		OCT 2	2 20	10	/					

EDGE PETROLEUM

Procedure to Plug and Abandon Well

S. Lusk 33 Fed. #1 Eddy County, NM

1545' FNL & 1980' FWL Sec. 33, T19S, R32E October 1, 2010

Elevation:

3,539' GL 3,566' KB

AFE #:

PBTD:

12,115' KB

CURRENT STATUS:

The well is currently shut in after uneconomic Atoka

recompletion efforts.

PROPOSED OPERATIONS:

Plug and abandon well in accordance with NM BLM

guidelines.

Casing Size: 5 1/2" 17# P-110 LTC ID/Drift: 4.862" / 4.767"

Procedure to Plug and Abandon Well

- (1) M.I.R.U. WSU. ND WH NU BOP. Unset and POOH w/ Tbg.
- (2) RIH to 12,000'. Set CIBP. Spot 35 sxs. Cmt.
- (3) PUH w/ Tbg.to 10,680' Spot 75 sxs. Cmt. WOC & tag.
- (4) PUH w/ Tbg.to 8,436' Spot 55 sxs. Cmt.
- (5) PUH w/ Tbg.to 4,360' Spot 45 sxs. Cmt. WOC & tag.
- (6) PUH w/ Tbg.to 3,062' Spot 35 sxs. Cmt.
- (7) PUH w/ Tbg.to 2,580' Spot 25 sxs. Cmt. WOC & tag.
- (8) PUH w/ Tbg.to 1,695' Spot 20 sxs. Cmt.
- (9) PUH to 890' Spot 45 sxs. Cmt. WOC & tag.
- (10) Spot 10 sxs. Cmt. To surface.

- (11) Cut off casing at base of cellar and cover wellbore with appropriate surface cap. Fill in cellar with suitable material. R.D.M.O.
- Cement will be Class C w/ 2% CaCl.

EDGE PETROLEUM OPERATING CO., INC. WELL SUMMARY .EASE: SOUTH LUSK 33 FED SURF LOC: SECTION 33, T19S, R32E ENGR: D. Hurd Updated 6/12/06 NELL: No. 1 BHL: STRAIGHT HOLE RIG: Big Dog #11 EDDY CO., NM AREA: X: ELEV. 3539 FIELD. **SOUTH LUSK** Y: KB: 3566 **OPEN HOLE** SANDS/ DEPTH CASING CASING LOGGING MARKERS TVD MD **PROFILE DETAILS** 40' 40' 30" Conductor 20", 106 ppf 890' 890, H-40, STC Yates 2695 2695* 13 3/8", 68 ppf P-110, L-80, K-55, BTC 2580 2580 0'-2580' Cmt'd w/2060 sks Capitan 3062 3062" TOC @ 9 5/8", 43.5 & 47 ppf E-LOGS P-110 & N-80 LTC NONE 4360' Delaware 4360' 0'-4360' Cmt'd w/900 sks TOC @ 4400' 2 7/8", 6.5#, P-110, EOT @ 11,920" **Wolfcamp Lime** 10605 10605 Strawn 11335 11335 SN FSG 2.25" Profile Nipple @ 11,920" Arrow-Set Paker @ 11,927 Atoka Clastic 11790 11790 Atoka Sand 12022 12022 Perf Atoka 12,023' - 12,028', 6 SPF w/ 2.125" Strip Gun . Ator 35' Cmt Plug Est PBTD 12,115' CIBP - Set 5/2/06 @ 12,150' **Upper Morrow** 12175 12175 Perf Upper Morrow 12176'-12184' Middle Morrow 124181 12418 **ZHAC** CIBP - Set 7/15/05 w/ 35' cmt PBTD 12,305 Perf Upper Morrow 12374'-12384' **Lower Morrow** 12515 12515 Perf Middle Morrow 12420'-12468' CIBP @ 12512' w/10 cmt on top TOWN Perf Lwr Morrow 12515'-25', wet E-LOGS 5 1/2", 17#, Triple Combo N-80 & P-110, LTC 4500' to 12800' TD 12834 12834 0'-12834' Cmt'd w/ 2757 sxs

Edge Petroleum Operating Company, Inc.

NM-01135: South Lusk 33 Federal #1

API: 30-025-36312

Lea County, New Mexico

RE: Plugging and Abandonment Requirements, Conditions of Approval

- 1. Tag to verify depth of CIBP and cement at 12115' prior to step 2 Otherwise OK
- 2. OK (Perfs)
- 3. Tag at 10370' or shallower Otherwise OK (Wolfcamp)
- 4. Move: Spot from 7365' to 7195' or shallower Otherwise OK (Bone Spring)
- 5. Change: Perf and squeeze from 4395'-4255'. Tag at 4255' or shallower Otherwise OK (Delaware)
- 6. Change: Perf and squeeze from 3155'-3025'. WOC and tag at 3025' or shallower Otherwise OK (Capitan Reef)
- 7. Change: Perf and squeeze a plug from 2705'-2530'. Tag at 2530' or shallower Otherwise OK (Yates BOS Casing shoe)
- 8. Change: Perf and squeeze a plug from 1050'-840'. WOC and tag at 840' or shallower. Minimum 25sx Otherwise OK (TOS Casing shoe)
- 9. Removed: Covered in previous step.
- 10. Plug to be from 60' to surface. Perforations required Otherwise OK
- 11. Verify that all annuluses have cement to surface and fill in as required. Ground level dry hole marker to be used in this area; **Requirements attached** Otherwise OK
- 12. Submit a subsequent report to the BLM.

H₂S monitoring equipment shall be on location.

See attached standard COAs.

DHW 102010

Requirements for ground level dry hole markers <u>Well Identification Markers</u> Conditions of Approval (COA)

The BLM Carlsbad Field Office (CFO) Conditions of Approval (COA) Requires that ground level dry hole markers be placed on well within the Lesser Prairie Chicken habitat area. The dry hole markers will be to the following specifications. The operator will construct the markers as follows:

- 1. An 8 inch X 8 inch steel plate 1/8 to 3/16 of an inch thick is to be placed on the old dry hole marker stand pipe 2 inches from ground level, in the Lesser Prairie Chicken habitat area.
- 2. Steel plate may be welded or bolted approximately 2 inches from ground level on the stand pipes. If plates are bolted to the stand pipe, the person installing the plate will be required to weld a pipe collar on the plate and place a minimum of two set screws/bolt on each collar. Aluminum data plates may be bolted with minimum ¼ inch bolt and locking nuts or self tapping fine threaded screws. A minimum of one in each corner is to be installed on each plate.
- 3. An 8 inch x 8 inch aluminum plate, which is 12 gauge or .080 sign material (1/8 inch aluminum plate may be used in place of the .080 plate) with the required information for that well stamped or engraved in a minimum 3/8 inch tall letter or number.
- 4. The following information will be stamped or engraved on the 8 inch X 8 inch aluminum plate in the following order.
 - a. First row: Operators name
 - b. Second row: Well name and number
 - c. Third row: Legal location to include ½ ¼, Section, Township, and range. If the legal location cannot be placed on one row it can be split into two rows with the ¼ ¼ (example: 1980 FNL 1980 FWL) being on the top row.
 - d. Fourth row: Lease Number and API number.
 - i. Example marker plate: (attached)

NMOCD Order No. R-12965 also required the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a ground level dry hole marker was installed as required in the COA's from the BLM.

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in a cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Any plug that requires a tag will have a minimum WOC time of 4 hours.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

- 6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified when the wellhead is cut off to verify that cement is to surface in the casing and all annuluses. The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation procedure.

DHW 112309



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its pre-disturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.

- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.
- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Environmental Protection Specialist 575-234-5909, 575-361-2648 (Cell)

Terry Gregston Environmental Protection Specialist 575-234-5958

Bobby Ballard Environmental Protection Specialist 575-234-2230

Randy Rust Natural Resource Specialist 575-234-5943

Linda Denniston Environmental Protection Specialist 575-234-5974

Jennifer Van Curen Environmental Protection Specialist 575-234-5905

Justin Frye Environmental Protection Specialist 575-234-5922 Cody Layton Natural Resource Specialist 575-234-5959

Trishia Bad Bear Natural Resource Specialist 575-393-3612

Todd Suter Surface Protection Specialist 575-234-5987

Doug Hoag Civil Engineering Technician 575-234-5979

Tanner Nygren Natural Resource Specialist 575-234-5975

John Fast Natural Resource Specialist 575-2345996