Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103
District I	State of New Mexico State of New Mexico Resources Resources Resources	WELL API NO.
District II	27 2010 IL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505	30-041-20416
1301 W. Grand Ave., Artesia, NM 88210	7 2018IL CONSERVATION DIVISION	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 8340	Sonta Fa NM 87505	STATE FEE S
District IV 1220 S. St. Francis Dr., Santa Fe, PAOB 87505	BSOCO Santa Fe, NM 87505 ICES AND REPORTS ON WELLS	6. State Oil & Gas Lease No.
		7. Lease Name or Unit Agréement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		Roberts
1. Type of Well: Oil Well Gas Well Other		8. Well Number #1
2. Name of Operator		9. OGRID Number 243978 /
Saber Oil & Gas Ventures, LLC 3. Address of Operator		10. Pool name or Wildcat
400 W. Illinois, Suite 950, Midland, TX 79701		Chaveroo Canyon, North
4. Well Location		
Unit LetterD:	660'feet from theNorth line and	660'feet from theWestline
Section 9 Township 7S Range 33E NMPM Roosevelt County		
	11. Elevation (Show whether DR, RKB, RT, GR, 6 4386' GR	etc.)
12. Check	Appropriate Box to Indicate Nature of Notic	ce, Report or Other Data
NOTICE OF IN	TENTION TO: SU	JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL WOR		
		DRILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL CASING/CEMI	ENT JOB
DOWNHOLE COMMINGLE		
OTHER:	☐ OTHER:	
	pleted operations. (Clearly state all pertinent details,	
of starting any proposed we proposed completion or rec	ork). SEE RULE 19.15.7.14 NMAC. For Multiple (completion.	Completions: Attach wellbore diagram of
	1 1 III II	70
P& A well as follows: (See attached wellbore diagrams). Set retainer at 6350'. Pump 70 sx cement through retainer at 6300'. Cut and pull 4-1/2" casing at 6250'. Set 30 sx stub plug in and out of casing at 6250' and tag / Load the hole with plug mud. Set 35		
and pull 4-1/2" casing at 6250'. Set 30 sx stub plug in and out of casing at 6250' and tag. Load the hole with plug mud. Set 35 sx plug at in and out at bottom of 8-5/8" casing. Perforate holes in 8-5/8" at 450'. Establish circulation up annulus between 8-		
5/8" and 11-3/4" surface pipe. Pump down 8-5/8" casing and fill inside and annulus of 8-5/8" with 225 sx cement. Circ cement		
to surface. Install dry hole marker.		
Coul Date	Pio Poloso Poss	
Spud Date:	Rig Release Date:	
I hereby certify that the information	above is true and complete to the best of my knowle	dge and belief.
SIGNATURE Man	TITLE VP of Enginee	ring DATE 9/23/2010
SIGNATURE_ JULY	THEEVI OI Enginee	MIIIgDATE9/25/2010
Type or print name _Doug Keathley E-mail address: doug@sagebrushoil.com_ PHONE: _432-685-0169		
For State Use Only	() $()$ $()$ $()$	
APPROVED BY: TITLE STAFF WAS DATE 10-28-10		
Conditions of Approval (if any):		
	THE OIL CONSERVATION DIVISION MUST BE NOTIFIED 24 HOURS PRIOR TO THE	
	BEGINNING OF PLUGGING OPERATIONS.	9. ^{2.}



