Submit 3 copies to Appropriate District Office

Type of Well:

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210 DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION O. Box 1980, Hobbs, NM 88240 STRICT II D. Box Drawer DD, Artesia, NM 88210 STRICT III OO Rio Brazos Rd., Aztec, NM 87410 OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088	WELL API NO. 30-025-06944 5. Indicate Type of Lease STATE ☐ FEE 6. State Oil / Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI (FORM C-101) FOR SUCH PROPOSALS.	7. Lease Name or Unit Agreement Name CENTRAL DRINKARD UNIT
Type of Well: OIL WELL OTHER Name of Operator CHEVRON USA INC	8. Well No. 450H

2. Name of Operator CHEVRON USA INC 150 9. Pool Name or Wildcat 3. Address of Operator 15 SMITH ROAD, MIDLAND, TX 79705 DRINKARD 4. Well Location 2086' Feet From The SOUTH Line and 2086' Feet From The EAST Unit Letter_ Township 21-S LEA COUNTY Section 32 Range 37-E

10. Elevation (Show whether DF, RKB, RT,GR, etc.)

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK		PLUG AND ABANDON		REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON		CHANGE PLANS		COMMENCE DRILLING OPERATION	PLUG AND ABANDONMENT	
PULL OR ALTER CASING				CASING TEST AND CEMENT JOB		
OTHER:	<u>:</u>			OTHER: HORI	ZONTAL	✓

- 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
- 1-05-04: MIRU. SET CIBP @ 6460'. TIH W/PROD TBG TO 6450. CIRC CLEAN.


- 1-06-04: NDBOP. NUWH. RIG DOWN. CLEAN LOCATION.
- 1-19-04: TIH W/PKR TO 5875. TEST CSG & PLUG TO 6460. PUH & SET PKR @ 5686. TEST SQZ PERFS 6495-6515.
- 1-20-04: RIG DOWN, CLEAN LOCATION. TURN WELL OVER TO PRODUCTION.

- 2-03-04: RIG IDLE. WILL BREAK TOUR 7 AM 2-04-04.
- 2-04-04: TAG CIBP @ 6453'. PU WHIPSTOCK.
- 2-05-04: SET WHIPSTOCK @ 61.15 AZ. CUT WINDOW FR 6444-6455. BOW @ 6452. 3' RAT HOLE. DRILL 6453-6455,6462
- 2-06-04: DRILL 6493,6505,6620,6683,6739,6894,6938,6963,7034,7044,7112,7127,7160,7170,7212,7234,7354,7362,7447,7544,7551,7600,

7660,7672,7780,7787,7861,7867,7879, 7969,8012,8066,8084,8133,8140,8154,8172,8187,8229,8249,8342,8349,8426,8439,8449,8520,8529, 8604,8613,8628,8709,8718,8745,8789,8799,8853,8873,8944. TD 6 1/8" LATERAL @ 0930 HRS 2-13-04.

2-14-04: RIG DOWN. RELEASE RIG @ 0200 HRS.

WAIT ON COMPLETION



	(<i>Q</i>			
I hereby certify that the information above SIGNATURE	is true and complete to the best of my knowledge and belief.	Regulatory Specialist	DATE	16/2004
TYPE OR PRINT NAME	Denise Leake		Telephone No.	915-687-7375

CONDITIONS OF APPROVAL IF ANY:

OG FIELD REPRESENTATIVE II/STAFF MANAGEE 2 3 2004