

Submit 3 Copies To Appropr District Office	Otate of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resou	urces May 27, 2004 WELL API NO.
1625 N. French Dr., Hobbs,	NM 88240	
1301 W. Grand Ave., Artesia	, NMRECEOVEONSERVATION DIVISIO	5. Indicate Type of Lease
88210	1220 South St. Francis Dr.	STATE FEE
District III 1000 Rio Brazos Rd Aztec	NOV 29 2010 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87410	•	o. State Oil & Gas Lease No.
District IV	HOBBSOCD	
1220 S. St. Francis Dr., San 87505	a Fe, NM	
	RY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement
(DO NOT USE THIS FORM DIFFERENT RESERVOIR.	FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACKUSE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	KTO A Name
PROPOSALS.) 1. Type of Well: Oil W	/ell ☐ Gas Well ☐ Other X ☐ 5 ~	8. Well Number H-280
2 Name of Operator	LEGACY RESERVES OPERATING LP -	9. OGRID Number 240974
3. Address of Operato		10. Pool name or Wildcat
	MIDLAND, TX 79702	JUSTIS-BLINEBRY-TUBB-DRINKARD
4. Well Location		
Unit Letter H	: 2590 feet from the NORTH line a	and <u>150</u> feet from the <u>East</u> line.
Section 3	6 Township T25S Range R	R37E NMPM LEA County
	11. Elevation (Show whether DR, RKB, F	RT, GR, etc.)
	3036' GR	
Pit or Below-grade Tank Ap	plication ☐ or Closure ☐	
Pit typeDept	h to GroundwaterDistance from nearest fresh water	well Distance from nearest surface
water		
Pit Liner Thickness:	mil Below-Grade Tank: Volume	bbls; Construction Material
40 06		
17 Lr	neck Appropriate Box to Indicate Nature of N	Notice Report or Other Data
12. 01	11 1	volice, report of Other Data
		•
NOTICE	E OF INTENTION TO:	SUBSEQUENT REPORT OF:
NOTICE PERFORM REMEDIAL W	E OF INTENTION TO: VORK □ PLUG AND ABANDON □ REMEDIA	SUBSEQUENT REPORT OF:
NOTICE PERFORM REMEDIAL W TEMPORARILY ABANDO	E OF INTENTION TO: VORK PLUG AND ABANDON REMEDIA ON CHANGE PLANS COMMEN	SUBSEQUENT REPORT OF: L WORK ALTERING CASING CE DRILLING OPNS. P AND A
NOTICE PERFORM REMEDIAL W	E OF INTENTION TO: VORK PLUG AND ABANDON REMEDIA ON CHANGE PLANS COMMEN	SUBSEQUENT REPORT OF:
NOTICE PERFORM REMEDIAL W TEMPORARILY ABANDO	E OF INTENTION TO: VORK PLUG AND ABANDON REMEDIA ON CHANGE PLANS COMMEN	SUBSEQUENT REPORT OF: LE WORK ALTERING CASING CE DRILLING OPNS. P AND A CEMENT JOB
NOTICE PERFORM REMEDIAL W TEMPORARILY ABANDO PULL OR ALTER CASING	E OF INTENTION TO: VORK PLUG AND ABANDON REMEDIA COMMEN COMMEN CASING/C	SUBSEQUENT REPORT OF: L WORK ALTERING CASING CE DRILLING OPNS. P AND A CEMENT JOB MIT & return to injection
NOTICE PERFORM REMEDIAL W TEMPORARILY ABANDO PULL OR ALTER CASING OTHER: 13. Describe propos	E OF INTENTION TO: VORK PLUG AND ABANDON REMEDIA DN CHANGE PLANS COMMEN CASING/O DOTHER: Seed or completed operations. (Clearly state all pertir	SUBSEQUENT REPORT OF: LE WORK ALTERING CASING CE DRILLING OPNS. PAND A CEMENT JOB MIT & return to injection Amount details, and give pertinent dates, including
NOTICE PERFORM REMEDIAL W TEMPORARILY ABANDO PULL OR ALTER CASING OTHER: 13. Describe proposestimated date of	E OF INTENTION TO: VORK PLUG AND ABANDON REMEDIA COMMEN COMMEN CASING/C	SUBSEQUENT REPORT OF: LE WORK ALTERING CASING CE DRILLING OPNS. PAND A CEMENT JOB MIT & return to injection Amount details, and give pertinent dates, including
NOTICE PERFORM REMEDIAL W TEMPORARILY ABANDO PULL OR ALTER CASING OTHER: 13. Describe propose estimated date of diagram of proport	E OF INTENTION TO: VORK PLUG AND ABANDON REMEDIA ON CHANGE PLANS COMMEN G MULTIPLE COMPL CASING/O OTHER: sed or completed operations. (Clearly state all pertir of starting any proposed work). SEE RULE 1103. Fosed completion or recompletion.	SUBSEQUENT REPORT OF: LE WORK ALTERING CASING CE DRILLING OPNS. PAND A CEMENT JOB MIT & return to injection Amount details, and give pertinent dates, including
NOTICE PERFORM REMEDIAL W TEMPORARILY ABANDO PULL OR ALTER CASING OTHER: 13. Describe propose estimated date of diagram of propose 11/10/10 – RU, re	E OF INTENTION TO: VORK PLUG AND ABANDON REMEDIA COMMEN COMMEN CASING/O OTHER: Sed or completed operations. (Clearly state all pertir of starting any proposed work). SEE RULE 1103. Fosed completion or recompletion.	SUBSEQUENT REPORT OF: LE WORK ALTERING CASING CE DRILLING OPNS. PAND A CEMENT JOB MIT & return to injection Amount details, and give pertinent dates, including
NOTICE PERFORM REMEDIAL W TEMPORARILY ABANDO PULL OR ALTER CASING OTHER: 13. Describe propose estimated date of diagram of propose 11/10/10 – RU, re 11/11/10 – RU te	E OF INTENTION TO: VORK PLUG AND ABANDON REMEDIA COMMEN COMMEN CASING/O OTHER: Seed or completed operations. (Clearly state all pertir of starting any proposed work). SEE RULE 1103. Fosed completion or recompletion. Pelease pkr & POOH w/ 2-3/8" tbg. SDFN. Ster & PU new pkr to test tbg in hole. SDFN.	SUBSEQUENT REPORT OF: LE WORK ALTERING CASING CE DRILLING OPNS. PAND A CEMENT JOB MIT & return to injection Amount details, and give pertinent dates, including
NOTICE PERFORM REMEDIAL W TEMPORARILY ABANDO PULL OR ALTER CASING OTHER: 13. Describe proposestimated date of diagram of proposestimated date of the diagram of proposestimated date of the diagram of proposestimated date of the diagram of the di	E OF INTENTION TO: VORK PLUG AND ABANDON REMEDIA COMMEN COMMEN CASING/O OTHER: Seed or completed operations. (Clearly state all pertir of starting any proposed work). SEE RULE 1103. Fosed completion or recompletion. Pelease pkr & POOH w/ 2-3/8" tbg. SDFN. Ster & PU new pkr to test tbg in hole. SDFN. H w/ tbg, cleanout fill to 6085'. SDFN.	SUBSEQUENT REPORT OF: L WORK ALTERING CASING CE DRILLING OPNS. P AND A CEMENT JOB MIT & return to injection Ment details, and give pertinent dates, including for Multiple Completions: Attach wellbore
NOTICE PERFORM REMEDIAL W TEMPORARILY ABANDO PULL OR ALTER CASING OTHER: 13. Describe proposestimated date of diagram of proposestimated to the diagram of proposestimated to	E OF INTENTION TO: VORK PLUG AND ABANDON REMEDIA COMMEN CHANGE PLANS COMMEN CASING/O OTHER: Sed or completed operations. (Clearly state all pertir of starting any proposed work). SEE RULE 1103. Fosed completion or recompletion. Selease pkr & POOH w/ 2-3/8" tbg. SDFN. Ster & PU new pkr to test tbg in hole. SDFN. H w/ tbg, cleanout fill to 6085'. SDFN. V/ pkr & tbg, circulate pkr fluid. Set pkr & tested OK.	SUBSEQUENT REPORT OF: L WORK ALTERING CASING CE DRILLING OPNS. P AND A CEMENT JOB MIT & return to injection Ment details, and give pertinent dates, including for Multiple Completions: Attach wellbore
NOTICE PERFORM REMEDIAL W TEMPORARILY ABANDO PULL OR ALTER CASING OTHER: 13. Describe proposestimated date of diagram of proposestimated to the diagram of proposestimated to	E OF INTENTION TO: VORK PLUG AND ABANDON REMEDIA COMMEN COMMEN CASING/O OTHER: Seed or completed operations. (Clearly state all pertir of starting any proposed work). SEE RULE 1103. Fosed completion or recompletion. Pelease pkr & POOH w/ 2-3/8" tbg. SDFN. Ster & PU new pkr to test tbg in hole. SDFN. H w/ tbg, cleanout fill to 6085'. SDFN.	SUBSEQUENT REPORT OF: L WORK ALTERING CASING CE DRILLING OPNS. P AND A CEMENT JOB MIT & return to injection Ment details, and give pertinent dates, including for Multiple Completions: Attach wellbore
NOTICE PERFORM REMEDIAL W TEMPORARILY ABANDO PULL OR ALTER CASING OTHER: 13. Describe proposestimated date of diagram of proposestimated at the diagram of proposestimated at	E OF INTENTION TO: VORK PLUG AND ABANDON REMEDIA COMMEN CHANGE PLANS COMMEN CASING/O OTHER: Sed or completed operations. (Clearly state all pertir of starting any proposed work). SEE RULE 1103. Fosed completion or recompletion. Elease pkr & POOH w/ 2-3/8" tbg. SDFN. Ster & PU new pkr to test tbg in hole. SDFN. H w/ tbg, cleanout fill to 6085'. SDFN. V/ pkr & tbg, circulate pkr fluid. Set pkr & tested OK. AS_1X pkr set @ 4991', with top perf @ 5054'.	SUBSEQUENT REPORT OF: LE WORK ALTERING CASING CE DRILLING OPNS. PAND A CEMENT JOB MIT & return to injection Ment details, and give pertinent dates, including for Multiple Completions: Attach wellbore RDMO. Wait on OCD approval.
NOTICE PERFORM REMEDIAL W TEMPORARILY ABANDO PULL OR ALTER CASING OTHER: 13. Describe proposestimated date of diagram of proposestimated at the diagram of proposestimated at	E OF INTENTION TO: VORK PLUG AND ABANDON REMEDIA COMMEN CHANGE PLANS COMMEN CASING/O OTHER: Sed or completed operations. (Clearly state all pertir of starting any proposed work). SEE RULE 1103. Fosed completion or recompletion. Selease pkr & POOH w/ 2-3/8" tbg. SDFN. Ster & PU new pkr to test tbg in hole. SDFN. H w/ tbg, cleanout fill to 6085'. SDFN. V/ pkr & tbg, circulate pkr fluid. Set pkr & tested OK.	SUBSEQUENT REPORT OF: LE WORK ALTERING CASING CE DRILLING OPNS. PAND A CEMENT JOB MIT & return to injection Ment details, and give pertinent dates, including for Multiple Completions: Attach wellbore RDMO. Wait on OCD approval.
NOTICE PERFORM REMEDIAL W TEMPORARILY ABANDO PULL OR ALTER CASING OTHER: 13. Describe proposestimated date of diagram of proposestimated at the diagram of proposestimated at	E OF INTENTION TO: VORK PLUG AND ABANDON REMEDIA COMMEN CHANGE PLANS COMMEN CASING/O OTHER: Sed or completed operations. (Clearly state all pertir of starting any proposed work). SEE RULE 1103. Fosed completion or recompletion. Elease pkr & POOH w/ 2-3/8" tbg. SDFN. Ster & PU new pkr to test tbg in hole. SDFN. H w/ tbg, cleanout fill to 6085'. SDFN. V/ pkr & tbg, circulate pkr fluid. Set pkr & tested OK. AS_1X pkr set @ 4991', with top perf @ 5054'.	SUBSEQUENT REPORT OF: LE WORK ALTERING CASING CE DRILLING OPNS. PAND A CEMENT JOB MIT & return to injection Ment details, and give pertinent dates, including for Multiple Completions: Attach wellbore RDMO. Wait on OCD approval.
NOTICE PERFORM REMEDIAL W TEMPORARILY ABANDO PULL OR ALTER CASING OTHER: 13. Describe proposestimated date of diagram of date of diagram of diagram of proposestimated date of diagram of date o	E OF INTENTION TO: VORK PLUG AND ABANDON REMEDIA COMMEN COMMEN CASING/O OTHER: Seed or completed operations. (Clearly state all pertir of starting any proposed work). SEE RULE 1103. For seed completion or recompletion. Selease pkr & POOH w/ 2-3/8" tbg. SDFN. Selease pkr &	SUBSEQUENT REPORT OF: LE WORK ALTERING CASING CE DRILLING OPNS. PAND A MIT & return to injection And the properties of
NOTICE PERFORM REMEDIAL W TEMPORARILY ABANDO PULL OR ALTER CASING OTHER: 13. Describe proposestimated date of diagram of proposestimated and the second data of the diagram of proposestimated date of diagram of date of diagram of proposestimated date of diagram of date of dat	E OF INTENTION TO: VORK PLUG AND ABANDON REMEDIA COMMEN COMMEN COMMEN CASING/O OTHER: Seed or completed operations. (Clearly state all pertir of starting any proposed work). SEE RULE 1103. For seed completion or recompletion. Selease pkr & POOH w/ 2-3/8" tbg. SDFN. Selea	SUBSEQUENT REPORT OF: LE WORK ALTERING CASING CE DRILLING OPNS. PAND A MIT & return to injection And the properties of
NOTICE PERFORM REMEDIAL W TEMPORARILY ABANDO PULL OR ALTER CASING OTHER: 13. Describe proposestimated date of diagram of date of diagram of diagram of proposestimated date of diagram of date o	E OF INTENTION TO: VORK PLUG AND ABANDON REMEDIA COMMEN COMMEN COMMEN CASING/O OTHER: Seed or completed operations. (Clearly state all pertir of starting any proposed work). SEE RULE 1103. For seed completion or recompletion. Selease pkr & POOH w/ 2-3/8" tbg. SDFN. Selea	SUBSEQUENT REPORT OF: LE WORK ALTERING CASING CE DRILLING OPNS. PAND A MIT & return to injection And the properties of
NOTICE PERFORM REMEDIAL W TEMPORARILY ABANDO PULL OR ALTER CASING OTHER: 13. Describe proposestimated date of diagram of proposestimated alternative occurrents. It is not below-grade tank has be alternative occurrents.	E OF INTENTION TO: VORK PLUG AND ABANDON REMEDIA COMMEN COMMEN COMMEN CASING/O DOTHER: Seed or completed operations. (Clearly state all pertir of starting any proposed work). SEE RULE 1103. For seed completion or recompletion. Selease pkr & POOH w/ 2-3/8" tbg. SDFN. Ster & PU new pkr to test tbg in hole. SDFN. Helease pkr & to test tbg in hole. SDFN. Help yellow by the set of the seen/will be constructed or closed according to NMOCD guidan .	SUBSEQUENT REPORT OF: L WORK ALTERING CASING CE DRILLING OPNS. PAND A MIT & return to injection Ment details, and give pertinent dates, including for Multiple Completions: Attach wellbore RDMO. Wait on OCD approval. RSSEED BY OCD. Chart attached. If my knowledge and belief. I further certify that any delines , a general permit or an (attached)
NOTICE PERFORM REMEDIAL W TEMPORARILY ABANDO PULL OR ALTER CASING OTHER: 13. Describe proposestimated date of diagram of proposestimated and the second data of the diagram of proposestimated date of diagram of date of diagram of proposestimated date of diagram of date of dat	E OF INTENTION TO: VORK PLUG AND ABANDON REMEDIA COMMEN COMMEN COMMEN CASING/O OTHER: Seed or completed operations. (Clearly state all pertir of starting any proposed work). SEE RULE 1103. For seed completion or recompletion. Selease pkr & POOH w/ 2-3/8" tbg. SDFN. Selea	SUBSEQUENT REPORT OF: LE WORK ALTERING CASING CEDRILLING OPNS. PAND A MIT & return to injection Ment details, and give pertinent dates, including for Multiple Completions: Attach wellbore RDMO. Wait on OCD approval. Ressed by OCD. Chart attached. If my knowledge and belief. I further certify that any delines , a general permit or an (attached)
NOTICE PERFORM REMEDIAL W TEMPORARILY ABANDO PULL OR ALTER CASING OTHER: 13. Describe proposestimated date of diagram of of dia	E OF INTENTION TO: VORK PLUG AND ABANDON REMEDIA COMMEN CHANGE PLANS COMMEN CASING/O OTHER: Seed or completed operations. (Clearly state all pertir of starting any proposed work). SEE RULE 1103. Fosed completion or recompletion. Selease pkr & POOH w/ 2-3/8" tbg. SDFN. Selease pkr & POOH w/ 2-3/8" tbg. SDFN. H w/ tbg, cleanout fill to 6085'. SDFN. M pkr & tbg, circulate pkr fluid. Set pkr & tested OK. AS_1X pkr set @ 4991', with top perf @ 5054'. Source tested to 540# for 60 min., tested OK. Not with Information above is true and complete to the best of open/will be constructed or closed according to NMOCD guid TITLE: Production Superintend	SUBSEQUENT REPORT OF: LEWORK ALTERING CASING CEDRILLING OPNS. PAND A MIT & return to injection Menent details, and give pertinent dates, including for Multiple Completions: Attach wellbore RDMO. Wait on OCD approval. Ressed by OCD. Chart attached. If my knowledge and belief. I further certify that any delines not a general permit or an (attached) MIT & return to injection or an (attached)
NOTICE PERFORM REMEDIAL W TEMPORARILY ABANDO PULL OR ALTER CASING OTHER: 13. Describe proposestimated date of diagram of proposestimated proposestimated date of diagram of proposestimated at the diagram of proposestimated at the diagram of proposestimated date of diagram of proposestimated dat	E OF INTENTION TO: VORK PLUG AND ABANDON REMEDIA COMMEN COMMEN COMMEN CASING/O DOTHER: Seed or completed operations. (Clearly state all pertir of starting any proposed work). SEE RULE 1103. For seed completion or recompletion. Selease pkr & POOH w/ 2-3/8" tbg. SDFN. Ster & PU new pkr to test tbg in hole. SDFN. Helease pkr & to test tbg in hole. SDFN. Help yellow by the set of the seen/will be constructed or closed according to NMOCD guidan .	SUBSEQUENT REPORT OF: L WORK ALTERING CASING CE DRILLING OPNS. PAND A MIT & return to injection Ment details, and give pertinent dates, including for Multiple Completions: Attach wellbore RDMO. Wait on OCD approval. RSSEED BY OCD. Chart attached. If my knowledge and belief. I further certify that any delines , a general permit or an (attached)
NOTICE PERFORM REMEDIAL W TEMPORARILY ABANDO PULL OR ALTER CASING OTHER: 13. Describe proposestimated date of diagram of of dia	E OF INTENTION TO: VORK PLUG AND ABANDON REMEDIA COMMEN CHANGE PLANS COMMEN CASING/O OTHER: Seed or completed operations. (Clearly state all pertir of starting any proposed work). SEE RULE 1103. Fosed completion or recompletion. Selease pkr & POOH w/ 2-3/8" tbg. SDFN. Selease pkr & POOH w/ 2-3/8" tbg. SDFN. H w/ tbg, cleanout fill to 6085'. SDFN. M pkr & tbg, circulate pkr fluid. Set pkr & tested OK. AS_1X pkr set @ 4991', with top perf @ 5054'. Source tested to 540# for 60 min., tested OK. Not with Information above is true and complete to the best of open/will be constructed or closed according to NMOCD guid TITLE: Production Superintend	SUBSEQUENT REPORT OF: LEWORK ALTERING CASING CEDRILLING OPNS. PAND A MIT & return to injection Menent details, and give pertinent dates, including for Multiple Completions: Attach wellbore RDMO. Wait on OCD approval. Ressed by OCD. Chart attached. If my knowledge and belief. I further certify that any delines not a general permit or an (attached) MIT & return to injection or an (attached)
NOTICE PERFORM REMEDIAL W TEMPORARILY ABANDO PULL OR ALTER CASING OTHER: 13. Describe proposestimated date of diagram of proposestimated proposestimated date of diagram of proposestimated at the diagram of proposestimated at the diagram of proposestimated date of diagram of proposestimated dat	E OF INTENTION TO: ORK PLUG AND ABANDON REMEDIA COMMEN COMMEN CASING/O OTHER: Seed or completed operations. (Clearly state all pertir of starting any proposed work). SEE RULE 1103. For seed completion or recompletion. Selease pkr & POOH w/ 2-3/8" tbg. SDFN. Ster & PU new pkr to test tbg in hole. SDFN. H w/ tbg, cleanout fill to 6085'. SDFN. H w/ tbg, circulate pkr fluid. Set pkr & tested OK. AS_1X pkr set @ 4991', with top perf @ 5054'. Source tested to 540# for 60 min., tested OK. Not without the seen/will be constructed or closed according to NMOCD guidan . E-mail address: E-mail address:	SUBSEQUENT REPORT OF: L WORK ALTERING CASING CE DRILLING OPNS. PAND A MIT & return to injection Menent details, and give pertinent dates, including for Multiple Completions: Attach wellbore RDMO. Wait on OCD approval. RSSEED BY OCD. Chart attached. If my knowledge and belief. I further certify that any delines ageneral permit or an (attached) MIT & return to injection or mile or mi
NOTICE PERFORM REMEDIAL W TEMPORARILY ABANDO PULL OR ALTER CASING OTHER: 13. Describe proposestimated date of diagram of proposestimated at the diagram of proposestimated date of diagram of proposest	E OF INTENTION TO: VORK PLUG AND ABANDON REMEDIA COMMEN CHANGE PLANS COMMEN CASING/O OTHER: Seed or completed operations. (Clearly state all pertir of starting any proposed work). SEE RULE 1103. Fosed completion or recompletion. Selease pkr & POOH w/ 2-3/8" tbg. SDFN. Selease pkr & POOH w/ 2-3/8" tbg. SDFN. H w/ tbg, cleanout fill to 6085'. SDFN. M pkr & tbg, circulate pkr fluid. Set pkr & tested OK. AS_1X pkr set @ 4991', with top perf @ 5054'. Source tested to 540# for 60 min., tested OK. Not with Information above is true and complete to the best of open/will be constructed or closed according to NMOCD guid TITLE: Production Superintend	SUBSEQUENT REPORT OF: L WORK ALTERING CASING CE DRILLING OPNS. PAND A MIT & return to injection Menent details, and give pertinent dates, including for Multiple Completions: Attach wellbore RDMO. Wait on OCD approval. RSSEED BY OCD. Chart attached. If my knowledge and belief. I further certify that any delines ageneral permit or an (attached) MIT & return to injection or middle in the certify that any delines or middle in the certify that any delines or an (attached) MIT & return to injection or middle in the certify that any delines or middle in the certify that any delines or an (attached) MIT & return to injection or middle in the certify that any delines or middle in the certification or middle in

WELLBORE SCHEMATIC





Recorder
Calcharted 11/15/10
Spring 1000#
Clock 60min
Thy 100#
Cog 540#
Braden 8#

Jillot
Legacy Reserves

TRM K-142 South Justis unit ## 4280