State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE OIL CONSERVAT	TION DIVISION
DISTRICT I 1625 N. French Dr., Hobbs, NM 88240 RECEIVED 1220 South St. Santa Fe, N	Francis Dr. WELL API NO. 30-025-31428
DISTRICT II 1301 W. Grand Ave, Artesia, NM 88210 DEC 1 4 2010	5. Indicate Type of Lease STATE X FEE
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410 HOBBSOCD	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELL	S 7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OF DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)
1. Type of Well: Oil Well X Gas Well Other	8. Well No. 234
Name of Operator Occidental Permian Ltd.	9. OGRID No. 157984
3. Address of Operator HCR I Box 90 Denver City, TX 79323	10. Pool name or Wildcat Hobbs (G/SA)
4. Well Location	
Unit Letter F : 2480 Feet From The North	Range 38-F NMPM Lea County
Section 4 Township 19-S 11. Elevation (Show whether DF, RKB, 3607' GL	70-E
Pit or Below-grade Tank Application or Closure	
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water	
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material	
12. Check Appropriate Box to Indicate Natur NOTICE OF INTENTION TO:	e of Notice, Report, or Other Data SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON F	REMEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS. PLUG & ABANDONMENT
PULL OR ALTER CASING Multiple Completion	CASING TEST AND CEMENT JOB
OTHER: X	OTHER: Temporarily abandon well/TA status request X
 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. RUPU & RU. POOH w/ESP equipment and tubing and lay down. NU BOP/ND wellhead. RIH w/bit & string mill. Run casing scraper to clean up casing walls. RU power swivel & stripper head. Clean out well from 4085-4245'. RD power swivel & stripper head. POOH w/bit & string mill. RIH w/CIBP set @4223' w/10' of cement on top & CIBP set @4035' w/35' of cement on top. 	
6. Test casing to 540 PSI and chart for the NMOCD. Mark Whittaker w/NMOCD on site for test.	
 ND BOP/NU TA wellhead. RDPU & RU. Clean location and leave well TA'd. 	
8. RDFU & RO. Clean location and leave well 1A d.	This Approval of Temporary Abandonment Expires 11-18-2015
RUPU 10/13/2010 RDPU 10/20/2010	Top perf @4085'
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or	
closed according to NMOCD guidelines , a general permit	or an (attached) alternative OCD-approved plan
SIGNATURE MENDER CLASH	•
	TITLE Administrative Associate DATE 12/10/2010
TYPE OR PRINT NAME Mendy A. Johnson E-mail address:	mendy johnson@oxy.com TELEPHONE NO. 806-592-6280
For State Use Only	mendy_johnson@oxy.com TELEPHONE NO. 806-592-6280

