

Submit 1 Copy To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
October 13, 2009

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-07270
1. Type of Well: Oil Well ☐ Gas Well ☐ Other Permitted SWD ☒		5. Indicate Type of Lease STATE ☐ FEE ☐
2. Name of Operator State of New Mexico / Platinum Exploration Inc.		6. State Oil & Gas Lease No.
3. Address of Operator		7. Lease Name or Unit Agreement Name Gulf State
4. Well Location Unit Letter C : 660 feet from the N line and 1880 feet from the W line Section 4 Township 16S Range 38E NMPM County LEA		8. Well Number 3
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number
		10. Pool name or Wildcat

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ DOWNHOLE COMMINGLE ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☐ P AND A ☐ CASING/CEMENT JOB ☐ OTHER: ☐
--	---

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1) GIH to 6,500'. Circulate hole w/ 10# brine w/ 25 sx salt gel per 100 bbls.
- 2) POOH to 5,050'. Spot 35 sx cmt. WOC & Tag.
- 3) POOH to 3,100'. Spot 35 sx cmt.
- 4) POOH to 2,100'. Spot 35 sx cmt.
- 5) POOH to 400'. Spot 35 sx cmt. WOC & Tag.
- 6) POOH to 60'. Spot 20 sx cmt.
- 7) Cut off wellhead and erect dry hole marker.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Mat Whitaker

TITLE

Comp. Officer

DATE

12-7-2011

Type or print name

E-mail address:

PHONE:

For State Use Only

APPROVED BY:

[Signature]

TITLE

Staff MGR

DATE

12-7-2011

Conditions of Approval (if any):

PLUGGING & ABANDONMENT WORKSHEET

(2 STRING CSNG)

OPERATOR

LEASENAME GULF STATE

SECT 4 TWN 16S WELL # 3
 FROM 660 (N) S L 1880 RNG 38E
 TD: 13,346 FORMATION @ TD E(W)
 PBTD: 6500 FORMATION @ PBTD

13 3/8
 @ 350'
 TOC

9 5/8
 @ 4,999'
 TOC

PBTD 6500'
 TD 13,346

	SIZE	SET @	TOC	TOC DETERMINED BY	
SURFACE	13 3/8	350'	CIRC		
INTMED 1	9 5/8	4,999'	CIRC		
INTMED 2					
PROD					
	SIZE	TOP	BOT	TOC	DETERMINED BY
LINER 1					
LINER 2					
	CUT & PULL @			TOP - BOTTOM	
INTMED 1			PERFS		-
INTMED 2			OPENHOLE		-
PROD					

*REQUIRED PLUGS DISTRICT I

KUSTLER (ANYTD)	2177	*
YATES	3233	
QUEEN	4083	
GRAYBURG	4664	
SAN ANDREW	4963	
CAPTAN REEF		*
DELAWARE		
BELL CANYON		
CHEEKY CANYON		
BRUSHY CANYON		
BOKE SPRING		
OKONKITA		*
BLINDBRY		
TUBB	7738	
DRIDGARD		
ABO	8450	
WCO		
PERCH	10,621	
STRAWN		
ATOKA		
MAKELOW		
LOIS		
DEVOREAN	13,286	

PLUG	TYPE	SACKS	DEPTH
	PLUG	CMNT	
EXAMPLES			
PLUG #1	OH	35 SXS	6400'
PLUG #2	SHOE	50 SXS	5350'-5450'
PLUG #3	CIBP/35'		4800'
PLUG #4	CIBP	25 SXS	4800'
PLUG #5	STUB	50 SXS	3600'-3700'
PLUG #6	REINRSQZ	200 SXS	400'
PLUG #7	SURF	10 SXS	0-10'
PLUG #1	SHOE	35 SX	4950-5050
PLUG #2	B SALT	35 SX	3000-3100
PLUG #3	T. SALT	35 SX	2000-2100
PLUG #4	SHOE	35 SX	300-400
PLUG #5	SURF	20 SX	0-60
PLUG #6			
PLUG #7			
PLUG #8			
PLUG #9			
PLUG #10			
PLUG #11			
PLUG #12			
PLUG #13			
PLUG #14			
PLUG #15			
PLUG #16			
PLUG #17			
PLUG #18			
PLUG #19			
PLUG #20			