
Submit 1 Copy To Appropriate District Office State of New Mexico	Form C-103 October 13, 2009
District I Energy, Minerals and Natural Resources	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-35597 5. Indicate Type of Lease
District III 1220 South St. Francis Dr.	STATE X FEE
DISTILLTY	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa FOBBSOCU 87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	S V Sundown State
1. Type of Well: Oil Well 🖾 Gas Well 🗌 Other	8. Well Number 2
2. Name of Operator Three Rivers Operating Company, LLC	9. OGRID Number 272295
3. Address of Operator	10. Pool name or Wildcat
1122 S Capital of Texas Hwy Ste 325 Austin, TX 79746	Echols; San Andres, East
4. Well Location Unit Letter M: 660 feet from the South line and 660 feet from the West line	
Section 14 Township 10S Range 37E NMPM County Lea	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3940 GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING	
TEMPORARILY ABANDON 🖾 CHANGE PLANS 🔲 COMMENCE DRILLING OPNS. 🗌 P AND A 🔲 PULL OR ALTER CASING 🔲 MULTIPLE COMPL 🔲 CASING/CEMENT JOB	
DOWNHOLE COMMINGLE	
OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and	d give pertinent dates, including estimated date
	d give pertinent dates, including estimated date inpletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Con	mpletions: Attach wellbore diagram of
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion.	npletions: Attach wellbore diagram of 11. RIH w/ pkr & set @
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. Notify OCD of test. Initial MIT was done 1/10/	npletions: Attach wellbore diagram of 11. RIH w/ pkr & set @ wtr, press to 500 psi
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Notify OCD of test. Initial MIT was done 1/10/4947¹, RU pump trk, load hole w/ 13 bbls fresh	npletions: Attach wellbore diagram of 11. RIH w/ pkr & set @ wtr, press to 500 psi w/ tbg & pkr. RIH w/
 13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. Notify OCD of test. Initial MIT was done 1/10/4947', RU pump trk, load hole w/ 13 bbls fresh and hold for 45 min, held good. Rel pkr, POOH 	npletions: Attach wellbore diagram of 11. RIH w/ pkr & set @ wtr, press to 500 psi w/ tbg & pkr. RIH w/ 15'. RIH w/ tbg to 4882',
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Notify OCD of test. Initial MIT was done 1/10/4947', RU pump trk, load hole w/ 13 bbls fresh and hold for 45 min, held good. Rel pkr, POOH CIBP & set @ 4950', dump bail 35' cement to 49 circ hole w/ 200 bbls fresh wtr w/ pkr fld. LD	npletions: Attach wellbore diagram of 11. RIH w/ pkr & set @ wtr, press to 500 psi w/ tbg & pkr. RIH w/ 15'. RIH w/ tbg to 4882',
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. Notify OCD of test. Initial MIT was done 1/10/4947', RU pump trk, load hole w/ 13 bbls fresh and hold for 45 min, held good. Rel pkr, POOH CIBP & set @ 4950', dump bail 35' cement to 49 circ hole w/ 200 bbls fresh wtr w/ pkr fld. LD	npletions: Attach wellbore diagram of 11. RIH w/ pkr & set @ wtr, press to 500 psi w/ tbg & pkr. RIH w/ 15'. RIH w/ tbg to 4882', tbg, NDBOP, NUWH SWI.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. Notify OCD of test. Initial MIT was done 1/10/4947', RU pump trk, load hole w/ 13 bbls fresh and hold for 45 min, held good. Rel pkr, POOH CIBP & set @ 4950', dump bail 35' cement to 49 circ hole w/ 200 bbls fresh wtr w/ pkr fld. LD	npletions: Attach wellbore diagram of 11. RIH w/ pkr & set @ wtr, press to 500 psi w/ tbg & pkr. RIH w/ 15'. RIH w/ tbg to 4882',
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Notify OCD of test. Initial MIT was done 1/10/4947', RU pump trk, load hole w/ 13 bbls fresh and hold for 45 min, held good. Rel pkr, POOH CIBP & set @ 4950', dump bail 35' cement to 49 circ hole w/ 200 bbls fresh wtr w/ pkr fld. LD Top Penr 4996' This Approval of The Abandonment Exp	npletions: Attach wellbore diagram of 11. RIH w/ pkr & set @ wtr, press to 500 psi w/ tbg & pkr. RIH w/ 15'. RIH w/ tbg to 4882', tbg, NDBOP, NUWH SWI.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. Notify OCD of test. Initial MIT was done 1/10/4947', RU pump trk, load hole w/ 13 bbls fresh and hold for 45 min, held good. Rel pkr, POOH CIBP & set @ 4950', dump bail 35' cement to 49 circ hole w/ 200 bbls fresh wtr w/ pkr fld. LD	npletions: Attach wellbore diagram of 11. RIH w/ pkr & set @ wtr, press to 500 psi w/ tbg & pkr. RIH w/ 15'. RIH w/ tbg to 4882', tbg, NDBOP, NUWH SWI.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Notify OCD of test. Initial MIT was done 1/10/4947', RU pump trk, load hole w/ 13 bbls fresh and hold for 45 min, held good. Rel pkr, POOH CIBP & set @ 4950', dump bail 35' cement to 49 circ hole w/ 200 bbls fresh wtr w/ pkr fld. LD Top Penr 4996' This Approval of The Abandonment Exp	npletions: Attach wellbore diagram of 11. RIH w/ pkr & set @ wtr, press to 500 psi w/ tbg & pkr. RIH w/ 15'. RIH w/ tbg to 4882', tbg, NDBOP, NUWH SWI.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Corproposed completion or recompletion. Notify OCD of test. Initial MIT was done 1/10/4947', RU pump trk, load hole w/ 13 bbls fresh and hold for 45 min, held good. Rel pkr, POOH CIBP & set @ 4950', dump bail 35' cement to 49 circ hole w/ 200 bbls fresh wtr w/ pkr fld. LD Top Penr 4996' This Approval of The Abandonment Exp	npletions: Attach wellbore diagram of 11. RIH w/ pkr & set @ wtr, press to 500 psi w/ tbg & pkr. RIH w/ 15'. RIH w/ tbg to 4882', tbg, NDBOP, NUWH SWI.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Notify OCD of test. Initial MIT was done 1/10/4947', RU pump trk, load hole w/ 13 bbls fresh and hold for 45 min, held good. Rel pkr, POOH CIBP & set @ 4950', dump bail 35' cement to 49 circ hole w/ 200 bbls fresh wtr w/ pkr fld. LD TOP Perre 4996' This Approval of Abandonment Exp	11. RIH w/ pkr & set @ wtr, press to 500 psi w/ tbg & pkr. RIH w/ 15'. RIH w/ tbg to 4882', tbg, NDBOP, NUWH SWI.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Notify OCD of test. Initial MIT was done 1/10/4947', RU pump trk, load hole w/ 13 bbls fresh and hold for 45 min, held good. Rel pkr, POOH CIBP & set @ 4950', dump bail 35' cement to 49 circ hole w/ 200 bbls fresh wtr w/ pkr fld. LD TOP Pearl 4996' This Approval of This Approval of The Abandonment Expendence of	11. RIH w/ pkr & set @ wtr, press to 500 psi w/ tbg & pkr. RIH w/ 15'. RIH w/ tbg to 4882', tbg, NDBOP, NUWH SWI.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Notify OCD of test. Initial MIT was done 1/10/4947', RU pump trk, load hole w/ 13 bbls fresh and hold for 45 min, held good. Rel pkr, POOH CIBP & set @ 4950', dump bail 35' cement to 49 circ hole w/ 200 bbls fresh wtr w/ pkr fld. LD TOP Ferre 4996' This Approval of Abandonment Exp. Spud Date: Rig Release Date: Rig Release Date: Thereby certify that the information above is true and complete to the best of my knowledges and the state of the best of my knowledges. Type or print name Angela Lightner E-mail address: angela@rk	11. RIH w/ pkr & set @ wtr, press to 500 psi w/ tbg & pkr. RIH w/ 15'. RIH w/ tbg to 4882', tbg, NDBOP, NUWH SWI.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Notify OCD of test. Initial MIT was done 1/10/4947', RU pump trk, load hole w/ 13 bbls fresh and hold for 45 min, held good. Rel pkr, POOH CIBP & set @ 4950', dump bail 35' cement to 49 circ hole w/ 200 bbls fresh wtr w/ pkr fld. LD TOP Perf 4996' This Approval of Abandonment Exp. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledg SIGNATURE Type or print name Angela Lightner For State Use Only E-mail address: angela@rk For State Use Only	npletions: Attach wellbore diagram of 11. RIH w/ pkr & set @ wtr, press to 500 psi w/ tbg & pkr. RIH w/ 15'. RIH w/ tbg to 4882', tbg, NDBOP, NUWH SWI. Temporary 4-20/6 e and belief. sultant DATE 1-17-11 ford.com PHONE: 432-682-0440
13. Describe proposed or completed operations. (Clearly state all pertinent details, and of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. Notify OCD of test. Initial MIT was done 1/10/4947', RU pump trk, load hole w/ 13 bbls fresh and hold for 45 min, held good. Rel pkr, POOH CIBP & set @ 4950', dump bail 35' cement to 49 circ hole w/ 200 bbls fresh wtr w/ pkr fld. LD TOP Perro 4996' This Approval of Abandonment Exp. Spud Date: Rig Release Date: Rig Release Date: Thereby certify that the information above is true and complete to the best of my knowledges and the state of the best of my knowledges. Type or print name Angela Lightner E-mail address: angela@rk	npletions: Attach wellbore diagram of 11. RIH w/ pkr & set @ wtr, press to 500 psi w/ tbg & pkr. RIH w/ 15'. RIH w/ tbg to 4882', tbg, NDBOP, NUWH SWI. Temporary Dires 1-1-20/6 e and belief. sultant DATE 1-17-11 ford.com PHONE: 432-682-0440



SU SUNDOWN #2

CIBP @ 4950'

Comp Rep Kant Ciastle Camara

CARDY COMP MICK 3 UNIT #605