

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0135

z.ipiivo. vary	
Lease Serial No.	•
NIMI COSETION	

112

Expire	s: July 31, 2010)
Lease Serial No.		
NMLC065710	Α,	

SUNDELM	JIICES AND REPORTS ON WELLS
Do not use this t	form for proposals to drill or to re-enter an
abandoned well.	Use form 3160-3 (APD) for such proposals.

=	oposais to airii oi to i	C-CIILCI AII				
abandoned well. Use form 3	6. I	6. If Indian, Allottee or Tribe Name				
SUBMIT IN TRIPLICATE - Oti	7. I	7. If Unit or CA/Agreement, Name and/or No. LUSK WEST DELAWAR				
1. Type of Well ☐ Gas Well ☐ Other		8. Well Name and No. LUSK WEST DELAWARE UNIT 998				
2. Name of Operator CIMAREX ENERGY CO. OF COLORAD Mail		PI Well No. 0-025-30494	1			
3a. Address 600 N. MARIENFELD ST., STE. 600 MIDLAND, TX 79701	Ph: 432-6 Fx: 432-6		E) 10.	Field and Pool, o USK; DELAW	r Exploratory VARE, WEST	
4. Location of Well (Footage, Sec., T., R., M., or Surve	y Description)		n.	County or Parish	, and State	
✓ Sec 20 T19S R32E SENE 1651FNL 330FEL	- /		L	EA COUNTY,	, NM	
12. CHECK APPROPRIATE BO	OX(ES) TO INDICAT	E NATURE OF	NOTICE, REPOR	T, OR OTHE	ER DATA	
TYPE OF SUBMISSION		ТҮРЕ О	F ACTION			
Notice of Intent ☐ Acidize	D De	epen	Production (S	tart/Resume)	☐ Water Shut-O	ff
Alter Cas	sing \square Fr	acture Treat	☐ Reclamation		☐ Well Integrity	
☐ Subsequent Report ☐ Casing Re	epair Ne	w Construction	Recomplete		Other	
Final Abandonment Notice Change P	rlans Plu	ig and Abandon	Temporarily A	Abandon		
Convert to	o Injection Plu	ıg Back	☐ Water Dispos	al		
3160-5 Notice of Intent to TA, then recomplet amendments to the plans below: TA Procedure 1.) MIRU, KILL WELL IF NEEDED, POOH 2.) ND WH? NU 3K BOP, RELEASE TAC At 3.) RIW WITH 5?? CIBP, SET @ 6450?, CAF 4.) SPOT 25 SXS PLUG ACROSS SQZ PER 5.) SPOT 25 SXS PLUG ACROSS SQZ PER 6.) RUN FREEPOINT, CUT AND PULL 5-1/2 7.) SPOT 50 SXS PLUG ACROSS STUB AN 8.) SPOT40 SXS @3243-3123? (ACROSS D	I WITH RODS/PUMP. ND POOH TBG. LD TI P WITH 25 SXS CMT, RF @ 5800-5600? IF @ 5100-4900? I? CASING @ +/- 4500 D SHOE. ~4425-4565	LD. CO JBING. CO CIRCULATE WIT	SEE ATTACHED FOR CONDITIONS OF APPROVENCE WITH MUD. WOC AND TAG. FEB 04 2			
14. I hereby certify that the foregoing is true and correct. Electronic Sub	omission #101514 verifi	d by the BLM We	II Information System		ADTEOIA!	
For CIM	IAREX ENERGY CO. OF	COLORADO, sen	it to the Hobbs			
Name (Printed/Typed) NATALIE E KRUEGER		Title REGUL	ATORY			
Signature (Electronic Submission)		Date 01/27/2		K	M	
, THIS SI	PACE FOR FEDER	AL OR STATE	APPEN9E/F	D T		
Approved By		Title			Date	
onditions of approval, if any are attached. Approval of this critify that the applicant holds legal or equitable title to those hich would entitle the applicant to conduct operations there	e rights in the subject lease	Office /s/	FEB 1 201 Dustin Wini	kler		
tle 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 121 States any false, fictitious or fraudulent statements or representations.	12, make it a crime for any sentations as to any matter	person knowingly and within its urisdiction	NU IPELEARIA MARIAN ARLSBAD FIELD OF	nt Viepaltment o	r agency of the United	

Additional data for EC transaction #101514 that would not fit on the form

32. Additional remarks, continued

9.) SPOT 35 SXS 2868-2768? OVER CAPITAN REEF. REVERSE TUBING CLEAN. WOC AND TAG.10.) Schedule MIT and submit chart.

Recompletion Procedure:

- 1.) RUN CBL/CCL/GAMMA FROM PBTD TO TOC, ~2370? BY TEMP SURVEY. REPORT TOC TO MIDLAND DECIDE IF WE NEED TO SQUEEZE CASING TO GET A HIGHER TOC. IF NECESSARY, CONTACT BLM AND DETERMINE TOC NEEDED, PUNCH SQUEEZE HOLES AND ATTEMPT TO CIRCULATE CMT ABOVE CURRENT TOC.
- 2.) RIH WITH 3-3/8? CASING GUN AND PERF: 2640-2695? W/ 2SPF. POOH AND RD WIRELINE. CORRELATE TO ATLAS NEUTRON/GR LOG DATED 12-8-1988.
- 3.) MU 8-5/8? PACKER ON 2-7/8? PRODUCTION TUBING, TEST IN HOLE TO 7000#. SPOT 100 GAL ACID ACROSS PERFS. PULL PACKER ABOVE PERFS AND CIRCULATE CLEAN.
- 4.) RIH AND SET PKR @ 2600?. LOAD BACKSIDE, HOLD 500# ON BACK. ACIDIZE WITH 2000 GAL 15% NEFE @ 6BPM (IF TREATING PRESSURE ALLOWS). MONITOR TREATING PRESSURES AND SURFACE CASING. SWAB WELL DOWN UNTIL PH RISES. POOH.
- 5.) RIW WITH PRODUCTION STRING, RODS AND PUMP. EVALUATE OIL CUT AND INFLOW FOR POTENTIAL FRAC.

If successful, well will be pulled from the Lusk West Delaware Unit and name will be changed to Lusk Deep Unit A No. 15. Recompletion 3160-4 and C-104 to be submitted for new completion.